

**EXECUTIVE SUMMARY - ENFORCEMENT MATTER**  
**DOCKET NO.:** 2005-1839-AIR-E    **TCEQ ID:** RN102535077    **CASE NO.:** 26897  
**RESPONDENT NAME:** BP Products North America Inc.

**ORDER TYPE:**

<input type="checkbox"/> 1660 AGREED ORDER	<input checked="" type="checkbox"/> FINDINGS AGREED ORDER	<input type="checkbox"/> AMENDED ORDER	<input type="checkbox"/> IMMINENT AND SUBSTANTIAL ENDANGERMENT ORDER
<input type="checkbox"/> SHUTDOWN ORDER	<input type="checkbox"/> FINDINGS DEFAULT ORDER	<input type="checkbox"/> EMERGENCY ORDER	

**CASE TYPE:**

<input type="checkbox"/> AGRICULTURE	<input checked="" type="checkbox"/> AIR	<input type="checkbox"/> INDUSTRIAL AND HAZARDOUS WASTE	<input type="checkbox"/> MUNICIPAL SOLID WASTE
<input type="checkbox"/> OCCUPATIONAL CERTIFICATION	<input type="checkbox"/> PETROLEUM STORAGE TANKS	<input type="checkbox"/> PUBLIC WATER SUPPLY	<input type="checkbox"/> RADIOACTIVE WASTE
<input type="checkbox"/> MULTI-MEDIA (check all that apply)	<input type="checkbox"/> SEWAGE SLUDGE	<input type="checkbox"/> UNDERGROUND INJECTION CONTROL	<input type="checkbox"/> USED OIL
<input type="checkbox"/> USED OIL FILTER	<input type="checkbox"/> WATER QUALITY		

**SITE WHERE VIOLATION(S) OCCURRED:** BP Products North America Texas City, 2401 5th Avenue South, Texas City, Galveston County

**TYPE OF OPERATION:** Refinery

**SMALL BUSINESS:**     Yes     No

**OTHER SIGNIFICANT MATTERS:** There are no complaints. There is no record of additional pending enforcement actions regarding this facility location.

**INTERESTED PARTIES:** No one other than the ED and the Respondent has expressed an interest in this matter.

**COMMENTS RECEIVED:** The *Texas Register* comment period expired on April 17, 2006. No comments were received.

**CONTACTS AND MAILING LIST:**

**TCEQ Attorney/SEP Coordinator:** None

**TCEQ Enforcement Coordinator:** Ms. Suzanne Walrath, Enforcement Division, Enforcement Section II, MC 219, (512) 239-2134; Mr. Steven Lopez, Enforcement Division, MC 219, (512) 239-1896

**Respondent:** Mr. Colin Maclean, Business Unit Leader, BP Products North America Inc., P.O. Box 401, Texas City, Texas 77592-0401

**Respondent's Attorney:** Not represented by counsel on this enforcement matter

**VIOLATION SUMMARY CHART:**

VIOLATION INFORMATION	PENALTY CONSIDERATIONS	CORRECTIVE ACTIONS TAKEN/REQUIRED
<p><b>Type of Investigation:</b> <input type="checkbox"/> Complaint <input checked="" type="checkbox"/> Routine <input type="checkbox"/> Enforcement Follow-up <input type="checkbox"/> Records Review</p> <p><b>Date of Complaint Relating to this Case:</b> None</p> <p><b>Dates of Investigations Relating to this Case:</b> July 12, and August 4, 2004, April 5, June 1, August 4, and 11, 2005.</p> <p><b>Dates of NOEs Relating to this Case:</b> August 30, September 1, 15, and 16, 2005. (NOE)</p> <p><b>Background Facts:</b> This was a routine investigation. Three violations were documented.</p> <p><b>AIR</b></p> <p>1) Failed to prevent the unauthorized release of air contaminants into the atmosphere, and failed to maintain opacity at 30% averaged over a six-minute period [30 TEX. ADMIN. CODE §§ 111.111(a)(1)(A), 116.115(c), Air Permit Nos. 3810 and PSD-TX-402M2, C-18706, 18707, 19599 and PSD-TX-023, Special Condition No.1, and TEX. HEALTH &amp; SAFETY CODE § 382.085(b)].</p> <p>2) Failed to equip an open-ended line with a cap, blind flange, plug, or a second valve [30 TEX. ADMIN. CODE §§ 101.20(2), 115.352(4), and 40 CODE OF FEDERAL REGULATIONS § 63.167(a)(1), and TEX. HEALTH &amp; SAFETY CODE § 382.085(b)].</p> <p>3) Failed to prevent the unauthorized release of air contaminants into the atmosphere [30 TEX. ADMIN. CODE § 116.116(a), and TEX. HEALTH AND SAFETY CODE § 382.085(b)].</p>	<p><b>Total Assessed:</b> \$130,625</p> <p><b>Total Deferred:</b> \$0</p> <p><input type="checkbox"/> Expedited Settlement</p> <p><input type="checkbox"/> Financial Inability to Pay</p> <p><b>SEP Conditional Offset:</b> \$0</p> <p><b>Total Paid to General Revenue:</b> \$130,625</p> <p><b>Site Compliance History Classification:</b> <input type="checkbox"/> High <input checked="" type="checkbox"/> Avg. <input type="checkbox"/> Poor</p> <p><b>Person Compliance History Classification:</b> <input type="checkbox"/> High <input checked="" type="checkbox"/> Avg. <input type="checkbox"/> Poor</p> <p><b>Major Source:</b> <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No</p> <p><b>Applicable Penalty Policy:</b> September 2002</p> <p><b>Findings Order Justification:</b> The Respondent has been issued 30 NOVs with same or similar violations, 12 NOVs without same or similar violations, one 1660 Order, and four Findings Orders.</p>	<p><b>Corrective Actions Taken</b></p> <p>The Executive Director recognizes that BP Products has implemented the following corrective measures at the Plant:</p> <p>a. On August 18, 2003, concerning Incident No. 25606 which occurred on August 8, 2003, BP Products installed new heat exchanger bundles in the fluid catalytic cracking unit 2 ("FCCU2"), and unit technicians replaced faulty wiring on November 30, 2004;</p> <p>b. On November 30, 2003, concerning Incident No. 17651 which occurred on March 18, 2003, BP Products re-routed the sour water tank vent at the FCCU3 to the low-pressure refinery fuel gas system. The gas is now recovered, scrubbed to remove hydrogen sulfide, and used in various combustion sources at the refinery;</p> <p>c. On November 11, 2004, concerning Incident No. 49293 which occurred on November 10, 2004, BP Products repaired the faulty level alarm on the vessel that overflowed on the UU3;</p> <p>d. On November 30, 2004, concerning Incident No. 49566 which occurred on November 17, 2004, BP Products replaced the faulty wiring in the Resid Hydrotreater Unit ("RHU");</p> <p>e. On January 4, 2005, concerning Incident Nos. 51878 and 51879 which occurred on January 4, 2005, BP Products replaced the float in the liquid level controller on the 506-E depropanizer tower;</p> <p>f. On March 31, 2005, concerning Incident No. 49944 which occurred on November 24, 2004, BP Products replaced the level transmitter in the RHU during unit turnaround;</p> <p>g. On May 4, 2005, concerning Incident Nos. 54083 and 54088 which occurred on February 16, 2005, plant shift personnel responsible for proper functioning of plant equipment were instructed to check every shift for water in the instrument header at the FCCU3;</p>

VIOLATION INFORMATION	PENALTY CONSIDERATIONS	CORRECTIVE ACTIONS TAKEN/REQUIRED
		<p>h. On June 1, 2005, BP Products placed a plug on the open-ended line (tag no. 16333) at the FCCU3;</p> <p>i. On June 22, 2005, concerning Incident No. 55147 which occurred on February 25, 2005, BP re-trained all plant shift personnel responsible for proper functioning of the levels of the Pipestill 3A;</p> <p>j. On August 12, 2005, concerning Incident Nos. 58226, 58227 and 58231 which occurred on May 12, 2005, shift personnel responsible for proper flow and functioning of the light cat cycle oil ("LCCO") were re-trained, and the valve on the FCCU3 was closed and locked;</p> <p>k. On September 15, 2005, concerning Incident No. 54786 which occurred on March 3, 2005, BP Products implemented computer controller changes, and changes to startup procedures at the RHU;</p> <p>l. On September 28, 2005, concerning Incident Nos. 55442 and 55443 which occurred on March 17, 2005, the valve was repaired at the electrostatic precipitator;</p> <p>m. On September 28, 2005, concerning Incident Nos. 55487 and 56049 which occurred on March 18, 2005, the valve was repaired at the FCCU3; and</p> <p>n. On November 18, 2005, BP Product's notarized certification of compliance was received at the TCEQ.</p>

<p>1. The first part of the document discusses the importance of maintaining accurate records of all transactions. It emphasizes that proper record-keeping is essential for the integrity of the financial system and for the ability to detect and prevent fraud.</p>	<p>2. The second part of the document outlines the specific procedures for recording transactions. It details the steps involved in the accounting cycle, from identifying the transaction to the final closing of the books. It also discusses the importance of using standardized accounting principles and practices.</p>
<p>3. The third part of the document addresses the role of internal controls in ensuring the accuracy and reliability of financial information. It describes various control mechanisms, such as segregation of duties, authorization requirements, and regular reconciliations, and explains how they contribute to the overall risk management of the organization.</p>	<p>4. The fourth part of the document discusses the impact of technology on accounting and financial reporting. It highlights the benefits of using accounting software and digital tools, such as increased efficiency, reduced errors, and improved data security. It also touches upon the challenges associated with implementing and maintaining these technologies.</p>
<p>5. The fifth part of the document explores the ethical considerations that accountants and financial professionals must navigate. It discusses the importance of honesty, integrity, and objectivity in their work, and provides guidance on how to handle potential conflicts of interest and other ethical dilemmas.</p>	<p>6. The sixth part of the document concludes by summarizing the key points discussed throughout the document. It reiterates the importance of a strong foundation in accounting principles and practices, and the need for continuous learning and adaptation in a rapidly changing financial landscape.</p>

Accounting Principles and Practices

**Penalty Calculation Worksheet (PCW)**

Policy Revision 2 (September 2002) PCW Revision May 19, 2005

<b>DATES</b>	Assigned	06-Sep-2005	<b>Screening</b>	12-Sep-2005	<b>EPA Due</b>	23-Jun-2006
	PCW	07-Feb-2006				

<b>RESPONDENT/FACILITY INFORMATION</b>	
Respondent	BP Products North America Inc.
Reg. Ent. Ref. No.	RN102535077
Facility/Site Region	12-Houston
<b>Major/Minor Source</b>	Major Source

<b>CASE INFORMATION</b>			
Enf./Case ID No.	26897	No. of Violations	3
Docket No.	2005-1839-AIR-E	Order Type	Findings
Media Program(s)	Air Quality	Enf. Coordinator	Suzanne Walrath
Multi-Media		EC's Team	Enforcement Team 4
Admin. Penalty \$	Limit Minimum \$0	Maximum	\$10,000

**Penalty Calculation Section**

**TOTAL BASE PENALTY (Sum of violation base penalties)** **Subtotal 1**

**ADJUSTMENTS (+/-) TO SUBTOTAL 1**

Subtotals 2-7 are obtained by multiplying the Total Base Penalty (Subtotal 1) by the indicated percentage.

**Compliance History** 285% Enhancement **Subtotals 2, 3, & 7**

Notes

**Culpability** No 0% Enhancement **Subtotal 4**

Notes

**Good Faith Effort to Comply** 10% Reduction **Subtotal 5**

	Before NOV	NOV to EDPRP/Settlement Offer
Extraordinary	<input type="text"/>	<input type="text"/>
Ordinary	<input type="text"/>	<input checked="" type="checkbox"/>
N/A	<small>(mark with a small x)</small>	

Notes

**Economic Benefit** 50% Enhancement\* **Subtotal 6**

Total EB Amounts	\$447,301	<small>*Capped at the Total EB \$ Amount</small>
Approx. Cost of Compliance	\$3,345,795	

**SUM OF SUBTOTALS 1-7** **Final Subtotal**

**OTHER FACTORS AS JUSTICE MAY REQUIRE**  **Adjustment**

Reduces or enhances the Final Subtotal by the indicated percentage. (Enter number only; e.g. -30 for -30%.)

Notes

**Final Penalty Amount**

**STATUTORY LIMIT ADJUSTMENT** **Final Assessed Penalty**

**DEFERRAL** 0% Reduction **Adjustment**

Reduces the Final Assessed Penalty by the indicted percentage. (Enter number only; e.g. 20 for 20% reduction.)

Notes

**PAYABLE PENALTY**

**Screening Date** 12-Sep-2005 **Docket No.** 2005-1839-AIR-E **PCW**  
**Respondent** BP Products North America Inc. *Policy Revision 2 (September 2002)*  
**Case ID No.** 26897 *PCW Revision May 19, 2005*  
**Reg. Ent. Reference No.** RN102535077  
**Media [Statute]** Air Quality  
**Enf. Coordinator** Suzanne Walrath

**Compliance History Worksheet**

>> **Compliance History Site Enhancement (Subtotal 2)**

Component	Number of...	Enter Number Here	Adjust.
NOVs	Written NOVs with same or similar violations as those in the current enforcement action <i>(number of NOVs meeting criteria)</i>	30	150%
	Other written NOVs	12	24%
Orders	Any agreed final enforcement orders containing a denial of liability <i>(number of orders meeting criteria)</i>	1	20%
	Any adjudicated final enforcement orders, agreed final enforcement orders without a denial of liability, or default orders of this state or the federal government, or any final prohibitory emergency orders issued by the commission	4	100%
Judgments and Consent Decrees	Any non-adjudicated final court judgments or consent decrees containing a denial of liability of this state or the federal government <i>(number of judgements or consent decrees meeting criteria)</i>	0	0%
	Any adjudicated final court judgments and default judgments, or non-adjudicated final court judgments or consent decrees without a denial of liability, of this state or the federal government	0	0%
Convictions	Any criminal convictions of this state or the federal government <i>(number of counts)</i>	0	0%
Emissions	Chronic excessive emissions events <i>(number of events)</i>	0	0%
Audits	Letters notifying the executive director of an intended audit conducted under the Texas Environmental, Health, and Safety Audit Privilege Act, 74th Legislature, 1995 <i>(number of audits for which notices were)</i>	3	-3%
	Disclosures of violations under the Texas Environmental, Health, and Safety Audit Privilege Act, 74th Legislature, 1995 <i>(number of audits for which violations were disclosed)</i>	3	-6%
<i>Please Enter Yes or No</i>			
Other	Environmental management systems in place for one year or more	No	0%
	Voluntary on-site compliance assessments conducted by the executive director under a special assistance program	No	0%
	Participation in a voluntary pollution reduction program	No	0%
	Early compliance with, or offer of a product that meets future state or federal government environmental requirements	No	0%

**Adjustment Percentage (Subtotal 2) 285%**

>> **Repeat Violator (Subtotal 3)**

No

**Adjustment Percentage (Subtotal 3) 0%**

>> **Compliance History Person Classification (Subtotal 7)**

Average Performer

**Adjustment Percentage (Subtotal 7) 0%**

>> **Compliance History Summary**

**Compliance History Notes**

The respondent has been issued 30 NOVs with same or similar violations, 12 NOVs without same or similar violations, one 1660 order, and four Findings Orders. The respondent also submitted three letters notifying of an audit, and disclosed violations three times with respect to those audits.

**Total Adjustment Percentage (Subtotals 2, 3, & 7) 285%**

<b>Screening Date</b>	12-Sep-2005	<b>Docket No.</b>	2005-1839-AIR-E	<b>PCW</b>
<b>Respondent</b>	BP Products North America Inc.			<i>Policy Revision 2 (September 2002)</i>
<b>Case ID No.</b>	26897			<i>PCW Revision May 19, 2005</i>
<b>Reg. Ent. Reference No.</b>	RN102535077			
<b>Media [Statute]</b>	Air Quality			
<b>Enf. Coordinator</b>	Suzanne Walrath			
<b>Violation Number</b>	1			
<b>Primary Rule Cite(s)</b>	30 Tex. Admin. Code §§ 111.111(a)(1)(A), 116.115(c), and TCEQ Air Permit Nos. 8810 and PSD-TX-402M2, C-18706, 18707, 19599 and PSD-TX-023, Special Condition No. 1			
<b>Secondary Rule Cite(s)</b>	Tex. Health & Safety Code § 382.085(b)			
<b>Violation Description</b>	Failed to prevent the unauthorized release of air contaminants into the atmosphere, and failed to maintain opacity at 30% averaged during a six-minute period. Please see attached table for details. The events did not meet the demonstration criteria necessary to present an affirmative defense for the unauthorized emissions.			
	<b>Base Penalty</b>	\$10,000		

>> **Environmental, Property and Human Health Matrix**

		<b>Harm</b>			
	<b>Release</b>	Major	Moderate	Minor	
OR	Actual			X	<b>Percent</b> <span style="border: 1px solid black; padding: 2px;">25%</span>
	Potential				

>> **Programmatic Matrix**

	<b>Falsification</b>	Major	Moderate	Minor	<b>Percent</b> <span style="border: 1px solid black; padding: 2px;"></span>

**Matrix Notes** Human health or the environment has been exposed to insignificant amounts of pollutants which do not exceed levels that are protective of human health or environmental receptors as a result of the violation.

**Adjustment** -\$7,500

**Base Penalty Subtotal** \$2,500

**Violation Events**

**Number of Violation Events** 11

<i>mark only one use a small x</i>	<i>daily</i>	
	<i>monthly</i>	
	<i>quarterly</i>	
	<i>semiannual</i>	
	<i>annual</i>	
	<i>single event</i>	X

**Violation Base Penalty** \$27,500

Eleven single events are recommended for the eleven emission events (see attached table for details).

**Economic Benefit (EB) for this violation**

**Statutory Limit Test**

**Estimated EB Amount** \$447,301

**Violation Final Penalty Total** \$116,875

**This violation Final Assessed Penalty (adjusted for limits)** \$110,000

### Economic Benefit Worksheet

Respondent BP Products North America Inc.  
 Case ID No. 26897  
 Reg. Ent. Reference No. RN102535077  
 Media [Statute] Air Quality  
 Violation No. 1

Percent Interest	Years of Depreciation
5.0	15

Item Description	Item Cost	Date Required	Final Date	Yrs	Interest Saved	Onetime Costs	EB Amount
<b>Delayed Costs</b>							
Equipment				0.0	\$0	\$0	\$0
Buildings				0.0	\$0	\$0	\$0
Other (as needed)				0.0	\$0	\$0	\$0
Engineering/construction				0.0	\$0	\$0	\$0
Land				0.0	\$0	n/a	\$0
Record Keeping System				0.0	\$0	n/a	\$0
Training/Sampling				0.0	\$0	n/a	\$0
Remediation/Disposal				0.0	\$0	n/a	\$0
Permit Costs				0.0	\$0	n/a	\$0
Other (as needed)	\$3,345,595	18-Mar-2003	18-Nov-2005	2.7	\$447,301	n/a	\$447,301

Notes for DELAYED costs: These costs represent the amount to repair the units that were the cause of the emission events beginning on the date of the first event, and ending on the date that the certification of compliance was received.

Item	ANNUALIZE [1] avoided costs before entering item (except for one-time avoided costs)
Disposal	0.0 \$0 \$0 \$0
Personnel	0.0 \$0 \$0 \$0
Inspection/Reporting/Sampling	0.0 \$0 \$0 \$0
Supplies/equipment	0.0 \$0 \$0 \$0
Financial Assurance [2]	0.0 \$0 \$0 \$0
ONE-TIME avoided costs [3]	0.0 \$0 \$0 \$0
Other (as needed)	0.0 \$0 \$0 \$0

Notes for AVOIDED costs

Approx. Cost of Compliance **\$3,345,595** TOTAL **\$447,301**



<b>Screening Date</b> 12-Sep-2005	<b>Docket No.</b> 2005-1839-AIR-E	<b>PCW</b>
<b>Respondent</b> BP Products North America Inc.		<i>Policy Revision 2 (September 2002)</i>
<b>Case ID No.</b> 26897		<i>PCW Revision May 19, 2005</i>
<b>Reg. Ent. Reference No.</b> RN102535077		
<b>Media [Statute]</b> Air Quality		
<b>Enf. Coordinator</b> Suzanne Walrath		
<b>Violation Number</b> <input type="text" value="2"/>		
<b>Primary Rule Cite(s)</b>	30 Tex. Admin. Code §§ 101.20(2), 115.352(4), and 40 Code of Federal Regulations § 63.167(a)(1)	
<b>Secondary Rule Cite(s)</b>	Tex. Health & Safety Code § 382.085(b)	
<b>Violation Description</b>	Failed to equip an open-ended line (tag no. 16333) in the fluid catalytic cracking unit 3 ("FCCU3") with a cap, blind flange, plug, or a second valve. The estimated amount of fugitive VOC emissions from this open ended line is 0.12 lbs.	
	<b>Base Penalty</b>	<input type="text" value="\$10,000"/>

>> **Environmental, Property and Human Health Matrix**

<b>Harm</b>				
<b>Release</b>	Major	Moderate	Minor	
Actual	<input type="text"/>	<input type="text"/>	<b>X</b>	<b>Percent</b> <input type="text" value="25%"/>
Potential	<input type="text"/>	<input type="text"/>	<input type="text"/>	

>> **Programmatic Matrix**

Falsification	Major	Moderate	Minor	
<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<b>Percent</b> <input type="text"/>

**Matrix Notes**

Human health or the environment has been exposed to insignificant amounts of pollutants which do not exceed levels that are protective of human health or environmental receptors as a result of the violation.

**Adjustment**

**Base Penalty Subtotal**

**Violation Events**

Number of Violation Events

<i>mark only one use a small x</i>	daily	<input type="text"/>
	monthly	<input type="text"/>
	quarterly	<b>X</b>
	semiannual	<input type="text"/>
	annual	<input type="text"/>
	single event	<input type="text"/>

**Violation Base Penalty**

One quarterly event is recommended for the event which occurred on 6/1/05, as documented by the inspection which occurred on 6/1/05.

**Economic Benefit (EB) for this violation**

**Statutory Limit Test**

**Estimated EB Amount**

**Violation Final Penalty Total**

**This violation Final Assessed Penalty (adjusted for limits)**

### Economic Benefit Worksheet

Respondent BP Products North America Inc.  
 Case ID No. 26897  
 Reg. Ent. Reference No. RN102535077  
 Media [Statute] Air Quality  
 Violation No. 2

Percent Interest	Years of Depreciation
5.0	15

Item	Item Cost	Date Required	Final Date	Yrs	Interest Saved	Onetime Costs	EB Amount
<b>Delayed Costs</b>							
Equipment				0.0	\$0	\$0	\$0
Buildings				0.0	\$0	\$0	\$0
Other (as needed)				0.0	\$0	\$0	\$0
Engineering/construction				0.0	\$0	\$0	\$0
Land				0.0	\$0	n/a	\$0
Record Keeping System				0.0	\$0	n/a	\$0
Training/Sampling				0.0	\$0	n/a	\$0
Remediation/Disposal				0.0	\$0	n/a	\$0
Permit Costs				0.0	\$0	n/a	\$0
Other (as needed)	\$100	01-Jun-2005	01-Jun-2005	0.0	\$0	n/a	\$0

Notes for DELAYED costs: These costs represent the amount to repair the valve on the FCCU3, beginning on the date the open-ended line was discovered, and ending on the same day when it was repaired.

Item	ANNUALIZE [1] avoided costs before entering item (except for one-time avoided costs)	Yrs	Interest Saved	Onetime Costs	EB Amount
<b>Avoided Costs</b>					
Disposal		0.0	\$0	\$0	\$0
Personnel		0.0	\$0	\$0	\$0
Inspection/Reporting/Sampling		0.0	\$0	\$0	\$0
Supplies/equipment		0.0	\$0	\$0	\$0
Financial Assurance [2]		0.0	\$0	\$0	\$0
ONE-TIME avoided costs [3]		0.0	\$0	\$0	\$0
Other (as needed)		0.0	\$0	\$0	\$0

Notes for AVOIDED costs:

Approx. Cost of Compliance  TOTAL

**Screening Date** 12-Sep-2005 **Docket No.** 2005-1839-AIR-E **PCW**  
**Respondent** BP Products North America Inc. *Policy Revision 2 (September 2002)*  
**Case ID No.** 26897 *PCW Revision May 19, 2005*  
**Reg. Ent. Reference No.** RN102535077  
**Media [Statute]** Air Quality  
**Enf. Coordinator** Suzanne Walrath  
**Violation Number** 3  
**Primary Rule Cite(s)** 30 Tex. Admin. Code § 116.116(a)  
**Secondary Rule Cite(s)** Tex. Health & Safety Code § 382.085(b)  
**Violation Description** Failed to prevent the unauthorized release of air contaminants into the atmosphere from the UU3. Specifically, an operator failed to close a valve to the blowdown system in the UU3 (Incident No. 49293). The drum was full, and as a result, it overflowed to the blowdown stack which then released liquid. The spilled liquid vaporized, and released seven pounds of benzene, 28 lbs. of toluene, and 904 lbs. of unauthorized VOCs to the atmosphere. The events did not meet the demonstration criteria necessary to present an affirmative defense for the unauthorized emissions.

**Base Penalty** \$10,000

>> **Environmental, Property and Human Health Matrix**

		Harm			
Release		Major	Moderate	Minor	
OR	Actual			X	Percent 25%
	Potential				

>> **Programmatic Matrix**

		Major	Moderate	Minor	
Falsification					Percent

**Matrix Notes** Human health or the environment has been exposed to insignificant amounts of pollutants which do not exceed levels that are protective of human health or environmental receptors as a result of the violation.

**Adjustment** -\$7,500

**Base Penalty Subtotal** \$2,500

**Violation Events**

**Number of Violation Events** 1

mark only one use a small x	daily	
	monthly	
	quarterly	
	semiannual	
	annual	
single event	X	

**Violation Base Penalty** \$2,500

One single event is recommended for the one emission event which occurred on 11/10/04.

**Economic Benefit (EB) for this violation**

**Statutory Limit Test**

**Estimated EB Amount** \$0

**Violation Final Penalty Total** \$10,625

**This violation Final Assessed Penalty (adjusted for limits)** \$10,000

### Economic Benefit Worksheet

Respondent BP Products North America Inc.  
 Case ID No. 26897  
 Reg. Ent. Reference No. RN102535077  
 Media [Statute] Air Quality  
 Violation No. 3

Percent Interest	Years of Depreciation
5.0	15

Item	Item Cost	Date Required	Final Date	Yrs	Interest Saved	Onetime Costs	EB Amount
<b>Delayed Costs</b>							
Equipment				0.0	\$0	\$0	\$0
Buildings				0.0	\$0	\$0	\$0
Other (as needed)				0.0	\$0	\$0	\$0
Engineering/construction				0.0	\$0	\$0	\$0
Land				0.0	\$0	n/a	\$0
Record Keeping System				0.0	\$0	n/a	\$0
Training/Sampling				0.0	\$0	n/a	\$0
Remediation/Disposal				0.0	\$0	n/a	\$0
Permit Costs				0.0	\$0	n/a	\$0
Other (as needed)	\$100	10-Nov-2004	11-Nov-2004	0.0	\$0	n/a	\$0

Notes for DELAYED costs: These costs represent the amount to repair the faulty level alarm on the vessel that overflowed on the UU3, beginning on the date the event occurred, and ending the next day when it was repaired.

Item	ANNUALIZE [1] avoided costs before entering item (except for one-time avoided costs)
Disposal	\$0
Personnel	\$0
Inspection/Reporting/Sampling	\$0
Supplies/equipment	\$0
Financial Assurance [2]	\$0
ONE-TIME avoided costs [3]	\$0
Other (as needed)	\$0

Notes for AVOIDED costs:

Approx. Cost of Compliance **\$100** TOTAL **\$0**

**BP Products North America Inc.**

**RN102535077**

**Docket No. 2005-1839-AIR-E**

<b>Incident No.</b>	<b>Violation No. 1 - Date/ Permit No./ Cause</b>	<b>Unauthorized Emissions</b>	<b>Incident No.</b>	<b>Date/Permit No./Cause</b>	<b>Unauthorized Emissions</b>
17651	3/18 - 3/19/03 - New Source Review ("NSR") Permit No. 18707: BP failed to prevent the over pressure of Tank Nos. 159 and 161 at the fluid catalytic cracking unit 3 ("FCCU3"), and it began venting to the atmosphere. (19 hrs.)	3,989 lbs. of Volatile Organic Compounds ("VOCs")	55147	2/25/05 - NSR Permit No. 19599 and PSD-TX-023: The light feed to the Pipestill 3A unit resulted in a pressure surge which caused a release from relief valve no. 189 to the atmosphere. (22 min.)	45 lbs. of butane, 2,512 lbs. of hexane, 9 lbs. of isobutane, 1,710 lbs. of isopentane, 1,238 lbs. of pentane, 81 lbs. of benzene, and 20 lbs. of H <sub>2</sub> S
25606	8/8 - 8/18/03 - NSR Permit C-18706: BP failed to prevent a heat exchanger leak which occurred at the fluid catalytic cracking unit 2 ("FCCU2") cooling tower. (247 hrs.)	14,260 lbs. of VOCs	54786	3/3/05 - NSR Permit No. 8810 and PSD-TX-402M2: BP failed to prevent an increase in system pressure at the RHU, which caused a pressure controller to relieve to the CRPII Flare (EPN No. 501). (5 hrs., 50 min.)	2,368 lbs. of SO <sub>2</sub> , and 215 lbs. of CO
49566	11/17/04 - NSR Permit No. 8810 and PSD-TX-402M2: The electrical relay failed on the switchgear cubicle to the 557J light hydrocarbon compressor, causing the 557J compressor to trip and flare at the CRPII Flare[Emission Point No. ("EPN") No. 501] at the Resid Hydrotreating Unit ("RHU"). (40 min.)	1,765 lbs. of sulfur dioxide ("SO <sub>2</sub> "), 0.39 lbs. of nitrogen dioxide ("NO <sub>2</sub> "), 3 lbs. of nitrogen oxide ("NOx"), and 37 lbs. of carbon monoxide ("CO")	55442 & 55443	3/17/05 - NSR Permit No. 18707 - BP failed to prevent a malfunction of a north upper slide valve which caused high differential pressure between a regenerator and a reactor at the FCCU3, and also caused an unplanned shutdown of the electrostatic precipitator ("ESP"). This resulted in an 87% opacity for 6 min.	18 lbs. of alumina silica catalyst fines, and a 87% opacity for 6 minutes
49944	11/24/04 - NSR Permit No. 8810 and PSD-TX-402M2: The L2467 A & B level transmitters at the RHU failed and caused the 201-E High Pressure Amine Absorber oil side to become full of liquid. This caused increased pressure to the system, and the 207-F flash drum pressure controller opened to the CP II flare (EPN No. 501). (9 hrs., 24 min.)	7,696 lbs. of SO <sub>2</sub> , 59 lbs. of NOx, 7 lbs. of NO <sub>2</sub> and 711 lbs. of CO	55487 & 56049	3/18/05 - NSR Permit No. 18707: BP failed to prevent a slide valve failure at the FCCU3 which caused a decrease in reactor pressure and inlet temperature. The decrease in pressure and temperature caused a low plug valve malfunction which shutdown the unit and resulted in emissions from Flare No. 5 to the atmosphere. (2 hrs., 55 min.)	2,211 lbs. Of VOCs
51878 & 51879	1/4/05 - NSR Permit No. 18707: BP failed to prevent the malfunction of a liquid level controller (L4834) on the 506-E depropanizer tower, which resulted in emissions from Flares No. 3 and 5 to the atmosphere. (13 hrs. 36 min.)	2100 lbs. of VOCs, and 27 lbs. hydrogen sulfide ("H <sub>2</sub> S")	58226, 58227, & 58231	5/12/05 - NSR Permit No. 18707: BP failed to properly direct the flow of Light Cat Cycle Oil ("LCCO") from a loading dock during an oil movements line-up procedure. The LCCO was inadvertently routed to FCCU3, which resulted in an increase in reactor pressure and the shutdown of the unit. The shutdown of the unit resulted in the release of unauthorized emissions from the ESP stack to the atmosphere. This also resulted in an 89% opacity for 6 minutes. (14 hrs., 16 min.)	4,028 lbs. of VOCs, 13.44 lbs. of H <sub>2</sub> S, 15.42 lbs. of alumina silica catalyst fines, and an 89% opacity for 6 minutes.
54083 & 54088	2/16/05 - NSR Permit No. 18707 - BP failed to prevent excessive water from collecting in an instrument air header which caused an increase in reactor pressure that resulted in venting to Flare No. 3 at the FCCU3, and also caused an unplanned shutdown of the ESP. This resulted in a 59% opacity for 6 minutes. (6 min.)	62 lbs. of alumina silica catalyst fines, and a 59% opacity for 6 minutes			

Date	Description	Debit	Credit	Balance
1912	Jan 1			
	Jan 2			
	Jan 3			
	Jan 4			
	Jan 5			
	Jan 6			
	Jan 7			
	Jan 8			
	Jan 9			
	Jan 10			
	Jan 11			
	Jan 12			
	Jan 13			
	Jan 14			
	Jan 15			
	Jan 16			
	Jan 17			
	Jan 18			
	Jan 19			
	Jan 20			
	Jan 21			
	Jan 22			
	Jan 23			
	Jan 24			
	Jan 25			
	Jan 26			
	Jan 27			
	Jan 28			
	Jan 29			
	Jan 30			
	Jan 31			
	Feb 1			
	Feb 2			
	Feb 3			
	Feb 4			
	Feb 5			
	Feb 6			
	Feb 7			
	Feb 8			
	Feb 9			
	Feb 10			
	Feb 11			
	Feb 12			
	Feb 13			
	Feb 14			
	Feb 15			
	Feb 16			
	Feb 17			
	Feb 18			
	Feb 19			
	Feb 20			
	Feb 21			
	Feb 22			
	Feb 23			
	Feb 24			
	Feb 25			
	Feb 26			
	Feb 27			
	Feb 28			
	Feb 29			
	Feb 30			
	Feb 31			

## Compliance History

Customer/Respondent/Owner-Operator:	CN600866800	BP Products North America Inc.	Classification: AVERAGE	Rating: 1.48
Regulated Entity:	RN102535077	BP PRODUCTS NORTH AMERICA TEXAS CITY	Classification: AVERAGE	Site Rating: 4.88
ID Number(s):	AIR NEW SOURCE PERMITS	PERMIT		1940
	AIR NEW SOURCE PERMITS	PERMIT		2231
	AIR NEW SOURCE PERMITS	PERMIT		2315
	AIR NEW SOURCE PERMITS	PERMIT		2529
	AIR NEW SOURCE PERMITS	PERMIT		2608
	AIR NEW SOURCE PERMITS	PERMIT		2609
	AIR NEW SOURCE PERMITS	PERMIT		2610A
	AIR NEW SOURCE PERMITS	PERMIT		2612
	AIR NEW SOURCE PERMITS	PERMIT		2938
	AIR NEW SOURCE PERMITS	PERMIT		3598
	AIR NEW SOURCE PERMITS	PERMIT		3758
	AIR NEW SOURCE PERMITS	PERMIT		4714
	AIR NEW SOURCE PERMITS	PERMIT		6488
	AIR NEW SOURCE PERMITS	PERMIT		6592
	AIR NEW SOURCE PERMITS	PERMIT		6600
	AIR NEW SOURCE PERMITS	PERMIT		7085
	AIR NEW SOURCE PERMITS	PERMIT		9463
	AIR NEW SOURCE PERMITS	PERMIT		9606
	AIR NEW SOURCE PERMITS	PERMIT		10060
	AIR NEW SOURCE PERMITS	PERMIT		10129
	AIR NEW SOURCE PERMITS	PERMIT		10156
	AIR NEW SOURCE PERMITS	PERMIT		10212
	AIR NEW SOURCE PERMITS	PERMIT		10597
	AIR NEW SOURCE PERMITS	PERMIT		11173
	AIR NEW SOURCE PERMITS	PERMIT		11175
	AIR NEW SOURCE PERMITS	PERMIT		11176
	AIR NEW SOURCE PERMITS	PERMIT		11787
	AIR NEW SOURCE PERMITS	PERMIT		13666
	AIR NEW SOURCE PERMITS	PERMIT		13667
	AIR NEW SOURCE PERMITS	PERMIT		15163
	AIR NEW SOURCE PERMITS	PERMIT		15271
	AIR NEW SOURCE PERMITS	PERMIT		15378
	AIR NEW SOURCE PERMITS	PERMIT		15436
	AIR NEW SOURCE PERMITS	PERMIT		15458
	AIR NEW SOURCE PERMITS	PERMIT		15497
	AIR NEW SOURCE PERMITS	PERMIT		15766
	AIR NEW SOURCE PERMITS	PERMIT		18506
	AIR NEW SOURCE PERMITS	PERMIT		19297
	AIR NEW SOURCE PERMITS	PERMIT		19599
	AIR NEW SOURCE PERMITS	PERMIT		20492
	AIR NEW SOURCE PERMITS	PERMIT		20850
	AIR NEW SOURCE PERMITS	PERMIT		22107
	AIR NEW SOURCE PERMITS	PERMIT		22932
	AIR NEW SOURCE PERMITS	PERMIT		24608
	AIR NEW SOURCE PERMITS	PERMIT		24936
	AIR NEW SOURCE PERMITS	PERMIT		38048
	AIR NEW SOURCE PERMITS	PERMIT		39093
	AIR NEW SOURCE PERMITS	PERMIT		41275
	AIR NEW SOURCE PERMITS	PERMIT		46052
	AIR NEW SOURCE PERMITS	PERMIT		46042
	AIR NEW SOURCE PERMITS	PERMIT		46255
	AIR NEW SOURCE PERMITS	PERMIT		46725
	AIR NEW SOURCE PERMITS	PERMIT		46724
	AIR NEW SOURCE PERMITS	PERMIT		47256
	AIR NEW SOURCE PERMITS	PERMIT		47563
	AIR NEW SOURCE PERMITS	PERMIT		47695
	AIR NEW SOURCE PERMITS	PERMIT		47696
	AIR NEW SOURCE PERMITS	PERMIT		47956
	AIR NEW SOURCE PERMITS	PERMIT		47955
	AIR NEW SOURCE PERMITS	PERMIT		47954
	AIR NEW SOURCE PERMITS	PERMIT		48412
	AIR NEW SOURCE PERMITS	PERMIT		83550
	AIR NEW SOURCE PERMITS	PERMIT		49200

AIR NEW SOURCE PERMITS	PERMIT	49771
AIR NEW SOURCE PERMITS	ACCOUNT NUMBER	GB0004L
AIR NEW SOURCE PERMITS	PERMIT	51875
AIR NEW SOURCE PERMITS	PERMIT	49128
AIR NEW SOURCE PERMITS	ACCOUNT NUMBER	GB0004R
AIR NEW SOURCE PERMITS	ACCOUNT NUMBER	GB0004L
AIR NEW SOURCE PERMITS	REGISTRATION	75507
AIR NEW SOURCE PERMITS	REGISTRATION	56657
AIR NEW SOURCE PERMITS	AFS NUM	0001
AIR NEW SOURCE PERMITS	PERMIT	PSDTX981
AIR NEW SOURCE PERMITS	PERMIT	58136
AIR NEW SOURCE PERMITS	PERMIT	70427
AIR NEW SOURCE PERMITS	EPA ID	PSDTX649
AIR NEW SOURCE PERMITS	PERMIT	71839
AIR NEW SOURCE PERMITS	REGISTRATION	72163
AIR NEW SOURCE PERMITS	PERMIT	55478
AIR NEW SOURCE PERMITS	PERMIT	53892
AIR NEW SOURCE PERMITS	PERMIT	50798
AIR NEW SOURCE PERMITS	PERMIT	54051
AIR NEW SOURCE PERMITS	PERMIT	52467
AIR NEW SOURCE PERMITS	PERMIT	54721
AIR NEW SOURCE PERMITS	PERMIT	PSDTX402
AIR NEW SOURCE PERMITS	EPA ID	PSDTX981
AIR NEW SOURCE PERMITS	REGISTRATION	76550
AIR NEW SOURCE PERMITS	EPA ID	PSDTX402
UNDERGROUND INJECTION CONTROL	PERMIT	WDW080
UNDERGROUND INJECTION CONTROL	PERMIT	WDW127
UNDERGROUND INJECTION CONTROL	PERMIT	WDW128
UNDERGROUND INJECTION CONTROL	PERMIT	WDW214
UNDERGROUND INJECTION CONTROL	PERMIT	WDW215
INDUSTRIAL AND HAZARDOUS WASTE GENERATION	EPA ID	TXD008080533
INDUSTRIAL AND HAZARDOUS WASTE GENERATION	SOLID WASTE REGISTRATION # (SWR)	30139
INDUSTRIAL AND HAZARDOUS WASTE GENERATION	PERMIT	50255
WASTE WATER GENERAL PERMIT	PERMIT	WQ0000443000
WASTE WATER GENERAL PERMIT	PERMIT	TXG670029
WASTEWATER	PERMIT	WQ0000443000
WASTEWATER	PERMIT	TPDES0003522
AIR OPERATING PERMITS	PERMIT	2657
AIR OPERATING PERMITS	ACCOUNT NUMBER	GB0004L
AIR OPERATING PERMITS	PERMIT	1541
AIR OPERATING PERMITS	PERMIT	2328
INDUSTRIAL AND HAZARDOUS WASTE STORAGE	PERMIT	50255
IHW CORRECTIVE ACTION	SOLID WASTE REGISTRATION # (SWR)	30139

Location: 2401 5TH AVE S, TEXAS CITY, TX, 77590 Rating Date: September 01 05 Repeat Violator: NO

---

TCEQ Region: REGION 12 - HOUSTON

---

Date Compliance History Prepared: November 02, 2005

---

Agency Decision Requiring Compliance History: Enforcement

---

Compliance Period: November 02, 2000 to November 02, 2005

---

TCEQ Staff Member to Contact for Additional Information Regarding this Compliance History

Name: Suzanne Walrath Phone: 512/239-2134

**Site Compliance History Components**

1. Has the site been in existence and/or operation for the full five year compliance period? Yes
2. Has there been a (known) change in ownership of the site during the compliance period? No
3. If Yes, who is the current owner? N/A
4. If Yes, who was/were the prior owner(s)? N/A
5. When did the change(s) in ownership occur? N/A

**Components (Multimedia) for the Site :**



A. Final Enforcement Orders, court judgements, and consent decrees of the state of Texas and the federal government.

Effective Date: 07/15/2005

ADMINORDER 2004-1532-AIR-E

Classification: Moderate

Citation: 30 TAC Chapter 116, SubChapter B 116.115(c)  
5C THC Chapter 382, SubChapter A 382.085(b)

Rqmt Prov: Special Condition No. 2 PERMIT

Description: Failed to prevent the unauthorized emission of volatile organic compounds (VOCs) exceeding the maximum allowable emission rate from the Ultraformer No. 4 Unit during a period of 2 hours and 55 minutes on March 30, 2004.

Classification: Minor

Citation: 30 TAC Chapter 101, SubChapter F 101.201(b)(8)  
5C THC Chapter 382, SubChapter A 382.085(b)

Description: Failed to submit an administratively complete final emissions event report with the preconstruction authorization number and the authorized emission limits.

Effective Date: 03/20/2003

ADMINORDER 2001-0329-AIR-E

Classification: Moderate

Citation: 30 TAC Chapter 101, SubChapter A 101.4  
30 TAC Chapter 112, SubChapter B 112.31  
30 TAC Chapter 112, SubChapter B 112.32  
5C THC Chapter 382, SubChapter A 382.085(a)  
5C THC Chapter 382, SubChapter A 382.085(b)

Description: Discharging one or more air contaminants in such a concentration and of such duration as are or may tend to be injurious to human health or welfare, as documented during TCEQ mobile monitoring conducted from 1995-2001.

Classification: Moderate

Citation: 30 TAC Chapter 101, SubChapter A 101.20(1)  
40 CFR Part 60, Subpart J 60.105(a)(4)  
5C THC Chapter 382, SubChapter A 382.085(b)

Description: Failed to continuously monitor the fuel gas in Distillate Desulfurization Unit (DDU) No. 300 during Third and Fourth Quarters of 2000.

Classification: Minor

Citation: 30 TAC Chapter 101, SubChapter A 101.20(1)  
40 CFR Chapter 60, SubChapter C, PT 60, SubPT A 60.13(a)  
5C THC Chapter 382, SubChapter A 382.085(b)

Description: Failed to include cylinder gases certified values in the CEMS reports for FCCU Nos. 1, 2, 3, DDU. Nos. 200 & 300, Hydrogen Recovery Unit, Sulfur Recovery Unit, and Power Stations Nos. 3 and 4 for First Quarter 1997 thru Fourth Quarter 2000.

Classification: Moderate

Citation: 30 TAC Chapter 115, SubChapter B 115.112(a)(2)(A)  
5C THC Chapter 382, SubChapter A 382.085(b)

Description: Failed to close the sampling hatch on Tank No. 91.

Classification: Moderate

Citation: 30 TAC Chapter 115, SubChapter B 115.131(a)  
5C THC Chapter 382, SubChapter A 382.085(b)

Description: Failed to control emissions from the Pipestill 3A water separator during a maintenance activity during the week of February 19, 2001.

Classification: Moderate

Citation: 30 TAC Chapter 101, SubChapter A 101.6(a)(2)(F)  
30 TAC Chapter 101, SubChapter A 101.6(b)(5)  
30 TAC Chapter 101, SubChapter A 101.6(b)(6)  
5C THC Chapter 382, SubChapter A 382.085(b)

Description: Failed to include all the required information in the initial notification and final report for the week of March 8, 2001 upset at FCCU No. 3.

Classification: Moderate

Citation: 5C THC Chapter 382, SubChapter A 382.085(a)

Description: Failed to prevent the unauthorized emissions resulting from a corroded pipeline rupture in FCCU No. 3 on March 8, 2001.

Classification: Moderate

Citation: 30 TAC Chapter 101, SubChapter A 101.6(a)[G]  
5C THC Chapter 382, SubChapter A 382.085(b)

Description: Failed to report a reportable upset that occurred on March 27-29, 2001 at FCCU No. 3 within 24 hours of discovery.

Classification: Moderate

Citation: 30 TAC Chapter 116, SubChapter B 116.115(c)  
5C THC Chapter 382, SubChapter A 382.085(b)

Rqmt Prov: SC 4 PERMIT

Description: Exceeded the allowable hourly emission rate for SO2 at FCCU No. 3 on March 27-29, 2001.

Classification: Moderate

Citation: 30 TAC Chapter 101, SubChapter A 101.6(a)(2)(F)  
30 TAC Chapter 101, SubChapter A 101.6(b)(6)  
5C THC Chapter 382, SubChapter A 382.085(b)

Description: Failed to include an estimate of the catalyst emission in the initial and final reports for the November 21, 2000 upset.

Classification: Moderate

Citation: 30 TAC Chapter 101, SubChapter A 101.20(1)  
30 TAC Chapter 101, SubChapter A 101.4  
30 TAC Chapter 111, SubChapter A 111.111(a)(1)(B)  
30 TAC Chapter 116, SubChapter B 116.115(c)  
5C THC Chapter 382, SubChapter A 382.085(a)  
5C THC Chapter 382, SubChapter A 382.085(b)

Rqmt Prov: SC 1 PERMIT  
SC 7 PERMIT

Description: Failed to control excess opacity and catalyst emissions from an upset at FCCU No. 1 on 11/21/00 resulting in nuisance conditions.

Effective Date: 02/02/2003

ADMINORDER 2002-0524-IWD-E

Classification: Moderate

Citation: 30 TAC Chapter 305, SubChapter F 305.125(1)  
TWC Chapter 26 26.121

Rqmt Prov: Not specified PERMIT

Description: Failure to comply with permit limits for Oil and Grease and Total Organic Carbon.

Effective Date: 03/09/2002

ADMINORDER 1999-1278-AIR-E

Classification: Moderate

Citation: 30 TAC Chapter 112, SubChapter B 112.32  
5C THC Chapter 382, SubChapter A 382.085(a)  
5C THC Chapter 382, SubChapter A 382.085(b)

Description: Exceeded the 30-minute hydrogen sulfide net ground level concentration standard of 0.12 parts per million on September 29, 1998 from 12:55 a.m. to 1:25 a.m.

Classification: Moderate

Citation: 30 TAC Chapter 112, SubChapter A 112.3(b)  
5C THC Chapter 382, SubChapter A 382.085(a)  
5C THC Chapter 382, SubChapter A 382.085(b)

Description: Exceeded the sulfur dioxide 30-minute net ground level concentration of 0.28 parts per million by volume on September 29, 1998 from 3:25 a.m. to 3:55 a.m.

Effective Date: 08/29/2005

ADMINORDER 2005-0284-AIR-E

Classification: Moderate

Citation: 30 TAC Chapter 111, SubChapter A 111.111(a)(1)(B)  
30 TAC Chapter 116, SubChapter B 116.110(a)[G]  
30 TAC Chapter 116, SubChapter B 116.115(b)(2)(F)  
5C THC Chapter 382, SubChapter A 382.085(b)

Rqmt Prov: No. 2315 Special Condition #1, PERMIT  
Special Condition 7 PERMIT

Description: Failed to comply with permitted emissions limits and allowed unauthorized emissions.

See addendum for information regarding federal actions.

B. Any criminal convictions of the state of Texas and the federal government.

N/A

C. Chronic excessive emissions events.

N/A

D. The approval dates of investigations. (CCEDS Inv. Track. No.)

1	04/13/2003	(31555)
2	12/30/2002	(156257)
3	12/27/2001	(156256)
4	08/09/2002	(4413)
5	06/26/2002	(1427)
6	12/20/2000	(156255)
7	05/07/2003	(28250)
8	11/11/2004	(281947)

9	12/14/2004	(338914)
10	09/23/2003	(294633)
11	03/22/2005	(372568)
12	11/25/2002	(156253)
13	01/10/2005	(339436)
14	05/26/2005	(345468)
15	09/16/2005	(406970)
16	10/21/2003	(294635)
17	12/27/2004	(274786)
18	12/16/2004	(339023)
19	12/14/2004	(340622)
20	11/24/2003	(294636)
21	11/26/2001	(156252)
22	04/28/2005	(378515)
23	12/14/2004	(339099)
24	09/23/2005	(432666)
25	12/19/2003	(294637)
26	11/21/2000	(156251)
27	01/22/2004	(294638)
28	05/11/2005	(374665)
29	02/23/2005	(350619)
30	10/19/2004	(290690)
31	08/30/2005	(405036)
32	08/31/2005	(406160)
33	04/24/2004	(254305)
34	08/16/2004	(276410)
35	02/23/2005	(350617)
36	04/25/2005	(377475)
37	05/16/2003	(38169)
38	11/19/2004	(339371)
39	01/07/2005	(291517)
40	09/26/2002	(12389)
41	05/26/2005	(282424)
42	08/24/2004	(351823)
43	12/27/2004	(283778)
44	04/26/2004	(251990)
45	10/21/2002	(156249)
46	04/22/2005	(377248)
47	08/31/2002	(7829)
48	04/05/2005	(345065)
49	12/13/2004	(282146)
50	02/15/2001	(246482)
51	10/24/2001	(156248)
52	09/01/2004	(291363)
53	12/22/2004	(344971)
54	02/14/2005	(341146)
55	01/04/2005	(289427)
56	11/05/2004	(339795)
57	08/23/2005	(400386)
58	06/29/2005	(348404)
59	12/31/2004	(344475)
60	12/16/2004	(338936)

61 09/23/2004 (351824)  
62 04/20/2005 (252264)  
63 07/18/2005 (380177)  
64 11/29/2004 (340626)  
65 03/28/2003 (28935)  
66 12/27/2004 (283882)  
67 08/29/2005 (403471)  
68 05/16/2003 (38170)  
69 02/10/2005 (282617)  
70 09/23/2002 (156246)  
71 10/25/2004 (351825)  
72 12/28/2004 (281660)  
73 12/28/2004 (339638)  
74 08/31/2002 (4786)  
75 10/12/2005 (252191)  
76 04/13/2003 (31558)  
77 11/04/2003 (248163)  
78 08/30/2005 (418478)  
79 01/03/2005 (284492)  
80 09/24/2001 (156245)  
81 10/19/2004 (291164)  
82 03/18/2003 (20996)  
83 04/24/2004 (254307)  
84 01/19/2005 (337943)  
85 11/16/2004 (351826)  
86 03/22/2005 (373360)  
87 05/11/2003 (28139)  
88 04/09/2004 (268950)  
89 09/14/2005 (406870)  
90 09/15/2005 (377149)  
91 06/03/2004 (268798)  
92 11/21/2000 (156243)  
93 02/22/2005 (381703)  
94 09/11/2003 (247716)  
95 09/05/2002 (9375)  
96 09/25/2002 (7870)  
97 03/21/2005 (381704)  
98 05/27/2004 (272970)  
99 08/12/2003 (149114)  
100 08/23/2002 (156242)  
101 08/31/2002 (7795)  
102 12/13/2004 (339102)  
103 12/27/2004 (381705)  
104 10/25/2004 (351827)  
105 08/29/2001 (156241)  
106 06/28/2005 (392489)  
107 11/05/2004 (339757)  
108 08/14/2002 (3273)  
109 10/01/2004 (293097)  
110 09/26/2002 (12042)  
111 12/14/2004 (339132)  
112 05/25/2005 (392490)

113	01/03/2005	(284816)
114	07/22/2003	(156239)
115	11/18/2004	(341134)
116	07/27/2004	(259089)
117	08/18/2005	(404903)
118	11/29/2004	(339366)
119	09/05/2003	(148573)
120	12/14/2004	(338125)
121	09/30/2004	(286082)
122	07/23/2002	(156238)
123	11/19/2004	(339082)
124	12/18/2002	(13671)
125	07/24/2001	(156237)
126	09/05/2002	(9373)
127	12/08/2003	(255385)
128	05/26/2004	(268395)
129	08/12/2005	(401566)
130	01/28/2004	(257477)
131	03/04/2004	(263718)
132	04/20/2005	(373601)
133	08/24/2005	(404566)
134	08/31/2004	(268075)
135	05/19/2004	(271625)
136	11/18/2004	(341140)
137	03/10/2004	(263897)
138	03/18/2004	(253458)
139	12/20/2004	(344346)
140	06/02/2004	(268755)
141	06/18/2003	(156235)
142	12/13/2004	(340541)
143	08/08/2005	(400685)
144	03/28/2003	(28949)
145	09/01/2004	(286037)
146	03/28/2003	(28942)
147	06/24/2002	(156234)
148	01/07/2004	(259035)
149	12/20/2004	(339027)
150	08/19/2005	(394676)
151	09/30/2004	(286092)
152	05/02/2003	(280657)
153	06/28/2001	(156233)
154	09/30/2004	(286067)
155	10/07/2005	(393826)
156	12/13/2004	(336747)
157	06/04/2004	(270179)
158	01/04/2005	(339567)
159	04/01/2005	(345035)
160	05/27/2004	(273891)
161	03/04/2004	(263712)
162	11/16/2004	(340113)
163	05/23/2003	(156231)
164	07/15/2004	(261949)

165 01/06/2005 (288366)  
166 09/11/2003 (247715)  
167 09/14/2005 (403367)  
168 12/29/2004 (344652)  
169 12/10/2004 (338900)  
170 01/07/2005 (341103)  
171 05/23/2002 (156230)  
172 04/25/2005 (377472)  
173 02/23/2005 (350616)  
174 12/14/2001 (IE0017395001001)  
175 08/31/2004 (280950)  
176 12/09/2004 (340663)  
177 02/18/2005 (343652)  
178 05/18/2001 (156229)  
179 08/19/2005 (402460)  
180 07/12/2002 (1488)  
181 09/01/2004 (286055)  
182 02/24/2004 (261244)  
183 04/21/2003 (156227)  
184 05/29/2003 (34942)  
185 04/22/2002 (156226)  
186 06/23/2005 (350406)  
187 04/18/2005 (419497)  
188 12/20/2004 (338583)  
189 12/31/2004 (345043)  
190 01/19/2005 (337942)  
191 05/27/2004 (273737)  
192 12/16/2004 (338890)  
193 04/23/2001 (156225)  
194 05/20/2005 (419498)  
195 11/29/2004 (340639)  
196 08/08/2005 (274224)  
197 12/17/2004 (340853)  
198 09/01/2004 (288979)  
199 03/10/2005 (371700)  
200 06/17/2005 (419499)  
201 08/28/2002 (9794)  
202 09/16/2005 (285680)  
203 08/28/2002 (9781)  
204 04/25/2005 (419500)  
205 09/15/2003 (248772)  
206 11/19/2004 (340338)  
207 11/21/2002 (11937)  
208 11/29/2004 (340062)  
209 09/19/2005 (404902)  
210 03/03/2005 (373069)  
211 05/27/2004 (273749)  
212 03/28/2003 (28893)  
213 08/29/2005 (400410)  
214 11/05/2004 (339803)  
215 08/16/2005 (403465)  
216 08/22/2005 (402317)

217	08/31/2002	(7886)
218	03/24/2003	(156222)
219	09/15/2005	(260589)
220	08/31/2002	(4776)
221	09/01/2004	(291083)
222	08/24/2005	(404569)
223	12/29/2004	(338297)
224	03/03/2005	(372375)
225	01/06/2005	(288634)
226	03/21/2002	(156221)
227	08/31/2004	(283764)
228	08/08/2005	(398880)
229	01/06/2005	(292125)
230	05/19/2004	(271629)
231	12/20/2004	(339872)
232	03/19/2001	(156220)
233	05/16/2003	(29638)
234	09/26/2002	(12031)
235	12/09/2004	(340574)
236	11/23/2004	(333630)
237	12/14/2004	(338108)
238	08/13/2004	(274408)
239	07/22/2005	(345720)
240	08/02/2005	(397176)
241	04/06/2004	(252241)
242	02/24/2003	(156219)
243	05/26/2005	(341932)
244	12/27/2004	(344688)
245	08/31/2004	(287046)
246	06/18/2004	(266747)
247	07/26/2005	(397181)
248	11/19/2004	(341137)
249	01/18/2005	(268595)
250	02/21/2003	(281259)
251	02/25/2002	(156218)
252	09/01/2005	(400327)
253	09/30/2004	(280208)
254	02/23/2001	(156217)
255	11/29/2004	(340125)
256	04/07/2005	(344347)
257	08/13/2004	(274792)
258	12/16/2004	(338891)
259	08/24/2005	(404560)
260	03/01/2004	(435191)
261	11/04/2004	(339482)
262	08/30/2005	(403600)
263	11/29/2004	(339078)
264	12/13/2004	(336751)
265	04/25/2005	(377471)
266	12/16/2004	(338892)
267	10/01/2004	(289600)
268	12/20/2004	(344329)

269 12/13/2004 (339031)  
270 09/06/2005 (399764)  
271 05/25/2005 (379936)  
272 12/14/2004 (339128)  
273 12/28/2004 (291446)  
274 12/09/2004 (338894)  
275 03/28/2003 (28927)  
276 08/31/2004 (283681)  
277 05/13/2003 (33667)  
278 08/31/2004 (285140)  
279 08/19/2005 (402082)  
280 10/12/2005 (433061)  
281 01/06/2005 (284616)  
282 09/01/2004 (291452)  
283 01/06/2005 (341553)  
284 12/31/2004 (289229)  
285 09/27/2005 (394338)  
286 02/23/2004 (294620)  
287 05/27/2004 (273717)  
288 12/13/2004 (339270)  
289 09/11/2003 (247707)  
290 12/29/2004 (339794)  
291 11/10/2003 (254108)  
292 08/28/2002 (9817)  
293 08/13/2004 (274627)  
294 01/03/2005 (338765)  
295 05/20/2005 (377045)  
296 10/11/2005 (432303)  
297 03/16/2004 (294622)  
298 12/28/2004 (340682)  
299 05/19/2004 (271621)  
300 04/13/2004 (294623)  
301 11/19/2004 (339079)  
302 02/26/2003 (14741)  
303 05/09/2005 (379955)  
304 08/19/2004 (289922)  
305 10/12/2005 (433072)  
306 12/14/2004 (338239)  
307 08/31/2004 (272768)  
308 05/17/2004 (294625)  
309 07/19/2004 (281796)  
310 09/16/2005 (380788)  
311 06/21/2004 (294627)  
312 08/13/2004 (274430)  
313 01/10/2005 (340723)  
314 09/15/2005 (418585)  
315 12/08/2004 (335444)  
316 07/12/2004 (294629)  
317 08/15/2005 (404281)  
318 12/31/2003 (250496)  
319 11/26/2004 (267345)  
320 12/08/2003 (255379)



321 01/22/2003 (156261)  
 322 08/08/2005 (336477)  
 323 05/20/2005 (379096)  
 324 12/14/2004 (339131)  
 325 05/11/2005 (373962)  
 326 01/02/2004 (250803)  
 327 12/14/2004 (340656)  
 328 12/20/2004 (339263)  
 329 08/31/2004 (283738)  
 330 12/29/2004 (288544)  
 331 12/28/2004 (344613)  
 332 08/25/2003 (294631)  
 333 01/23/2002 (156260)  
 334 05/27/2004 (272823)  
 335 12/30/2004 (284317)  
 336 11/11/2004 (282297)  
 337 03/28/2003 (28954)  
 338 04/13/2003 (31549)  
 339 12/31/2004 (284156)  
 340 08/31/2004 (278218)  
 341 01/16/2001 (156259)  
 342 11/22/2004 (282861)  
 343 12/16/2004 (340555)

E. Written notices of violations (NOV). (CCEDS Inv. Track. No.)

N/A

Date: 11/30/2000 (156255)

Classification: Moderate

Self Report? YES

Citation: 30 TAC Chapter 305, SubChapter F 305.125(1)  
 TWC Chapter 26 26.121(a)[G]

Description: Failure to meet the limit for one or more permit parameter

Date: 10/31/2002 (156253)

Classification: Moderate

Self Report? YES

Citation: 30 TAC Chapter 305, SubChapter F 305.125(1)  
 TWC Chapter 26 26.121(a)[G]

Description: Failure to meet the limit for one or more permit parameter

Date: 05/28/2005 (345468)

Classification: Moderate

Self Report? NO

Citation: 30 TAC Chapter 116, SubChapter B 116.110(a)[G]  
 5C THC Chapter 382, SubChapter A 382.085(b)

Description: Failure to prevent an avoidable emissions event.

Failure to avoid leak in the system.

Date: 05/23/2005 (377045)

Classification: Minor

Self Report? NO

Citation: 30 TAC Chapter 116, SubChapter B 116.115(c)  
 30 TAC Chapter 117, SubChapter B 117.206(e)(2)

Rqmt Prov: PERMIT IA

Description: Facility did not maintain ammonia emissions below permitted level.  
 Facility exceeded NH3 slip

Date: 09/14/2005 (406870)

Classification: Moderate

Self Report? NO

Citation: 30 TAC Chapter 111, SubChapter A 111.111(a)(1)(A)  
 30 TAC Chapter 116, SubChapter B 116.115(c)  
 5C THC Chapter 382, SubChapter A 382.085(b)

Rqmt Prov: PERMIT IA

Description: Failure to maintain steady catalyst circulation rates while the unit was operating at reduced throughput.

Date: 08/30/2004 (268075) Classification: Moderate  
 Self Report? NO  
 Citation: 30 TAC Chapter 116, SubChapter B 116.115(c)  
 5C THC Chapter 382, SubChapter A 382.085(b)  
 Rqmt Prov: PERMIT IA  
 Description: Exceeded VOC permit limit.

Self Report? NO Classification: Moderate  
 Citation: 30 TAC Chapter 116, SubChapter B 116.115(c)  
 5C THC Chapter 382, SubChapter A 382.085(b)  
 Rqmt Prov: PERMIT IA  
 Description: Exceeded VOC limits.

Date: 02/15/2001 (246482) Classification: Moderate  
 Self Report? NO  
 Citation: 30 TAC Chapter 305, SubChapter F 305.125(1)  
 Description: NON-RPT VIOS FOR MONIT PER OR PIPE

Self Report? NO Classification: Moderate  
 Citation: 30 TAC Chapter 305, SubChapter F 305.125(1)  
 Description: NON-RPT VIOS FOR MONIT PER OR PIPE

Self Report? NO Classification: Moderate  
 Citation: 30 TAC Chapter 305, SubChapter F 305.125(1)  
 Description: NON-RPT VIOS FOR MONIT PER OR PIPE

Self Report? NO Classification: Moderate  
 Citation: 30 TAC Chapter 305, SubChapter F 305.125(1)  
 Description: NON-RPT VIOS FOR MONIT PER OR PIPE

Date: 02/18/2005 (343652) Classification: Moderate  
 Self Report? NO  
 Citation: 30 TAC Chapter 111, SubChapter A 111.111(a)(1)(A)  
 5C THC Chapter 382, SubChapter A 382.085(b)  
 Description: BP failed to properly control the air flow in the ESP Stack resulting in an opacity of 57%, averaged over a six-minute period, for 30 minutes.

Date: 01/02/2004 (250803) Classification: Moderate  
 Self Report? NO  
 Citation: 30 TAC Chapter 116, SubChapter B 116.115(c)  
 5C THC Chapter 382, SubChapter A 382.085(b)  
 Rqmt Prov: PERMIT IA  
 Description: BP failed to properly control VOC, H2S, and CO emissions during a Coker C Drum cooldown cycle.

Date: 04/24/2004 (254305) Classification: Moderate  
 Self Report? NO  
 Citation: 30 TAC Chapter 101, SubChapter F 101.201(a)(2)(D)  
 5C THC Chapter 382, SubChapter A 382.085(a)  
 Description: Failed to properly report an emissions event.

Date: 12/27/2004 (283882) Classification: Moderate  
 Self Report? NO  
 Citation: 30 TAC Chapter 116, SubChapter B 116.115(c)  
 5C THC Chapter 382, SubChapter A 382.085(b)  
 Rqmt Prov: PERMIT IA  
 Description: Exceeded permit limits during an avoidable emissions event.

Date: 08/31/2002 (156246) Classification: Moderate  
 Self Report? YES  
 Citation: 30 TAC Chapter 305, SubChapter F 305.125(1)  
 TWC Chapter 26 26.121(a)[G]  
 Description: Failure to meet the limit for one or more permit parameter

Date: 08/31/2001 (156245) Classification: Moderate  
 Self Report? YES  
 Citation: 30 TAC Chapter 305, SubChapter F 305.125(1)  
 TWC Chapter 26 26.121(a)[G]  
 Description: Failure to meet the limit for one or more permit parameter

Date: 09/15/2005 (418585)

Self Report? NO Classification: Moderate  
 Citation: 30 TAC Chapter 116, SubChapter B 116.115(c)  
 5C THC Chapter 382, SubChapter A 382.085(b)  
 Rqmt Prov: PERMIT IA  
 Description: BP failed to prevent a leak from the short loop in the regeneration system.  
 Date: 07/15/2004 (261949)

Self Report? NO Classification: Moderate  
 Citation: 30 TAC Chapter 115, SubChapter C 115.212(a)(3)(B)  
 5C THC Chapter 382, SubChapter A 382.085(b)  
 Description: Failure to prevent VOC leaks during a transfer operation.  
 Date: 09/14/2005 (403367)

Self Report? NO Classification: Moderate  
 Citation: 30 TAC Chapter 116, SubChapter B 116.115(c)  
 5C THC Chapter 382, SubChapter A 382.085(b)  
 Rqmt Prov: PERMIT IA  
 Description: Failure to prevent an avoidable emissions event.  
 Date: 08/23/2005 (402317)

Self Report? NO Classification: Moderate  
 Citation: 30 TAC Chapter 116, SubChapter B 116.115(c)  
 5C THC Chapter 382, SubChapter A 382.085(b)  
 Rqmt Prov: PERMIT IA  
 Description: Failure to prevent an avoidable emissions event.  
 Date: 12/31/2003 (250496)

Self Report? NO Classification: Moderate  
 Citation: 30 TAC Chapter 116, SubChapter B 116.115(c)  
 5C THC Chapter 382, SubChapter A 382.085(b)  
 Rqmt Prov: PERMIT IA  
 Description: BP failed to properly control VOC and H2S emissions during a shutdown operation.  
 Date: 11/30/2004 (381705)

Self Report? YES Classification: Moderate  
 Citation: 30 TAC Chapter 305, SubChapter F 305.125(1)  
 TWC Chapter 26 26.121(a)[G]  
 Description: Failure to meet the limit for one or more permit parameter  
 Date: 04/24/2004 (254307)

Self Report? NO Classification: Moderate  
 Citation: 30 TAC Chapter 101, SubChapter F 101.201(b)(9)  
 5C THC Chapter 382, SubChapter A 382.085(b)  
 Description: Failed to properly report an emissions event.  
 Date: 06/30/2001 (156237)

Self Report? YES Classification: Moderate  
 Citation: 30 TAC Chapter 305, SubChapter F 305.125(1)  
 TWC Chapter 26 26.121(a)[G]  
 Description: Failure to meet the limit for one or more permit parameter  
 Date: 01/03/2005 (284492)

Self Report? NO Classification: Moderate  
 Citation: 30 TAC Chapter 116, SubChapter B 116.115(c)  
 5C THC Chapter 382, SubChapter A 382.085(b)  
 Rqmt Prov: PERMIT IA  
 Description: Exceeded permit limit during an avoidalbe emissions event.  
 Date: 11/22/2004 (282861)

Self Report? NO Classification: Moderate  
 Citation: 30 TAC Chapter 111, SubChapter A 111.111(a)(1)(A)  
 5C THC Chapter 382, SubChapter A 382.085(b)  
 Description: Avoidable upset which caused visible emissions with opacity over 30% for more than six minutes.  
 Date: 02/28/2003 (156222)

Self Report? YES Classification: Moderate  
 Citation: 30 TAC Chapter 305, SubChapter F 305.125(1)  
 TWC Chapter 26 26.121(a)[G]  
 Description: Failure to meet the limit for one or more permit parameter

Date: 01/06/2005 (288366) Classification: Moderate  
 Self Report? NO  
 Citation: 30 TAC Chapter 116, SubChapter B 116.115(c)  
 5C THC Chapter 382, SubChapter A 382.085(b)  
 Rqmt Prov: PERMIT IA  
 Description: BP Products North America, Texas City, failed to properly maintain and operate the J-475 wet gas compressor. BP failed to repair the power piston to prevent sticking in the 38% - 42% position for extended periods of time, which in-turn caused the turbine to trip.

Date: 01/31/2003 (156219) Classification: Moderate  
 Self Report? YES  
 Citation: 30 TAC Chapter 305, SubChapter F 305.125(1)  
 TWC Chapter 26 26.121(a)[G]  
 Description: Failure to meet the limit for one or more permit parameter

Date: 04/06/2004 (252241) Classification: Moderate  
 Self Report? NO  
 Citation: 30 TAC Chapter 116, SubChapter B 116.115(c)  
 5C THC Chapter 382, SubChapter A 382.085(b)  
 Rqmt Prov: PERMIT IA  
 Description: Exceeded a permit limit during an emissions event.

Date: 12/29/2004 (288544) Classification: Moderate  
 Self Report? NO  
 Citation: 30 TAC Chapter 116, SubChapter B 116.115(c)  
 5C THC Chapter 382, SubChapter A 382.085(b)  
 Rqmt Prov: PERMIT IA  
 Description: BP representatives failed to properly maintain or operate the 10 ft. K-ray level detector on the F-301B coke drum. BP failed to repair the 10 ft. K-ray level detector on the F-301B coke drum for an extended period of time, which in-turn caused the turbine to trip.

Date: 01/06/2005 (284616) Classification: Minor  
 Self Report? NO  
 Citation: 30 TAC Chapter 101, SubChapter F 101.201(a)(1)(B)  
 30 TAC Chapter 101, SubChapter F 101.201(c)  
 Description: BP failed to submit initial and final notifications in a timely manner.

Self Report? NO Classification: Moderate  
 Citation: 30 TAC Chapter 116, SubChapter B 116.115(c)  
 5C THC Chapter 382, SubChapter A 382.085(b)  
 Rqmt Prov: PERMIT IA  
 Description: Failure to prevent the overpressure of the 401E overhead tower

Date: 12/15/2004 (282146) Classification: Moderate  
 Self Report? NO  
 Citation: 30 TAC Chapter 116, SubChapter B 116.115(c)  
 5C THC Chapter 382, SubChapter A 382.085(b)  
 Rqmt Prov: PERMIT IA  
 Description: Failure to prevent the premature failure of the SO2 analyzer and the pH analyzer.

Date: 06/09/2004 (269846) Classification: Moderate  
 Self Report? NO  
 Citation: 30 TAC Chapter 101, SubChapter A 101.4  
 Description: Facility failed to prevent a nuisance violation.

Date: 01/06/2005 (292125) Classification: Moderate  
 Self Report? NO  
 Citation: 30 TAC Chapter 116, SubChapter B 116.115(c)  
 5C THC Chapter 382, SubChapter A 382.085(b)  
 Rqmt Prov: PERMIT IA  
 Description: Failure to prevent the H3566 relief valve from leaking to the CRPII Flare (501).

Date: 09/05/2003 (148573) Classification: Moderate  
 Self Report? NO  
 Citation: 30 TAC Chapter 116, SubChapter B 116.115(c)  
 Description: BP failed to control emissions during a caustic dumping operation.

Date: 09/16/2005 (406970) Classification: Moderate  
 Self Report? NO  
 Citation: 30 TAC Chapter 111, SubChapter A 111.111(a)(1)(A)

5C THC Chapter 382, SubChapter A 382.085(b)  
Description: Failure to maintain proper catalyst aeration and catalyst circulation.  
Classification: Minor

Self Report? NO  
Citation: 30 TAC Chapter 101, SubChapter F 101.201(g)  
Description: BP failed to submit a written Initial Notification for Incident # 55146 to the TCEQ within 24 hours of discovery of the incident.

Date: 05/26/2005 (341932)  
Classification: Moderate

Self Report? NO  
Citation: 30 TAC Chapter 116, SubChapter B 116.110(a)[G]  
5C THC Chapter 382, SubChapter A 382.085(b)  
Description: Failure to prevent the release of Freon emissions to the atmosphere.

Self Report? NO  
Citation: 30 TAC Chapter 101, SubChapter F 101.201(a)(1)(B)  
Description: Failure to report in a timely manner.  
Classification: Minor

Date: 01/03/2005 (284816)  
Classification: Moderate

Self Report? NO  
Citation: 30 TAC Chapter 111, SubChapter A 111.111(a)(1)(A)  
5C THC Chapter 382, SubChapter A 382.085(b)  
Description: Exceeded opacity limits during an avoidable emissions event.

Date: 12/31/2002 (156261)  
Classification: Moderate

Self Report? YES  
Citation: 30 TAC Chapter 305, SubChapter F 305.125(1)  
TWC Chapter 26 26.121(a)[G]  
Description: Failure to meet the limit for one or more permit parameter

Date: 12/21/2004 (344971)  
Classification: Moderate

Self Report? NO  
Citation: 30 TAC Chapter 111, SubChapter A 111.111(a)(1)(A)  
5C THC Chapter 382, SubChapter A 382.085(b)  
Description: BP maintenance personnel failed to lockout the switch to the UPS output static switch and they failed to prevent a precipitator trip that resulted in an opacity of 73% (averaged over two (2) six-minute periods).

Date: 12/28/2004 (291446)  
Classification: Moderate

Self Report? NO  
Citation: 30 TAC Chapter 111, SubChapter A 111.111(a)(1)(B)  
30 TAC Chapter 116, SubChapter B 116.115(c)  
5C THC Chapter 382, SubChapter A 382.085(b)  
Rqmt Prov: PERMIT IA  
Description: Failure to prevent the J4 air blower surge.

Date: 08/19/2005 (394676)  
Classification: Moderate

Self Report? NO  
Citation: 30 TAC Chapter 116, SubChapter B 116.115(c)  
5C THC Chapter 382, SubChapter A 382.085(b)  
Rqmt Prov: PERMIT IA  
Description: BP failed to prevent an avoidable emissions event.

Date: 07/27/2004 (259089)  
Classification: Moderate

Self Report? NO  
Citation: 30 TAC Chapter 116, SubChapter B 116.115(c)  
5C THC Chapter 382, SubChapter A 382.085(b)  
Rqmt Prov: PERMIT IA  
Description: Exceeded permit limit during an avoidable emissions event.

Self Report? NO  
Citation: 30 TAC Chapter 101, SubChapter F 101.201(g)  
Description: Failure to submit final report via STEERS  
Classification: Minor

Date: 01/07/2005 (341103)  
Classification: Moderate

Self Report? NO  
Citation: 30 TAC Chapter 111, SubChapter A 111.111(a)(1)(A)  
5C THC Chapter 382, SubChapter A 382.085(b)  
Description: Failure to an unscheduled shutdown.

Notice of Intent Date: 06/17/2003 (251315)

Disclosure Date: 12/16/2003

Viol. Classification: Moderate

YES

Citation: 30 TAC Chapter 116, SubChapter B 116.115(c) Req Prpv, PERMIT2610

Description: Failure to comply with permit special condition by allowing emissions from atmospheric vents Nos. 1 and 2 emit to the atmosphere instead of first going to the flare.

Viol. Classification: Moderate

YES

Citation: 30 TAC Chapter 115, SubChapter B 115.127(a)  
(2)[G]

Description: Emissions from the short loop vents exceeded the exemption criteria level on an intermittent basis.

Notice of Intent Date: 07/15/2002 (32987)

Disclosure Date: 01/23/2003

Viol. Classification: Moderate

YES

Citation: 30 TAC Chapter 331, SubChapter A 331.10(a)  
[G]

Description: Failure to submit an inventory information of wells authorized by rule.

Notice of Intent Date: 05/21/2002 (35078)

Disclosure Date: 12/20/2002

Viol. Classification: Moderate

YES

Citation: 40 CFR Chapter 61, SubChapter C, PT 61,  
SubPT A 61.01(a)

Description: Failure to identify liquid hydrocarbons containing benzene that were routed to blowdown stacks in the Total Annual Benzene (TAB) report

Viol. Classification: Moderate

YES

Citation: 40 CFR Chapter 61, SubChapter C, PT 61,  
SubPT A 61.01(a)

Description: Failure to manage waste streams containing greater than 2 Megagrams per year ("2Mg/yr") of benzene in controlled waste management units

Viol. Classification: Moderate

YES

Citation: 30 TAC Chapter 115, SubChapter B 115.143(b)  
(2)

Description: Failure to include emissions from blowdown stacks in the calculation of the percent reduction from the 1990 baseline for volatile organic compound ("VOC") emissions from wastewater sources

Viol. Classification: Moderate

YES

Citation: 40 CFR Chapter 63, SubChapter C, PT 63,  
SubPT A 63.1(a)

Description: Failure to control a gaseous stream venting from valve PV-3407 at the Ultraformer No. 3 blowdown stack, which renders the blowdown stack a Group 1 Miscellaneous Process Vent ("MPV")

Viol. Classification: Moderate

YES

Citation: 30 TAC Chapter 115, SubChapter B 115.127(a)  
[G]

30 TAC Chapter 115, SubChapter B 115.142[G]

Description: VOCs in the gaseous stream referred to in Violation No. 4 exceed exemption criteria for control requirements

Viol. Classification: Moderate

YES

Citation: 30 TAC Chapter 112, SubChapter B 112.31

30 TAC Chapter 112, SubChapter B 112.33[G]

Description: Failure to comply with hydrogen sulfide emission requirements for the Ultracracker and Ultraformer No. 3 Units

Viol. Classification: Major

YES

Citation: 30 TAC Chapter 116, SubChapter B 116.110(a)  
[G]

Description: Failure to obtain authorization for routine emissions from wastewater streams routed to the Coker Unit blowdown stack listed as emission point number ("EPN") 73 in Air Permit No. 2315

Viol. Classification: Major

YES

Citation: 30 TAC Chapter 116, SubChapter B 116.110(a)  
[G]

Description: Failure to authorize blowdown stack routine operational emissions not otherwise grandfathered under new source review ("NSR") regulations

Viol. Classification: Minor

YES

Citation: 30 TAC Chapter 106, SubChapter K 106.263

30 TAC Chapter 106, SubChapter A 106.8[G]

Description: Failure to maintain records of maintenance emissions from blowdown stacks  
Viol. Classification: Minor YES

Citation: 30 TAC Chapter 101, SubChapter F 101.211[G]

Description: Failure to report emissions from blowdown stacks which exceeded reportable quantities for hydrogen sulfide and benzene

Viol. Classification: Minor YES

Citation: 30 TAC Chapter 101, SubChapter A 101.10(a)  
[G]

Description: Failure to report emissions from the blowdown stacks in the annual emission inventory report

G. Type of environmental management systems (EMSs).

N/A

H. Voluntary on-site compliance assessment dates.

N/A

I. Participation in a voluntary pollution reduction program.

N/A

J. Early compliance.

N/A

Sites Outside of Texas

N/A





TEXAS COMMISSION ON ENVIRONMENTAL QUALITY



**IN THE MATTER OF AN  
ENFORCEMENT ACTION  
CONCERNING  
BP PRODUCTS NORTH AMERICA  
INC.  
RN102535077**

§  
§  
§  
§  
§  
§

**BEFORE THE  
  
TEXAS COMMISSION ON  
  
ENVIRONMENTAL QUALITY**

**AGREED ORDER  
DOCKET NO. 2005-1839-AIR-E**

At its \_\_\_\_\_ agenda, the Texas Commission on Environmental Quality ("the Commission" or "TCEQ") considered this agreement of the parties, resolving an enforcement action regarding BP Products North America Inc. ("BP Products") under the authority of TEX. HEALTH & SAFETY CODE ch. 382 and TEX. WATER CODE ch. 7. The Executive Director of the TCEQ, through the Enforcement Division, and BP Products North America Inc., presented this agreement to the Commission.

BP Products understands that they have certain procedural rights at certain points in the enforcement process, including, but not limited to, the right to formal notice of violations, notice of an evidentiary hearing, the right to an evidentiary hearing, and a right to appeal. By entering into this Agreed Order, BP Products agrees to waive all notice and procedural rights.

It is further understood and agreed that this Order represents the complete and fully-integrated settlement of the parties. The provisions of this Agreed Order are deemed severable and, if a court of competent jurisdiction or other appropriate authority deems any provision of this Agreed Order unenforceable, the remaining provisions will be valid and enforceable. The duties and responsibilities imposed by this Agreed Order are binding upon BP Products.

The Commission makes the following Findings of Fact and Conclusions of Law:

**I. FINDINGS OF FACT**

1. BP Products owns and operates a refinery located at 2401 5th Avenue South, Texas City, Galveston County, Texas (the "Plant").
2. The Plant consists of one or more sources as defined in TEX. HEALTH & SAFETY CODE § 382.003(12).
3. During inspections conducted on August 4, 2004, April 5, and June 1, 2005, and record reviews conducted on July 12, 2004, August 4, and 11, 2005, it was documented that BP Products failed to prevent the unauthorized release of air contaminants into the atmosphere, and failed to maintain opacity at 30% averaged during a six-minute period. The events did not meet the demonstration criteria necessary to present an affirmative defense for the unauthorized emissions. (See table below)



Incident No.	Date/ Permit No./ Cause	Unauthorized Emissions	Incident No.	Date/Permit No./Cause	Unauthorized Emissions
17651	3/18 - 3/19/03 - New Source Review ("NSR") Permit No. 18707: BP failed to prevent the over pressure of Tank Nos. 159 and 161 at the fluid catalytic cracking unit 3 ("FCCU3"), and it began venting to the atmosphere. (19 hrs.)	3,989 lbs. of Volatile Organic Compounds ("VOCs")	55147	2/25/05 - NSR Permit No. 19599 and PSD-TX-023: The light feed to the Pipestill 3A unit resulted in a pressure surge which caused a release from relief valve no. 189 to the atmosphere. (22 min.)	45 lbs. of butane, 2,512 lbs. of hexane, 9 lbs. of isobutane, 1,710 lbs. of isopentane, 1,238 lbs. of pentane, 81 lbs. of benzene, and 20 lbs. of H <sub>2</sub> S
25606	8/8 - 8/18/03 - NSR Permit C-18706: BP failed to prevent a heat exchanger leak which occurred at the fluid catalytic cracking unit 2 ("FCCU2") cooling tower. (247 hrs.)	14,260 lbs. of VOCs	54786	3/3/05 - NSR Permit No. 8810 and PSD-TX-402M2: BP failed to prevent an increase in system pressure at the RHU, which caused a pressure controller to relieve to the CRPII Flare (EPN No. 501). (5 hrs., 50 min.)	2,368 lbs. of SO <sub>2</sub> , and 215 lbs. of CO
49566	11/17/04 - NSR Permit No. 8810 and PSD-TX-402M2: The electrical relay failed on the switchgear cubicle to the 557J light hydrocarbon compressor, causing the 557J compressor to trip and flare at the CRPII Flare [Emission Point No. ("EPN") No. 501] at the Resid Hydrotreating Unit ("RHU"). (40 min.)	1,765 lbs. of sulfur dioxide ("SO <sub>2</sub> "), 0.39 lbs. of nitrogen dioxide ("NO <sub>2</sub> "), 3 lbs. of nitrogen oxide ("NOx"), and 37 lbs. of carbon monoxide ("CO")	55442 & 55443	3/17/05 - NSR Permit No. 18707 - BP failed to prevent a malfunction of a north upper slide valve which caused high differential pressure between a regenerator and a reactor at the FCCU3, and also caused an unplanned shutdown of the electrostatic precipitator ("ESP"). This resulted in an 87% opacity for 6 min.	18 lbs. of alumina silica catalyst fines, and a 87% opacity for 6 minutes
49944	11/24/04 - NSR Permit No. 8810 and PSD-TX-402M2: The L2467 A & B level transmitters at the RHU failed and caused the 201-E High Pressure Amine Absorber oil side to become full of liquid. This caused increased pressure to the system, and the 207-F flash drum pressure controller opened to the CP II flare (EPN No. 501). (9 hrs., 24 min.)	7,696 lbs. of SO <sub>2</sub> , 59 lbs. of NOx, 7 lbs. of NO <sub>2</sub> and 711 lbs. of CO	55487 & 56049	3/18/05 - NSR Permit No. 18707: BP failed to prevent a slide valve failure at the FCCU3 which caused a decrease in reactor pressure and inlet temperature. The decrease in pressure and temperature caused a low plug valve malfunction which shutdown the unit and resulted in emissions from Flare No. 5 to the atmosphere. (2 hrs., 55 min.)	2,211 lbs. OF VOCs
51878 & 51879	1/4/05 - NSR Permit No. 18707: BP failed to prevent the malfunction of a liquid level controller (L4834) on the 506-E depropanizer tower, which resulted in emissions from Flares No. 3 and 5 to the atmosphere. (13 hrs. 36 min.)	2100 lbs. of VOCs, and 27 lbs. hydrogen sulfide ("H <sub>2</sub> S")	58226, 58227, & 58231	5/12/05 - NSR Permit No. 18707: BP failed to properly direct the flow of Light Cat Cycle Oil ("LCCO") from a loading dock during an oil movements line-up procedure. The LCCO was inadvertently routed to FCCU3, which resulted in an increase in reactor pressure and the shutdown of the unit. The shutdown of the unit resulted in the release of unauthorized emissions from the ESP stack to the atmosphere. This also resulted in an 89% opacity for 6 minutes. (14 hrs., 16 min.)	4,028 lbs. of VOCs, 13.44 lbs. of H <sub>2</sub> S, 15.42 lbs. of alumina silica catalyst fines, and an 89% opacity for 6 minutes.
54083 & 54088	2/16/05 - NSR Permit No. 18707 - BP failed to prevent excessive water from collecting in an instrument air header which caused an increase in reactor pressure that resulted in venting to Flare No. 3 at the FCCU3, and also caused an unplanned shutdown of the ESP. This resulted in a 59% opacity for 6 minutes. (6 min.)	62 lbs. of alumina silica catalyst fines, and a 59% opacity for 6 minutes			

Date	Description	Particulars	Debit	Credit	Balance
1900					
Jan 1	Balance forward				
Jan 5	Received from A				
Jan 10	Received from B				
Jan 15	Received from C				
Jan 20	Received from D				
Jan 25	Received from E				
Jan 30	Received from F				
Feb 1	Received from G				
Feb 5	Received from H				
Feb 10	Received from I				
Feb 15	Received from J				
Feb 20	Received from K				
Feb 25	Received from L				
Feb 30	Received from M				
Mar 1	Received from N				
Mar 5	Received from O				
Mar 10	Received from P				
Mar 15	Received from Q				
Mar 20	Received from R				
Mar 25	Received from S				
Mar 30	Received from T				
Apr 1	Received from U				
Apr 5	Received from V				
Apr 10	Received from W				
Apr 15	Received from X				
Apr 20	Received from Y				
Apr 25	Received from Z				
Apr 30	Received from AA				
May 1	Received from AB				
May 5	Received from AC				
May 10	Received from AD				
May 15	Received from AE				
May 20	Received from AF				
May 25	Received from AG				
May 30	Received from AH				
Jun 1	Received from AI				
Jun 5	Received from AJ				
Jun 10	Received from AK				
Jun 15	Received from AL				
Jun 20	Received from AM				
Jun 25	Received from AN				
Jun 30	Received from AO				
Jul 1	Received from AP				
Jul 5	Received from AQ				
Jul 10	Received from AR				
Jul 15	Received from AS				
Jul 20	Received from AT				
Jul 25	Received from AU				
Jul 30	Received from AV				
Aug 1	Received from AW				
Aug 5	Received from AX				
Aug 10	Received from AY				
Aug 15	Received from AZ				
Aug 20	Received from BA				
Aug 25	Received from BB				
Aug 30	Received from BC				
Sep 1	Received from BD				
Sep 5	Received from BE				
Sep 10	Received from BF				
Sep 15	Received from BG				
Sep 20	Received from BH				
Sep 25	Received from BI				
Sep 30	Received from BJ				
Oct 1	Received from BK				
Oct 5	Received from BL				
Oct 10	Received from BM				
Oct 15	Received from BN				
Oct 20	Received from BO				
Oct 25	Received from BP				
Oct 30	Received from BQ				
Nov 1	Received from BR				
Nov 5	Received from BS				
Nov 10	Received from BT				
Nov 15	Received from BU				
Nov 20	Received from BV				
Nov 25	Received from BW				
Nov 30	Received from BX				
Dec 1	Received from BY				
Dec 5	Received from BZ				
Dec 10	Received from CA				
Dec 15	Received from CB				
Dec 20	Received from CC				
Dec 25	Received from CD				
Dec 30	Received from CE				
Total					

Received of \_\_\_\_\_  
 the sum of \_\_\_\_\_  
 Dollars for \_\_\_\_\_  
 \_\_\_\_\_  
 \_\_\_\_\_  
 \_\_\_\_\_

4. During an investigation conducted on June 1, 2005, it was documented that BP Products failed to equip an open-ended line (tag no. 16333) in the fluid catalytic cracking unit 3 ("FCCU3") with a cap, blind flange, plug, or a second valve. The estimated amount of fugitive volatile organic compound emissions ("VOCs") from this open ended line is 0.12 lbs.
5. During a record review conducted on August 4, 2005, it was documented that BP Products failed to prevent the unauthorized release of air contaminants into the atmosphere from the UU3. Specifically, an operator failed to close a valve to the blowdown system in the UU3 (Incident No. 49293). The drum was full, and as a result, it overflowed to the blowdown stack which then released liquid. The spilled liquid vaporized, and released seven pounds of benzene, 28 lbs. of toluene, and 904 lbs. of unauthorized VOCs to the atmosphere.
6. BP Products received notices of the violations on September 4, 6, 20, and 21, 2005.
7. The Executive Director recognizes that BP Products has implemented the following corrective measures at the Plant:
  - a. On August 18, 2003, concerning Incident No. 25606 which occurred on August 8, 2003, BP Products installed new heat exchanger bundles in the fluid catalytic cracking unit 2 ("FCCU2"), and unit technicians replaced faulty wiring on November 30, 2004;
  - b. On November 30, 2003, concerning Incident No. 17651 which occurred on March 18, 2003, BP Products re-routed the sour water tank vent at the FCCU3 to the low-pressure refinery fuel gas system. The gas is now recovered, scrubbed to remove hydrogen sulfide, and used in various combustion sources at the refinery;
  - c. On November 11, 2004, concerning Incident No. 49293 which occurred on November 10, 2004, BP Products repaired the faulty level alarm on the vessel that overflowed on the UU3;
  - d. On November 30, 2004, concerning Incident No. 49566 which occurred on November 17, 2004, BP Products replaced the faulty wiring in the Resid Hydrotreater Unit ("RHU");
  - e. On January 4, 2005, concerning Incident Nos. 51878 and 51879 which occurred on January 4, 2005, BP Products replaced the float in the liquid level controller on the 506-E depropanizer tower;
  - f. On March 31, 2005, concerning Incident No. 49944 which occurred on November 24, 2004, BP Products replaced the level transmitter in the RHU during unit turnaround;
  - g. On May 4, 2005, concerning Incident Nos. 54083 and 54088 which occurred on February 16, 2005, plant shift personnel responsible for proper functioning of plant equipment were instructed to check every shift for water in the instrument header at the FCCU3;



- h. On June 1, 2005, BP Products placed a plug on the open-ended line (tag no. 16333) at the FCCU3;
- i. On June 22, 2005, concerning Incident No. 55147 which occurred on February 25, 2005, BP re-trained all plant shift personnel responsible for proper functioning of the levels of the Pipestill 3A;
- j. On August 12, 2005, concerning Incident Nos. 58226, 58227 and 58231 which occurred on May 12, 2005, shift personnel responsible for proper flow and functioning of the light cat cycle oil ("LCCO") were re-trained, and the valve on the FCCU3 was closed and locked;
- k. On September 15, 2005, concerning Incident No. 54786 which occurred on March 3, 2005, BP Products implemented computer controller changes, and changes to startup procedures at the RHU;
- l. On September 28, 2005, concerning Incident Nos. 55442 and 55443 which occurred on March 17, 2005, the valve was repaired at the electrostatic precipitator;
- m. On September 28, 2005, concerning Incident Nos. 55487 and 56049 which occurred on March 18, 2005, the valve was repaired at the FCCU3; and
- n. On November 18, 2005, BP Product's notarized certification of compliance was received at the TCEQ.

## II. CONCLUSIONS OF LAW

1. BP Products is subject to the jurisdiction of the TCEQ pursuant to TEX. WATER CODE § 7.002, TEX. HEALTH & SAFETY CODE ch. 382, and the rules of the Commission.
2. As evidenced by Finding of Fact No. 3, BP Products failed to prevent the unauthorized release of air contaminants into the atmosphere, and failed to maintain opacity at 30% averaged over a six-minute period, in violation of 30 TEX. ADMIN. CODE §§ 111.111(a)(1)(A), 116.115(c), Air Permit Nos. 8810 and PSD-TX-402M2, C-18706, 18707, 19599 and PSD-TX-023, Special Condition No.1, and TEX. HEALTH & SAFETY CODE § 382.085(b).
3. As evidenced by Finding of Fact No. 4, BP Products failed to equip an open-ended line with a cap, blind flange, plug, or a second valve, in violation of 30 TEX. ADMIN. CODE §§ 101.20(2), 115.352(4), and 40 CODE OF FEDERAL REGULATIONS § 63.167(a)(1), and TEX. HEALTH & SAFETY CODE § 382.085(b).
4. As evidenced by Finding of Fact No. 5, BP Products failed to prevent the unauthorized release of air contaminants into the atmosphere, in violation of 30 TEX. ADMIN. CODE § 116.116(a), and TEX. HEALTH AND SAFETY CODE § 382.085(b).





5. Pursuant to TEX. WATER CODE § 7.051, the Commission has the authority to assess an administrative penalty against BP Products for violations of the Texas Water Code and the Texas Health and Safety Code within the Commission's jurisdiction; for violations of rules adopted under such statutes; or for violations of orders or permits issued under such statutes.
6. An administrative penalty in the amount of One Hundred Thirty Thousand Six Hundred Twenty-Five Dollars (\$130,625) is justified by the facts recited in this Agreed Order, and considered in light of the factors set forth in TEX. WATER CODE § 7.053. BP Products has paid the One Hundred Thirty Thousand Six Hundred Twenty-Five Dollar (\$130,625) administrative penalty.

### III. ORDERING PROVISIONS

NOW, THEREFORE, THE TEXAS COMMISSION ON ENVIRONMENTAL QUALITY ORDERS that:

1. BP Products is assessed an administrative penalty in the amount of One Hundred Thirty Thousand Six Hundred Twenty-Five Dollars (\$130,625), as set forth in Section II, Paragraph 6 above, for violations of TCEQ rules and state statutes. The imposition of this administrative penalty and BP Products's compliance with all the terms and conditions set forth in this Agreed Order completely resolve the violations set forth by this Agreed Order in this action. However, the Commission shall not be constrained in any manner from requiring corrective actions or penalties for other violations that are not raised here. Administrative penalty payments shall be made payable to "TCEQ" and shall be sent with the notation "Re: BP Products North America Inc., Docket No. 2005-1839-AIR-E" to:

Financial Administration Division, Revenues Section  
Attention: Cashier's Office, MC 214  
Texas Commission on Environmental Quality  
P.O. Box 13088  
Austin, Texas 78711-3088

2. The provisions of this Agreed Order shall apply to and be binding upon BP Products. BP Products is ordered to give notice of this Agreed Order to personnel who maintain day-to-day control over the Plant operations referenced in this Agreed Order.
3. The Executive Director may refer this matter to the Office of the Attorney General of the State of Texas ("OAG") for further enforcement proceedings without notice to BP Products if the Executive Director determines that BP Products has not complied with one or more of the terms or conditions in this Agreed Order.
4. This Agreed Order shall terminate five years from its effective date or upon compliance with all the terms and conditions set forth in this Agreed Order, whichever is later.

...the ... of ...

...the ... of ...

... ..

...the ... of ...

...the ... of ...

... ..

...the ... of ...

...the ... of ...

...the ... of ...

5. This Agreed Order, issued by the Commission, shall not be admissible against BP Products in a civil proceeding, unless the proceeding is brought by the OAG to: (1) enforce the terms of this Agreed Order; or (2) pursue violations of a statute within the Commission's jurisdiction, or of a rule adopted or an order or permit issued by the Commission under such a statute.
6. This agreement may be executed in multiple counterparts, which together shall constitute a single original instrument. Any executed signature page to this Agreement may be transmitted by facsimile transmission to the other parties, which shall constitute an original signature for all purposes.
7. The Chief Clerk shall provide a copy of this Agreed Order to each of the parties. By law, the effective date of this Agreed Order is the third day after the mailing date, as provided by 30 TEX. ADMIN. CODE § 70.10(b) and TEX. GOV'T CODE § 2001.142.



BP Products North America Inc.  
DOCKET NO 2005-1839-AIR-E  
Page 7

SIGNATURE PAGE

TEXAS COMMISSION ON ENVIRONMENTAL QUALITY

For the Commission

*[Handwritten Signature]*

6/15/06

For the Executive Director

Date

I, the undersigned, have read and understand the attached Agreed Order in the matter of BP Products North America Inc. I am authorized to agree to the attached Agreed Order on behalf of BP Products North America Inc., and do agree to the specified terms and conditions. I further acknowledge that the TCEQ, in accepting payment for the penalty amount, is materially relying on such representation.

I understand that by entering into this Agreed Order, BP Products North America Inc. waives certain procedural rights, including, but not limited to, the right to formal notice of violations addressed by this Agreed Order, notice of an evidentiary hearing, the right to an evidentiary hearing, and the right to appeal. I agree to the terms of the Agreed Order in lieu of an evidentiary hearing. This Agreed Order constitutes full and final adjudication by the Commission of the violations set forth in this Agreed Order.

I also understand that my failure to comply with the Ordering Provisions, if any, in this order and/or my failure to timely pay the penalty amount, may result in:

- A negative impact on my compliance history;
- Greater scrutiny of any permit applications submitted by me;
- Referral of this case to the Attorney General's Office for contempt, injunctive relief, additional penalties, and/or attorney fees, or to a collection agency;
- Increased penalties in any future enforcement actions against me;
- Automatic referral to the Attorney General's Office of any future enforcement actions against me; and
- TCEQ seeking other relief as authorized by law.

In addition, any falsification of any compliance documents may result in criminal prosecution.

*[Handwritten Signature]*

5/22/06

Signature

Date

COVIN H. J. MACLEEN

BUSINESS UNIT LEADER

Name (printed or typed)

Title

Authorized Representative

BP Products North America Inc

Instructions: Send the original, signed Agreed Order with penalty payment to the Financial Administration Division, Revenues Section at the address in Ordering Provision 1 of this Agreed Order.

Very faint, illegible text at the top of the page, possibly a header or title area.

Main body of very faint, illegible text, appearing to be several paragraphs of a document.

Bottom section of very faint, illegible text, possibly a signature block or footer.