

**Photographic Log,  
CES Environmental Services Facility Site Visit,  
Houston, Texas**

The following photographs were taken and described by Terry Andrews, Remediation Division, Texas Commission on Environmental Quality (TCEQ), while visiting the CES Environmental Services (CES) facility in Houston, Texas on September 2, 2014, from approximately 12:40 to 2:25 PM. The goal of this site visit was to evaluate the stormwater that is ponded on the site. Mr. Andrews was accompanied during the visit by Gary Moore, OSC, EPA Region 6 ER.

During the site visit, there was a light wind blowing out of the south, with mostly clear skies.



**Photograph #1, September 2, 2014 – View looking southwest at stormwater ponded along earthen berm in the southwest corner of the CES site.**



**Photograph #2, September 2, 2014 – View looking west at stormwater ponded along earthen berm in the southwest corner of the CES site. Note that in the shadowed area near the center of the photograph, there is only 9-10 inches of freeboard available.**



**Photograph #3, August 2, 2014 - View looking northwest at team removing oil from the surface of the stormwater that is ponded against the berm. The team thought that the oil was coming from either the berm or soils under the berm.**



Photograph #4, September 2, 2014 – View looking north at stormwater ponded in the north part of the site.



Photograph #5, September 2, 2014 – View looking north from residential property located south of the earthen berm. The fenceline (with trees and in the middle of the berm) separates the CES property from the residential property. There was no visible staining, sheen or oil on the water in the drainage ditch.

