


03/26/2014 10:56



03/26/2014 11:00

PA

PA
640

640

03/26/2014 11:12

oil water



641

03/26/2014 11:13

607

oil sludge

03/26/2014 11:13

601

WASH
see sample
zzz

AN
TH
LO
TAN

03/26/2014 11:13

Oil Sludge

610

 CES Environmental
Services, Inc.
HOUSTON, TX

03/26/2014 11:13



18
633

03/26/2014 11:13

ww?

639

Environmental
Services, Inc.

STON, TX
76-1

03/26/2014 11:13






03/26/2014 11:17



DANA DANA


03/26/2014 11:17



Google earth

Imagery Date: 10/31/2013 29°41'51.58" N 86°20'38.15" W elev. 39 ft

Eye alt: 622 ft




03/26/2014 11:19







Highlighted dashed lines represent where berms were noted during the site investigation




Berm along southwest fence line



03/26/2014 10:19

Berm along southwest fence line




Berm along portion of west fence line



03/26/2014 11:16

Berm near eastern fence line



03/26/2014 11:32