



Photograph No. 1. Black galvestos coating on the west exterior wall of Facility No. 1, approximately 15 to 30 feet above ground level, view facing south. Photograph taken by K. Brandner, November 27, 2006.



Photograph No. 2. Black galvestos coating on the north exterior wall of Facility No. 2, view facing southeast. Photograph taken by K. Brandner, November 27, 2006.



Photograph No. 3. Black galvestos coating on concrete pillars and south exterior wall of East Cell House, view facing west. Photograph taken by K. Brandner, November 29, 2006.



Photograph No. 4. Black galvestos coating on steel I-beam at east end, 2nd floor of East Cell House, view facing east. Photograph taken by K. Brandner, November 29, 2006.



Photograph No. 5. Black galvestos coating on concrete pillars, exterior wall, and steel pipe at east end of West Cell House, view facing south. Photograph taken by K. Brandner, November 29, 2006.



Photograph No. 6. Black galvestos coating on two large steel cone-shaped tanks north of Facility No. 1, view facing southeast. Photograph taken by K. Brandner, November 27, 2006.



Photograph No. 7. Brown linoleum floor covering in office on 2nd floor of Facility No. 1, view facing southwest. Photograph taken by K. Brandner, November 27, 2006.



Photograph No. 8. Brown linoleum floor covering in office on 2nd floor of Facility No. 2, view facing west. Photograph taken by K. Brandner, November 27, 2006.



Photograph No. 9. White pipe wrap on 2nd floor of Facility No. 1, view facing southwest. Photograph taken by K. Brandner, November 27, 2006.



Photograph No. 10. White pipe wrap on 2nd floor of Facility No. 2, view facing west. Photograph taken by K. Brandner, November 27, 2006.



Photograph No. 11. White pipe wrap on 2nd floor of West Cell House, view facing north. Photograph taken by K. Brandner, November 29, 2006.



Photograph No. 12. White pipe wrap in basement of Admin Building and Lab (Building 46), view facing north. Photograph taken by K. Brandner, December 1, 2006.



Photograph No. 13. 12" x 12" light brown floor tile in office at northeast end of Facility No. 2, view facing north. Photograph taken by K. Brandner, November 28, 2006.



Photograph No. 14. Red brick building in foreground (Building 12) has a tar and gravel roof, view facing east. Blue reactor/clarifier tank in background. Photograph taken by K. Brandner, November 28, 2006.



Photograph No. 15. 9" x 9" light brown floor tile on 2nd floor office at south end of Power House, view facing south. Photograph taken by K. Brandner, November 29, 2006.



Photograph No. 16. 18"-diameter white pipe wrap with orange exterior jacket on steel pipe running north-south approximately 12 feet above ground level above the 1st floor of the Power House, view facing south. Photograph taken by K. Brandner, November 29, 2006.



Photograph No. 17. Boilers on the 2nd floor of the Power House, view facing north. Photograph taken by K. Brandner, November 29, 2006.



Photograph No. 18. Boiler in the Zinc Building, view facing south. Photograph taken by K. Brandner, November 29, 2006.




Photograph No. 19. White pipe wrap with outer sheet metal jacket on pipes on the 1st floor at the east end of Facility No. 4, view facing south. Photograph taken by K. Brandner, November 28, 2006.



Photograph No. 20. White pipe wrap with outer sheet metal jacket on pipes on the 1st floor at the southeast end of the Power House, view facing south. Photograph taken by K. Brandner, November 29, 2006.



Photograph No. 21. 12" x 12" white floor tile with light gray streaks in Change House/Guard House, view facing south. Photograph taken by K. Brandner, December 1, 2006.



Photograph No. 22. 9" x 9" cream-white floor tile in office at northeast end of Warehouse Storage Building 51, view facing east. Photograph taken by K. Brandner, December 1, 2006.



Photograph No. 23. Large red and white smokestack directly southwest of Facility No. 4, view facing northwest. Photograph taken by K. Brandner, December 1, 2006.