

Recreational Use Attainability Analysis of Duck Creek (Segment 1209H)

Appendix 3

Photographic Record

*** Photos in JPEG format are available as an electronic supplement on the CD insert found in Appendix 5**

Photograph Number	Site Location	Date	Description	Direction Photo Taken
DkCrBruaaFS1 01-01	Field Survey Site #1 - White Rock Rd	5/28/2010	View facing upstream from the bridge	West/Northwest
DkCrBruaaFS1 01-02	Field Survey Site #1 - White Rock Rd	5/28/2010	View of left bank from the bridge	North/Northeast
DkCrBruaaFS1 01-03	Field Survey Site #1 - White Rock Rd	5/28/2010	View facing downstream from the bridge	Southeast
DkCrBruaaFS1 01-04	Field Survey Site #1 - White Rock Rd	5/28/2010	View of right bank from the bridge	Southwest
DkCrBruaaFS1 01-05	Field Survey Site #1 - White Rock Rd	5/28/2010	View of graffiti along the edge of the bridge facing upstream	West/Northwest
DkCrBruaaFS1 01-06	Field Survey Site #1 - White Rock Rd	5/28/2010	View of graffiti on the road on the bridge	South/Southwest
DkCrBruaaFS1 02-01	Field Survey Site #2 - FM979 (TCEQ site: 16390)	5/28/2010	View of old fence wire going across the creek above the water at 120m	West
DkCrBruaaFS1 02-02	Field Survey Site #2 - FM979 (TCEQ site: 16390)	5/28/2010	View of old fence wire grown into trunk of leaning tree at 120m	North
DkCrBruaaFS1 02-03	Field Survey Site #2 - FM979	5/28/2010	View facing upstream at 30m	West/Southwest
DkCrBruaaFS1 02-04	Field Survey Site #2 - FM979	5/28/2010	View of left bank at 30m	North/Northwest
DkCrBruaaFS1 02-05	Field Survey Site #2 - FM979	5/28/2010	View facing downstream at 30m	Northeast
DkCrBruaaFS1 02-06	Field Survey Site #2 - FM979	5/28/2010	View of right bank at 30m	South/Southeast
DkCrBruaaFS1 02-07	Field Survey Site #2 - FM979	5/28/2010	View facing upstream at 180m at	West
DkCrBruaaFS1 02-08	Field Survey Site #2 - FM979	5/28/2010	View of left bank at 180m at bridge	North
DkCrBruaaFS1 02-09	Field Survey Site #2 - FM979	5/28/2010	View facing downstream at 180m at	East
DkCrBruaaFS1 02-10	Field Survey Site #2 - FM979	5/28/2010	View of right bank at 180m at bridge	South
DkCrBruaaFS1 02-11	Field Survey Site #2 - FM979	5/28/2010	View of raccoon trap on right bank	South
DkCrBruaaFS1 02-12	Field Survey Site #2 - FM979	5/28/2010	View of fencing across water	East
DkCrBruaaFS1 03-01	Field Survey Site #3 - FM2096	5/28/2010	View facing upstream at 150m	West
DkCrBruaaFS1 03-02	Field Survey Site #3 - FM2096	5/28/2010	View of left bank at 150m	North
DkCrBruaaFS1 03-03	Field Survey Site #3 - FM2096	5/28/2010	View facing downstream at 150m	East
DkCrBruaaFS1 03-04	Field Survey Site #3 - FM2096	5/28/2010	View of right bank at 150m	South
DkCrBruaaFS1 03-05	Field Survey Site #3 - FM2096	5/28/2010	View of fencing across water upstream of bridge	West
DkCrBruaaFS1 04-01	Field Survey Site #4 - US79	5/28/2010	View facing upstream at 30m	North
DkCrBruaaFS1 04-02	Field Survey Site #4 - US79	5/28/2010	View of left bank at 30m	East
DkCrBruaaFS1 04-03	Field Survey Site #4 - US79	5/28/2010	View facing downstream at 30m	South
DkCrBruaaFS1 04-04	Field Survey Site #4 - US79	5/28/2010	View of right bank at 30m	West
DkCrBruaaFS1 04-05	Field Survey Site #4 - US79	5/28/2010	View of possible hog or deer resting	West
DkCrBruaaFS1 04-06	Field Survey Site #4 - US79	5/28/2010	View facing upstream at 150m	North
DkCrBruaaFS1 04-07	Field Survey Site #4 - US79	5/28/2010	View of left bank at 150m	East
DkCrBruaaFS1 04-08	Field Survey Site #4 - US79	5/28/2010	View facing downstream at 150m	South
DkCrBruaaFS1 04-09	Field Survey Site #4 - US79	5/28/2010	View of right bank at 150m	West
DkCrBruaaFS1 04-10	Field Survey Site #4 - US79	5/28/2010	View facing upstream at 300m	Northwest
DkCrBruaaFS1 04-11	Field Survey Site #4 - US79	5/28/2010	View of left bank at 300m	North/Northeast
DkCrBruaaFS1 04-12	Field Survey Site #4 - US79	5/28/2010	View facing downstream at 300m	East/Southeast
DkCrBruaaFS1 04-13	Field Survey Site #4 - US79	5/28/2010	View of right bank at 300m	South/Southeast
DkCrCruaaRecon01-01	Recon Site #1 - LCR704 A	1/12/2010	View of closed gate	East/Northeast
DkCrCruaaRecon02-01	Recon Site #2 - LCR704 B	1/12/2010	View of closed gate with "Private Property - No Trespassing" sign	East/Southeast

Photograph Number	Site Location	Date	Description	Direction Photo
DkCrCruaaRecon03-01	Recon Site #3 - LCR704 C	1/12/2010	View 4C's Game Ranch's open gate	East/Southeast
DkCrCruaaRecon04-01	Recon Site #4 - White Rock Rd	1/12/2010	View of barbed wire fence under bridge on right bank from downstream side	East/Northeast
DkCrCruaaRecon04-02	Recon Site #4 - White Rock Rd	1/12/2010	View of trash downstream right bank from downstream side	Southwest
DkCrCruaaRecon04-03	Recon Site #4 - White Rock Rd	1/12/2010	View of barbed wire fence under bridge on left bank from downstream side	Northeast
DkCrCruaaRecon04-04	Recon Site #4 - White Rock Rd	1/12/2010	View upstream from middle of bridge	Northwest
DkCrCruaaRecon04-05	Recon Site #4 - White Rock Rd	1/12/2010	View of right bank from upstream side of bridge	Northeast
DkCrCruaaRecon04-06	Recon Site #4 - White Rock Rd	1/12/2010	View downstream from middle of bridge	Southeast
DkCrCruaaRecon04-07	Recon Site #4 - White Rock Rd	1/12/2010	View of left bank from upstream side of bridge	West/Southwest
DkCrCruaaRecon05-01	Recon Site #5 - CR477	1/12/2010	View of closed and locked gate with "No Trespassing" sign	East/Southeast
DkCrCruaaRecon06-01	Recon Site #6 - TCEQ Sta 16390 - FM979	1/12/2010	View upstream from middle of bridge	West/Northwest
DkCrCruaaRecon06-02	Recon Site #6 - TCEQ Sta 16390 - FM979	1/12/2010	View of right bank from upstream side of bridge	North/Northeast
DkCrCruaaRecon06-03	Recon Site #6 - TCEQ Sta 16390 - FM979	1/12/2010	View downstream from middle of bridge	East/Southeast
DkCrCruaaRecon06-04	Recon Site #6 - TCEQ Sta 16390 - FM979	1/12/2010	View of left bank from upstream side of bridge	Southwest
DkCrCruaaRecon06-05	Recon Site #6 - TCEQ Sta 16390 - FM979	1/12/2010	View under bridge from upstream left bank, tire marks visible	Northeast
DkCrCruaaRecon07-01	Recon Site #7 - FM2096	1/12/2010	View upstream from right bank under bridge	West
DkCrCruaaRecon07-02	Recon Site #7 - FM2096	1/12/2010	View of right bank from right bank under bridge	Vertical
DkCrCruaaRecon07-03	Recon Site #7 - FM2096	1/12/2010	View downstream from right bank under bridge	Southeast
DkCrCruaaRecon07-04	Recon Site #7 - FM2096	1/12/2010	View of left bank from right bank under bridge	North/Northeast
DkCrCruaaRecon10-01	Recon Site #10 - TCEQ Sta 11389 - US79	1/13/2010	View upstream from left bank under bridge	North/Northwest
DkCrCruaaRecon10-02	Recon Site #10 - TCEQ Sta 11389 - US79	1/13/2010	View of right bank from left bank under bridge	North
DkCrCruaaRecon10-03	Recon Site #10 - TCEQ Sta 11389 - US79	1/13/2010	View downstream from left bank under bridge	North
DkCrCruaaRecon10-04	Recon Site #10 - TCEQ Sta 11389 - US79	1/13/2010	View of left bank from left bank under bridge	South
DkCrCruaaRecon10-05	Recon Site #10 - TCEQ Sta 11389 - US79	1/13/2010	View of footprint under bridge on left bank	
DkCrCruaaRecon10-06	Recon Site #10 - TCEQ Sta 11389 - US79	1/13/2010	View of EIH truck parked along the road with large gravelled area	Southwest
DkCrCruaaRecon11-01	Recon Site #11 - Hoxie Chapel Rd 1	1/13/2010	View of open gate and "No Trespassing" sign	East



DkCrBruaaFS1 01-01



DkCrBruaaFS1 01-02




DkCrBruaaFS1 01-03



DkCrBruaaFS1 01-04



DkCrBruaaFS1 01-05



DkCrBruaaFS1 01-06



DkCrBruaaFS1 02-01



DkCrBruaaFS1 02-02



DkCrBruaaFS1 02-03



DkCrBruaaFS1 02-04



DkCrBruaaFS1 02-05



DkCrBruaaFS1 02-06



DkCrBruaaFS1 02-07



DkCrBruaaFS1 02-08



DkCrBruaaFS1 02-09



DkCrBruaaFS1 02-10



DkCrBruaaFS1 02-11



DkCrBruaaFS1 02-12



DkCrBruaaFS1 03-01



DkCrBruaaFS1 03-02



DkCrBruaaFS1 03-03



DkCrBruaaFS1 03-04



DkCrBruaaFS1 03-05



DkCrBruaaFS1 04-01



DkCrBruaaFS1 04-02



DkCrBruaaFS1 04-03



DkCrBruaaFS1 04-04



DkCrBruaaFS1 04-05



DkCrBruaaFS1 04-06



DkCrBruaaFS1 04-07



DkCrBruaaFS1 04-08



DkCrBruaaFS1 04-09



DkCrBruaaFS1 04-10



DkCrBruaaFS1 04-11



DkCrBruaaFS1 04-12



DkCrBruaaFS1 04-13



DkCrBruaaRecon01-01



DkCrBruaaRecon02-01



DkCrBruaaRecon03-01



DkCrBruaaRecon04-01



DkCrBruaaRecon04-02



DkCrBruaaRecon04-03



DkCrBruaaRecon04-04



DkCrBruaaRecon04-05




DkCrBruaaRecon04-06



DkCrBruaaRecon04-07




DkCrBruaaRecon05-01



DkCrBruaaRecon06-01



DkCrBruaaRecon06-02



DkCrBruaaRecon06-03



DkCrBruaaRecon06-04




DkCrBruaaRecon06-05



DkCrBruaaRecon07-01



DkCrBruaaRecon07-02



DkCrBruaaRecon07-03



DkCrBruaaRecon07-04



DkCrBruaaRecon10-01



DkCrBruaaRecon10-02



DkCrBruaaRecon10-03



DkCrBruaaRecon10-04



DkCrBruaaRecon10-05



DkCrBruaaRecon10-06



DkCrBruaaRecon11-01