

Recreational Use Attainability Analysis of Steele Creek (Segment 1209K)

Appendix 3

Photographic Record

*** Photos in JPEG format are available as an electronic supplement on the CD insert found in Appendix 5**

Photograph Number	Site Location	Date	Description	Direction Taken
StCrBruaaFS1 01-01	FM 147 @ Steele Creek	5/28/2010	View facing upstream at culvert	North/Northwest
StCrBruaaFS1 01-02	FM 147 @ Steele Creek	5/28/2010	View of left bank at culvert	Northeast
StCrBruaaFS1 01-03	FM 147 @ Steele Creek	5/28/2010	View facing downstream at culvert	South/Southeast
StCrBruaaFS1 01-04	FM 147 @ Steele Creek	5/28/2010	View of right bank at culvert	Southwest
StCrBruaaFS1 02-01	LCR 648 @ Steele Creek	5/28/2010	View facing upstream at 115m	West/Northwest
StCrBruaaFS1 02-02	LCR 648 @ Steele Creek	5/28/2010	View of left bank at 115m	North/Northeast
StCrBruaaFS1 02-03	LCR 648 @ Steele Creek	5/28/2010	View facing downstream at 115m	East/Southeast
StCrBruaaFS1 02-04	LCR 648 @ Steele Creek	5/28/2010	View of right bank at 115m	South/Southwest
StCrBruaaFS1 02-05	LCR 648 @ Steele Creek	5/28/2010	View of oil sheen on top of water	North
StCrBruaaFS1 02-06	LCR 648 @ Steele Creek	5/28/2010	View facing upstream at 150m	West/Northwest
StCrBruaaFS1 02-07	LCR 648 @ Steele Creek	5/28/2010	View of left bank at 150m	North
StCrBruaaFS1 02-08	LCR 648 @ Steele Creek	5/28/2010	View facing downstream at 150m	East/Southeast
StCrBruaaFS1 02-09	LCR 648 @ Steele Creek	5/28/2010	View of right bank at 150m	South
StCrBruaaFS1 02-10	LCR 648 @ Steele Creek	5/28/2010	View of large pool at 158m	East/Southeast
StCrBruaaFS1 02-11	LCR 648 @ Steele Creek	5/28/2010	View of hay twine and trash on the bank	East/Southeast
StCrBruaaFS1 03-01	LCR 656 @ Steele Creek	5/28/2010	View facing upstream at the bridge	West
StCrBruaaFS1 03-02	LCR 656 @ Steele Creek	5/28/2010	View of left bank at the bridge	North
StCrBruaaFS1 03-03	LCR 656 @ Steele Creek	5/28/2010	View facing downstream at the bridge	East/Southeast
StCrBruaaFS1 03-04	LCR 656 @ Steele Creek	5/28/2010	View of right bank at the bridge	Southwest
StCrBruaaFS1 04-01	SH 14 @ Steele Creek	5/28/2010	View facing upstream at 30m and view of log jam	Northwest
StCrBruaaFS1 04-02	SH 14 @ Steele Creek	5/28/2010	View of left bank at 30m	North/Northeast
StCrBruaaFS1 04-03	SH 14 @ Steele Creek	5/28/2010	View facing downstream at 30m	East/Southeast
StCrBruaaFS1 04-04	SH 14 @ Steele Creek	5/28/2010	View of right bank at 30m	South/Southeast
StCrBruaaFS1 04-05	SH 14 @ Steele Creek	5/28/2010	View of downed tree from a beaver	South/Southeast
StCrBruaaFS1 04-06	SH 14 @ Steele Creek	5/28/2010	View of downed tree over the creek	Northeast
StCrBruaaFS1 04-07	SH 14 @ Steele Creek	5/28/2010	View facing upstream at 150m	Northwest
StCrBruaaFS1 04-08	SH 14 @ Steele Creek	5/28/2010	View of left bank at 150m	East/Northeast
StCrBruaaFS1 04-09	SH 14 @ Steele Creek	5/28/2010	View facing downstream at 150m	South/Southeast
StCrBruaaFS1 04-10	SH 14 @ Steele Creek	5/28/2010	View of right bank at 150m	West/Southwest
StCrBruaaFS1 04-11	SH 14 @ Steele Creek	5/28/2010	View of log jam from the side at 150	East
StCrBruaaFS1 04-12	SH 14 @ Steele Creek	5/28/2010	View facing upstream at 300m	Northwest
StCrBruaaFS1 04-13	SH 14 @ Steele Creek	5/28/2010	View of left bank at 300m	North/Northeast
StCrBruaaFS1 04-14	SH 14 @ Steele Creek	5/28/2010	View facing downstream at 300m	East/Southeast
StCrBruaaFS1 04-15	SH 14 @ Steele Creek	5/28/2010	View of right bank at 300m	South/Southwest
StCrBruaaFS1 04-16	SH 14 @ Steele Creek	5/28/2010	View of tributary feeding into Steele Creek at 150m on right bank	North/Northwest
StCrBruaaFS1 05-01	LCR 722 @ Steele Creek	5/28/2010	View facing upstream at wooden bridge	West/Northwest
StCrBruaaFS1 05-02	LCR 722 @ Steele Creek	5/28/2010	View of left bank at wooden bridge	North/Northeast
StCrBruaaFS1 05-03	LCR 722 @ Steele Creek	5/28/2010	View facing downstream at wooden bridge	Southeast
StCrBruaaFS1 05-04	LCR 722 @ Steele Creek	5/28/2010	View of right bank at wooden bridge	South
StCrBruaaFS1 05-05	LCR 722 @ Steele Creek	5/28/2010	View of abundant trash upstream of the wooden bridge	Southeast
StCrBruaaFS1 05-06	LCR 722 @ Steele Creek	5/28/2010	View of abundant trash downstream of the wooden bridge	South/Southeast

Photograph Number	Site Location	Date	Description	Direction Taken
StCrBruaaFS1 05-07	LCR 722 @ Steele Creek	5/28/2010	View of log jams downstream of wooden bridge	East/Southeast
StCrBruaaFS1 06-01	FM 2749 @ Steele Creek	5/28/2010	View facing upstream at 30m	West/Northwest
StCrBruaaFS1 06-02	FM 2749 @ Steele Creek	5/28/2010	View of left bank at 30m	North/Northeast
StCrBruaaFS1 06-03	FM 2749 @ Steele Creek	5/28/2010	View facing downstream at 30m	East/Southeast
StCrBruaaFS1 06-04	FM 2749 @ Steele Creek	5/28/2010	View of right bank at 30m	Southeast
StCrBruaaFS1 06-05	FM 2749 @ Steele Creek	5/28/2010	View of cement piece from possible erosion control structure	Northwest
StCrBruaaFS1 06-06	FM 2749 @ Steele Creek	5/28/2010	View of erosion control structure	South/Southwest
StCrBruaaFS1 06-07	FM 2749 @ Steele Creek	5/28/2010	View upstream at 150m	West/Southwest
StCrBruaaFS1 06-08	FM 2749 @ Steele Creek	5/28/2010	View of left bank at 150m	North/Northwest
StCrBruaaFS1 06-09	FM 2749 @ Steele Creek	5/28/2010	View downstream at 150m	East
StCrBruaaFS1 06-10	FM 2749 @ Steele Creek	5/28/2010	View of right bank at 150m	South/Southeast
StCrBruaaFS1 06-11	FM 2749 @ Steele Creek	5/28/2010	View facing upstream at 300m	North/Northwest
StCrBruaaFS1 06-12	FM 2749 @ Steele Creek	5/28/2010	View of left bank at 300m	East/Northeast
StCrBruaaFS1 06-13	FM 2749 @ Steele Creek	5/28/2010	View facing downstream at 300m	South/Southeast
StCrBruaaFS1 06-14	FM 2749 @ Steele Creek	5/28/2010	View of right bank at 300m	West/Southwest
StCrBruaaFS1 07-01	CR 477 @ Steele Creek	5/28/2010	View upstream from upstream side of bridge	West/Northwest
StCrBruaaFS1 07-02	CR 477 @ Steele Creek	5/28/2010	View of left bank from upstream side of bridge	North/Northeast
StCrBruaaFS1 07-03	CR 477 @ Steele Creek	5/28/2010	View of right bank on upstream side of bridge	West/Southwest
StCrBruaaFS1 07-04	CR 477 @ Steele Creek	5/28/2010	View downstream from downstream side of bridge	South/Southeast
StCrBruaaFS1 07-05	CR 477 @ Steele Creek	5/28/2010	View upstream from under bridge on left bank	West/Northwest
StCrBruaaFS1 07-06	CR 477 @ Steele Creek	5/28/2010	View downstream from under bridge on left bank	Southeast
StCrBruaaFS1 07-07	CR 477 @ Steele Creek	5/28/2010	View of possible tire tracks leading to water on downstream left bank	Southwest
StCrBruaaFS1 07-08	CR 477 @ Steele Creek	5/28/2010	View of tire tracks on downstream, left bank facing away from water	Southwest
StCrBrauuFS1 08-01	SH 7 @ Steel Creek	5/28/2010	View of beer can	
StCrBrauuFS1 08-02	SH 7 @ Steel Creek	5/28/2010	View upstream at 30m	West
StCrBrauuFS1 08-03	SH 7 @ Steel Creek	5/28/2010	View of left bank at 30m	North
StCrBrauuFS1 08-04	SH 7 @ Steel Creek	5/28/2010	View downstream at 30m	East
StCrBrauuFS1 08-05	SH 7 @ Steel Creek	5/28/2010	View of right bank at 30m	South
StCrBrauuFS1 08-06	SH 7 @ Steel Creek	5/28/2010	View upstream at 150m	West/Northwest
StCrBrauuFS1 08-07	SH 7 @ Steel Creek	5/28/2010	View of left bank at 150m	North/Northeast
StCrBrauuFS1 08-08	SH 7 @ Steel Creek	5/28/2010	View downstream at 150m	East/Southeast
StCrBrauuFS1 08-09	SH 7 @ Steel Creek	5/28/2010	View of right bank at 150m	South/Southwest
StCrBrauuFS1 08-10	SH 7 @ Steel Creek	5/28/2010	View upstream at 300m	North
StCrBrauuFS1 08-11	SH 7 @ Steel Creek	5/28/2010	View of left bank at 300m	East
StCrBrauuFS1 08-12	SH 7 @ Steel Creek	5/28/2010	View downstream at 300m	South
StCrBrauuFS1 08-13	SH 7 @ Steel Creek	5/28/2010	View of right bank at 300m	West
StCrBruaaFS1 09-01	CR 472 @ Steel Creek	5/28/2010	View upstream from bridge	Northwest
StCrBruaaFS1 09-02	CR 472 @ Steel Cree	5/28/2010	View of left bank of bridge	Northeast
StCrBruaaFS1 09-03	CR 472 @ Steel Cree	5/28/2010	View downstream from bridge	Southeast

Photograph Number	Site Location	Date	Description	Direction Taken
StCrBruaaFS1 09-04	CR 472 @ Steel Cree	5/28/2010	View of right bank of bridge	Southwest
StCrBruaaFS1 09-05	CR 472 @ Steel Cree	5/28/2010	View of fence hendering creek access	Northeast
StCrBruaaRecon01-01	Recon Site #1 - FM147	1/12/2010	Upstream from bridge crossing	North
StCrBruaaRecon01-02	Recon Site #1 - FM147	1/12/2010	Right bank from bridge crossing from upstream side of bridge	East
StCrBruaaRecon01-03	Recon Site #1 - FM147	1/12/2010	Downstream from bridge crossing	South
StCrBruaaRecon01-04	Recon Site #1 - FM147	1/12/2010	Left bank from bridge crossing from upstream side of bridge	West
StCrBruaaRecon01-05	Recon Site #1 - FM147	1/12/2010	Tire tracks across the stream on the downstream side of bridge crossing	West
StCrBruaaRecon01-06	Recon Site #1 - FM147	1/12/2010	View of under bridge from the downstream side facing upstream	North
StCrBruaaRecon02-01	Recon Site #2 - LCR648	1/12/2010	View upstream from bridge	Northwest
StCrBruaaRecon02-02	Recon Site #2 - LCR648	1/12/2010	View of right bank from downstream side of bridge	Northeast
StCrBruaaRecon02-03	Recon Site #2 - LCR648	1/12/2010	View downstream from bridge	Northeast
StCrBruaaRecon02-04	Recon Site #2 - LCR648	1/12/2010	View of left bank from downstream side of bridge	South
StCrBruaaRecon03-01	Recon Site #3 - LCR656	1/12/2010	View upstream from bridge	West
StCrBruaaRecon03-02	Recon Site #3 - LCR656	1/12/2010	View of right bank from upstream side of bridge	North/Northeast
StCrBruaaRecon03-03	Recon Site #3 - LCR656	1/12/2010	View downstream from bridge	Southeast
StCrBruaaRecon03-04	Recon Site #3 - LCR656	1/12/2010	View of left bank from upstream side of bridge	West/Northwest
StCrBruaaRecon03-05	Recon Site #3 - LCR656	1/12/2010	View of left bank from downstream side of bridge with barbed wire fence to	East/Northeast
StCrBruaaRecon04-01	Recon Site #4 - SH14	1/12/2010	View upstream from bridge	Southwest
StCrBruaaRecon04-02	Recon Site #4 - SH14	1/12/2010	View of right bank from upstream side of bridge	North
StCrBruaaRecon04-03	Recon Site #4 - SH14	1/12/2010	View of left bank from upstream side of bridge	Southeast
StCrBruaaRecon04-04	Recon Site #4 - SH14	1/12/2010	View of downstream from bridge	Southwest
StCrBruaaRecon04-05	Recon Site #4 - SH14	1/12/2010	View under bridge from upstream side left bank	East/Southeast
StCrBruaaRecon05-01	Recon Site #5 - LCR722	1/12/2010	View of "Weight Limit" sign shot with a shotgun	West
StCrBruaaRecon05-02	Recon Site #5 - LCR722	1/12/2010	View upstream from bridge	West/Northwest
StCrBruaaRecon05-03	Recon Site #5 - LCR722	1/12/2010	View of right bank from downstream side of bridge	East/Northeast
StCrBruaaRecon05-04	Recon Site #5 - LCR722	1/12/2010	View of left bank from downstream side of bridge	East/Southeast
StCrBruaaRecon05-05	Recon Site #5 - LCR722	1/12/2010	View downstream from bridge	East/Southeast
StCrBruaaRecon05-06	Recon Site #5 - LCR722	1/12/2010	Vertical view of debris and trash on downstream side of bridge	East/Southeast
StCrBruaaRecon05-07	Recon Site #5 - LCR722	1/12/2010	Vertical view of debris/trees damming water on upstream side of bridge	North/Northwest
StCrBruaaRecon06-01	Recon Site #6 - Moss Springs Rd	1/12/2010	View of locked gate and "No Trespassing" sign, cattle behind	East/Northeast
StCrBruaaRecon07-01	Recon Site #7 - FM2749	1/12/2010	View upstream from bridge	West

Photograph Number	Site Location	Date	Description	Direction Taken
StCrBruaaRecon07-02	Recon Site #7 - FM2749	1/12/2010	View of right bank from downstream side of bridge	Northeast
StCrBruaaRecon07-03	Recon Site #7 - FM2749	1/12/2010	View downstream from bridge	East/Northeast
StCrBruaaRecon07-04	Recon Site #7 - FM2749	1/12/2010	View of left bank from downstream side of bridge	Southeast
StCrBruaaRecon07-05	Recon Site #7 - FM2749	1/12/2010	View of right bank under bridge from right bank at water	North/Northwest
StCrBruaaRecon08-01	Recon Site #8 - LCR730	1/12/2010	View of locked gate and "Kosse Mine - No Trespassing" sign	East/Southeast
StCrBruaaRecon09-01	Recon Site #9 - TCEQ Sta 16384 - CR477	1/12/2010	View upstream from bridge	Northwest
StCrBruaaRecon09-02	Recon Site #9 - TCEQ Sta 16384 - CR477	1/12/2010	View of right bank from downstream side of bridge	Southeast
StCrBruaaRecon09-03	Recon Site #9 - TCEQ Sta 16384 - CR477	1/12/2010	View downstream from bridge	East/Northeast
StCrBruaaRecon09-04	Recon Site #9 - TCEQ Sta 16384 - CR477	1/12/2010	View of left bank from downstream side of bridge	North/Northeast
StCrBruaaRecon10-01	Recon Site #10 - SH7	1/12/2010	View upstream from left bank under bridge	North/Northeast
StCrBruaaRecon10-02	Recon Site #10 - SH7	1/12/2010	View of right bank from left bank under bridge	North/Northeast
StCrBruaaRecon10-03	Recon Site #10 - SH7	1/12/2010	View downstream from left bank under bridge	South/Southeast
StCrBruaaRecon10-04	Recon Site #10 - SH7	1/12/2010	View of left bank from left bank under bridge	South/Southwest
StCrBruaaRecon10-05	Recon Site #10 - SH7	1/12/2010	View downstream of the bridge and tire tracks from upstream left bank	South
StCrBruaaRecon11-01	Recon Site #11 - CR472	1/12/2010	View upstream from bridge	Northwest
StCrBruaaRecon11-02	Recon Site #11 - CR472	1/12/2010	View of right bank from downstream side of bridge	Southeast
StCrBruaaRecon11-03	Recon Site #11 - CR472	1/12/2010	View downstream from bridge	South/Southwest
StCrBruaaRecon11-04	Recon Site #11 - CR472	1/12/2010	View of left bank from downstream side of bridge	West/Southwest
StCrBruaaRecon11-05	Recon Site #11 - CR472	1/12/2010	View of EIH truck parked on left bank upstream from middle of bridge	West/Southwest
StCrBruaaRecon11-06	Recon Site #11 - CR472	1/12/2010	View of fence crossing water on upstream side of bridge	Northwest
StCrBruaaRecon12-01	Recon Site #12 - Camp Cooley	1/13/2010	View of "Private Road - Camp Cooley Ranch" sign	South/Southeast



StCrBruaaFS1 01-01



StCrBruaaFS1 01-02



StCrBruaaFS1 01-03



StCrBruaaFS1 01-04



StCrBruaaFS1 02-01



StCrBruaaFS1 02-02



StCrBruaaFS1 02-03



StCrBruaaFS1 02-04



StCrBruaaFS1 02-05



StCrBruaaFS1 02-06



StCrBruaaFS1 02-07



StCrBruaaFS1 02-08



StCrBruaaFS1 02-09



StCrBruaaFS1 02-10



StCrBruaaFS1 02-11



StCrBruaaFS1 03-01



StCrBruaaFS1 03-02



StCrBruaaFS1 03-03



StCrBruaaFS1 03-04



StCrBruaaFS1 04-01



StCrBruaaFS1 04-02



StCrBruaaFS1 04-03



StCrBruaaFS1 04-04



StCrBruaaFS1 04-05



StCrBruaaFS1 04-06



StCrBruaaFS1 04-07



StCrBruaaFS1 04-08



StCrBruaaFS1 04-09



StCrBruaaFS1 04-10



StCrBruaaFS1 04-11



StCrBruaaFS1 04-12



StCrBruaaFS1 04-13



StCrBruaaFS1 04-14



StCrBruaaFS1 04-15



StCrBruaaFS1 04-16



StCrBruaaFS1 05-01



StCrBruaaFS1 05-02



StCrBruaaFS1 05-03



StCrBruaaFS1 05-04



StCrBruaaFS1 05-05



StCrBruaaFS1 05-06



StCrBruaaFS1 05-07



StCrBruaaFS1 06-01



StCrBruaaFS1 06-02



StCrBruaaFS1 06-03



StCrBruaaFS1 06-04



StCrBruaaFS1 06-05



StCrBruaaFS1 06-06



StCrBruaaFS1 06-07



StCrBruaaFS1 06-08



StCrBruaaFS1 06-09



StCrBruaaFS1 06-10



StCrBruaaFS1 06-11



StCrBruaaFS1 06-12



StCrBruaaFS1 06-13



StCrBruaaFS1 06-14



StCrBruaaFS1 07-01



StCrBruaaFS1 07-02



StCrBruaaFS1 07-03



StCrBruaaFS1 07-04



StCrBruaaFS1 07-05



StCrBruaaFS1 07-06



StCrBruaaFS1 07-07



StCrBruaaFS1 07-08



StCrBruaaFS1 08-01



StCrBruaaFS1 08-02



StCrBruaaFS1 08-03



StCrBruaaFS1 08-04



StCrBruaaFS1 08-05



StCrBruaaFS1 08-06



StCrbruaaFS1 08-07



StCrbruaaFS1 08-08



StCrbruaaFS1 08-09



StCrbruaaFS1 08-10



StCrbruaaFS1 08-11



StCrbruaaFS1 08-12



StCrbruaaFS1 08-13



StCrBruaaFS1 09-01



StCrBruaaFS1 09-02



StCrbruaaFS1 09-03



StCrbruaaFS1 09-04



StCrbruaaFS1 09-05



StCrBruaaRecon01-01



StCrBruaaRecon01-02



StCrBruaaRecon01-03



StCrBruaaRecon01-04



StCrBruaaRecon01-05



StCrBruaaRecon01-06



StCrBruaaRecon02-01



StCrBruaaRecon02-02



StCrBruaaRecon02-03



StCrBruaaRecon02-04



StCrBruaaRecon03-01



StCrBruaaRecon03-02



StCrBruaaRecon03-03



StCrBruaaRecon03-04



StCrBruaaRecon03-05



StCrBruaaRecon04-01



StCrBruaaRecon04-02



StCrBruaaRecon04-03



StCrBruaaRecon04-04



StCrBruaaRecon04-05



StCrBruaaRecon05-01



StCrBruaaRecon05-02



StCrBruaaRecon05-03



StCrBruaaRecon05-04



StCrBruaaRecon05-05



StCrBruaaRecon05-06



StCrBruaaRecon05-07



StCrBruaaRecon06-01



StCrBruaaRecon07-01



StCrBruaaRecon07-02



StCrBruaaRecon07-03



StCrBruaaRecon07-04



StCrBruaaRecon07-05



StCrBruaaRecon08-01



StCrBruaaRecon09-01



StCrBruaaRecon09-02



StCrBruaaRecon09-03



StCrBruaaRecon09-04



StCrBruaaRecon10-01



StCrBruaaRecon10-02



StCrBruaaRecon10-03



StCrBruaaRecon10-04




StCrBruaaRecon10-05



StCrBruaaRecon11-01



StCrBruaaRecon11-02



StCrBruaaRecon11-03



StCrBruaaRecon11-04



StCrBruaaRecon11-05



StCrBruaaRecon11-06



StCrBruaaRecon12-01