

Recreational Use Attainability Analysis of Wickson Creek (Segment 1209E)

Appendix 3

Photographic Record

*** Photos in JPEG format are available as an electronic supplement on the CD insert found in Appendix 5**

Photograph Number	Site Location	Date	Description	Direction Photo Taken
WCrBruaaFS1 01-01	Field Survey Site #1 - Bickham Cemetery Rd	5/29/2010	View facing upstream at the beginning of the creek	Northwest
WCrBruaaFS1 01-02	Field Survey Site #1 - Bickham Cemetery Rd	5/29/2010	View of left bank facing downstream of the culvert	Northeast
WCrBruaaFS1 01-03	Field Survey Site #1 - Bickham Cemetery Rd	5/29/2010	View facing downstream of the culvert	Southeast
WCrBruaaFS1 01-04	Field Survey Site #1 - Bickham Cemetery Rd	5/29/2010	View of right bank facing downstream of the culvert	Southwest
WCrBruaaFS1 02-01	Field Survey Site #2 - Francis Rd	5/29/2010	View facing upstream of the culvert	Northwest
WCrBruaaFS1 02-02	Field Survey Site #2 - Francis Rd	5/29/2010	View of left bank facing downstream of the culvert	Northeast
WCrBruaaFS1 02-03	Field Survey Site #2 - Francis Rd	5/29/2010	View facing downstream of the culvert	Southeast
WCrBruaaFS1 02-04	Field Survey Site #2 - Francis Rd	5/29/2010	View of right bank facing downstream of the culvert	Southwest
WCrBruaaFS1 02-05	Field Survey Site #2 - Francis Rd	5/29/2010	View of a snake in the water	Southeast
WCrBruaaFS1 03-01	Field Survey Site #3 - Dick Elliot Rd	5/29/2010	View facing upstream of the culvert	Northeast
WCrBruaaFS1 03-02	Field Survey Site #3 - Dick Elliot Rd	5/29/2010	View of left bank facing upstream of the culvert	East/Southeast
WCrBruaaFS1 03-03	Field Survey Site #3 - Dick Elliot Rd	5/29/2010	View facing downstream of the culvert	Southwest
WCrBruaaFS1 03-04	Field Survey Site #3 - Dick Elliot Rd	5/29/2010	View of right bank facing upstream of the culvert	North/Northwest
WCrBruaaFS1 04-01	Field Survey Site #4 - FM 974/Tabor Ln	5/29/2010	View facing upstream of the cement culvert	West/Northwest
WCrBruaaFS1 04-02	Field Survey Site #4 - FM 974/Tabor Ln	5/29/2010	View of left bank facing upstream of the cement culvert	Northeast
WCrBruaaFS1 04-03	Field Survey Site #4 - FM 974/Tabor Ln	5/29/2010	View facing downstream of the cement culvert	East/Southeast
WCrBruaaFS1 04-04	Field Survey Site #4 - FM 974/Tabor Ln	5/29/2010	View of right bank facing upstream of the cement culvert	Southwest
WCrBruaaFS1 05-01	Field Survey Site #5 - Wilcox Ln.	5/29/2010	View facing upstream at 150m	West/Southwest
WCrBruaaFS1 05-02	Field Survey Site #5 - Wilcox Ln.	5/29/2010	View of left bank at 150m	North
WCrBruaaFS1 05-03	Field Survey Site #5 - Wilcox Ln.	5/29/2010	View facing downstream at 150m	East
WCrBruaaFS1 05-04	Field Survey Site #5 - Wilcox Ln.	5/29/2010	View of right bank at 150m	South
WCrBruaaFS1 05-05	Field Survey Site #5 - Wilcox Ln.	5/29/2010	View of Clint attempting to walk upstream but too deep	West/Southwest
WCrBruaaFS1 06-01	Field Survey Site #6 - Dilly Shaw Tap Rd	5/29/2010	View facing upstream of cement control structure at 150m	West
WCrBruaaFS1 06-02	Field Survey Site #6 - Dilly Shaw Tap Rd	5/29/2010	View of left bank upstream of cement control structure	North
WCrBruaaFS1 06-03	Field Survey Site #6 - Dilly Shaw Tap Rd	5/29/2010	View of downstream at 150m	East
WCrBruaaFS1 06-04	Field Survey Site #6 - Dilly Shaw Tap Rd	5/29/2010	View of right bank at 150m	South

Photograph Number	Site Location	Date	Description	Direction Photo Taken
WCrBruaaFS1 06-05	Field Survey Site #6 - Dilly Shaw Tap Rd	5/29/2010	View of downstream fence across the water	East
WCrBruaaFS1 06-06	Field Survey Site #6 - Dilly Shaw Tap Rd	5/29/2010	View of cement control structure facing upstream at 150m	West
WCrBruaaFS1 07-01	Field Survey Site #7 - SH21/US190	5/29/2010	View of red color in water on right bank under bridge	Southwest
WCrBruaaFS1 07-02	Field Survey Site #7 - SH21/US190	5/29/2010	View of red color in water on right bank under bridge	Southwest
WCrBruaaFS1 07-03	Field Survey Site #7 - SH21/US190	5/29/2010	View facing upstream at 30m	Northwest
WCrBruaaFS1 07-04	Field Survey Site #7 - SH21/US190	5/29/2010	View of left bank at 30m	Northeast
WCrBruaaFS1 07-05	Field Survey Site #7 - SH21/US190	5/29/2010	View facing downstream at 30m	Southeast
WCrBruaaFS1 07-06	Field Survey Site #7 - SH21/US190	5/29/2010	View of right bank at 30m	Southwest
WCrBruaaFS1 07-07	Field Survey Site #7 - SH21/US190	5/29/2010	View facing upstream at 150m	Northwest
WCrBruaaFS1 07-08	Field Survey Site #7 - SH21/US190	5/29/2010	View of left bank at 150m	Northeast
WCrBruaaFS1 07-09	Field Survey Site #7 - SH21/US190	5/29/2010	View facing downstream at 150m	Southeast
WCrBruaaFS1 07-10	Field Survey Site #7 - SH21/US190	5/29/2010	View of right bank at 150m	Southwest
WCrBruaaFS1 07-11	Field Survey Site #7 - SH21/US190	5/29/2010	View facing upstream at 300m	West
WCrBruaaFS1 07-12	Field Survey Site #7 - SH21/US190	5/29/2010	View of left bank at 300m	North
WCrBruaaFS1 07-13	Field Survey Site #7 - SH21/US190	5/29/2010	View facing downstream at 300m	East/Southeast
WCrBruaaFS1 07-14	Field Survey Site #7 - SH21/US190	5/29/2010	View of right bank at 300m	South/Southeast
WCrBruaaFS1 08-01	Field Survey Site #8 - Old Reliance Rd	5/30/2010	View of Construction Zone and Road Closed sign	Northeast
WCrBruaaFS1 08-02	Field Survey Site #8 - Old Reliance Rd	5/30/2010	View of Road Closed sign and bridge under construction in distance	Northeast
WCrBruaaFS1 09-01	Field Survey Site #9 - Grassbur Rd	5/30/2010	View facing upstream at 150m	Northeast
WCrBruaaFS1 09-02	Field Survey Site #9 - Grassbur Rd	5/30/2010	View of left bank at 150m	East
WCrBruaaFS1 09-03	Field Survey Site #9 - Grassbur Rd	5/30/2010	View facing downstream at 150m	Southeast
WCrBruaaFS1 09-04	Field Survey Site #9 - Grassbur Rd	5/30/2010	View of right bank at 150m	Southwest
WCrBruaaFS1 09-05	Field Survey Site #9 - Grassbur Rd	5/30/2010	View of person's footprints in the mud on right bank	West
WCrBruaaFS1 10-01	Field Survey Site #10 - Elmo Weeden Rd	5/30/2010	View facing upstream at 30m looking fence across water	North
WCrBruaaFS1 10-02	Field Survey Site #10 - Elmo Weeden Rd	5/30/2010	View of left bank at 30m	East
WCrBruaaFS1 10-03	Field Survey Site #10 - Elmo Weeden Rd	5/30/2010	View facing downstream at 30m	South

Photograph Number	Site Location	Date	Description	Direction Photo Taken
WCrBruaaFS1 10-04	Field Survey Site #10 - Elmo Weeden Rd	5/30/2010	View of right bank at 30m	West
WCrBruaaFS1 10-05	Field Survey Site #10 - Elmo Weeden Rd	5/30/2010	View facing upstream at 130m	Northwest
WCrBruaaFS1 10-06	Field Survey Site #10 - Elmo Weeden Rd	5/30/2010	View of left bank at 130m	Northeast
WCrBruaaFS1 10-07	Field Survey Site #10 - Elmo Weeden Rd	5/30/2010	View facing downstream at 130m	Southeast
WCrBruaaFS1 10-08	Field Survey Site #10 - Elmo Weeden Rd	5/30/2010	View of left bank at 130m	Southwest
WCrBruaaFS1 11-01	Field Survey Site #11 - Weeden Loop	5/29/2010	View facing upstream at 300m	North/Northeast
WCrBruaaFS1 11-02	Field Survey Site #11 - Weeden Loop	5/29/2010	View of left bank at 300m	East/Southeast
WCrBruaaFS1 11-03	Field Survey Site #11 - Weeden Loop	5/29/2010	View facing downstream at 300m	Southwest
WCrBruaaFS1 11-04	Field Survey Site #11 - Weeden Loop	5/29/2010	View of right bank at 300m	Northwest
WCrBruaaFS1 11-05	Field Survey Site #11 - Weeden Loop	5/29/2010	View facing upstream at 150m	Northeast
WCrBruaaFS1 11-06	Field Survey Site #11 - Weeden Loop	5/29/2010	View of left bank at 150m	Southeast
WCrBruaaFS1 11-07	Field Survey Site #11 - Weeden Loop	5/29/2010	View facing downstream at 150m	West/Southwest
WCrBruaaFS1 11-08	Field Survey Site #11 - Weeden Loop	5/29/2010	View of right bank at 150m	North/Northwest
WCrBruaaRecon01-01	Recon Site #1 - Bickham Cemetery Rd	1/14/2010	View of locked gate at power lines	South
WCrBruaaRecon01-02	Recon Site #1 - Bickham Cemetery Rd	1/14/2010	View upstream from middle of road	Northwest
WCrBruaaRecon01-03	Recon Site #1 - Bickham Cemetery Rd	1/14/2010	View of right bank on downstream side of road	Northeast
WCrBruaaRecon01-04	Recon Site #1 - Bickham Cemetery Rd	1/14/2010	View downstream from middle of road	Southeast
WCrBruaaRecon01-05	Recon Site #1 - Bickham Cemetery Rd	1/14/2010	View of left bank from downstream side of road, ATV tracks across water visible	South/Southwest
WCrBruaaRecon02-01	Recon Site #2 - Francis Rd	1/14/2010	View upstream from middle of road	Northwest
WCrBruaaRecon02-02	Recon Site #2 - Francis Rd	1/14/2010	View of right bank on downstream side of road	Northeast
WCrBruaaRecon02-03	Recon Site #2 - Francis Rd	1/14/2010	View downstream from middle of road	East/Southeast
WCrBruaaRecon02-04	Recon Site #2 - Francis Rd	1/14/2010	View of left bank from downstream side of road	South/Southwest
WCrBruaaRecon03-01	Recon Site #3 - Dick Elliot Rd	1/14/2010	View upstream from middle of road	Northeast
WCrBruaaRecon03-02	Recon Site #3 - Dick Elliot Rd	1/14/2010	View of right bank from upstream side of road	East/Southeast
WCrBruaaRecon03-03	Recon Site #3 - Dick Elliot Rd	1/14/2010	View downstream from middle of road	South/Southwest
WCrBruaaRecon03-04	Recon Site #3 - Dick Elliot Rd	1/14/2010	View of left bank from upstream side of road	North/Northeast

Photograph Number	Site Location	Date	Description	Direction Photo Taken
WCrBruaaRecon04-01	Recon Site #4 - FM974	1/14/2010	View upstream from middle of road	Northwest
WCrBruaaRecon04-02	Recon Site #4 - FM974	1/14/2010	View of right bank from upstream side of road	West/Northwest
WCrBruaaRecon04-03	Recon Site #4 - FM974	1/14/2010	View downstream from middle of road	South/Southeast
WCrBruaaRecon04-04	Recon Site #4 - FM974	1/14/2010	View of left bank from upstream side of road	Southwest
WCrBruaaRecon05-01	Recon Site #5 - Wilcox Ln	1/14/2010	View upstream from middle of bridge	West/Southwest
WCrBruaaRecon05-02	Recon Site #5 - Wilcox Ln	1/14/2010	View of right bank from upstream side of bridge	South
WCrBruaaRecon05-03	Recon Site #5 - Wilcox Ln	1/14/2010	View downstream form middle of bridge	East
WCrBruaaRecon05-04	Recon Site #5 - Wilcox Ln	1/14/2010	View of left bank from upstream side of bridge	Northeast
WCrBruaaRecon05-05	Recon Site #5 - Wilcox Ln	1/14/2010	View under bridge from downstream left bank	West/Northwest
WCrBruaaRecon06-01	Recon Site #6 - Dilly Shaw Tap Rd	1/14/2010	View upstream from middle of bridge	West
WCrBruaaRecon06-02	Recon Site #6 - Dilly Shaw Tap Rd	1/14/2010	View of right bank from downstream side of bridge	East/Southeast
WCrBruaaRecon06-03	Recon Site #6 - Dilly Shaw Tap Rd	1/14/2010	View downstream from middle of bridge	Southeast
WCrBruaaRecon06-04	Recon Site #6 - Dilly Shaw Tap Rd	1/14/2010	View of left bank from downstream side of bridge	South/Southeast
WCrBruaaRecon06-05	Recon Site #6 - Dilly Shaw Tap Rd	1/14/2010	View under bridge from downstream right bank	Southwest
WCrBruaaRecon07-01	Recon Site #7 - TCEQ Sta 20386 - SH21	1/14/2010	View upstream from left bank under bridge	Northwest
WCrBruaaRecon07-02	Recon Site #7 - TCEQ Sta 20386 - SH21	1/14/2010	View of right bank from left bank under bridge	Northeast
WCrBruaaRecon07-03	Recon Site #7 - TCEQ Sta 20386 - SH21	1/14/2010	View downstream from left bank under bridge	Southeast
WCrBruaaRecon07-04	Recon Site #7 - TCEQ Sta 20386 - SH21	1/14/2010	View of left bank from left bank under bridge	Northeast
WCrBruaaRecon07-05	Recon Site #7 - TCEQ Sta 20386 - SH21	1/14/2010	View of animal print under bridge on left bank	North/Northwest
WCrBruaaRecon08-01	Recon Site #8 - Old Reliance Rd	1/14/2010	View upstream from middle of bridge	West/Northwest
WCrBruaaRecon08-02	Recon Site #8 - Old Reliance Rd	1/14/2010	View of right bank from downstream side of bridge	East/Northeast
WCrBruaaRecon08-03	Recon Site #8 - Old Reliance Rd	1/14/2010	View downstream from middle of bridge	Northeast
WCrBruaaRecon08-04	Recon Site #8 - Old Reliance Rd	1/14/2010	View of left bank from downstream side of bridge	East
WCrBruaaRecon09-01	Recon Site #9 - TCEQ Sta 15033 - FM1179	1/14/2010	View upstream from middle of bridge	West/Southwest
WCrBruaaRecon09-02	Recon Site #9 - TCEQ Sta 15033 - FM1179	1/14/2010	View of right bank from downstream side of bridge	Northwest
WCrBruaaRecon09-03	Recon Site #9 - TCEQ Sta 15033 - FM1179	1/14/2010	View downstream from middle of bridge	Southeast
WCrBruaaRecon09-04	Recon Site #9 - TCEQ Sta 15033 - FM1179	1/14/2010	View of left bank from downstream side of bridge	West/Northwest

Photograph Number	Site Location	Date	Description	Direction Photo Taken
WCrBruaaRecon09-05	Recon Site #9 - TCEQ Sta 15033 - FM1179	1/14/2010	Vertical view of worn path to water on right bank downstream	N/A
WCrBruaaRecon10-01	Recon Site #10 - Grassbur Rd	1/14/2010	View upstream from middle of bridge	West/Northwest
WCrBruaaRecon10-02	Recon Site #10 - Grassbur Rd	1/14/2010	View of right bank from downstream side of bridge	South/Southeast
WCrBruaaRecon10-03	Recon Site #10 - Grassbur Rd	1/14/2010	View downstream from middle of bridge	Southeast
WCrBruaaRecon10-04	Recon Site #10 - Grassbur Rd	1/14/2010	View of left bank from downstream side of bridge	West/Southwest
WCrBruaaRecon11-01	Recon Site #11 - C-6 Ranch Rd	1/14/2010	View of closed/locked gate with "No Trespassing" sign at Cargill Ranch	East/Northeast
WCrBruaaRecon12-01	Recon Site #12 - Elmo Weeden Rd	1/14/2010	View upstream from middle of bridge	North/Northwest
WCrBruaaRecon12-02	Recon Site #12 - Elmo Weeden Rd	1/14/2010	View of right bank from downstream side of bridge	Southwest
WCrBruaaRecon12-03	Recon Site #12 - Elmo Weeden Rd	1/14/2010	View down stream from middle of bridge	North
WCrBruaaRecon12-04	Recon Site #12 - Elmo Weeden Rd	1/14/2010	View of left bank from downstream side of bridge	South/Southwest
WCrBruaaRecon12-05	Recon Site #12 - Elmo Weeden Rd	1/14/2010	View of small cleared area along water on right bank downstream	Southeast
WCrBruaaRecon12-06	Recon Site #12 - Elmo Weeden Rd	1/14/2010	Vertical view of two boot prints on right bank downstream	N/A
WCrBruaaRecon13-01	Recon Site #13 - TCEQ Sta 11789 - Weeden Loop	1/14/2010	View upstream from middle of bridge	Northeast
WCrBruaaRecon13-02	Recon Site #13 - TCEQ Sta 11789 - Weeden Loop	1/14/2010	View of right bank from upstream side of bridge	Southeast
WCrBruaaRecon13-03	Recon Site #13 - TCEQ Sta 11789 - Weeden Loop	1/14/2010	View downstream from middle of bridge	South/Southwest
WCrBruaaRecon13-04	Recon Site #13 - TCEQ Sta 11789 - Weeden Loop	1/14/2010	View of left bank from upstream side of bridge	Northwest
WCrBruaaRecon14-01	Recon Site #14 - Unnamed Rd off Weeden Loop	1/14/2010	View of closed gate	Southwest



WCrBruaaFS1 01-01



WCrBruaaFS1 01-02



WCrBruaaFS1 01-03



WCrBruaaFS1 01-04



WCrBruaaFS1 02-01



WCrBruaaFS1 02-02



WCrBruaaFS1 02-03



WCrBruaaFS1 02-04



WCrBruaaFS1 02-05



WCrBruaaFS1 03-01



WCrBruaaFS1 03-02



WCrBruaaFS1 03-03



WCrBruaaFS1 03-04



WCrBruaaFS1 04-01



WCrBruaaFS1 04-02



WCrBruaaFS1 04-03



WCrBruaaFS1 04-04



WCrBruaaFS1 05-01



WCrBruaaFS1 05-02



WCrBruaaFS1 05-03



WCrBruaaFS1 05-04



WCrBruaaFS1 05-05



WCrBruaaFS1 06-01



WCrBruaaFS1 06-02



WCrBruaaFS1 06-03



WCrBruaaFS1 06-04



WCrBruaaFS1 06-05



WCrBruaaFS1 06-06



WCrBruaaFS1 07-01



WCrBruaaFS1 07-02



WCrBruaaFS1 07-03



WCrBruaaFS1 07-04



WCrBruaaFS1 07-05



WCrBruaaFS1 07-06



WCrBruaaFS1 07-07



WCrBruaaFS1 07-08



WCrBruaaFS1 07-09



WCrBruaaFS1 07-10



WCrBruaaFS1 07-11



WCrBruaaFS1 07-12



WCrBruaaFS1 07-13



WCrBruaaFS1 07-14



WCrBruaaFS1 08-01



WCrBruaaFS1 08-02



WCrBruaaFS1 09-01



WCrBruaaFS1 09-02



WCrBruaaFS1 09-03



WCrBruaaFS1 09-04



WCrBruaaFS1 09-05



WCrBruaaFS1 10-01



WCrBruaaFS1 10-02



WCrBruaaFS1 10-03



WCrBruaaFS1 10-04



WCrBruaaFS1 10-05



WCrBruaaFS1 10-06



WCrBruaaFS1 10-07



WCrBruaaFS1 10-08



WCrBruaaFS1 11-01



WCrBruaaFS1 11-02



WCrBruaaFS1 11-03



WCrBruaaFS1 11-04



WCrBruaaFS1 11-05



WCrBruaaFS1 11-06



WCrBruaaFS1 11-07



WCrBruaaFS1 11-08



WCrBruaaRecon01-01



WCrBruaaRecon01-02



WCrBruaaRecon01-03



WCrBruaaRecon01-04



WCrBruaaRecon01-05



WCrBruaaRecon02-01




WCrBruaaRecon02-02



WCrBruaaRecon02-03



WCrBruaaRecon02-04



WCrBruaaRecon03-01



WCrBruaaRecon03-02



WCrBruaaRecon03-03



WCrBruaaRecon03-04



WCrBruaaRecon04-01



WCrBruaaRecon04-02



WCrBruaaRecon04-03



WCrBruaaRecon04-04



WCrBruaaRecon05-01



WCrBruaaRecon05-02



WCrBruaaRecon05-03



WCrBruaaRecon05-04



WCrBruaaRecon05-05



WCrBruaaRecon06-01



WCrBruaaRecon06-02



WCrBruaaRecon06-03



WCrBruaaRecon06-04



WCrBruaaRecon06-05



WCrBruaaRecon07-01



WCrBruaaRecon07-02



WCrBruaaRecon07-03



WCrBruaaRecon07-04



WCrBruaaRecon07-05



WCrBruaaRecon08-01



WCrBruaaRecon08-02



WCrBruaaRecon08-03



WCrBruaaRecon08-04



WCrBruaaRecon09-01



WCrBruaaRecon09-02



WCrBruaaRecon09-03



WCrBruaaRecon09-04



WCrBruaaRecon09-05



WCrBruaaRecon10-01



WCrBruaaRecon10-02



WCrBruaaRecon10-03



WCrBruaaRecon10-04



WCrBruaaRecon11-01



WCrBruaaRecon12-01



WCrBruaaRecon12-02



WCrBruaaRecon12-03




WCrBruaaRecon12-04



WCrBruaaRecon12-05




WCrBruaaRecon12-06



WCrBruaaRecon13-01




WCrBruaaRecon13-02



WCrBruaaRecon13-03



WCrBruaaRecon13-04



WCrBruaaRecon14-01