					Brazos		Authorit Vater Co	-		ation							
TX#	Da	n Name Latitude Longitude			Operat	or	Operation & Maintenance/Rehab Schedule							4 O&M ost	Method	d of Financ	e Note
TX03956	DE CORDOVA	BEND DAM	32.373464	-97.687911	Brazos River Aut	hority L	ow Flow Fac	ilities						1,000,000	Res	erves/Debt	
							Electric Vulnerability Assessment							250,000			
							Buttress 1 and 44 Repairs Hearth Stability Analysis						\$	302,000 225,000			
					Tainter Gate Evaluation						\$	250,000					
					Stoplog Replacement System Dam Operations (includes dam operations, maintenance and inspections.)						\$	450,000	Reserves/Debt				
							am Operatio			ations, main	tenance and	inspection		2,222,353	Curre	nt Revenues	
											\$	8,202,000 650,000		erves/Debt erves/Debt			
Hydrostatic Relief System Assessment & Replacement Low Flow Facility Modifications & Improvements											\$	513,000		erves/Debt			
						D	am Operatio	ons (include	s dam opera		tenance and	inspection:		1,897,823	Curre	nt Revenues	
TX03849	MORRIS SHEE	PPARD DAM	32.871177	-98.426833	Brazos River Aut		ay 9 Transiti		eak Remedi	ation			\$	294,000		nt Revenues	
						Bay 9 Weir Box Operating Pier Trash Rack Replacement						\$	200,000 189,000	Res Curre			
						F	Flow Control Gate Replacement							1,528,000	Res	erves/Debt	
							COC Recoating & Repairs							491,000		nt Revenues erves/Debt	
				Spillway Pump & Piping Dam Operations (includes dam operations, maintenance and inspections.								3,071,000	Res				
							oesn't includ			audio, ilidili	onunct all	opecuon		5,243,588	Curre	nt Revenues	
						-	Ti		_								
						-	roject Ti	-		_D		<u> </u>	<u>.</u>	A /	<u> </u>	<u> </u>	/ 3
Basin	Location		Project		CIP/OP	4	(B) 44	4	12 Fr	(P) E	2ª En	4	Cop Con	4	ريم الم	(P) 4-(S)	E CON
LB	LL	Tainter Gate Replace	cement & Improv	vements	CIP												
UB	PK	CAASLE			OP					1							
UB	PK	Operating Pier Tras		ement	OP												
UB	LG	Low Flow Facilities			CIP												
UB	PK	Spillway Pump & Pi			CIP												
UB	PK	Flow Control Gate F Hydrostatic Relief S		nont 9	CIP												
LB	LL	Replacement		nerk ox	CIP												
UB	PK	COC Recoating & R			OP								i –				
UB	LG	Hearth Stability Ana			OP						-						
UB	PK	Bay 9 Transition Be	eam Leak Remed	diation	OP												
UB	PK	Bay 9 Wier Box			CIP												
LB	LL	Low Flow Facility M		provements	CIP												
UB	LG	Buttress 1 and 44 R			CIP												
UB	LG	Stoplog Replaceme			CIP												
UB	LG	Tainter Gate Evalua			OP												
UB	LG	Electric Vulnerability Seismic Analysis &		adimentation	OP												
UB	PK	Survey			OP												
UB	LG	Embankment Stabil		ssessment	OP												
UB	LG	Low Flow Facility A			CIP								i			ı	
LB	LL	Upstream Embankn			OP/CIP												1
LB	LL	Concrete Assessme			OP												
UB	LG	Targeted Concrete Assessment (CAAS)		nation	OP												
UB	LG	Inspection Walkway	/ Lighting		CIP												
UB	LG	Tainter Gate Trans	mission System	Mods	CIP												
UB	LG	Rip Rap Repair			CIP												
UB	LG	South Dike Erosion	Repair		OP												
UB	PK	North/South Bank F	Reconstruction		CIP												
UB	LG	Tainter Gate Recoa	ting		CIP												
Assessi	nent/Design																

Construction