

40 CFR Part 60, Subpart P - Requirements Reference Tables

Subpart P Standards

- [§60.162\(a\)](#) Particulate limits on dryer gases
- [§60.163\(a\)](#) Roaster, Smelting furnace, and copper converter SO₂ limits
- [§60.164\(a\)](#) Opacity limits on dryers
- [§60.164\(b\)](#) Opacity limits on a plant that utilizes sulfuric acid

These relationship entry screens and flowcharts are for use by sources subject to the Texas Federal Operating Permits Program only and are subject to revision.

Last Modified: July 30, 1997



Document: Below is a Relationship Entry Screen Table describing 40 CFR Part 60, Subpart P. It will likely not be accessible using a screen reader. For the text of the statute/rule, please go to [40 CFR Part 60, Subpart P](#)

Standard	Monitoring/Testing	Recordkeeping	Reporting
§60.162(a)	[R]§60.166(a) [R]§60.166(b)(1)		
§60.163(a) [D]§60.163(b) [D]§60.163(c)	[D]§60.165(a) [GR]§60.165(b)(2) [R]§60.165(c) [R]§60.165(d) [R]§60.165(d)(2) [R]§60.166(a) [R]§60.166(b)(2)	[D]§60.165(a) [GR]§60.165(b)(2) [R]§60.165(c)	[R]§60.165(d) [R]§60.165(d)(2)
§60.164(a)	[R]§60.165(b)(1) [R]§60.165(d) [R]§60.165(d)(1) [R]§60.166(a) [R]§60.166(b)(3)	[R]§60.165(b)(1)	[R]§60.165(d) [R]§60.165(d)(1)
§60.164(b)	[R]§60.166(a) [R]§60.166(b)(3)		