TX#		Dam Name Latitude Longitude Operator				Operation & Maintenance/Rehab Schedule			lule	Y 25 O&M Cost	Method of Finance	Notes
(03849	MORRIS SHER	PPARD DAM	32.871177	-98.426833	Brazos River Authority	Operating Pier Tras		nent	\$	230,000	Current Revenues/Reserves	
						Spillway Pump & P			\$	571,000	Reserves/Debt	
						Flow Control Gate			\$	1,301,000	Reserves/Debt	
						COC Recoating & I			\$		Current Revenues	
						Bay 9 Transition Be	eam Leak Remedia	ation	\$	564,000	Current Revenues	
						Bay 9 Weir Box			\$	461,000	Reserves/Debt	
						Seismic Analysis &			\$	200,000	Current Revenues	
								ations, maintenance and				
						inspections. Doesn	't include overhead	d.)	\$	5,638,200	Current Revenues	
03956	DE CORDOVA	BEND DAM	32.373464	-97.68791	1 Brazos River Authority	Hearth Stability And	alysis		\$	41,000	Current Revenues	
						Tainter Gate Évalua	ation		\$	350,000	Current Revenues	
						Electrical Vulnerab	ility Assessment		\$	240,000	Current Revenues	
						Embankment Stabi	ility Analysis & Ass	sessment	\$	250,000	Current Revenues	
						Low Flow Facilities	;		\$	2,000,000	Reserves/Debt	
						Dam Operations (in	ncludes dam opera	ations, maintenance and				
						inspections. Doesn	't include overhead	d.)	\$	2,746,429	Current Revenues	
04455	STERLING C.	ROBERTSON DAM	31.325659	-96.317206	Brazos River Authority	Tainter Gate Repla	cement & Improve	ments	\$	4,074,000	Reserves/Debt	
					<u> </u>	Hydrostatic Relief S	System Assessmer	nt & Replacement	\$	500,000	Reserves/Debt	
						Low Flow Facility N			\$	355,000	Reserves/Debt	
								ations, maintenance and				
						inspections. Doesn			\$	2,252,935	Current Revenues	
								·				
						Duning Times	P					
						Project Time	eiines					
asin	Location		Project		CIP/OP	£478 £471	ETTO ETTO	ETOS ETOS	EAUE	ETAT E	128 ×128 ×128 ×	131.35
		Talatan Cata E	tor Cote Bankasament & Immericancete									
LB	LL Tainter Gate Replacement & Improvements CIP											

