




Below is a flowchart describing 40 CFR Part 60, Subpart Ja. For the text of the statute/rule, please go to


40 CFR Part 60, Subpart Ja


(1 of 41)













































































The process heater shall conduct biennial performance tests according to §60.104a(i), establish a maximum excess O₂ operating limit or operating curve according to the requirements in §60.104a(i)(6) and comply with the O₂ monitoring requirements in §60.107a(c)(3)-(5) per §60.107a(c)(6) and §60.107a(d)(8).

