

40 CFR Part 60, Subpart P - Requirements Reference Tables

Subpart P Standards

- [§60.162\(a\)](#) Particulate limits on dryer gases
- [§60.163\(a\)](#) Roaster, Smelting furnace, and copper converter SO₂ limits
- [§60.164\(a\)](#) Opacity limits on dryers
- [§60.164\(b\)](#) Opacity limits on a plant that utilizes sulfuric acid

These relationship entry screens and flowcharts are for use by sources subject to the Texas Federal Operating Permits Program only and are subject to revision.

Last Modified: July 30, 1997