

40 CFR Part 60, Subpart R - Requirements Reference Tables

Subpart R Standards

- [§60.182\(a\)](#) Particulate discharge limits on blast/dross reverberatory furnaces and sintering machine
- [§60.183\(a\)](#) SO₂ discharge limits on sintering machines, electric smelting furnaces, and converters
- [§60.184\(a\)](#) Opacity discharge limits blast/dross reverberatory furnaces and sintering machine
- [§60.184\(b\)](#) Opacity limits from a plant that utilizes sulfuric acid

These relationship entry screens and flowcharts are for use by sources subject to the Texas Federal Operating Permits Program only and are subject to revision.

Last Modified: August 11, 1997