

40 CFR Part 61, Subpart O - Requirements Reference Tables

Subpart O Standards

- ! [§61.172](#) Copper converter facilities that produce less than 75 kg/h of arsenic
- ! [§61.172\(b\)\(1\)](#) Secondary hood systems copper converter facilities that produce arsenic
- ! [§61.172\(c\)](#) Standards for copper converter facilities that produce arsenic

These relationship entry screens and flowcharts are for use by sources subject to the Texas Federal Operating Permits Program only and are subject to revision.

Last Modified: July 29, 1997