

40 CFR 60 Subpart AAa - Rule Interpretation Memos

- ! [Typographical error in citation 60.274a\(b\)](#) [March 26, 1998]
- ! [Typographical error in 60.247a\(c\), references 60.247a\(b\)\(1\) and \(b\)\(2\) which do not exist.](#)
[July 21, 2000]

Last Modified: July 21, 2000

Rule Interpretation Summary Form

Rule/Regulation Citation(s):	Federal Rule: <u> X </u> State Regulation: <u> </u>
40 CFR 60, Subpart AAa § 60.274a(b)	Description: Standards of Performance for Steel Plants: Electric Arc Furnaces and Argon-Oxygen Decarburization Vessels Constructed After August 7, 1983
Interpretation Request:	
Section 60.274a(b) states “Except as provided under paragraph (d) of this section, the owner or operator subject to the provisions of this subpart shall...” The reference to § 60.274a(d) in this citation appears to be incorrect. If it is incorrect, then what is the correct reference?	
Determination:	
Section 60.274a(b) should reference § 60.274a(e). Therefore, § 60.274a(b) should read: “Except as provided under paragraph (e) of this section,...”	

Air Rule Interpretation Summary Form

Code Number	60AA_a.002
-------------	------------

Typographical error in 60.274a(c), references 60.274a(b)(1) and (b)(2) which do not exist.	July 21, 2000
--	---------------

Rule/Regulation Citation(s):	Federal Rule: <u> X </u> State Regulation: <u> </u>
	Description:
40 C.F.R. Part 60 Subpart AAa § 60.274a(c)	Standards of Performance for Steel Plants: Electric Arc Furnaces and Argon-Oxygen Decarburization Vessels Constructed After August 17, 1983

Interpretation Request:

Title 40 Code of Federal Regulations (C.F.R.) § 60.274a(c) states: “When the owner or operator of an affected facility is required to demonstrate compliance with the standards under Sec. 60.272a(a)(3) . . . , the volumetric flow rate at the control device inlet and all damper positions shall be . . . for the purpose of capturing emissions from the affected facility subject to paragraph (b)(1) or (b)(2) of this section.” However, paragraphs (b)(1) and (b)(2) of 40 C.F.R. § 60.274 do not exist. What should be the correct reference?

Determination:

The reference to paragraphs (b)(1) and (b)(2) in 40 C.F.R. § 60.274a(c) is incorrect. The correct reference should be to 40 C.F.R. § 60.274a(b). Therefore, 40 C.F.R. § 60.274a(c) should read as follows:

When the owner or operator of an affected facility is required to demonstrate compliance with the standards under Sec. 60.272a(a)(3) and at any other time the Administrator may require that (under section 114 of the Act, as amended) either: the control system fan motor amperes and all damper positions; the volumetric flow rate through each separately ducted hood; or the volumetric flow rate at the control device inlet and all damper positions shall be determined during all periods in which a hood is operated for the purpose of capturing emissions from the affected facility subject to paragraph (b) of this section. . . .

Bibliography:

Title 40 C.F.R. Part 60, Subpart AAa. [Revised as of July 1, 1999]

49 Fed. Reg. 43,838 (1984). [Oct. 31, 1984]

64 Fed. Reg. 10,105 (1999). [March 2, 1999]