40 CFR 60 Subpart AA - Rule Interpretation Memos

! Typographical error in 60.247(c), references 60.247(b)(1) and (b)(2) which do not exist. [July 21, 2000]

Last Modified: July 21, 2000

Air Rule Interpretation Summary Form

Code Number 60AA.001

Typographical error in 60.274(c), references 60.247(b)(1) and (b)(2) which do not exist.	July 21, 2000
--	---------------

Rule/Regulation Citation(s):	Federal Rule: X State Regulation: Description:
40 C.F.R. Part 60 Subpart AA	Standards of Performance for Steel Plants: Electric Arc Furnaces
§ 60.274(c)	Constructed After October 21, 1974, and On or Before August 17, 1983

Interpretation Request:

Title 40 Code of Federal Regulations (C.F.R.) \S 60.274(c) states: "When the owner or operator of an EAF [electric arc furnaces] is required to demonstrate compliance with the standards of Sec. 60.272(a)(3) . . . the volumetric flow rate at the control device inlet and all damper positions shall be . . . for the purpose of capturing emissions from the EAF subject to paragraph (b)(1) or (b)(2) of this section." However, paragraphs (b)(1) and (b)(2) of 40 C.F.R. \S 60.274 do not exist. What should be the correct reference?

Determination:

The reference to paragraphs (b)(1) and (b)(2) in 40 C.F.R. § 60.274(c) is incorrect. The correct reference should be to 40 C.F.R. § 60.274(b). Therefore, 40 C.F.R. § 60.274(c) should read as follows:

When the owner or operator of an EAF is required to demonstrate compliance with the standards under Sec. 60.272(a)(3) and at any other time the Administrator may require that (under section 114 of the Act, as amended) either: the control system fan motor amperes and all damper positions; the volumetric flow rate through each separately ducted hood; or the volumetric flow rate at the control device inlet and all damper positions shall be determined during all periods in which a hood is operated for the purpose of capturing emissions from the EAF subject to paragraph (b) of this section. . . .

Bibliography:

Title 40 C.F.R. Part 60, Subpart AA. [Revised as of July 1, 1999]

49 Fed. Reg. 43,838 (1984). [Oct. 31, 1984]

64 Fed. Reg. 10,105 (1999). [March 2, 1999]

Please note, in the event that an external customer feels that this rule interpretation is in error or a source of information has been overlooked which would change the determination, a request for reconsideration may be submitted. Requests must be submitted on a Reconsideration Process Form which is available at the TNRCC's homepage: http://www.tnrcc.state.tx.us/air/opd/rimhmpg.htm, or from any of the air rule interpretation team members.