

**EXECUTIVE SUMMARY - ENFORCEMENT MATTER**  
**DOCKET NO.:** 2010-0808-PST-E **TCEQ ID:** RN100699495 **CASE NO.:** 39710  
**RESPONDENT NAME:** UNITED PARCEL SERVICE, INC.

<b>ORDER TYPE:</b>		
<input checked="" type="checkbox"/> 1660 AGREED ORDER	<input type="checkbox"/> FINDINGS AGREED ORDER	<input type="checkbox"/> FINDINGS ORDER FOLLOWING SOAH HEARING
<input type="checkbox"/> FINDINGS DEFAULT ORDER	<input type="checkbox"/> SHUTDOWN ORDER	<input type="checkbox"/> IMMINENT AND SUBSTANTIAL ENDANGERMENT ORDER
<input type="checkbox"/> AMENDED ORDER	<input type="checkbox"/> EMERGENCY ORDER	

<b>CASE TYPE:</b>		
<input type="checkbox"/> AIR	<input type="checkbox"/> MULTI-MEDIA (check all that apply)	<input type="checkbox"/> INDUSTRIAL AND HAZARDOUS WASTE
<input type="checkbox"/> PUBLIC WATER SUPPLY	<input checked="" type="checkbox"/> PETROLEUM STORAGE TANKS	<input type="checkbox"/> OCCUPATIONAL CERTIFICATION
<input type="checkbox"/> WATER QUALITY	<input type="checkbox"/> SEWAGE SLUDGE	<input type="checkbox"/> UNDERGROUND INJECTION CONTROL
<input type="checkbox"/> MUNICIPAL SOLID WASTE	<input type="checkbox"/> RADIOACTIVE WASTE	<input type="checkbox"/> DRY CLEANER REGISTRATION

**SITE WHERE VIOLATION(S) OCCURRED:** UPS Fort Worth, 1300 East Northside Drive, Fort Worth, Tarrant County

**TYPE OF OPERATION:** Fleet refueling facility

**SMALL BUSINESS:**  Yes  No

**OTHER SIGNIFICANT MATTERS:** There are no complaints. There is no record of additional pending enforcement actions regarding this facility location.

**INTERESTED PARTIES:** No one other than the ED and the Respondent has expressed an interest in this matter.

**COMMENTS RECEIVED:** The *Texas Register* comment period expired on September 6, 2010. No comments were received.

**CONTACTS AND MAILING LIST:**

**TCEQ Attorney/SEP Coordinator:** None

**TCEQ Enforcement Coordinator:** Mr. Keith Frank, Enforcement Division, Enforcement Team 7, MC 128, (512) 239-1203; Ms. Laurie Eaves, Enforcement Division, MC 219, (512) 239-4495

**Respondent:** Ms. Pam Gantt, Environmental Coordinator, UNITED PARCEL SERVICE, INC., 10155 Monroe Drive, Dallas, Texas 75229

Ms. Susan Fritsche, District Plant Engineering Manager, UNITED PARCEL SERVICE, INC., 10155 Monroe Drive, Dallas, Texas 75229

**Respondent's Attorney:** Not represented by counsel on this enforcement matter

**VIOLATION SUMMARY CHART:**

VIOLATION INFORMATION	PENALTY CONSIDERATIONS	CORRECTIVE ACTIONS TAKEN/REQUIRED
<p><b>Type of Investigation:</b>  <input type="checkbox"/> Complaint  <input checked="" type="checkbox"/> Routine  <input type="checkbox"/> Enforcement Follow-up  <input type="checkbox"/> Records Review</p> <p><b>Date(s) of Complaints Relating to this Case:</b> None</p> <p><b>Date of Investigation Relating to this Case:</b> March 23, 2010</p> <p><b>Date of NOV/NOE Relating to this Case:</b> May 12, 2010 (NOE)</p> <p><b>Background Facts:</b> This was a routine investigation.</p> <p><b>WASTE</b></p> <p>1) Failure to verify proper operation of the Stage II equipment at least once every 12 months. Specifically, the Stage II annual compliance testing had not been conducted [30 TEX. ADMIN. CODE § 115.245(2) and TEX. HEALTH &amp; SAFETY CODE § 382.085(b)].</p> <p>2) Failure to maintain the Stage II vapor recovery system in proper operating condition, as specified by the manufacturer and/or any applicable California Air Resources Board Executive Order, and free of defects that would impair the effectiveness of the system. Specifically, the dust cap gasket was not on the Stage I vapor return adapter [30 TEX. ADMIN. CODE § 115.242(3) and TEX. HEALTH &amp; SAFETY CODE § 382.085(b)].</p>	<p><b>Total Assessed:</b> \$3,025</p> <p><b>Total Deferred:</b> \$605  <input checked="" type="checkbox"/> Expedited Settlement  <input type="checkbox"/> Financial Inability to Pay</p> <p><b>SEP Conditional Offset:</b> \$0</p> <p><b>Total Paid to General Revenue:</b> \$2,420</p> <p><b>Person Compliance History Classification</b>  <input type="checkbox"/> High <input checked="" type="checkbox"/> Average <input type="checkbox"/> Poor</p> <p><b>Site Compliance History Classification</b>  <input type="checkbox"/> High <input checked="" type="checkbox"/> Average <input type="checkbox"/> Poor</p> <p><b>Major Source:</b> <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No</p> <p><b>Applicable Penalty Policy:</b> September 2002</p>	<p><b>Corrective Actions Taken:</b></p> <p>The Executive Director recognizes that the Respondent has implemented the following corrective measures at the Station:</p> <p>a. Completed testing of the Stage II vapor recovery system on March 23, 2010, with passing results; and</p> <p>b. Replaced the dust cap gasket on the Stage I vapor return adapter on March 23, 2010.</p>

Additional ID No(s): 48002



# Penalty Calculation Worksheet (PCW)

Policy Revision 2 (September 2002)

PCW Revision October 30, 2008

**TCEQ**

<b>DATES</b>	<b>Assigned</b>	17-May-2010	<b>Screening</b>	18-May-2010	<b>EPA Due</b>	
	<b>PCW</b>	18-May-2010				

## RESPONDENT/FACILITY INFORMATION

<b>Respondent</b>	UNITED PARCEL SERVICE, INC.		
<b>Reg. Ent. Ref. No.</b>	RN100699495		
<b>Facility/Site Region</b>	4-Dallas/Fort Worth	<b>Major/Minor Source</b>	Minor

## CASE INFORMATION

<b>Enf./Case ID No.</b>	39710	<b>No. of Violations</b>	2
<b>Docket No.</b>	2010-0808-PST-E	<b>Order Type</b>	1660
<b>Media Program(s)</b>	Petroleum Storage Tank	<b>Government/Non-Profit</b>	No
<b>Multi-Media</b>		<b>Enf. Coordinator</b>	Keith Frank
		<b>EC's Team</b>	Enforcement Team 7
<b>Admin. Penalty \$ Limit Minimum</b>	\$0	<b>Maximum</b>	\$10,000

## Penalty Calculation Section

**TOTAL BASE PENALTY (Sum of violation base penalties)** **Subtotal 1**

### ADJUSTMENTS (+/-) TO SUBTOTAL 1

Subtotals 2-7 are obtained by multiplying the Total Base Penalty (Subtotal 1) by the indicated percentage.

**Compliance History**  **Subtotals 2, 3, & 7**

**Notes**

**Culpability**   **Subtotal 4**

**Notes**

**Good Faith Effort to Comply Total Adjustments** **Subtotal 5**

**Economic Benefit**  **Subtotal 6**

Total EB Amounts   
Approx. Cost of Compliance  \*Capped at the Total EB \$ Amount

**SUM OF SUBTOTALS 1-7** **Final Subtotal**

**OTHER FACTORS AS JUSTICE MAY REQUIRE**  **Adjustment**

Reduces or enhances the Final Subtotal by the indicated percentage.

**Notes**

**Final Penalty Amount**

**STATUTORY LIMIT ADJUSTMENT** **Final Assessed Penalty**

**DEFERRAL**  Reduction **Adjustment**

Reduces the Final Assessed Penalty by the indicated percentage. (Enter number only; e.g. 20 for 20% reduction.)

**Notes**

**PAYABLE PENALTY**

Screening Date 18-May-2010

Docket No. 2010-0808-PST-E

PCW

Respondent UNITED PARCEL SERVICE, INC.

Policy Revision 2 (September 2002)

Case ID No. 39710

PCW Revision October 30, 2008

Reg. Ent. Reference No. RN100699495

Media [Statute] Petroleum Storage Tank

Enf. Coordinator Keith Frank

### Compliance History Worksheet

>> Compliance History Site Enhancement (Subtotal 2)

Component	Number of...	Enter Number Here	Adjust.
NOVs	Written NOVs with same or similar violations as those in the current enforcement action (number of NOVs meeting criteria)	0	0%
	Other written NOVs	0	0%
Orders	Any agreed final enforcement orders containing a denial of liability (number of orders meeting criteria)	0	0%
	Any adjudicated final enforcement orders, agreed final enforcement orders without a denial of liability, or default orders of this state or the federal government, or any final prohibitory emergency orders issued by the commission	0	0%
Judgments and Consent Decrees	Any non-adjudicated final court judgments or consent decrees containing a denial of liability of this state or the federal government (number of judgements or consent decrees meeting criteria)	0	0%
	Any adjudicated final court judgments and default judgments, or non-adjudicated final court judgments or consent decrees without a denial of liability, of this state or the federal government	0	0%
Convictions	Any criminal convictions of this state or the federal government (number of counts)	0	0%
Emissions	Chronic excessive emissions events (number of events)	0	0%
Audits	Letters notifying the executive director of an intended audit conducted under the Texas Environmental, Health, and Safety Audit Privilege Act, 74th Legislature, 1995 (number of audits for which notices were submitted)	0	0%
	Disclosures of violations under the Texas Environmental, Health, and Safety Audit Privilege Act, 74th Legislature, 1995 (number of audits for which violations were disclosed)	0	0%
Please Enter Yes or No			
Other	Environmental management systems in place for one year or more	No	0%
	Voluntary on-site compliance assessments conducted by the executive director under a special assistance program	No	0%
	Participation in a voluntary pollution reduction program	No	0%
	Early compliance with, or offer of a product that meets future state or federal government environmental requirements	No	0%

Adjustment Percentage (Subtotal 2)

>> Repeat Violator (Subtotal 3)

Adjustment Percentage (Subtotal 3)

>> Compliance History Person Classification (Subtotal 7)

Adjustment Percentage (Subtotal 7)

>> Compliance History Summary

Compliance History Notes

No adjustment due to compliance history.

Total Adjustment Percentage (Subtotals 2, 3, & 7)

Screening Date 18-May-2010

Docket No. 2010-0808-PST-E

PCW

Respondent UNITED PARCEL SERVICE, INC.

Policy Revision 2 (September 2002)

Case ID No. 39710

PCW Revision October 30, 2008

Reg. Ent. Reference No. RN100699495

Media [Statute] Petroleum Storage Tank

Enf. Coordinator Keith Frank

Violation Number 1

Rule Cite(s) 30 Tex. Admin. Code § 115.245(2) and Tex. Health & Safety Code § 382.085(b)

Violation Description Failed to verify proper operation of the Stage II equipment at least once every 12 months. Specifically, the Stage II annual compliance testing had not been conducted.

Base Penalty \$10,000

>> Environmental, Property and Human Health Matrix

OR

Release	Harm			Percent
	Major	Moderate	Minor	
Actual				25%
Potential	x			

>> Programmatic Matrix

Falsification	Major	Moderate	Minor	Percent
				0%

Matrix Notes Human health or the environment will or could be exposed to pollutants which would exceed levels that are protective of human health or environmental receptors as a result of the violation.

Adjustment \$7,500

\$2,500

Violation Events

Number of Violation Events 1 23 Number of violation days

mark only one with an x	daily	
	weekly	
	monthly	
	quarterly	
	semiannual	
	annual	x
	single event	

Violation Base Penalty \$2,500

One annual event is recommended for the period preceding the March 23, 2010 investigation.

Good Faith Efforts to Comply

25.0% Reduction

\$625

	Before NOV	NOV to EDPRP/Settlement
	Extraordinary	
Ordinary	x	
N/A		(mark with x)

Notes The Respondent came into compliance on March 23, 2010 prior to the Notice of Enforcement ("NOE") dated May 12, 2010.

Violation Subtotal \$1,875

Economic Benefit (EB) for this violation

Statutory Limit Test

Estimated EB Amount \$400

Violation Final Penalty Total \$2,161

This violation Final Assessed Penalty (adjusted for limits) \$2,161

## Economic Benefit Worksheet

**Respondent** UNITED PARCEL SERVICE, INC.  
**Case ID No.** 39710  
**Reg. Ent. Reference No.** RN100699495  
**Media** Petroleum Storage Tank  
**Violation No.** 1

Percent Interest	Years of Depreciation
5.0	15

Item Description	Item Cost	Date Required	Final Date	Yrs	Interest Saved	Onetime Costs	EB Amount
------------------	-----------	---------------	------------	-----	----------------	---------------	-----------

No commas or \$

**Delayed Costs**

Equipment				0.00	\$0	\$0	\$0
Buildings				0.00	\$0	\$0	\$0
Other (as needed)				0.00	\$0	\$0	\$0
Engineering/construction				0.00	\$0	\$0	\$0
Land				0.00	\$0	n/a	\$0
Record Keeping System				0.00	\$0	n/a	\$0
Training/Sampling				0.00	\$0	n/a	\$0
Remediation/Disposal				0.00	\$0	n/a	\$0
Permit Costs				0.00	\$0	n/a	\$0
Other (as needed)				0.00	\$0	n/a	\$0

Notes for DELAYED costs

**Avoided Costs**

ANNUALIZE [1] avoided costs before entering item (except for one-time avoided costs)

Disposal				0.00	\$0	\$0	\$0
Personnel				0.00	\$0	\$0	\$0
Inspection/Reporting/Sampling				0.00	\$0	\$0	\$0
Supplies/equipment				0.00	\$0	\$0	\$0
Financial Assurance [2]				0.00	\$0	\$0	\$0
ONE-TIME avoided costs [3]	\$400	28-Feb-2010	23-Mar-2010	0.00	\$0	\$400	\$400
Other (as needed)				0.00	\$0	\$0	\$0

Notes for AVOIDED costs

Actual avoided cost for annual testing to verify proper operation of the Stage II equipment as indicated on the invoice. Date Required is the date testing was due. Final Date is the date of compliance.

Approx. Cost of Compliance

\$400

TOTAL

\$400

Screening Date 18-May-2010

Docket No. 2010-0808-PST-E

PCW

Respondent UNITED PARCEL SERVICE, INC.

Policy Revision 2 (September 2002)

Case ID No. 39710

PCW Revision October 30, 2009

Reg. Ent. Reference No. RN100699495

Media [Statute] Petroleum Storage Tank

Enf. Coordinator Keith Frank

Violation Number 2

Rule Cite(s) 30 Tex. Admin. Code § 115.242(3) and Tex. Health & Safety Code § 382.085(b)

Violation Description

Failed to maintain the Stage II vapor recovery system in proper operating condition, as specified by the manufacturer and/or any applicable California Air Resources Board Executive Order, and free of defects that would impair the effectiveness of the system. Specifically, the dust cap gasket was not on the Stage I vapor return adapter.

Base Penalty \$10,000

>> Environmental, Property and Human Health Matrix

OR	Release	Harm			Percent
		Major	Moderate	Minor	
Actual					10%
Potential			x		

>> Programmatic Matrix

Matrix Notes	Falsification	Harm			Percent
		Major	Moderate	Minor	
					0%

Human health or the environment will or could be exposed to significant amounts of pollutants which would not exceed levels that are protective of human health or environmental receptors as a result of the violation.

Adjustment \$9,000

\$1,000

Violation Events

Number of Violation Events 1 1 Number of violation days

mark only one with an x	daily	
	weekly	
	monthly	
	quarterly	x
	semiannual	
	annual	
	single event	

Violation Base Penalty \$1,000

One quarterly event is recommended based on documentation of the violation during the March 23, 2010 investigation to the March 23, 2010 date of compliance.

Good Faith Efforts to Comply

25.0% Reduction

\$250

	Before NOV	NOV to EDPRP/Settlement Offer
Extraordinary		
Ordinary	x	
N/A		(mark with x)

Notes The Respondent came into compliance on March 23, 2010 prior to the NOE dated May 12, 2010.

Violation Subtotal \$750

Economic Benefit (EB) for this violation

Statutory Limit Test

Estimated EB Amount \$0

Violation Final Penalty Total \$864

This violation Final Assessed Penalty (adjusted for limits) \$864

## Economic Benefit Worksheet

**Respondent** UNITED PARCEL SERVICE, INC.  
**Case ID No.** 39710  
**Reg. Ent. Reference No.** RN100699495  
**Media** Petroleum Storage Tank  
**Violation No.** 2

Percent Interest	Years of Depreciation
5.0	15

Item Description	Item Cost	Date Required	Final Date	Yrs	Interest Saved	Onetime Costs	EB Amount
------------------	-----------	---------------	------------	-----	----------------	---------------	-----------

No commas or \$

**Delayed Costs**

Equipment				0.00	\$0	\$0	\$0
Buildings				0.00	\$0	\$0	\$0
Other (as needed)				0.00	\$0	\$0	\$0
Engineering/construction				0.00	\$0	\$0	\$0
Land				0.00	\$0	n/a	\$0
Record Keeping System				0.00	\$0	n/a	\$0
Training/Sampling				0.00	\$0	n/a	\$0
Remediation/Disposal				0.00	\$0	n/a	\$0
Permit Costs				0.00	\$0	n/a	\$0
Other (as needed)	\$50	22-Mar-2010	23-Mar-2010	0.00	\$0	n/a	\$0

Notes for DELAYED costs

Estimated cost to replace the dust cap gasket on the Stage I vapor return adapter. Date Required is one day prior to the investigation date. Final Date is the date of compliance.

**Avoided Costs**

**ANNUALIZE [1] avoided costs before entering item (except for one-time avoided costs)**

Disposal				0.00	\$0	\$0	\$0
Personnel				0.00	\$0	\$0	\$0
Inspection/Reporting/Sampling				0.00	\$0	\$0	\$0
Supplies/equipment				0.00	\$0	\$0	\$0
Financial Assurance [2]				0.00	\$0	\$0	\$0
ONE-TIME avoided costs [3]				0.00	\$0	\$0	\$0
Other (as needed)				0.00	\$0	\$0	\$0

Notes for AVOIDED costs

Approx. Cost of Compliance

\$50

TOTAL

\$0

# Compliance History Report

Customer/Respondent/Owner-Operator: CN602297624 UNITED PARCEL SERVICE, INC. Classification: AVERAGE Rating: 2.10  
 Regulated Entity: RN100699495 UPS Fort Worth Classification: AVERAGE Site Rating: 3.01

ID Number(s): INDUSTRIAL AND HAZARDOUS WASTE GENERATION EPA ID TXD981594922  
 INDUSTRIAL AND HAZARDOUS WASTE GENERATION SOLID WASTE REGISTRATION # (SWR) 61554  
 PETROLEUM STORAGE TANK REGISTRATION 48002  
 STORMWATER PERMIT TXR05M793  
 Location: 1300 E NORTHSIDE DR, FORT WORTH, TX, 76102

TCEQ Region: REGION 04 - DFW METROPLEX

Date Compliance History Prepared: May 18, 2010

Agency Decision Requiring Compliance History: Enforcement

Compliance Period: May 18, 2005 to May 18, 2010

TCEQ Staff Member to Contact for Additional Information Regarding this Compliance History

Name: Keith Frank Phone: (512) 239-1203

### Site Compliance History Components

1. Has the site been in existence and/or operation for the full five year compliance period? Yes
2. Has there been a (known) change in ownership/operator of the site during the compliance period? No
3. If Yes, who is the current owner/operator? N/A
4. If Yes, who was/were the prior owner(s)/operator(s) ? N/A
5. When did the change(s) in owner or operator occur? N/A
6. Rating Date: 9/1/2009 Repeat Violator: NO

### Components (Multimedia) for the Site :

- A. Final Enforcement Orders, court judgements, and consent decrees of the state of Texas and the federal government.  
N/A
- B. Any criminal convictions of the state of Texas and the federal government.  
N/A
- C. Chronic excessive emissions events.  
N/A
- D. The approval dates of investigations. (CCEDS Inv. Track. No.)  
1 05/12/2010 (796903)
- E. Written notices of violations (NOV). (CCEDS Inv. Track. No.)  
N/A
- F. Environmental audits.  
N/A
- G. Type of environmental management systems (EMSs).  
N/A
- H. Voluntary on-site compliance assessment dates.  
N/A
- I. Participation in a voluntary pollution reduction program.  
N/A
- J. Early compliance.

N/A

Sites Outside of Texas

N/A

TEXAS COMMISSION ON ENVIRONMENTAL QUALITY



IN THE MATTER OF AN  
ENFORCEMENT ACTION  
CONCERNING  
UNITED PARCEL SERVICE, INC.  
RN100699495

§  
§  
§  
§  
§

BEFORE THE  
TEXAS COMMISSION ON  
ENVIRONMENTAL QUALITY

**AGREED ORDER  
DOCKET NO. 2010-0808-PST-E**

**I. JURISDICTION AND STIPULATIONS**

At its \_\_\_\_\_ agenda, the Texas Commission on Environmental Quality ("the Commission" or "TCEQ") considered this agreement of the parties, resolving an enforcement action regarding UNITED PARCEL SERVICE, INC. ("the Respondent") under the authority of TEX. HEALTH & SAFETY CODE ch. 382 and TEX. WATER CODE ch. 7. The Executive Director of the TCEQ, through the Enforcement Division, and the Respondent appear before the Commission and together stipulate that:

1. The Respondent owns and operates a fleet refueling facility at 1300 East Northside Drive in Fort Worth, Tarrant County, Texas (the "Station").
2. The Station consists of one or more sources as defined in TEX. HEALTH & SAFETY CODE § 382.003(12).
3. The Commission and the Respondent agree that the Commission has jurisdiction to enter this Agreed Order, and that the Respondent is subject to the Commission's jurisdiction.
4. The Respondent received notice of the violations alleged in Section II ("Allegations") on or about May 17, 2010.
5. The occurrence of any violation is in dispute and the entry of this Agreed Order shall not constitute an admission by the Respondent of any violation alleged in Section II ("Allegations"), nor of any statute or rule.
6. An administrative penalty in the amount of Three Thousand Twenty-Five Dollars (\$3,025) is assessed by the Commission in settlement of the violations alleged in Section II ("Allegations"). The Respondent has paid Two Thousand Four Hundred Twenty Dollars (\$2,420) of the administrative penalty and Six Hundred Five Dollars (\$605) is deferred contingent upon the

Respondent's timely and satisfactory compliance with all the terms of this Agreed Order. The deferred amount will be waived upon full compliance with the terms of this Agreed Order. If the Respondent fails to timely and satisfactorily comply with all requirements of this Agreed Order, the Executive Director may require the Respondent to pay all or part of the deferred penalty.

7. Any notice and procedures, which might otherwise be authorized or required in this action, are waived in the interest of a more timely resolution of the matter.
8. The Executive Director of the TCEQ and the Respondent have agreed on a settlement of the matters alleged in this enforcement action, subject to the approval of the Commission.
9. The Executive Director recognizes that the Respondent has implemented the following corrective measures at the Station:
  - a. Completed testing of the Stage II vapor recovery system on March 23, 2010, with passing results; and
  - b. Replaced the dust cap gasket on the Stage I vapor return adapter on March 23, 2010.
10. The Executive Director may, without further notice or hearing, refer this matter to the Office of the Attorney General of the State of Texas ("OAG") for further enforcement proceedings if the Executive Director determines that the Respondent has not complied with one or more of the terms or conditions in this Agreed Order.
11. This Agreed Order shall terminate five years from its effective date or upon compliance with all the terms and conditions set forth in this Agreed Order, whichever is later.
12. The provisions of this Agreed Order are deemed severable and, if a court of competent jurisdiction or other appropriate authority deems any provision of this Agreed Order unenforceable, the remaining provisions shall be valid and enforceable.

## II. ALLEGATIONS

As owner and operator of the Station, the Respondent is alleged to have:

1. Failed to verify proper operation of the Stage II equipment at least once every 12 months, in violation of 30 TEX. ADMIN. CODE § 115.245(2) and TEX. HEALTH & SAFETY CODE § 382.085(b), as documented during an investigation conducted on March 23, 2010. Specifically, the Stage II annual compliance testing had not been conducted.
2. Failed to maintain the Stage II vapor recovery system in proper operating condition, as specified by the manufacturer and/or any applicable California Air Resources Board Executive Order, and free of defects that would impair the effectiveness of the system, in violation of 30 TEX. ADMIN. CODE § 115.242(3) and TEX. HEALTH & SAFETY CODE § 382.085(b), as documented during an investigation conducted on March 23, 2010. Specifically, the dust cap gasket was not on the Stage I vapor return adapter.

### III. DENIALS

The Respondent generally denies each allegation in Section II ("Allegations").

### IV. ORDERING PROVISIONS


1. It is, therefore, ordered by the TCEQ that the Respondent pay an administrative penalty as set forth in Section I, Paragraph 6 above. The payment of this administrative penalty and the Respondent's compliance with all the terms and conditions set forth in this Agreed Order resolve only the allegations in Section II. The Commission shall not be constrained in any manner from requiring corrective action or penalties for violations which are not raised here. Administrative penalty payments shall be made payable to "TCEQ" and shall be sent with the notation "Re: UNITED PARCEL SERVICE, INC., Docket No. 2010-0808-PST-E" to:  

Financial Administration Division, Revenues Section  
Attention: Cashier's Office, MC 214  
Texas Commission on Environmental Quality  
P.O. Box 13088  
Austin, Texas 78711-3088
2. The provisions of this Agreed Order shall apply to and be binding upon the Respondent. The Respondent is ordered to give notice of the Agreed Order to personnel who maintain day-to-day control over the Station operations referenced in this Agreed Order.
3. This Agreed Order, issued by the Commission, shall not be admissible against the Respondent in a civil proceeding, unless the proceeding is brought by the OAG to: (1) enforce the terms of this Agreed Order; or (2) pursue violations of a statute within the Commission's jurisdiction, or of a rule adopted or an order or permit issued by the Commission under such a statute.
4. This Agreed Order may be executed in multiple counterparts, which together shall constitute a single original instrument. Any executed signature page to this Agreed Order may be transmitted by facsimile transmission to the other parties, which shall constitute an original signature for all purposes under this Agreed Order.
5. Under 30 TEX. ADMIN. CODE § 70.10(b), the effective date is the date of hand-delivery of the Order to the Respondent, or three days after the date on which the Commission mails notice of the Order to the Respondent, whichever is earlier. The Chief Clerk shall provide a copy of this Agreed Order to each of the parties.

**SIGNATURE PAGE**

TEXAS COMMISSION ON ENVIRONMENTAL QUALITY

\_\_\_\_\_  
For the Commission

  
\_\_\_\_\_  
For the Executive Director

\_\_\_\_\_  
Date 8/13/2010

I, the undersigned, have read and understand the attached Agreed Order. I am authorized to agree to the attached Agreed Order on behalf of the entity indicated below my signature, and I do agree to the terms and conditions specified therein. I further acknowledge that the TCEQ, in accepting payment for the penalty amount, is materially relying on such representation.

I also understand that failure to comply with the Ordering Provisions, if any, in this order and/or failure to timely pay the penalty amount, may result in:

- A negative impact on compliance history;
- Greater scrutiny of any permit applications submitted;
- Referral of this case to the Attorney General's Office for contempt, injunctive relief, additional penalties, and/or attorney fees, or to a collection agency;
- Increased penalties in any future enforcement actions;
- Automatic referral to the Attorney General's Office of any future enforcement actions; and
- TCEQ seeking other relief as authorized by law.

In addition, any falsification of any compliance documents may result in criminal prosecution.

  
\_\_\_\_\_  
Signature

\_\_\_\_\_  
Date 7/9/10

SUSAN E. FRITSCHÉ  
\_\_\_\_\_  
Name (Printed or typed)  
Authorized Representative of  
UNITED PARCEL SERVICE, INC.

DISTRICT PLANT ENGINEERING MGR.  
\_\_\_\_\_  
Title

**Instructions:** Send the original, signed Agreed Order with penalty payment to the Financial Administration Division, Revenues Section at the address in Section IV, Paragraph 1 of this Agreed Order.