

Executive Summary – Enforcement Matter – Case No. 41677
SANDFORD OIL COMPANY, INC. dba Circle S 17
RN101546257
Docket No. 2011-0787-PST-E

Order Type:

1660 Agreed Order

Findings Order Justification:

N/A

Media:

PST

Small Business:

Yes

Location(s) Where Violation(s) Occurred:

Circle S 17, 1504 Chico Highway, Bridgeport, Wise County

Type of Operation:

Convenience store with retail sales of gasoline

Other Significant Matters:

Additional Pending Enforcement Actions: No

Past-Due Penalties: No

Other: N/A

Interested Third-Parties: None

Texas Register Publication Date: July 22, 2011

Comments Received: No

Penalty Information

Total Penalty Assessed: \$3,875

Amount Deferred for Expedited Settlement: \$775

Amount Deferred for Financial Inability to Pay: \$0

Total Paid to General Revenue: \$3,100

Total Due to General Revenue: \$0

Payment Plan: N/A

SEP Conditional Offset: \$0

Name of SEP: N/A

Compliance History Classifications:

Person/CN - Average

Site/RN - Average by Default

Major Source: Yes

Statutory Limit Adjustment: N/A

Applicable Penalty Policy: September 2002

**Executive Summary – Enforcement Matter – Case No. 41677
SANDFORD OIL COMPANY, INC. dba Circle S 17
RN101546257
Docket No. 2011-0787-PST-E**

Investigation Information

Complaint Date(s): N/A
Complaint Information: N/A
Date(s) of Investigation: May 6, 2010
Date(s) of NOE(s): April 17, 2011

Violation Information

1. Failed to provide proper release detection for the pressurized piping associated with the underground storage tanks. Specifically, the Respondent did not conduct the annual piping tightness test [30 TEX. ADMIN. CODE § 334.50(b)(2) and TEX. WATER CODE § 26.3475(a)].
2. Failed to test the line leak detectors at least once per year for performance and operational reliability [30 TEX. ADMIN. CODE § 334.50(b)(2)(A)(i)(III) and TEX. WATER CODE § 26.3475(a)].

Corrective Actions/Technical Requirements

Corrective Action(s) Completed:

The Executive Director recognizes that the Respondent has successfully conducted the annual piping tightness and line leak detection tests on May 19, 2010, with passing results.

Technical Requirements:

N/A

Litigation Information

Date Petition(s) Filed: N/A
Date Answer(s) Filed: N/A
SOAH Referral Date: N/A
Hearing Date(s): N/A
Settlement Date: N/A

Contact Information

TCEQ Attorney: N/A
TCEQ Enforcement Coordinator: Elvia Maske, Enforcement Division, Enforcement Team 7, MC 128, (512) 239-0789; Debra Barber, Enforcement Division, MC 219, (512) 239-0412
TCEQ SEP Coordinator: N/A
Respondent: Robert Blake Sandford, President, SANDFORD OIL COMPANY, INC., P.O. Box 660, Decatur, Texas 76234
Respondent's Attorney: N/A



Penalty Calculation Worksheet (PCW)

Policy Revision 2 (September 2002)

PCW Revision October 30, 2008

TCEQ

DATES	Assigned	25-Apr-2011	Screening	2-May-2011	EPA Due	
	PCW	10-May-2011				

RESPONDENT/FACILITY INFORMATION

Respondent	SANDFORD OIL COMPANY, INC. dba Circle S 17	
Reg. Ent. Ref. No.	RN101546257	
Facility/Site Region	4-Dallas/Fort Worth	Major/Minor Source Major

CASE INFORMATION

Enf./Case ID No.	41677	No. of Violations	1
Docket No.	2011-0787-PST-E	Order Type	1660
Media Program(s)	Petroleum Storage Tank	Government/Non-Profit	No
Multi-Media		Enf. Coordinator	Elvia Maske
		EC's Team	Enforcement Team 7
Admin. Penalty \$ Limit Minimum	\$0	Maximum	\$10,000

Penalty Calculation Section

TOTAL BASE PENALTY (Sum of violation base penalties) **Subtotal 1**

ADJUSTMENTS (+/-) TO SUBTOTAL 1

Subtotals 2-7 are obtained by multiplying the Total Base Penalty (Subtotal 1) by the indicated percentage.

Compliance History Enhancement **Subtotals 2, 3, & 7**

Notes

Culpability Enhancement **Subtotal 4**

Notes

Good Faith Effort to Comply Total Adjustments **Subtotal 5**

Economic Benefit Enhancement* **Subtotal 6**

Total EB Amounts *Capped at the Total EB \$ Amount
 Approx. Cost of Compliance

SUM OF SUBTOTALS 1-7 **Final Subtotal**

OTHER FACTORS AS JUSTICE MAY REQUIRE **Adjustment**

Reduces or enhances the Final Subtotal by the indicated percentage.

Notes

Final Penalty Amount

STATUTORY LIMIT ADJUSTMENT **Final Assessed Penalty**

DEFERRAL Reduction **Adjustment**

Reduces the Final Assessed Penalty by the indicted percentage. (Enter number only; e.g. 20 for 20% reduction.)

Notes

PAYABLE PENALTY

Screening Date 2-May-2011

Docket No. 2011-0787-PST-E

PCW

Respondent SANDFORD OIL COMPANY, INC. dba Circle S 17

Policy Revision 2 (September 2002)

Case ID No. 41677

PCW Revision October 30, 2008

Reg. Ent. Reference No. RN101546257

Media [Statute] Petroleum Storage Tank

Enf. Coordinator Elvia Maske

Compliance History Worksheet

>> Compliance History Site Enhancement (Subtotal 2)

Component	Number of...	Enter Number Here	Adjust.
NOVs	Written notices of violation ("NOVs") with same or similar violations as those in the current enforcement action (<i>number of NOVs meeting criteria</i>)	0	0%
	Other written NOVs	0	0%
Orders	Any agreed final enforcement orders containing a denial of liability (<i>number of orders meeting criteria</i>)	0	0%
	Any adjudicated final enforcement orders, agreed final enforcement orders without a denial of liability, or default orders of this state or the federal government, or any final prohibitory emergency orders issued by the commission	0	0%
Judgments and Consent Decrees	Any non-adjudicated final court judgments or consent decrees containing a denial of liability of this state or the federal government (<i>number of judgments or consent decrees meeting criteria</i>)	0	0%
	Any adjudicated final court judgments and default judgments, or non-adjudicated final court judgments or consent decrees without a denial of liability, of this state or the federal government	0	0%
Convictions	Any criminal convictions of this state or the federal government (<i>number of counts</i>)	0	0%
Emissions	Chronic excessive emissions events (<i>number of events</i>)	0	0%
Audits	Letters notifying the executive director of an intended audit conducted under the Texas Environmental, Health, and Safety Audit Privilege Act, 74th Legislature, 1995 (<i>number of audits for which notices were submitted</i>)	0	0%
	Disclosures of violations under the Texas Environmental, Health, and Safety Audit Privilege Act, 74th Legislature, 1995 (<i>number of audits for which violations were disclosed</i>)	0	0%

Please Enter Yes or No

Other	Environmental management systems in place for one year or more	No	0%
	Voluntary on-site compliance assessments conducted by the executive director under a special assistance program	No	0%
	Participation in a voluntary pollution reduction program	No	0%
	Early compliance with, or offer of a product that meets future state or federal government environmental requirements	No	0%

Adjustment Percentage (Subtotal 2) 0%

>> Repeat Violator (Subtotal 3)

No

Adjustment Percentage (Subtotal 3) 0%

>> Compliance History Person Classification (Subtotal 7)

Average Performer

Adjustment Percentage (Subtotal 7) 0%

>> Compliance History Summary

Compliance History Notes

No adjustment for Compliance History.

Total Adjustment Percentage (Subtotals 2, 3, & 7) 0%

Screening Date 2-May-2011

Docket No. 2011-0787-PST-E

PCW

Respondent SANDFORD OIL COMPANY, INC. dba Circle S 17

Policy Revision 2 (September 2002)

Case ID No. 41677

PCW Revision October 30, 2008

Reg. Ent. Reference No. RN101546257

Media [Statute] Petroleum Storage Tank

Enf. Coordinator Elvia Maske

Violation Number 1

Rule Cite(s) 30 Tex. Admin. Code § 334.50(b)(2) and (b)(2)(A)(i)(III) and Tex. Water Code § 26.3475(a)

Violation Description Failed to provide proper release detection for the pressurized piping associated with the underground storage tank (UST). Specifically, the Respondent did not conduct the annual piping tightness test. Also, failed to test the line leak detectors at least once per year for performance and operational reliability.

Base Penalty \$10,000

>> Environmental, Property and Human Health Matrix

Release	Harm			Percent
	Major	Moderate	Minor	
Actual				50%
Potential	x			

>> Programmatic Matrix

Falsification	Major	Moderate	Minor	Percent
				0%

Matrix Notes Human health or the environment will or could be exposed to pollutants which would exceed levels that are protective of human health or environmental receptors as a result of the violation.

Adjustment \$5,000

\$5,000

Violation Events

Number of Violation Events 1 Number of violation days 81

daily	
weekly	
monthly	
quarterly	
semiannual	
annual	x
single event	

mark only one with an x

Violation Base Penalty \$5,000

One annual event is recommended for the period preceding the May 6, 2010 investigation.

Good Faith Efforts to Comply

25.0% Reduction

\$1,250

	Before NOV	NOV to EDPRP/Settlement Offer
Extraordinary		
Ordinary	x	
N/A		(mark with x)

Notes The Respondent achieved compliance on May 19, 2010 prior to the April 17, 2011 Notice of Enforcement.

Violation Subtotal \$3,750

Economic Benefit (EB) for this violation

Statutory Limit Test

Estimated EB Amount \$125

Violation Final Penalty Total \$3,875

This violation Final Assessed Penalty (adjusted for limits) \$3,875

Economic Benefit Worksheet

Respondent SANDFORD OIL COMPANY, INC. dba Circle S 17
Case ID No. 41677
Req. Ent. Reference No. RN101546257
Media Violation No. 1
 Petroleum Storage Tank

Percent Interest	Years of Depreciation
5.0	15

Item Description	Item Cost	Date Required	Final Date	Yrs	Interest Saved	Onetime Costs	EB Amount
No commas or \$							

Delayed Costs

Equipment				0.00	\$0	\$0	\$0
Buildings				0.00	\$0	\$0	\$0
Other (as needed)				0.00	\$0	\$0	\$0
Engineering/construction				0.00	\$0	\$0	\$0
Land				0.00	\$0	n/a	\$0
Record Keeping System				0.00	\$0	n/a	\$0
Training/Sampling				0.00	\$0	n/a	\$0
Remediation/Disposal				0.00	\$0	n/a	\$0
Permit Costs				0.00	\$0	n/a	\$0
Other (as needed)				0.00	\$0	n/a	\$0

Notes for DELAYED costs

Avoided Costs

ANNUALIZE [1] avoided costs before entering item (except for one-time avoided costs)

Disposal				0.00	\$0	\$0	\$0
Personnel				0.00	\$0	\$0	\$0
Inspection/Reporting/Sampling				0.00	\$0	\$0	\$0
Supplies/equipment				0.00	\$0	\$0	\$0
Financial Assurance [2]				0.00	\$0	\$0	\$0
ONE-TIME avoided costs [3]	\$118	27-Feb-2010	19-May-2010	1.14	\$7	\$118	\$125
Other (as needed)				0.00	\$0	\$0	\$0

Notes for AVOIDED costs

Estimated cost for conducting annual piping tightness and line leak detector tests. The date required is the date the tests were due and the final date is the date of compliance.

Approx. Cost of Compliance

\$118

TOTAL

\$125

Compliance History

Customer/Respondent/Owner-Operator: CN600806558 SANDFORD OIL COMPANY, INC. Classification: AVERAGE Rating: 2.94

Regulated Entity: RN101546257 Circle S 17 Classification: AVERAGE Site Rating: 3.01
BY DEFAULT

ID Number(s): PETROLEUM STORAGE TANK REGISTRATION 6810
REGISTRATION
AIR NEW SOURCE PERMITS REGISTRATION 52951

Location: 1504 CHICO HWY, BRIDGEPORT, TX, 76426

TCEQ Region: REGION 04 - DFW METROPLEX

Date Compliance History Prepared: May 02, 2011

Agency Decision Requiring Compliance History: Enforcement

Compliance Period: May 02, 2006 to May 02, 2011

TCEQ Staff Member to Contact for Additional Information Regarding this Compliance History

Name: Elvia Maske Phone: (512) 239 - 0789

Site Compliance History Components

1. Has the site been in existence and/or operation for the full five year compliance period? Yes
2. Has there been a (known) change in ownership/operator of the site during the compliance period? No
3. If Yes, who is the current owner/operator? N/A
4. If Yes, who was/were the prior owner(s)/operator(s)? N/A
5. When did the change(s) in owner or operator occur? N/A
6. Rating Date: 9/1/2010 Repeat Violator: NO

Components (Multimedia) for the Site :

- A. Final Enforcement Orders, court judgments, and consent decrees of the State of Texas and the federal government.
N/A
 - B. Any criminal convictions of the state of Texas and the federal government.
N/A
 - C. Chronic excessive emissions events.
N/A
 - D. The approval dates of investigations. (CCEDS Inv. Track. No.)
1 04/17/2011 (895122)
 - E. Written notices of violations (NOV). (CCEDS Inv. Track. No.)
N/A
 - F. Environmental audits.
N/A
 - G. Type of environmental management systems (EMSs).
N/A
 - H. Voluntary on-site compliance assessment dates.
N/A
 - I. Participation in a voluntary pollution reduction program.
N/A
 - J. Early compliance.
N/A
- Sites Outside of Texas
N/A

TEXAS COMMISSION ON ENVIRONMENTAL QUALITY



**IN THE MATTER OF AN
ENFORCEMENT ACTION
CONCERNING
SANDFORD OIL COMPANY, INC.
DBA CIRCLE S 17
RN101546257**

§
§
§
§
§
§
§

**BEFORE THE

TEXAS COMMISSION ON

ENVIRONMENTAL QUALITY**

AGREED ORDER DOCKET NO. 2011-0787-PST-E

I. JURISDICTION AND STIPULATIONS

At its _____ agenda, the Texas Commission on Environmental Quality ("the Commission" or "TCEQ") considered this agreement of the parties, resolving an enforcement action regarding SANDFORD OIL COMPANY, INC. dba Circle S 17 ("the Respondent") under the authority of TEX. WATER CODE chs. 7 and 26. The Executive Director of the TCEQ, through the Enforcement Division, and the Respondent appear before the Commission and together stipulate that:

1. The Respondent operates a convenience store with retail sales of gasoline at 1504 Chico Highway in Bridgeport, Wise County, Texas (the "Facility").
2. The Respondent's four underground storage tanks ("USTs") are not exempt or excluded from regulation under the Texas Water Code or the rules of the Commission.
3. The Commission and the Respondent agree that the Commission has jurisdiction to enter this Agreed Order, and that the Respondent is subject to the Commission's jurisdiction.
4. The Respondent received notice of the violations alleged in Section II ("Allegations") on or about April 22, 2011.
5. The occurrence of any violation is in dispute and the entry of this Agreed Order shall not constitute an admission by the Respondent of any violation alleged in Section II ("Allegations"), nor of any statute or rule.
6. An administrative penalty in the amount of Three Thousand Eight Hundred Seventy-Five Dollars (\$3,875) is assessed by the Commission in settlement of the violations alleged in

Section II ("Allegations"). The Respondent has paid Three Thousand One Hundred Dollars (\$3,100) of the administrative penalty and Seven Hundred Seventy-Five Dollars (\$775) is deferred contingent upon the Respondent's timely and satisfactory compliance with all the terms of this Agreed Order. The deferred amount will be waived upon full compliance with the terms of this Agreed Order. If the Respondent fails to timely and satisfactorily comply with all requirements of this Agreed Order, the Executive Director may require the Respondent to pay all or part of the deferred penalty.

7. Any notice and procedures, which might otherwise be authorized or required in this action, are waived in the interest of a more timely resolution of the matter.
8. The Executive Director of the TCEQ and the Respondent have agreed on a settlement of the matters alleged in this enforcement action, subject to the approval of the Commission.
9. The Executive Director recognizes that the Respondent has successfully conducted the annual piping tightness and line leak detection tests on May 19, 2010, with passing results.
10. The Executive Director may, without further notice or hearing, refer this matter to the Office of the Attorney General of the State of Texas ("OAG") for further enforcement proceedings if the Executive Director determines that the Respondent has not complied with one or more of the terms or conditions in this Agreed Order.
11. This Agreed Order shall terminate five years from its effective date or upon compliance with all the terms and conditions set forth in this Agreed Order, whichever is later.
12. The provisions of this Agreed Order are deemed severable and, if a court of competent jurisdiction or other appropriate authority deems any provision of this Agreed Order unenforceable, the remaining provisions shall be valid and enforceable.

II. ALLEGATIONS

As operator of the Facility, the Respondent is alleged to have:

1. Failed to provide proper release detection for the pressurized piping associated with the USTs, in violation of 30 TEX. ADMIN. CODE § 334.50(b)(2) and TEX. WATER CODE § 26.3475(a), as documented during an investigation conducted on May 6, 2010. Specifically, the Respondent did not conduct the annual piping tightness test.
2. Failed to test the line leak detectors at least once per year for performance and operational reliability, in violation of 30 TEX. ADMIN. CODE § 334.50(b)(2)(A)(i)(III) and TEX. WATER CODE § 26.3475(a), as documented during an investigation conducted on May 6, 2010.

III. DENIALS

The Respondent generally denies each allegation in Section II ("Allegations").

IV. ORDERING PROVISIONS

1. It is, therefore, ordered by the TCEQ that the Respondent pay an administrative penalty as set forth in Section I, Paragraph 6 above. The payment of this administrative penalty and the Respondent's compliance with all the terms and conditions set forth in this Agreed Order resolve only the allegations in Section II. The Commission shall not be constrained in any manner from requiring corrective action or penalties for violations which are not raised here. Administrative penalty payments shall be made payable to "TCEQ" and shall be sent with the notation "Re: SANDFORD OIL COMPANY, INC. dba Circle S 17, Docket No. 2011-0787-PST-E" to:

Financial Administration Division, Revenues Section
Attention: Cashier's Office, MC 214
Texas Commission on Environmental Quality
P.O. Box 13088
Austin, Texas 78711-3088
2. The provisions of this Agreed Order shall apply to and be binding upon the Respondent. The Respondent is ordered to give notice of the Agreed Order to personnel who maintain day-to-day control over the Facility operations referenced in this Agreed Order.
3. This Agreed Order, issued by the Commission, shall not be admissible against the Respondent in a civil proceeding, unless the proceeding is brought by the OAG to: (1) enforce the terms of this Agreed Order; or (2) pursue violations of a statute within the Commission's jurisdiction, or of a rule adopted or an order or permit issued by the Commission under such a statute.
4. This Agreed Order may be executed in separate and multiple counterparts, which together shall constitute a single instrument. Any page of this Agreed Order may be copied, scanned, digitized, converted to electronic portable document format ("pdf"), or otherwise reproduced and may be transmitted by digital or electronic transmission, including but not limited to facsimile transmission and electronic mail. Any signature affixed to this Agreed Order shall constitute an original signature for all purposes and may be used, filed, substituted, or issued for any purpose for which an original signature could be used. The term "signature" shall include manual signatures and true and accurate reproductions of manual signatures created, executed, endorsed, adopted, or authorized by the person or persons to whom the signatures are attributable. Signatures may be copied or reproduced digitally, electronically, by photocopying, engraving, imprinting, lithographing, electronic mail, facsimile transmission, stamping, or any other means or process which the Executive Director deems acceptable. In this paragraph exclusively, the terms "electronic transmission", "owner", "person", "writing", and "written" shall have the meanings assigned to them under TEX. BUS. ORG. CODE § 1.002.
5. Under 30 TEX. ADMIN. CODE § 70.10(b), the effective date is the date of hand-delivery of the Order to the Respondent, or three days after the date on which the Commission mails notice of the Order to the Respondent, whichever is earlier. The Chief Clerk shall provide a copy of this Agreed Order to each of the parties.

SIGNATURE PAGE

TEXAS COMMISSION ON ENVIRONMENTAL QUALITY

For the Commission

Robert H. Hylleberg
For the Executive Director

8/5/11
Date

I, the undersigned, have read and understand the attached Agreed Order. I am authorized to agree to the attached Agreed Order on behalf of the entity indicated below my signature, and I do agree to the terms and conditions specified therein. I further acknowledge that the TCEQ, in accepting payment for the penalty amount, is materially relying on such representation.

I also understand that failure to comply with the Ordering Provisions, if any, in this order and/or failure to timely pay the penalty amount, may result in:

- A negative impact on compliance history;
- Greater scrutiny of any permit applications submitted;
- Referral of this case to the Attorney General's Office for contempt, injunctive relief, additional penalties, and/or attorney fees, or to a collection agency;
- Increased penalties in any future enforcement actions;
- Automatic referral to the Attorney General's Office of any future enforcement actions; and
- TCEQ seeking other relief as authorized by law.

In addition, any falsification of any compliance documents may result in criminal prosecution.

RB Sandford, Pres.
Signature

6-22-11
Date

RB Sandford
Name (Printed or typed)
Authorized Representative of
SANDFORD OIL COMPANY, INC. dba Circle S 17

Pres.
Title

Instructions: Send the original, signed Agreed Order with penalty payment to the Financial Administration Division, Revenues Section at the address in Section IV, Paragraph 1 of this Agreed Order.