

Executive Summary – Enforcement Matter – Case No. 44020
Jack A. Terhune dba Jack's Flying Service
RN102037470
Docket No. 2012-0853-PST-E

Order Type:

1660 Agreed Order

Findings Order Justification:

N/A

Media:

PST

Small Business:

No

Location(s) Where Violation(s) Occurred:

Jack's Flying Service, 11869 County Road J, Perryton, Ochiltree County

Type of Operation:

Fleet refueling facility

Other Significant Matters:

Additional Pending Enforcement Actions: No

Past-Due Penalties: No

Other: N/A

Interested Third-Parties: None

Texas Register Publication Date: October 5, 2012

Comments Received: No

Penalty Information

Total Penalty Assessed: \$10,327

Amount Deferred for Expedited Settlement: \$2,065

Amount Deferred for Financial Inability to Pay: \$0

Total Paid to General Revenue: \$8,262

Total Due to General Revenue: \$0

Payment Plan: N/A

SEP Conditional Offset: \$0

Name of SEP: N/A

Compliance History Classifications:

Person/CN - Average

Site/RN – Average by default

Major Source: No

Statutory Limit Adjustment: N/A

Applicable Penalty Policy: September 2002

Executive Summary – Enforcement Matter – Case No. 44020
Jack A. Terhune dba Jack's Flying Service
RN102037470
Docket No. 2012-0853-PST-E

Investigation Information

Complaint Date(s): N/A

Complaint Information: N/A

Date(s) of Investigation: June 9, 2011 and March 27, 2012

Date(s) of NOE(s): March 27, 2012

Violation Information

1. Failed to submit a properly completed underground storage tank ("UST") registration and self-certification form and obtain a delivery certificate in a timely manner [30 TEX. ADMIN. CODE § 334.8(c)(4)(B) and (c)(5)(B)(ii)].
2. Failed to make available to a common carrier a valid, current TCEQ delivery certificate before accepting delivery of a regulated substance into the UST. Specifically, one fuel delivery was accepted without a delivery certificate [30 TEX. ADMIN. CODE § 334.8(c)(5)(A)(i) and TEX. WATER CODE § 26.3467(a)].
3. Failed to demonstrate acceptable financial assurance for taking corrective action and for compensating third parties for bodily injury and property damage caused by accidental releases arising from the operation of the petroleum UST [30 TEX. ADMIN. CODE § 37.815(a) and (b)].
4. Failed to provide proper corrosion protection for the UST system [30 TEX. ADMIN. CODE § 334.49(a)(1) and TEX. WATER CODE § 26.3475(d)].
5. Failed to monitor the UST for releases at a frequency of at least once every month (not to exceed 35 days between each monitoring) [30 TEX. ADMIN. CODE § 334.50(b)(1)(A) and TEX. WATER CODE § 26.3475(c)(1)].
6. Failed to provide release detection for the piping associated with the UST. Specifically, the Respondent did not conduct the annual piping tightness test [30 TEX. ADMIN. CODE § 334.50(b)(2) and TEX. WATER CODE § 26.3475(a)].
7. Failed to equip the UST with spill containment and overfill prevention equipment [30 TEX. ADMIN. CODE § 334.51(b)(2) and TEX. WATER CODE § 26.3475(c)(2)].
8. Failed to maintain UST records and make them immediately available for inspection upon request by agency personnel [30 TEX. ADMIN. CODE § 334.10(b)].

Corrective Actions/Technical Requirements

Corrective Action(s) Completed:

N/A

Executive Summary – Enforcement Matter – Case No. 44020
Jack A. Terhune dba Jack's Flying Service
RN102037470
Docket No. 2012-0853-PST-E

Technical Requirements:

The Order will require the Respondent to:

a. Immediately:

i. Cease accepting fuel until such time as a valid delivery certificate is obtained from the TCEQ by submitting a properly completed UST registration and self-certification form; and

ii. Begin maintaining all UST records and ensure they are made immediately available for inspection upon request by agency personnel.

b. Within 30 days:

i. Submit documentation that demonstrates acceptable financial assurance for taking corrective action and for compensating third parties for bodily injury and property damage caused by accidental releases arising from the operation of the petroleum UST;

ii. Install a corrosion protection system and test the system;

iii. Implement a release detection method for the UST at the Facility and conduct the annual piping tightness test; and

iv. Equip the UST with spill containment and overfill prevention equipment; and

c. Within 45 days, submit written certification demonstrating compliance.

Litigation Information

Date Petition(s) Filed: N/A

Date Answer(s) Filed: N/A

SOAH Referral Date: N/A

Hearing Date(s): N/A

Settlement Date: N/A

Contact Information

TCEQ Attorney: N/A

TCEQ Enforcement Coordinator: Clinton Sims, Enforcement Division, Enforcement Team 6, MC 128, (512) 239-6933; Debra Barber, Enforcement Division, MC 219, (512) 239-0412.

TCEQ SEP Coordinator: N/A

Respondent: Jack A. Terhune, Owner, Jack's Flying Service, 401 South Colgate Street, Perryton, Texas 79070

Respondent's Attorney: N/A



Penalty Calculation Worksheet (PCW)

Policy Revision 2 (September 2002)

PCW Revision October 30, 2008

TCEQ

DATES	Assigned	2-Apr-2012	Screening	19-Apr-2012	EPA Due	
	PCW	20-Apr-2012				

RESPONDENT/FACILITY INFORMATION

Respondent	Jack A. Terhune dba Jack's Flying Service		
Reg. Ent. Ref. No.	RN102037470		
Facility/Site Region	1-Amarillo	Major/Minor Source	Minor

CASE INFORMATION

Enf./Case ID No.	44020	No. of Violations	7
Docket No.	2012-0853-PST-E	Order Type	1660
Media Program(s)	Petroleum Storage Tank	Government/Non-Profit	No
Multi-Media		Enf. Coordinator	Clinton Sims
		EC's Team	Enforcement Team 6
Admin. Penalty \$ Limit Minimum	\$0	Maximum	\$10,000

Penalty Calculation Section

TOTAL BASE PENALTY (Sum of violation base penalties)	Subtotal 1	\$9,500
---	-------------------	----------------

ADJUSTMENTS (+/-) TO SUBTOTAL 1

Subtotals 2-7 are obtained by multiplying the Total Base Penalty (Subtotal 1) by the indicated percentage.

Compliance History	0.0% Enhancement	Subtotals 2, 3, & 7	\$0
---------------------------	------------------	--------------------------------	------------

Notes: No adjustment for compliance history.

Culpability	No	0.0% Enhancement	Subtotal 4	\$0
--------------------	----	------------------	-------------------	------------

Notes: The Respondent does not meet the culpability criteria.

Good Faith Effort to Comply Total Adjustments	Subtotal 5	\$0
--	-------------------	------------

Economic Benefit	0.0% Enhancement*	Subtotal 6	\$0
-------------------------	-------------------	-------------------	------------

Total EB Amounts	\$1,756
Approx. Cost of Compliance	\$9,878

*Capped at the Total EB \$ Amount

SUM OF SUBTOTALS 1-7	Final Subtotal	\$9,500
-----------------------------	-----------------------	----------------

OTHER FACTORS AS JUSTICE MAY REQUIRE	8.7%	Adjustment	\$827
---	------	-------------------	--------------

Reduces or enhances the Final Subtotal by the indicated percentage.

Notes: Recommended enhancement to capture the avoided cost of compliance associated with violation nos. 3 and 5.

Final Penalty Amount	\$10,327
-----------------------------	-----------------

STATUTORY LIMIT ADJUSTMENT	Final Assessed Penalty	\$10,327
-----------------------------------	-------------------------------	-----------------

DEFERRAL	20.0% Reduction	Adjustment	-\$2,065
-----------------	-----------------	-------------------	-----------------

Reduces the Final Assessed Penalty by the indicted percentage. (Enter number only; e.g. 20 for 20% reduction.)

Notes: Deferral offered for expedited settlement.

PAYABLE PENALTY	\$8,262
------------------------	----------------

Screening Date 19-Apr-2012

Docket No. 2012-0853-PST-E

PCW

Respondent Jack A. Terhune dba Jack's Flying Service

Policy Revision 2 (September 2002)

Case ID No. 44020

PCW Revision October 30, 2008

Reg. Ent. Reference No. RN102037470

Media [Statute] Petroleum Storage Tank

Enf. Coordinator Clinton Sims

Compliance History Worksheet

>> Compliance History Site Enhancement (Subtotal 2)

Component	Number of...	Enter Number Here	Adjust.
NOVs	Written notices of violation ("NOVs") with same or similar violations as those in the current enforcement action (<i>number of NOVs meeting criteria</i>)	0	0%
	Other written NOVs	0	0%
Orders	Any agreed final enforcement orders containing a denial of liability (<i>number of orders meeting criteria</i>)	0	0%
	Any adjudicated final enforcement orders, agreed final enforcement orders without a denial of liability, or default orders of this state or the federal government, or any final prohibitory emergency orders issued by the commission	0	0%
Judgments and Consent Decrees	Any non-adjudicated final court judgments or consent decrees containing a denial of liability of this state or the federal government (<i>number of judgements or consent decrees meeting criteria</i>)	0	0%
	Any adjudicated final court judgments and default judgments, or non-adjudicated final court judgments or consent decrees without a denial of liability, of this state or the federal government	0	0%
Convictions	Any criminal convictions of this state or the federal government (<i>number of counts</i>)	0	0%
Emissions	Chronic excessive emissions events (<i>number of events</i>)	0	0%
Audits	Letters notifying the executive director of an intended audit conducted under the Texas Environmental, Health, and Safety Audit Privilege Act, 74th Legislature, 1995 (<i>number of audits for which notices were submitted</i>)	0	0%
	Disclosures of violations under the Texas Environmental, Health, and Safety Audit Privilege Act, 74th Legislature, 1995 (<i>number of audits for which violations were disclosed</i>)	0	0%
<i>Please Enter Yes or No</i>			
Other	Environmental management systems in place for one year or more	No	0%
	Voluntary on-site compliance assessments conducted by the executive director under a special assistance program	No	0%
	Participation in a voluntary pollution reduction program	No	0%
	Early compliance with, or offer of a product that meets future state or federal government environmental requirements	No	0%

Adjustment Percentage (Subtotal 2)

>> Repeat Violator (Subtotal 3)

Adjustment Percentage (Subtotal 3)

>> Compliance History Person Classification (Subtotal 7)

Adjustment Percentage (Subtotal 7)

>> Compliance History Summary

Compliance History Notes

No adjustment for compliance history.

Total Adjustment Percentage (Subtotals 2, 3, & 7)

Screening Date 19-Apr-2012

Docket No. 2012-0853-PST-E

PCW

Respondent Jack A. Terhune dba Jack's Flying Service

Policy Revision 2 (September 2002)

Case ID No. 44020

PCW Revision October 30, 2008

Reg. Ent. Reference No. RN102037470

Media [Statute] Petroleum Storage Tank

Enf. Coordinator Clinton Sims

Violation Number 1

Rule Cite(s) 30 Tex. Admin. Code § 334.8(c)(4)(B) and (c)(5)(B)(ii)

Violation Description Failed to submit a properly completed underground storage tank ("UST") registration and self-certification form and obtain a delivery certificate in a timely manner.

Base Penalty \$10,000

>> Environmental, Property and Human Health Matrix

Table with columns: Release (Actual, Potential), Harm (Major, Moderate, Minor), Percent (0%).

>> Programmatic Matrix

Table with columns: Falsification, Major, Moderate, Minor, Percent (10%).

Matrix Notes 100% of the rule requirement was not met.

Adjustment \$9,000

\$1,000

Violation Events

Number of Violation Events 1 Number of violation days 365

Table for event frequency: daily, weekly, monthly, quarterly, semiannual, annual (marked with X), single event.

Violation Base Penalty \$1,000

One annual event is recommended.

Good Faith Efforts to Comply

0.0% Reduction

\$0

Table for Good Faith Efforts: Extraordinary, Ordinary, N/A (marked with X).

Notes The Respondent does not meet the good faith criteria for this violation.

Violation Subtotal \$1,000

Economic Benefit (EB) for this violation

Estimated EB Amount \$8

Statutory Limit Test

Violation Final Penalty Total \$1,087

This violation Final Assessed Penalty (adjusted for limits) \$1,087

Economic Benefit Worksheet

Respondent Jack A. Terhune dba Jack's Flying Service
Case ID No. 44020
Req. Ent. Reference No. RN102037470
Media Petroleum Storage Tank
Violation No. 1

Percent Interest	Years of Depreciation
5.0	15

Item Description	Item Cost	Date Required	Final Date	Yrs	Interest Saved	Onetime Costs	EB Amount
No commas or \$							

Delayed Costs

Equipment				0.00	\$0	\$0	\$0
Buildings				0.00	\$0	\$0	\$0
Other (as needed)				0.00	\$0	\$0	\$0
Engineering/construction				0.00	\$0	\$0	\$0
Land				0.00	\$0	n/a	\$0
Record Keeping System				0.00	\$0	n/a	\$0
Training/Sampling				0.00	\$0	n/a	\$0
Remediation/Disposal				0.00	\$0	n/a	\$0
Permit Costs				0.00	\$0	n/a	\$0
Other (as needed)	\$100	9-Jun-2011	31-Dec-2012	1.56	\$8	n/a	\$8

Notes for DELAYED costs

Estimated cost to submit a properly completed UST registration and self-certification form and obtain a delivery certificate. The Date Required is the investigation date and the Final Date is the estimated date of compliance.

Avoided Costs

ANNUALIZE [1] avoided costs before entering item (except for one-time avoided costs)

Disposal				0.00	\$0	\$0	\$0
Personnel				0.00	\$0	\$0	\$0
Inspection/Reporting/Sampling				0.00	\$0	\$0	\$0
Supplies/equipment				0.00	\$0	\$0	\$0
Financial Assurance [2]				0.00	\$0	\$0	\$0
ONE-TIME avoided costs [3]				0.00	\$0	\$0	\$0
Other (as needed)				0.00	\$0	\$0	\$0

Notes for AVOIDED costs

Approx. Cost of Compliance

\$100

TOTAL

\$8

Screening Date 19-Apr-2012

Docket No. 2012-0853-PST-E

PCW

Respondent Jack A. Terhune dba Jack's Flying Service

Policy Revision 2 (September 2002)

Case ID No. 44020

PCW Revision October 30, 2008

Reg. Ent. Reference No. RN102037470

Media [Statute] Petroleum Storage Tank

Enf. Coordinator Clinton Sims

Violation Number 2

Rule Cite(s) 30 Tex. Admin. Code § 334.8(c)(5)(A)(i) and Tex. Water Code § 26.3467(a)

Violation Description Failed to make available to a common carrier a valid, current TCEQ delivery certificate before accepting delivery of a regulated substance into the UST. Specifically, one fuel delivery was accepted without a delivery certificate.

Base Penalty \$10,000

>> Environmental, Property and Human Health Matrix

OR	Release	Harm			Percent
		Major	Moderate	Minor	
	Actual				5%
	Potential			x	

>> Programmatic Matrix

Matrix Notes	Falsification	Harm			Percent
		Major	Moderate	Minor	
					0%
Human health or the environment will or could be exposed to insignificant amounts of pollutants which would not exceed levels that are protective of human health or environmental receptors as a result of the violation.					

Adjustment \$9,500

\$500

Violation Events

Number of Violation Events 1 Number of violation days 1

mark only one with an x	daily	
	weekly	
	monthly	
	quarterly	
	semiannual	
	annual	
	single event	x

Violation Base Penalty \$500

One single event are recommended.

Good Faith Efforts to Comply

0.0% Reduction \$0

	Before NOV	NOV to EDPRP/Settlement Offer
Extraordinary		
Ordinary		
N/A	x	(mark with x)

Notes The Respondent does not meet the good faith criteria for this violation.

Violation Subtotal \$500

Economic Benefit (EB) for this violation

Statutory Limit Test

Estimated EB Amount \$0

Violation Final Penalty Total \$544

This violation Final Assessed Penalty (adjusted for limits) \$544

Economic Benefit Worksheet

Respondent Jack A. Terhune dba Jack's Flying Service
Case ID No. 44020
Req. Ent. Reference No. RN102037470
Media Petroleum Storage Tank
Violation No. 2

Percent Interest	Years of Depreciation
5.0	15

Item Description	Item Cost	Date Required	Final Date	Yrs	Interest Saved	Onetime Costs	EB Amount
<small>No commas or \$</small>							

Delayed Costs

Equipment				0.00	\$0	\$0	\$0
Buildings				0.00	\$0	\$0	\$0
Other (as needed)				0.00	\$0	\$0	\$0
Engineering/construction				0.00	\$0	\$0	\$0
Land				0.00	\$0	n/a	\$0
Record Keeping System				0.00	\$0	n/a	\$0
Training/Sampling				0.00	\$0	n/a	\$0
Remediation/Disposal				0.00	\$0	n/a	\$0
Permit Costs				0.00	\$0	n/a	\$0
Other (as needed)				0.00	\$0	n/a	\$0

Notes for DELAYED costs

Economic benefit included in violation no. 1.

Avoided Costs

ANNUALIZE [1] avoided costs before entering item (except for one-time avoided costs)

Disposal				0.00	\$0	\$0	\$0
Personnel				0.00	\$0	\$0	\$0
Inspection/Reporting/Sampling				0.00	\$0	\$0	\$0
Supplies/equipment				0.00	\$0	\$0	\$0
Financial Assurance [2]				0.00	\$0	\$0	\$0
ONE-TIME avoided costs [3]				0.00	\$0	\$0	\$0
Other (as needed)				0.00	\$0	\$0	\$0

Notes for AVOIDED costs

Approx. Cost of Compliance

\$0

TOTAL

\$0

Screening Date 19-Apr-2012

Docket No. 2012-0853-PST-E

PCW

Respondent Jack A. Terhune dba Jack's Flying Service

Policy Revision 2 (September 2002)

Case ID No. 44020

PCW Revision October 30, 2008

Reg. Ent. Reference No. RN102037470

Media [Statute] Petroleum Storage Tank

Enf. Coordinator Clinton Sims

Violation Number 3

Rule Cite(s) 30 Tex. Admin. Code § 37.815(a) and (b)

Violation Description Failed to demonstrate acceptable financial assurance for taking corrective action and for compensating third parties for bodily injury and property damage caused by accidental releases arising from the operation of the petroleum UST.

Base Penalty \$10,000

>> Environmental, Property and Human Health Matrix

OR

Release	Harm		
	Major	Moderate	Minor
Actual			
Potential			

Percent 0%

>> Programmatic Matrix

Falsification	Major	Moderate	Minor
	x		

Percent 10%

Matrix Notes

100% of the rule requirement was not met.

Adjustment \$9,000

\$1,000

Violation Events

Number of Violation Events 1

365 Number of violation days

mark only one with an x

daily	
weekly	
monthly	
quarterly	
semiannual	
annual	
single event	x

Violation Base Penalty \$1,000

One single event is recommended.

Good Faith Efforts to Comply

0.0% Reduction

\$0

	Before NOV	NOV to EDPRP/Settlement Offer
Extraordinary		
Ordinary		
N/A	x	(mark with x)

Notes

The Respondent does not meet the good faith criteria for this violation.

Violation Subtotal \$1,000

Economic Benefit (EB) for this violation

Statutory Limit Test

Estimated EB Amount \$693

Violation Final Penalty Total \$1,087

This violation Final Assessed Penalty (adjusted for limits) \$1,087

Economic Benefit Worksheet

Respondent Jack A. Terhune dba Jack's Flying Service
Case ID No. 44020
Req. Ent. Reference No. RN102037470
Media Petroleum Storage Tank
Violation No. 3

Percent Interest	Years of Depreciation
5.0	15

Item Description	Item Cost	Date Required	Final Date	Yrs	Interest Saved	Onetime Costs	EB Amount
No commas or \$							

Delayed Costs

Equipment				0.00	\$0	\$0	\$0
Buildings				0.00	\$0	\$0	\$0
Other (as needed)				0.00	\$0	\$0	\$0
Engineering/construction				0.00	\$0	\$0	\$0
Land				0.00	\$0	n/a	\$0
Record Keeping System				0.00	\$0	n/a	\$0
Training/Sampling				0.00	\$0	n/a	\$0
Remediation/Disposal				0.00	\$0	n/a	\$0
Permit Costs				0.00	\$0	n/a	\$0
Other (as needed)				0.00	\$0	n/a	\$0

Notes for DELAYED costs

Avoided Costs

ANNUALIZE [1] avoided costs before entering item (except for one-time avoided costs)

Disposal				0.00	\$0	\$0	\$0
Personnel				0.00	\$0	\$0	\$0
Inspection/Reporting/Sampling				0.00	\$0	\$0	\$0
Supplies/equipment				0.00	\$0	\$0	\$0
Financial Assurance [2]	\$660	27-Mar-2011	27-Mar-2012	1.00	\$33	\$660	\$693
ONE-TIME avoided costs [3]				0.00	\$0	\$0	\$0
Other (as needed)				0.00	\$0	\$0	\$0

Notes for AVOIDED costs

Estimated cost to provide financial assurance for one UST. The Date Required is one year prior to the record review date and the Final Date is the record review date.

Approx. Cost of Compliance	\$660	TOTAL	\$693
-----------------------------------	-------	--------------	-------

Screening Date 19-Apr-2012

Docket No. 2012-0853-PST-E

PCW

Respondent Jack A. Terhune dba Jack's Flying Service

Policy Revision 2 (September 2002)

Case ID No. 44020

PCW Revision October 30, 2008

Reg. Ent. Reference No. RN102037470

Media [Statute] Petroleum Storage Tank

Enf. Coordinator Clinton Sims

Violation Number 4

Rule Cite(s) 30 Tex. Admin. Code § 334.49(a)(1) and Tex. Water Code § 26.3475(d)

Violation Description Failed to provide proper corrosion protection for the UST system.

Base Penalty \$10,000

>> Environmental, Property and Human Health Matrix

Release	Harm			Percent
	Major	Moderate	Minor	
Actual				25%
Potential	x			

>> Programmatic Matrix

Falsification	Major	Moderate	Minor	Percent
				0%

Matrix Notes Human health or the environment will or could be exposed to pollutants which would exceed levels that are protective of human health or environmental receptors as a result of the violation.

Adjustment \$7,500

\$2,500

Violation Events

Number of Violation Events 1 Number of violation days 23

daily	
weekly	
monthly	x
quarterly	
semiannual	
annual	
single event	

mark only one with an x

Violation Base Penalty \$2,500

One monthly event is recommended based on documentation of the violation during the March 27, 2012 record review date to the April 19, 2012 screening date.

Good Faith Efforts to Comply

0.0% Reduction

\$0

	Before NOV	NOV to EDPRP/Settlement Offer
Extraordinary		
Ordinary		
N/A	x	(mark with x)

Notes The Respondent does not meet the good faith criteria for this violation.

Violation Subtotal \$2,500

Economic Benefit (EB) for this violation

Statutory Limit Test

Estimated EB Amount \$657

Violation Final Penalty Total \$2,718

This violation Final Assessed Penalty (adjusted for limits) \$2,718

Economic Benefit Worksheet

Respondent Jack A. Terhune dba Jack's Flying Service
Case ID No. 44020
Req. Ent. Reference No. RN102037470
Media Petroleum Storage Tank
Violation No. 4

Percent Interest	Years of Depreciation
5.0	15

Item Description	Item Cost	Date Required	Final Date	Yrs	Interest Saved	Onetime Costs	EB Amount
No commas or \$							

Delayed Costs

Equipment	\$6,000	9-Jun-2011	31-Dec-2012	1.56	\$31	\$626	\$657
Buildings				0.00	\$0	\$0	\$0
Other (as needed)				0.00	\$0	\$0	\$0
Engineering/construction				0.00	\$0	\$0	\$0
Land				0.00	\$0	n/a	\$0
Record Keeping System				0.00	\$0	n/a	\$0
Training/Sampling				0.00	\$0	n/a	\$0
Remediation/Disposal				0.00	\$0	n/a	\$0
Permit Costs				0.00	\$0	n/a	\$0
Other (as needed)				0.00	\$0	n/a	\$0

Notes for DELAYED costs

Estimated cost to install a corrosion protection system and test the system. The Date Required is the investigation date and the Final Date is the estimated date of compliance.

Avoided Costs

ANNUALIZE [1] avoided costs before entering item (except for one-time avoided costs)

Disposal				0.00	\$0	\$0	\$0
Personnel				0.00	\$0	\$0	\$0
Inspection/Reporting/Sampling				0.00	\$0	\$0	\$0
Supplies/equipment				0.00	\$0	\$0	\$0
Financial Assurance [2]				0.00	\$0	\$0	\$0
ONE-TIME avoided costs [3]				0.00	\$0	\$0	\$0
Other (as needed)				0.00	\$0	\$0	\$0

Notes for AVOIDED costs

Approx. Cost of Compliance

\$6,000

TOTAL

\$657

Screening Date 19-Apr-2012

Docket No. 2012-0853-PST-E

PCW

Respondent Jack A. Terhune dba Jack's Flying Service

Policy Revision 2 (September 2002)

Case ID No. 44020

PCW Revision October 30, 2008

Reg. Ent. Reference No. RN102037470

Media [Statute] Petroleum Storage Tank

Enf. Coordinator Clinton Sims

Violation Number 5

Rule Cite(s) 30 Tex. Admin. Code § 334.50(b)(1)(A) and (b)(2), and Tex. Water Code § 26.3475(a) and (c)(1)

Violation Description

Failed to monitor the UST for releases at a frequency of at least once every month (not to exceed 35 days between each monitoring). Also, failed to provide release detection for the piping associated with the UST. Specifically, the Respondent did not conduct the annual piping tightness test.

Base Penalty \$10,000

>> Environmental, Property and Human Health Matrix

OR

Release	Harm		
	Major	Moderate	Minor
Actual			
Potential	x		

Percent 25%

>> Programmatic Matrix

Falsification	Major	Moderate	Minor

Percent 0%

Matrix Notes

Human health or the environment will or could be exposed to pollutants which would exceed levels that are protective of human health or environmental receptors as a result of the violation.

Adjustment \$7,500

\$2,500

Violation Events

Number of Violation Events 1

23 Number of violation days

mark only one with an x

daily	
weekly	
monthly	x
quarterly	
semiannual	
annual	
single event	

Violation Base Penalty \$2,500

One monthly event is recommended based on documentation of the violation during the March 27, 2012 record review date to the April 19, 2012 screening date.

Good Faith Efforts to Comply

0.0% Reduction

\$0

	Before NOV	NOV to EDPRP/Settlement Offer
Extraordinary		
Ordinary		
N/A	x	(mark with x)

Notes

The Respondent does not meet the good faith criteria for this violation.

Violation Subtotal \$2,500

Economic Benefit (EB) for this violation

Statutory Limit Test

Estimated EB Amount \$251

Violation Final Penalty Total \$2,718

This violation Final Assessed Penalty (adjusted for limits) \$2,718

Economic Benefit Worksheet

Respondent Jack A. Terhune dba Jack's Flying Service
Case ID No. 44020
Reg. Ent. Reference No. RN102037470
Media Petroleum Storage Tank
Violation No. 5

Percent Interest	Years of Depreciation
5.0	15

Item Description	Item Cost	Date Required	Final Date	Yrs	Interest Saved	Onetime Costs	EB Amount
No commas or \$							

Delayed Costs

Equipment				0.00	\$0	\$0	\$0
Buildings				0.00	\$0	\$0	\$0
Other (as needed)				0.00	\$0	\$0	\$0
Engineering/construction				0.00	\$0	\$0	\$0
Land				0.00	\$0	n/a	\$0
Record Keeping System				0.00	\$0	n/a	\$0
Training/Sampling				0.00	\$0	n/a	\$0
Remediation/Disposal				0.00	\$0	n/a	\$0
Permit Costs				0.00	\$0	n/a	\$0
Other (as needed)	\$1,500	9-Jun-2011	31-Dec-2012	1.56	\$117	n/a	\$117

Notes for DELAYED costs

Estimated cost to monitor the UST for releases. The Date Required is the investigation date and the Final Date is the estimated date of compliance.

Avoided Costs

ANNUALIZE [1] avoided costs before entering item (except for one-time avoided costs)

Disposal				0.00	\$0	\$0	\$0
Personnel				0.00	\$0	\$0	\$0
Inspection/Reporting/Sampling				0.00	\$0	\$0	\$0
Supplies/equipment				0.00	\$0	\$0	\$0
Financial Assurance [2]				0.00	\$0	\$0	\$0
ONE-TIME avoided costs [3]	\$118	9-Jun-2010	27-Mar-2012	2.72	\$16	\$118	\$134
Other (as needed)				0.00	\$0	\$0	\$0

Notes for AVOIDED costs

Estimated avoided cost for conducting the annual piping tightness test. The Date Required is one year prior to the investigation date and the Final Date is the record review date.

Approx. Cost of Compliance

\$1,618

TOTAL

\$251

Screening Date 19-Apr-2012

Docket No. 2012-0853-PST-E

PCW

Respondent Jack A. Terhune dba Jack's Flying Service

Policy Revision 2 (September 2002)

Case ID No. 44020

PCW Revision October 30, 2008

Reg. Ent. Reference No. RN102037470

Media [Statute] Petroleum Storage Tank

Enf. Coordinator Clinton Sims

Violation Number 6

Rule Cite(s) 30 Tex. Admin. Code § 334.51(b)(2) and Tex. Water Code § 26.3475(c)(2)

Violation Description Failed to equip the UST with spill containment and overfill prevention equipment.

Base Penalty \$10,000

>> Environmental, Property and Human Health Matrix

OR

Release	Harm		
	Major	Moderate	Minor
Actual			
Potential		x	

Percent 10%

>> Programmatic Matrix

Falsification	Major	Moderate	Minor

Percent 0%

Matrix Notes

Human health or the environment will or could be exposed to significant amounts of pollutants which would not exceed levels that are protective of human health or environmental receptors as a result of the violation.

Adjustment \$9,000

\$1,000

Violation Events

Number of Violation Events 1

23 Number of violation days

daily	
weekly	
monthly	x
quarterly	
semiannual	
annual	
single event	

mark only one with an x

Violation Base Penalty \$1,000

One monthly event is recommended based on documentation of the violation during the March 27, 2012 record review date to the April 19, 2012 screening date.

Good Faith Efforts to Comply

0.0% Reduction

\$0

	Before NOV	NOV to EDRP/Settlement Offer
Extraordinary		
Ordinary		
N/A	x	(mark with x)

Notes

The Respondent does not meet the good faith criteria for this violation.

Violation Subtotal \$1,000

Economic Benefit (EB) for this violation

Statutory Limit Test

Estimated EB Amount \$110

Violation Final Penalty Total \$1,087

This violation Final Assessed Penalty (adjusted for limits) \$1,087

Economic Benefit Worksheet

Respondent Jack A. Terhune dba Jack's Flying Service
Case ID No. 44020
Req. Ent. Reference No. RN102037470
Media Petroleum Storage Tank
Violation No. 6

Percent Interest	Years of Depreciation
5.0	15

Item Description	Item Cost	Date Required	Final Date	Yrs	Interest Saved	Onetime Costs	EB Amount
No commas or \$							

Delayed Costs

Equipment	\$1,000	9-Jun-2011	31-Dec-2012	1.56	\$5	\$104	\$110
Buildings				0.00	\$0	\$0	\$0
Other (as needed)				0.00	\$0	\$0	\$0
Engineering/construction				0.00	\$0	\$0	\$0
Land				0.00	\$0	n/a	\$0
Record Keeping System				0.00	\$0	n/a	\$0
Training/Sampling				0.00	\$0	n/a	\$0
Remediation/Disposal				0.00	\$0	n/a	\$0
Permit Costs				0.00	\$0	n/a	\$0
Other (as needed)				0.00	\$0	n/a	\$0

Notes for DELAYED costs

Estimated cost to equip the UST with spill containment and overfill prevention equipment. The Date Required is the investigation date and the Final Date is the estimated date of compliance.

Avoided Costs

ANNUALIZE [1] avoided costs before entering item (except for one-time avoided costs)

Disposal				0.00	\$0	\$0	\$0
Personnel				0.00	\$0	\$0	\$0
Inspection/Reporting/Sampling				0.00	\$0	\$0	\$0
Supplies/equipment				0.00	\$0	\$0	\$0
Financial Assurance [2]				0.00	\$0	\$0	\$0
ONE-TIME avoided costs [3]				0.00	\$0	\$0	\$0
Other (as needed)				0.00	\$0	\$0	\$0

Notes for AVOIDED costs

Approx. Cost of Compliance

\$1,000

TOTAL

\$110

Screening Date 19-Apr-2012

Docket No. 2012-0853-PST-E

PCW

Respondent Jack A. Terhune dba Jack's Flying Service

Policy Revision 2 (September 2002)

Case ID No. 44020

PCW Revision October 30, 2008

Reg. Ent. Reference No. RN102037470

Media [Statute] Petroleum Storage Tank

Enf. Coordinator Clinton Sims

Violation Number 7

Rule Cite(s) 30 Tex. Admin. Code § 334.10(b)

Violation Description Failed to maintain UST records and make them immediately available for inspection upon request by agency personnel.

Base Penalty \$10,000

>> Environmental, Property and Human Health Matrix

OR	Release	Harm			Percent
		Major	Moderate	Minor	
	Actual				0%
	Potential				

>> Programmatic Matrix

Matrix Notes	Falsification	Harm			Percent
		Major	Moderate	Minor	
		x			10%
100% of the rule requirement was not met.					

Adjustment \$9,000

\$1,000

Violation Events

		1	23	Number of violation days	
mark only one with an x	daily				
	weekly				
	monthly				
	quarterly				
	semiannual				
	annual				
	single event		x		

One single event is recommended.

Good Faith Efforts to Comply

	0.0%	Reduction	\$0
		Before NOV	NOV to EDPRP/Settlement Offer
Extraordinary			
Ordinary			
N/A	x	(mark with x)	
Notes	The Respondent does not meet the good faith criteria for this violation.		

Violation Subtotal \$1,000

Economic Benefit (EB) for this violation

Statutory Limit Test

Estimated EB Amount \$37 Violation Final Penalty Total \$1,087

This violation Final Assessed Penalty (adjusted for limits) \$1,087

Economic Benefit Worksheet

Respondent Jack A. Terhune dba Jack's Flying Service
Case ID No. 44020
Reg. Ent. Reference No. RN102037470
Media Petroleum Storage Tank
Violation No. 7

Percent Interest	Years of Depreciation
5.0	15

Item Description	Item Cost	Date Required	Final Date	Yrs	Interest Saved	Onetime Costs	EB Amount
No commas or \$							

Delayed Costs

Equipment				0.00	\$0	\$0	\$0
Buildings				0.00	\$0	\$0	\$0
Other (as needed)				0.00	\$0	\$0	\$0
Engineering/construction				0.00	\$0	\$0	\$0
Land				0.00	\$0	n/a	\$0
Record Keeping System	\$500	9-Jun-2011	1-Dec-2012	1.48	\$37	n/a	\$37
Training/Sampling				0.00	\$0	n/a	\$0
Remediation/Disposal				0.00	\$0	n/a	\$0
Permit Costs				0.00	\$0	n/a	\$0
Other (as needed)				0.00	\$0	n/a	\$0

Notes for DELAYED costs

Estimated cost to maintain UST records. The Date Required is the investigation date and the Final Date is the estimated date of compliance.

Avoided Costs

ANNUALIZE [1] avoided costs before entering item (except for one-time avoided costs)

Disposal				0.00	\$0	\$0	\$0
Personnel				0.00	\$0	\$0	\$0
Inspection/Reporting/Sampling				0.00	\$0	\$0	\$0
Supplies/equipment				0.00	\$0	\$0	\$0
Financial Assurance [2]				0.00	\$0	\$0	\$0
ONE-TIME avoided costs [3]				0.00	\$0	\$0	\$0
Other (as needed)				0.00	\$0	\$0	\$0

Notes for AVOIDED costs

Approx. Cost of Compliance

\$500

TOTAL

\$37

Compliance History Report

Customer/Respondent/Owner-Operator: CN601108020 Terhune, Jack A. Classification: AVERAGE Rating: 3.01

Regulated Entity: RN102037470 JACK'S FLYING SERVICE Classification: AVERAGE Site Rating: 3.01
BY DEFAULT

ID Number(s): PETROLEUM STORAGE TANK REGISTRATION 21641
REGISTRATION

Location: 11869 County Road J, PERRYTON, TX 79070

TCEQ Region: REGION 01 - AMARILLO

Date Compliance History Prepared: April 19, 2012

Agency Decision Requiring Compliance History: Enforcement

Compliance Period: April 19, 2007 to April 19, 2012

TCEQ Staff Member to Contact for Additional Information Regarding this Compliance History

Name: Clinton Sims Phone: (512) 239-6933

Site Compliance History Components

1. Has the site been in existence and/or operation for the full five year compliance period? YES
2. Has there been a (known) change in ownership/operator of the site during the compliance period? NO
3. If YES, who is the current owner/operator? N/A
4. If YES, who was/were the prior owner(s)/operator(s)? N/A
5. If YES, when did the change(s) in owner or operator occur? N/A
6. Rating Date: 9/1/2011 Repeat Violator: NO

Components (Multimedia) for the Site :

- A. Final Enforcement Orders, court judgments, and consent decrees of the State of Texas and the federal government.
N/A
 - B. Any criminal convictions of the state of Texas and the federal government.
N/A
 - C. Chronic excessive emissions events.
N/A
 - D. The approval dates of investigations. (CCEDS Inv. Track. No.)
1 03/27/2012 (988367)
 - E. Written notices of violations (NOV). (CCEDS Inv. Track. No.)
N/A
 - F. Environmental audits.
N/A
 - G. Type of environmental management systems (EMSs).
N/A
 - H. Voluntary on-site compliance assessment dates.
N/A
 - I. Participation in a voluntary pollution reduction program.
N/A
 - J. Early compliance.
N/A
- Sites Outside of Texas
N/A

TEXAS COMMISSION ON ENVIRONMENTAL QUALITY



**IN THE MATTER OF AN
ENFORCEMENT ACTION
CONCERNING
JACK A. TERHUNE DBA JACK'S
FLYING SERVICE
RN102037470**

§ **BEFORE THE**
§
§ **TEXAS COMMISSION ON**
§
§ **ENVIRONMENTAL QUALITY**

**AGREED ORDER
DOCKET NO. 2012-0853-PST-E**

I. JURISDICTION AND STIPULATIONS

On _____, the Texas Commission on Environmental Quality ("the Commission" or "TCEQ") considered this agreement of the parties, resolving an enforcement action regarding Jack A. Terhune dba Jack's Flying Service ("Respondent") under the authority of TEX. WATER CODE chs. 7 and 26. The Executive Director of the TCEQ, through the Enforcement Division, and the Respondent together stipulate that:

1. The Respondent owns and operates a fleet refueling facility at 11869 County Road J in Perryton, Ochiltree County, Texas (the "Facility").
2. The Respondent's one underground storage tanks ("UST") is not exempt or excluded from regulation under the Texas Water Code or the rules of the Commission.
3. The Executive Director and the Respondent agree that the Commission has jurisdiction to enter this Agreed Order, and that the Respondent is subject to the Commission's jurisdiction.
4. The Respondent received notice of the violations alleged in Section II ("Allegations") on or about April 1, 2012.
5. The occurrence of any violation is in dispute and the entry of this Agreed Order shall not constitute an admission by the Respondent of any violation alleged in Section II ("Allegations"), nor of any statute or rule.
6. An administrative penalty in the amount of Ten Thousand Three Hundred Twenty-Seven Dollars (\$10,327) is assessed by the Commission in settlement of the violations alleged in Section II ("Allegations"). The Respondent has paid Eight Thousand Two Hundred

Sixty-Two Dollars (\$8,262) of the administrative penalty and Two Thousand Sixty-Five Hundred Dollars (\$2,065) is deferred contingent upon the Respondent's timely and satisfactory compliance with all the terms of this Agreed Order. The deferred amount will be waived upon full compliance with the terms of this Agreed Order. If the Respondent fails to timely and satisfactorily comply with all requirements of this Agreed Order, the Executive Director may require the Respondent to pay all or part of the deferred penalty.

7. Any notice and procedures, which might otherwise be authorized or required in this action, are waived in the interest of a more timely resolution of the matter.
8. The Executive Director and the Respondent agree on a settlement of the matters alleged in this enforcement action, subject to final approval in accordance with 30 TEX. ADMIN. CODE § 70.10(a).
9. The Executive Director may, without further notice or hearing, refer this matter to the Office of the Attorney General of the State of Texas ("OAG") for further enforcement proceedings if the Executive Director determines that the Respondent has not complied with one or more of the terms or conditions in this Agreed Order.
10. This Agreed Order shall terminate five years from its effective date or upon compliance with all the terms and conditions set forth in this Agreed Order, whichever is later.
11. The provisions of this Agreed Order are deemed severable and, if a court of competent jurisdiction or other appropriate authority deems any provision of this Agreed Order unenforceable, the remaining provisions shall be valid and enforceable.

II. ALLEGATIONS

As owner and operator of the Facility, the Respondent is alleged to have:

1. Failed to submit a properly completed UST registration and self-certification form and obtain a delivery certificate in a timely manner, in violation of 30 TEX. ADMIN. CODE § 334.8(c)(4)(B) and (c)(5)(B)(ii), as documented during an investigation conducted on June 9, 2011 and a record review conducted on March 27, 2012.
2. Failed to make available to a common carrier a valid, current TCEQ delivery certificate before accepting delivery of a regulated substance into the UST, in violation of 30 TEX. ADMIN. CODE § 334.8(c)(5)(A)(i) and TEX. WATER CODE § 26.3467(a), as documented during an investigation conducted on June 9, 2011 and a record review conducted on March 27, 2012. Specifically, one fuel delivery was accepted without a delivery certificate.
3. Failed to demonstrate acceptable financial assurance for taking corrective action and for compensating third parties for bodily injury and property damage caused by accidental releases arising from the operation of the petroleum UST, in violation of 30 TEX. ADMIN. CODE § 37.815(a) and (b), as documented during an investigation conducted on June 9, 2011 and a record review conducted on March 27, 2012.

4. Failed to provide proper corrosion protection for the UST system, in violation of 30 TEX. ADMIN. CODE § 334.49(a)(1) and TEX. WATER CODE § 26.3475(d), as documented during an investigation conducted on June 9, 2011 and a record review conducted on March 27, 2012.
5. Failed to monitor the UST for releases at a frequency of at least once every month (not to exceed 35 days between each monitoring), in violation of 30 TEX. ADMIN. CODE § 334.50(b)(1)(A) and TEX. WATER CODE § 26.3475(c)(1), as documented during an investigation conducted on June 9, 2011 and a record review conducted on March 27, 2012.
6. Failed to provide release detection for the piping associated with the UST, in violation of 30 TEX. ADMIN. CODE § 334.50(b)(2) and TEX. WATER CODE § 26.3475(a), as documented during a investigation conducted on June 9, 2011 and a record review conducted on March 27, 2012. Specifically, the Respondent did not conduct the annual piping tightness test.
7. Failed to equip the UST with spill containment and overflow prevention equipment, in violation of 30 TEX. ADMIN. CODE § 334.51(b)(2) and TEX. WATER CODE § 26.3475(c)(2), as documented during an investigation conducted on June 9, 2011 and a record review conducted on March 27, 2012.
8. Failed to maintain UST records and make them immediately available for inspection upon request by agency personnel, in violation of 30 TEX. ADMIN. CODE § 334.10(b), as documented during an investigation conducted on June 9, 2011 and a record review conducted on March 27, 2012.

III. DENIALS

The Respondent generally denies each allegation in Section II ("Allegations").

IV. ORDERING PROVISIONS

1. It is, therefore, ordered by the TCEQ that the Respondent pay an administrative penalty as set forth in Section I, Paragraph 6 above. The payment of this administrative penalty and the Respondent's compliance with all the terms and conditions set forth in this Agreed Order resolve only the allegations in Section II. The Commission shall not be constrained in any manner from requiring corrective action or penalties for violations which are not raised here. Administrative penalty payments shall be made payable to "TCEQ" and shall be sent with the notation "Re: Jack A. Terhune dba Jack's Flying Service, Docket No. 2012-0853-PST-E" to:

Financial Administration Division, Revenues Section
Attention: Cashier's Office, MC 214
Texas Commission on Environmental Quality
P.O. Box 13088
Austin, Texas 78711-3088

2. It is further ordered that the Respondent shall undertake the following technical requirements:

a. Immediately upon the effective date of this Agreed Order:

- i. Cease accepting fuel until such time as a valid delivery certificate is obtained from the TCEQ by submitting a properly completed UST registration and self-certification form, in accordance with 30 TEX. ADMIN. CODE § 334.8; and
- ii. Begin maintaining all UST records and ensure they are made immediately available for inspection upon request by agency personnel, in accordance with 30 TEX. ADMIN. CODE § 334.10.

b. Within 30 days after the effective date of this Agreed Order:

- i. Submit documentation that demonstrates acceptable financial assurance for taking corrective action and for compensating third parties for bodily injury and property damage caused by accidental releases arising from the operation of the petroleum UST, in accordance with 30 TEX. ADMIN. CODE § 37.815;
- ii. Install a corrosion protection system and test the system, in accordance with 30 TEX. ADMIN. CODE § 334.49;
- iii. Implement a release detection method for the UST at the Facility and conduct the annual piping tightness test, in accordance with 30 TEX. ADMIN. CODE § 334.50; and
- iv. Equip the UST with spill containment and overfill prevention equipment, in accordance with 30 TEX. ADMIN. CODE § 334.51.

c. Within 45 days after the effective date of this Agreed Order, submit written certification as described below, and include detailed supporting documentation including photographs, receipts, and/or other records to demonstrate compliance with Ordering Provision Nos. 2.a.i. through 2.b.iv. The certification shall be notarized by a State of Texas Notary Public and include the following certification language:

"I certify under penalty of law that I have personally examined and am familiar with the information submitted and all attached documents, and that based on my inquiry of those individuals immediately responsible for obtaining the information, I believe that the submitted information is true, accurate and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fines and imprisonment for knowing violations."

The certification shall be submitted to:

Order Compliance Team
Enforcement Division, MC 149A
Texas Commission on Environmental Quality
P.O. Box 13087
Austin, Texas 78711-3087

with a copy to:

Waste Section Manager
Amarillo Regional Office
Texas Commission on Environmental Quality
3918 Canyon Drive
Amarillo, Texas 79109-4933

3. The provisions of this Agreed Order shall apply to and be binding upon the Respondent. The Respondent is ordered to give notice of the Agreed Order to personnel who maintain day-to-day control over the Facility operations referenced in this Agreed Order.
4. If the Respondent fails to comply with any of the Ordering Provisions in this Agreed Order within the prescribed schedules, and that failure is caused solely by an act of God, war, strike, riot, or other catastrophe, the Respondent's failure to comply is not a violation of this Agreed Order. The Respondent shall have the burden of establishing to the Executive Director's satisfaction that such an event has occurred. The Respondent shall notify the Executive Director within seven days after the Respondent becomes aware of a delaying event and shall take all reasonable measures to mitigate and minimize any delay.
5. The Executive Director may grant an extension of any deadline in this Agreed Order or in any plan, report, or other document submitted pursuant to this Agreed Order, upon a written and substantiated showing of good cause. All requests for extensions by the Respondent shall be made in writing to the Executive Director. Extensions are not effective until the Respondent receives written approval from the Executive Director. The determination of what constitutes good cause rests solely with the Executive Director.
6. This Agreed Order, issued by the Commission, shall not be admissible against the Respondent in a civil proceeding, unless the proceeding is brought by the OAG to: (1) enforce the terms of this Agreed Order; or (2) pursue violations of a statute within the Commission's jurisdiction, or of a rule adopted or an order or permit issued by the Commission under such a statute.
7. This Agreed Order may be executed in separate and multiple counterparts, which together shall constitute a single instrument. Any page of this Agreed Order may be copied, scanned, digitized, converted to electronic portable document format ("pdf"), or otherwise reproduced and may be transmitted by digital or electronic transmission, including but not limited to facsimile transmission and electronic mail. Any signature affixed to this Agreed Order shall constitute an original signature for all purposes and

may be used, filed, substituted, or issued for any purpose for which an original signature could be used. The term "signature" shall include manual signatures and true and accurate reproductions of manual signatures created, executed, endorsed, adopted, or authorized by the person or persons to whom the signatures are attributable. Signatures may be copied or reproduced digitally, electronically, by photocopying, engraving, imprinting, lithographing, electronic mail, facsimile transmission, stamping, or any other means or process which the Executive Director deems acceptable. In this paragraph exclusively, the terms "electronic transmission", "owner", "person", "writing", and "written" shall have the meanings assigned to them under TEX. BUS. ORG. CODE § 1.002.

8. Under 30 TEX. ADMIN. CODE § 70.10(b), the effective date is the date of hand-delivery of the Order to the Respondent, or three days after the date on which the Commission mails notice of the Order to the Respondent, whichever is earlier.

SIGNATURE PAGE

TEXAS COMMISSION ON ENVIRONMENTAL QUALITY

For the Commission

Pam Dawkins
For the Executive Director

2/8/13
Date

I, the undersigned, have read and understand the attached Agreed Order. I am authorized to agree to the attached Agreed Order on behalf of the entity indicated below my signature, and I do agree to the terms and conditions specified therein. I further acknowledge that the TCEQ, in accepting payment for the penalty amount, is materially relying on such representation.

I also understand that failure to comply with the Ordering Provisions, if any, in this order and/or failure to timely pay the penalty amount, may result in:

- A negative impact on compliance history;
- Greater scrutiny of any permit applications submitted;
- Referral of this case to the Attorney General's Office for contempt, injunctive relief, additional penalties, and/or attorney fees, or to a collection agency;
- Increased penalties in any future enforcement actions;
- Automatic referral to the Attorney General's Office of any future enforcement actions; and
- TCEQ seeking other relief as authorized by law.

In addition, any falsification of any compliance documents may result in criminal prosecution.

Jack A. Terhune
Signature

Aug 14, 2012
Date

Jack A Terhune
Name (Printed or typed)
Authorized Representative of
Jack A. Terhune dba Jack's Flying Service

Pres/owner
Title

Instructions: Send the original, signed Agreed Order with penalty payment to the Financial Administration Division, Revenues Section at the address in Section IV, Paragraph 1 of this Agreed Order.