

## **40 CFR Part 60, Subpart Q - Requirements Reference Tables**

### **Subpart Q Standards**

[§60.172\(a\)](#) Particulate matter standard for sintering machines

[§60.173\(a\)](#) SO<sub>2</sub> standard for roasters

[§60.174\(a\)](#) Visible emissions standard for sintering machines

[§60.174\(b\)](#) Visible emissions standard for affected facilities that use sulfuric plants to comply with the standard in §60.173

These relationship entry screens and flowcharts are for use by sources subject to the Texas Federal Operating Permits Program only and are subject to revision.

Last Modified: August 11, 1997