

Recreational Use Attainability Analysis of Cedar Creek (Segment 1209G)

Appendix 3

Photographic Record

*** Photos in JPEG format are available as an electronic supplement on the CD insert found in Appendix 5**

Photograph Number	Site Location	Date	Description	Direction Photo Taken
CeCrBruaaFS1 01-01	Field Survey #1 - FM 46 A	5/29/2010	View facing upstream at 30m	North
CeCrBruaaFS1 01-02	Field Survey #1 - FM 46 A	5/29/2010	View of left bank at 30m	East
CeCrBruaaFS1 01-03	Field Survey #1 - FM 46 A	5/29/2010	View facing downstream at 30m	South/Southeast
CeCrBruaaFS1 01-04	Field Survey #1 - FM 46 A	5/29/2010	View of right bank at 30m	West
CeCrBruaaFS1 01-05	Field Survey #1 - FM 46 A	5/29/2010	View of fence across water downstream of bridge	South/Southeast
CeCrBruaaFS1 02-01	Field Survey #2 - FM 46 B	5/29/2010	View facing upstream at 30m and view of gate across water	Southwest
CeCrBruaaFS1 02-02	Field Survey #2 - FM 46 B	5/29/2010	View of left bank at 30m	Northwest
CeCrBruaaFS1 02-03	Field Survey #2 - FM 46 B	5/29/2010	View facing downstream at 30m	Northeast
CeCrBruaaFS1 02-04	Field Survey #2 - FM 46 B	5/29/2010	View of right bank at 30m	Southeast
CeCrBruaaFS1 02-05	Field Survey #2 - FM 46 B	5/29/2010	View facing upstream at 130m	South/Southeast
CeCrBruaaFS1 02-06	Field Survey #2 - FM 46 B	5/29/2010	View of left bank at 130m	West/Southwest
CeCrBruaaFS1 02-07	Field Survey #2 - FM 46 B	5/29/2010	View facing downstream at 130m and gate across water	Northeast
CeCrBruaaFS1 02-08	Field Survey #2 - FM 46 B	5/29/2010	View of right bank at 130m	East
CeCrBruaaFS1 02-09	Field Survey #2 - FM 46 B	5/29/2010	View of cow above the stream on the right bank	East
CeCrBruaaFS1 02-10	Field Survey #2 - FM 46 B	5/29/2010	View of survey team taking flow	Northeast
CeCrBruaaFS1 03-01	Field Survey #3 - CR323	5/29/2010	View facing upstream at 150m at bridge and view of wood fence across water	North
CeCrBruaaFS1 03-02	Field Survey #3 - CR323	5/29/2010	View of left bank at 150m at bridge	East/Northeast
CeCrBruaaFS1 03-03	Field Survey #3 - CR323	5/29/2010	View facing downstream at 150m at bridge and view of wood fence across water	South
CeCrBruaaFS1 03-04	Field Survey #3 - CR323	5/29/2010	View of right bank at 150m at bridge	Southwest
CeCrBruaaFS1 04-01	Field Survey #4 - Cedar Creek Rd	5/29/2010	View of beetle moving dung across the road	South/Southeast
CeCrBruaaFS1 04-02	Field Survey #4 - Cedar Creek Rd	5/29/2010	View of another beetle moving dung across the road	Southeast
CeCrBruaaFS1 04-03	Field Survey #4 - Cedar Creek Rd	5/29/2010	View upstream at 30m and view of fence and log jam	Northwest
CeCrBruaaFS1 04-04	Field Survey #4 - Cedar Creek Rd	5/29/2010	View of left bank at 30m	North/Northeast
CeCrBruaaFS1 04-05	Field Survey #4 - Cedar Creek Rd	5/29/2010	View of downstream at 30m	Southeast
CeCrBruaaFS1 04-06	Field Survey #4 - Cedar Creek Rd	5/29/2010	View of right bank	Southwest
CeCrBruaaFS1 04-07	Field Survey #4 - Cedar Creek Rd	5/29/2010	View upstream at 150m	North

Photograph Number	Site Location	Date	Description	Direction Photo Taken
CeCrBruaaFS1 04-08	Field Survey #4 - Cedar Creek Rd	5/29/2010	View of left bank at 150m	East
CeCrBruaaFS1 04-09	Field Survey #4 - Cedar Creek Rd	5/29/2010	View downstream at 150m	South/Southeast
CeCrBruaaFS1 04-10	Field Survey #4 - Cedar Creek Rd	5/29/2010	View of right bank at 150m	West/Southwest
CeCrBruaaFS1 04-11	Field Survey #4 - Cedar Creek Rd	5/29/2010	View upstream at 210m	Northwest
CeCrBruaaFS1 04-12	Field Survey #4 - Cedar Creek Rd	5/29/2010	View of left bank at 210m	Northeast
CeCrBruaaFS1 04-13	Field Survey #4 - Cedar Creek Rd	5/29/2010	View of downstream at 210m	East/Southeast
CeCrBruaaFS1 04-14	Field Survey #4 - Cedar Creek Rd	5/29/2010	View of right bank at 210m	South
CeCrBruaaFS1 04-15	Field Survey #4 - Cedar Creek Rd	5/29/2010	View of fence/log jam at 220m	East
CeCrBruaaFS1 05-01	Field Survey #5 -Old Spanish Rd	5/29/2010	View of fishing line attached to PVC pipe on the left bank	Northeast
CeCrBruaaFS1 05-02	Field Survey #5 -Old Spanish Rd	5/29/2010	View facing upstream at 130m	West/Northwest
CeCrBruaaFS1 05-03	Field Survey #5 -Old Spanish Rd	5/29/2010	View of left bank at 130m	Northeast
CeCrBruaaFS1 05-04	Field Survey #5 -Old Spanish Rd	5/29/2010	View facing downsream at 130m	East/Southeast
CeCrBruaaFS1 05-05	Field Survey #5 -Old Spanish Rd	5/29/2010	View of right bank at 130m	South/Southeast
CeCrBruaaFS1 05-06	Field Survey #5 -Old Spanish Rd	5/29/2010	View facing upstream at 150m	North/Northeast
CeCrBruaaFS1 05-07	Field Survey #5 -Old Spanish Rd	5/29/2010	View of left bank at 150	East
CeCrBruaaFS1 05-08	Field Survey #5 -Old Spanish Rd	5/29/2010	View facing downstream at 150m	South/Southeast
CeCrBruaaFS1 05-09	Field Survey #5 -Old Spanish Rd	5/29/2010	View of right bank at 150m	West/Southwest
CeCrBruaaFS1 05-10	Field Survey #5 -Old Spanish Rd	5/29/2010	View facing upstream at 170m	North/Northeast
CeCrBruaaFS1 05-11	Field Survey #5 -Old Spanish Rd	5/29/2010	View of left bank at 170m	East/Southeast
CeCrBruaaFS1 05-12	Field Survey #5 -Old Spanish Rd	5/29/2010	View facing downstream at 170m	South
CeCrBruaaFS1 05-13	Field Survey #5 -Old Spanish Rd	5/29/2010	View of right bank at 170m	West/Northwest
CeCrBruaaFS1 06-01	Field Survey #6 - FM974	5/29/2010	View facing upstream at 50m	West/Southwest
CeCrBruaaFS1 06-02	Field Survey #6 - FM974	5/29/2010	View of left bank at 50m	Northwest
CeCrBruaaFS1 06-03	Field Survey #6 - FM974	5/29/2010	View facing downstream at 50m	Northeast
CeCrBruaaFS1 06-04	Field Survey #6 - FM974	5/29/2010	View of right bank at 50m	Southeast
CeCrBruaaFS1 06-05	Field Survey #6 - FM974	5/29/2010	View facing upstream at 150m	Northwest

Photograph Number	Site Location	Date	Description	Direction Photo Taken
CeCrBruaaFS1 06-06	Field Survey #6 - FM974	5/29/2010	View of left bank at 150m	North/Northeast
CeCrBruaaFS1 06-07	Field Survey #6 - FM974	5/29/2010	View facing downstream at 150m	East/Southeast
CeCrBruaaFS1 06-08	Field Survey #6 - FM974	5/29/2010	View of right bank at 150m	South/Southeast
CeCrBruaaFS1 06-09	Field Survey #6 - FM974	5/29/2010	View facing upstream at 240m	Northwest
CeCrBruaaFS1 06-10	Field Survey #6 - FM974	5/29/2010	View of left bank at 240m	Northeast
CeCrBruaaFS1 06-11	Field Survey #6 - FM974	5/29/2010	View facing downstream at 240m	Southeast
CeCrBruaaFS1 06-12	Field Survey #6 - FM974	5/29/2010	View of right bank at 240m	South/Southwest
CeCrBruaaFS1 07-01	Field Survey #7 - SH21	5/29/2010	View of L. Ray interviewing fisherman on right bank	South/Southeast
CeCrBruaaFS1 07-02	Field Survey #7 - SH21	5/29/2010	View of woman behind limbs fishing on right bank	South/Southeast
CeCrBruaaFS1 07-03	Field Survey #7 - SH21	5/29/2010	View of fisherman couple next to creek on right bank	South/Southeast
CeCrBruaaFS1 07-04	Field Survey #7 - SH21	5/29/2010	View facing upstream at 150m	Southwest
CeCrBruaaFS1 07-05	Field Survey #7 - SH21	5/29/2010	View of left bank at 150m	Northwest
CeCrBruaaFS1 07-06	Field Survey #7 - SH21	5/29/2010	View facing downstream at 150m	Northeast
CeCrBruaaFS1 07-07	Field Survey #7 - SH21	5/29/2010	View of right bank at 150m	South/Southeast
CeCrBruaaFS1 07-08	Field Survey #7 - SH21	5/29/2010	View facing upstream at 185m	Southwest
CeCrBruaaFS1 07-09	Field Survey #7 - SH21	5/29/2010	View of left bank at 185m	Northwest
CeCrBruaaFS1 07-10	Field Survey #7 - SH21	5/29/2010	View facing downstream at 185m	Northeast
CeCrBruaaFS1 07-11	Field Survey #7 - SH21	5/29/2010	View of right bank at 185m	South/Southeast
CeCrBruaaRecon01-01	Recon Site #1 - Cedar Creek Rd	1/13/2010	View upstream from middle of bridge	North/Northeast
CeCrBruaaRecon01-02	Recon Site #1 - Cedar Creek Rd	1/13/2010	View of right bank from upstream side of bridge	North/Northeast
CeCrBruaaRecon01-03	Recon Site #1 - Cedar Creek Rd	1/13/2010	View downstream from middle of bridge	North/Northeast
CeCrBruaaRecon01-04	Recon Site #1 - Cedar Creek Rd	1/13/2010	View of left bank from upstream side of bridge	North/Northeast
CeCrBruaaRecon01-05	Recon Site #1 - Cedar Creek Rd	1/13/2010	View of right bank from right bank upstream side of bridge	North/Northeast
CeCrBruaaRecon02-01	Recon Site #2 - Old Spanish Rd	1/13/2010	View upstream from left bank downstream of bridge	North/Northeast
CeCrBruaaRecon02-02	Recon Site #2 - Old Spanish Rd	1/13/2010	View of right bank from left bank downstream of bridge	Northeast
CeCrBruaaRecon02-03	Recon Site #2 - Old Spanish Rd	1/13/2010	View downstream from left bank downstream of bridge	Southeast

Photograph Number	Site Location	Date	Description	Direction Photo Taken
CeCrBruaaRecon02-04	Recon Site #2 - Old Spanish Rd	1/13/2010	View of left bank from left bank downstream of bridge	Vertical
CeCrBruaaRecon03-01	Recon Site #3 - FM974	1/13/2010	View upstream from middle of bridge	West/Southwest
CeCrBruaaRecon03-02	Recon Site #3 - FM974	1/13/2010	View of right bank from downstream side of bridge	Northeast
CeCrBruaaRecon03-03	Recon Site #3 - FM974	1/13/2010	View downstream from middle of bridge	East
CeCrBruaaRecon03-04	Recon Site #3 - FM974	1/13/2010	View of left bank from downstream side of bridge	Southwest
CeCrBruaaRecon03-05	Recon Site #3 - FM974	1/13/2010	View of narrow slide to water downstream right bank	West/Southwest
CeCrBruaaRecon03-06	Recon Site #3 - FM974	1/13/2010	View of worms and beer can on upstream right bank	Vertical
CeCrBruaaRecon04-01	Recon Site #4 - Dilly Shaw Tap Rd	1/13/2010	View upstream from middle of bridge	West/Northwest
CeCrBruaaRecon04-02	Recon Site #4 - Dilly Shaw Tap Rd	1/13/2010	View of right bank from downstream side of bridge	South/Southeast
CeCrBruaaRecon04-03	Recon Site #4 - Dilly Shaw Tap Rd	1/13/2010	View downstream from middle of bridge	East
CeCrBruaaRecon04-04	Recon Site #4 - Dilly Shaw Tap Rd	1/13/2010	View of left bank from downstream side of bridge	South/Southeast
CeCrBruaaRecon04-05	Recon Site #4 - Dilly Shaw Tap Rd	1/13/2010	Vertical view of dead dog on downstream side left bank	Vertical
CeCrBruaaRecon05-01	Recon Site #5 - Tauber Ranch Rd	1/13/2010	View of closed gate	East/Northeast
CeCrBruaaRecon06-01	Recon Site #6 - TCEQ Sta 11787 - SH21	1/13/2010	View of Brazos River Authority water gauge from upstream right bank	Southwest
CeCrBruaaRecon06-02	Recon Site #6 - TCEQ Sta 11787 - SH21	1/13/2010	View upstream from right bank upstream side of bridge	Southwest
CeCrBruaaRecon06-03	Recon Site #6 - TCEQ Sta 11787 - SH21	1/13/2010	View of right bank from right bank upstream side of bridge	Vertical
CeCrBruaaRecon06-04	Recon Site #6 - TCEQ Sta 11787 - SH21	1/13/2010	View downstream from right bank upstream side of bridge	East
CeCrBruaaRecon06-05	Recon Site #6 - TCEQ Sta 11787 - SH21	1/13/2010	View of left bank from right bank upstream side of bridge	South/Southeast
CeCrBruaaRecon06-06	Recon Site #6 - TCEQ Sta 11787 - SH21	1/13/2010	View of footpath on right bank taken from upstream	North/Northeast



CeCrBruaaFS1 01-01



CeCrBruaaFS1 01-02



CeCrBruaaFS1 01-03



CeCrBruaaFS1 01-04



CeCrBruaaFS1 01-05



CeCrBruaaFS1 02-01



CeCrBruaaFS1 02-02



CeCrBruaaFS1 02-03



CeCrBruaaFS1 02-04



CeCrBruaaFS1 02-05



CeCrBruaaFS1 02-06



CeCrBruaaFS1 02-07



CeCrBruaaFS1 02-08



CeCrBruaaFS1 02-09



CeCrBruaaFS1 02-10



CeCrBruaaFS1 03-01



CeCrBruaaFS1 03-02



CeCrBruaaFS1 03-03



CeCrBruaaFS1 03-04



CeCrBruaaFS1 04-01



CeCrBruaaFS1 04-02



CeCrBruaaFS1 04-03



CeCrBruaaFS1 04-04



CeCrBruaaFS1 04-05



CeCrBruaaFS1 04-06



CeCrBruaaFS1 04-07



CeCrBruaaFS1 04-08



CeCrBruaaFS1 04-09



CeCrBruaaFS1 04-10



CeCrBruaaFS1 04-11



CeCrBruaaFS1 04-12



CeCrBruaaFS1 04-13



CeCrBruaaFS1 04-14



CeCrBruaaFS1 04-15



CeCrBruaaFS1 05-01



CeCrBruaaFS1 05-02



CeCrBruaaFS1 05-03



CeCrBruaaFS1 05-04



CeCrBruaaFS1 05-05



CeCrBruaaFS1 05-06



CeCrBruaaFS1 05-07



CeCrBruaaFS1 05-08



CeCrBruaaFS1 05-09



CeCrBruaaFS1 05-10



CeCrBruaaFS1 05-11



CeCrBruaaFS1 05-12



CeCrBruaaFS1 05-13



CeCrBruaaFS1 06-01



CeCrBruaaFS1 06-02



CeCrBruaaFS1 06-03



CeCrBruaaFS1 06-04



CeCrBruaaFS1 06-05



CeCrBruaaFS1 06-06



CeCrBruaaFS1 06-07



CeCrBruaaFS1 06-08



CeCrBruaaFS1 06-09



CeCrBruaaFS1 06-10



CeCrBruaaFS1 06-11



CeCrBruaaFS1 06-12



CeCrBruaaFS1 07-01



CeCrBruaaFS1 07-02



CeCrBruaaFS1 07-03



CeCrBruaaFS1 07-04



CeCrBruaaFS1 07-05



CeCrBruaaFS1 07-06



CeCrBruaaFS1 07-07



CeCrBruaaFS1 07-08



CeCrBruaaFS1 07-09



CeCrBruaaFS1 07-10



CeCrBruaaFS1 07-11

