

Texas Commission on Environmental Quality Cross-Connection Control Subcommittee

June 6, 2019

Building F, Room 2210

Time: 9:00 – 3:00

- 9:00 Announcements Mr. Charlie Middleton
Introductions
Adoption of previous meeting summary
- 9:15 Program Updates:
- Cross-Connection Control Program Mr. Charlie Middleton
 - Landscape Irrigation Mr. Al Fuentes
 - IAC Rule Petition Update Mr. Al Fuentes
 - Occupational Licensing Ms. Linda Saladino/Ms. Tamara Calhoun
 - BPAT and CSI experience considerations and process for licensing.
- 10:30 Break
- 10:45 LF 289 Spill-Resistant AVB: point-of-use untestable device, stamped as “SVB”, let’s have a look.
- 11:00 DIY Sprinkler Systems Mr. James Garvin
- 11:30 Annual testing requirements. Are purveyors using the most recent test date, installation date, or date of first test to determine the due date of the next test? Mr. Charlie Middleton
- 12:00 Working Lunch
- BPATs and/or CSIs representing themselves as TCEQ inspectors.
 - Impact of potential Plumbing Board dissolution on Cross-Connection Control
 - Topics for next meeting?
- 1:00 Group Discussion:
- BPAT tests an RP, the RP passes, both checks held tight with adequate pressure, etc. However, the tester checks the NO box for “Is the assembly installed in accordance with the manufacturers recommendations and/or local codes” and checks the “TEST RESULT” box as **failed**.
- Should this be a failed test? Thoughts?

1:30 Licensed plumbers who have a WSPS conducting a TCEQ required CSI on their own plumbing work.

2:00 Cross Connection Control Program Surveys

Ms. Katherine McGlaughlin

2:30 Other Topics to Discuss?

3:00 Adjourn