# Ballard Pits State Superfund Site



## Commissioners

Buddy Garcia, Chairman

Larry R. Soward

Bryan Shaw, Ph.D.

### **Executive Director**

Mark Vickery
P.O. Box 13087
Austin, Texas
78711-3087
1-800-633-9363

Si tiene alguna pregunta o necesita informacion adicional favor de llamar al 1-800-633-9363 y hable con John Flores

# Site Update

#### West Pit

Texas Commission Environmental Quality (TCEQ) completed removal activities in the West Pit in 2008. total. the TCEQ disposed approximately 16,000 tons of waste materials generated from the cleanup of the West Pit in an approved waste After removal and disposal facility. disposal of the waste material, the West Pit was filled to grade with clean soil and the original monitoring wells displaced by the removal activities were reestablished.

# East Pit

The TCEQ performed additional investigation of the East Pit to reexamine the remaining waste and the options for cleanup and is gearing up to begin removal activities at the East Pit soon. Similar to the removal activities in the West Pit, the TCEQ and its contractor will be excavating the waste material from the East Pit, mixing it with cement kiln dust to make it more solid, and transporting it to an approved waste disposal facility.

TCEQ's contractor is currently preparing the Site for removal activities. This includes construction of the berm around the pit, the mobilization of equipment, and road work within the Ballard property. Road work is necessary to ensure the dump trucks and other heavy equipment that will eventually excavate and transport the contaminated material from the East Pit have suitable road surface.

# Other Site Updates

TCEQ worked with our contractor to secure the Site in preparation for the 2008 hurricane season. The pits were inspected following Hurricanes Dolly and Ike and no adverse impacts to the Site were reported. In preparation for this hurricane season, a Hurricane Contingency Plan has been added to the onsite Health & Safety Plan.

The TCEQ continues to sample area wells to monitor for movement of contamination away from the Site. The residential wells adjacent to the pits and Site monitoring wells were sampled in November and December 2008 and again in March 2009.

Analytical results from the November 2008 sampling event indicated the possible contamination of two residential wells adjacent to the pits. The chemical bis(2-ethylhexyl)phthalate, factured chemical that is commonly added to plastics, was detected above the health based level set by the U.S. Environmental Protection Agency. Although detection of this chemical is believed to be associated with the type of sampling equipment used and not related to the Site, filtration systems were installed on both wells as a precaution.

To date, no groundwater impacts from contaminants of concern attributable to the site have been observed in residential water wells.

#### Site Contacts

Omar Valdez
Project Manager
P. O. Box 13087, MC-136
Austin, Texas 78711-3087
Tel. 1-800-633-9363 ext. 6547

Cullen McMorrow
Site Attorney
P. O. Box 13087, MC-175
Austin, Texas 78711-3087
Tel. 1-800-633-9363 ext. 0607

Kelly Peavler
Community Relations Liaison
P. O. Box 13087, MC-142
Austin, Texas 78711-3087
Tel. 1-800-633-9363 ext. 1352

#### Information Repositories

TCEQ Records Management Center
Building E, First Floor
12100 Park 35 Circle
Austin, Texas 78753

(512) 239-2920

Corpus Christi Public Library

Northwest Branch

3202 McKinzie Road

Corpus Christi, Texas 78410

(361) 241-9329

Internet address:

www.tceq.state.tx.us/remediation /superfund/index.html

# Announcement

The Texas Commission on Environmental Quality has been invited to attend the Nueces County Commissioner's bi-monthly meeting on May 20<sup>th</sup> to provide an update on the Ballard Pits site. The meeting is scheduled for 9:00 am at the Nueces County Courthouse at 901 Leopard Street, Corpus Christi, Texas 78401.