

**From:** Jonathan Walling  
**To:** Terry Baxter<[Terry.Baxter@SPR.DOE.GOV](mailto:Terry.Baxter@SPR.DOE.GOV)>  
**Cc:** OCE  
**Subject:** U.S. Dept. of Energy, Strategic Petroleum Reserve, Big Hill facility - Request for Extended Delay of BHT-7 Tank Seal Inspection  
**Date:** Thursday, June 4, 2020 10:31:27 AM  
**Attachments:** [BHT-7 Enforcement Discretion Request.pdf](#)  
**Importance:** High

---

Good morning Mr. Baxter

Your request to delay the semi-annual seal inspection of external floating roof tank BHT-7 as required by 30 TAC §115.114 40 CFR §60.113b and New Source Review Permit No. 9256 at the U.S. Department of Energy- Big Hill Facility is approved and will be valid until September 30 2020. The inspection shall be completed as soon as practicable before this date.

Enforcement discretion is limited to the Texas Commission on Environmental Quality. It does not limit EPA's ability to enforce federal regulations.

Regulated entities must maintain records adequate to document activities related to the noncompliance under enforcement discretion including details of the regulated entity's best efforts to comply.

Regards

Jonathan Walling Area Director  
Coastal & East Texas Area  
Texas Commission on Environmental Quality

---

**From:** Baxter Terry <[Terry.Baxter@SPR.DOE.GOV](mailto:Terry.Baxter@SPR.DOE.GOV)>  
**Sent:** Wednesday June 3 2020 1 23 PM  
**To:** Ramiro Garcia <[ramiro.garcia@tceq.texas.gov](mailto:ramiro.garcia@tceq.texas.gov)>  
**Cc:** Jonathan Walling <[jonathan.walling@tceq.texas.gov](mailto:jonathan.walling@tceq.texas.gov)>  
**Subject:** U.S. Dept. of Energy Strategic Petroleum Reserve Big Hill facility - Request for Extended Delay of BHT-7 Tank Seal Inspection  
**Importance:** High

Mr. Ramiro Garcia Jr. Deputy Director  
Texas Commission on Environmental Quality  
Office of Compliance and Enforcement MC 172

Dear Mr. Garcia

Please find attached a request from the U.S. Department of Energy Strategic Petroleum Reserve to extend the delay of the semi-annual seal inspection of the Big Hill external floating roof tank (BHT-7) until September 30 2020. This request for TCEQ Enforcement Discretion is needed due to the COVID-19 Pandemic and the current mandatory crude oil fill of the Big Hill facility as ordered by the President of the United States.

If you have any questions please e-mail or call me at (225) 892-9661.

Thank you

Terry Baxter

---

Terry Baxter | Fluor Federal Petroleum Operations LLC | Air Quality Specialist Environmental | Contractor to the U. S. Department of Energy SPR | [Terry.Baxter@spr.doe.gov](mailto:Terry.Baxter@spr.doe.gov)  
O 504.734.4193|F 504.818.5193|850 S. Clearview Parkway New Orleans LA 70123

CONFIDENTIALITY NOTICE The information transmitted in this message is intended only for the person(s) or entity to whom it is addressed and may contain proprietary business-confidential and/or privileged material. Any unauthorized review use or distribution is prohibited. If you are not the intended recipient please contact the sender by reply e-mail and destroy all copies of the original message.

---

**From:** Jonathan Walling <[jonathan.walling@tceq.texas.gov](mailto:jonathan.walling@tceq.texas.gov)>  
**Sent:** Thursday April 16 2020 2 19 PM  
**To:** Baxter Terry <[Terry.Baxter@SPR.DOE.GOV](mailto:Terry.Baxter@SPR.DOE.GOV)>  
**Cc:** OCE <[OCE@tceq.texas.gov](mailto:OCE@tceq.texas.gov)>  
**Subject:** U.S. Dept. of Energy Strategic Petroleum Reserve Big Hill facility - Delayed BHT-7 Tank Seal Inspection  
**Importance:** High

Good afternoon Mr. Baxter

Your request for enforcement discretion as presented relating to the delay in conducting a semi-annual seal inspection of external floating roof tank BHT-7 at Strategic Petroleum Reserve- Big Hill Facility as required by 30 TAC §115.114 40 CFR §60.113b and New Source Review Permit No. 9256 is approved with the following qualifications

- Enforcement discretion is limited to the Texas Commission on Environmental Quality. It does not limit EPA's ability to enforce federal regulations; and
- This enforcement discretion will be in effect until July 15 2020. The required inspection should be completed as soon as practicable as conditions allow before this date. **Should an extension beyond this be needed please re-submit your request.** Subsequent inspections shall be based on the actual test date.

Regulated entities must maintain records adequate to document activities related to the noncompliance under enforcement discretion including details of the regulated entity's best efforts to comply.

Regards

Jonathan Walling Area Director  
Coastal & East Texas Area  
Texas Commission on Environmental Quality

---

**From:** Baxter Terry <[Terry.Baxter@SPR.DOE.GOV](mailto:Terry.Baxter@SPR.DOE.GOV)>  
**Sent:** Thursday April 16 2020 10 23 AM  
**To:** Ramiro Garcia <[ramiro.garcia@tceq.texas.gov](mailto:ramiro.garcia@tceq.texas.gov)>; OCE <[OCE@tceq.texas.gov](mailto:OCE@tceq.texas.gov)>  
**Subject:** U.S. Dept. of Energy Strategic Petroleum Reserve Big Hill facility - Delayed BHT-7 Tank Seal Inspection  
**Importance:** High

Mr. Ramiro Garcia Jr. Deputy Director  
Texas Commission on Environmental Quality  
Office of Compliance and Enforcement MC 172

Dear Mr. Garcia

Please find attached a request from the U.S. Department of Energy Strategic Petroleum Reserve to delay the semi-annual seal inspection of the Big Hill external floating roof tank (BHT-7) due to the COVID-19 Pandemic.

If you have any questions please e-mail or call me at (225) 892-9661.

Thank you

Terry Baxter

---

Terry Baxter | [Fluor Federal Petroleum Operations, LLC](#) | Air Quality Specialist, Environmental | Contractor to the U. S. Department of Energy SPR | [Terry.Baxter@spr.doe.gov](mailto:Terry.Baxter@spr.doe.gov)  
O 504.734.4193|F 504.818.5193|850 S. Clearview Parkway, New Orleans, LA 70123

CONFIDENTIALITY NOTICE: The information transmitted in this message is intended only for the person(s) or entity to whom it is addressed and may contain proprietary, business-confidential and/or privileged material. Any unauthorized review, use, or distribution is prohibited. If you are not the intended recipient, please contact the sender by reply e-mail and destroy all copies of the original message.



June 3, 2020  
31016-TAB-20-039

Mr. Ramiro Garcia, Jr., Deputy Director  
Texas Commission on Environmental Quality  
Office of Compliance and Enforcement, MC 172  
P.O. Box 13087  
Austin, TX 78711-3087

Dear Mr. Garcia:

Subject: COVID-19 Pandemic Delay of Semi-Annual Secondary Seal Inspection on External Floating Roof Tank at U.S. Department of Energy - Strategic Petroleum Reserve, Big Hill Facility, Permit No. 9256

On behalf of the U.S. Department of Energy (owner, operator, and permittee), Fluor Federal Petroleum Operations, LLC (Management and Operations Contractor for the Strategic Petroleum Reserve) submits this request to extend the delay of the semi-annual secondary seal inspection of the Big Hill external floating roof tank (BHT-7) until September 30, 2020. TCEQ approved our original request for enforcement discretion on April 16, 2020.

Due to the COVID-19 Pandemic, [REDACTED]

[REDACTED] Additionally, tank BHT-7 is being utilized to receive crude oil until August 31, 2020, due to the mandatory fill of the Strategic Petroleum Reserve facilities as ordered by the President of the United States.

The citation of rule for which enforcement discretion is requested is 30 TAC §115.114 – Storage of Volatile Organic Compounds, Inspection, and Repair Requirements. BHT-7 is an external floating roof crude oil surge tank, located in the Beaumont-Port Arthur area. This regulation requires that the secondary seals are visually inspected at least once every six months. Subsequent semi-annual inspections will commence accordingly based on this new schedule.

Please call Mr. Terry Baxter at (225) 892-9661 should you require additional information.

Sincerely,

*Robert Sevcik*

Robert Sevcik  
Director  
Environmental and Sustainability