

2008 Water Bodies and Impairments Added to the Texas 303(d) List (March 19, 2008)

Explanation of Column Headings

SegID and Name: The unique identifier (SegID), segment name, and location of the water body. The SegID may be one of two types of numbers. The first type is a classified segment number (4 digits, *e.g.* 0218), as defined in the Texas Surface Water Quality Standards. The second type is an unclassified water body (0218A), not defined in the Standards, though associated with a classified water body because it is in the same watershed. The segment name and description immediately follow SegID.

Parameter(s): Pollutants or water quality conditions that assessment procedures indicate do not meet assigned water quality standards.

Category: On this report, one of three categories is assigned to each combination of parameter and water body to provide information about the water quality status and management activities. The categories are defined below:

Category 5: The water body does not meet applicable water quality standards or is threatened for one or more designated uses by one or more pollutants.

Category 5a - A TMDL is underway, scheduled, or will be scheduled.

Category 5b - A review of the water quality standards for this water body will be conducted before a TMDL is scheduled.

Category 5c - Additional data and information will be collected before a TMDL is scheduled.

SegID	Segment Name	Parameter	Category
0306	Upper South Sulphur River	pH	5b
0407	James' Bayou	pH	5b
0507	Lake Tawakoni	pH	5c
0606	Neches River Above Lake Palestine	bacteria	5c
0607	Pine Island Bayou	bacteria	5c
0803	Lake Livingston	pH	5c
0819	East Fork Trinity River	sulfate	5b
0819	East Fork Trinity River	total dissolved solids	5b
0819	East Fork Trinity River	chloride	5b
0901	Cedar Bayou Tidal	PCBs in edible tissue	5a
1205	Lake Granbury	chloride	5c
1206	Brazos River Below Possum Kingdom Lake	impaired macrobenthic community	5c
1208	Brazos River Above Possum Kingdom Lake	bacteria	5c
1212	Somerville Lake	depressed dissolved oxygen	5c
1214	San Gabriel River	chloride	5c

2008 Water Bodies and Impairments Added to the Texas 303(d) List (March 19, 2008)

SegID	Segment Name	Parameter	Category
1223	Leon River Below Leon Reservoir	depressed dissolved oxygen	5c
1229	Paluxy River /North Paluxy River	sulfate	5c
1229	Paluxy River /North Paluxy River	total dissolved solids	5c
1229	Paluxy River /North Paluxy River	chloride	5c
1255	Upper North Bosque River	depressed dissolved oxygen	5c
1402H	Skull Creek (unclassified water body)	depressed dissolved oxygen	5b
1412	Colorado River Below Lake J. B. Thomas	bacteria	5c
1413	Lake J. B. Thomas	chloride	5c
1416	San Saba River	bacteria	5c
1421	Concho River	bacteria	5c
1421	Concho River	depressed dissolved oxygen	5c
1602	Lavaca River Above Tidal	bacteria	5c
2117	Frio River Above Choke Canyon Reservoir	bacteria	5c
2201	Arroyo Colorado Tidal	mercury in edible tissue	5c
2201	Arroyo Colorado Tidal	PCBs in edible tissue	5c
2202	Arroyo Colorado Above Tidal	PCBs in edible tissue	5c
2202	Arroyo Colorado Above Tidal	mercury in edible tissue	5c