

JONES ROAD GROUNDWATER PLUME SITE QUARTERLY SAMPLING RESULTS																					Updated: July 1, 2008	
Location ID	May '03	Aug. '03	Nov. '03	Feb. '04	May '04	Aug. '04	Nov. '04	Feb. '05	May '05	Aug. '05	Nov. '05	Feb. '06	May/ Jul. '06	Aug. '06	Nov. '06	Feb. '07	May '07	Aug. '07	Nov. '07	Feb. '08	May '08	Comments
AD11502	NS	NS	NS	NS	ND	NS	NS	NS	NS	NS	ND	NS	ND	NS	NS	NS	ND	NS	ND	NS	NS	
AD11511	NS	NS	NS	NS	ND	NS	NS	NS	NS	NS	NS	NS	NS	ND	NS	NS	NS	ND	NS	ND	NS	
AD11603	NS	NS	NS	NS	ND	NS	NS	NS	NS	NS	NS	NS	NS	ND	NS	NS	NS	ND	NS	ND	NS	
AD11619	NS	NS	NS	NS	ND	ND	ND	ND	ND	ND	ND	ND	NS	ND	ND	ND	ND	ND	ND	ND	ND	
AD11702	NS	NS	NS	NS	ND	NS	NS	NS	NS	NS	NS	NS	NS	ND	NS	NS	NS	ND	NS	NS	NS	
AD11714	NS	NS	NS	NS	ND	NS	NS	NS	NS	NS	NS	NS	NS	ND	NS	NS	NS	ND	NS	NS	NS	
BH11603	NS	NS	NS	NS	NS	ND	NS	NS	NS	NS	NS	NS	NS	ND	NS	NS	ND	NS	NS	NS	NS	
BH11614	NS	NS	NS	NS	NS	ND	NS	ND	NS	NS	ND	NS	ND	ND	NS	NS	ND	NS	NS	NS	NS	
BH11710	NS	NS	NS	NS	ND	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	May '06-no access
BL10810	NS	NS	ND	ND	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	
BL10818A	ND	ND	ND	ND	0.5	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	
BL10819	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	0.069 LJ	ND	ND	0.071 LJ	ND	ND	
BL10825	ND	ND	ND	ND	.5 J	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	UR	
CP11510	NS	NS	NS	NS	ND	ND	ND	ND	ND	ND	ND	ND	NS	NS	NS	NS	NS	NS	NS	NS	NS	
CP11610	NS	NS	NS	NS	ND	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	
CP11650	NS	NS	NS	NS	ND	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	
CP11710	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	
CP11711	NS	NS	NS	NS	NS	NS	ND	NS	NS	NS	NS	NS	NS	NS	NS	ND	NS	NS	NS	NS	NS	
CP11718	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	
DK11503	NS	NS	NS	NS	NS	ND	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	
DK11603	NS	NS	NS	NS	NS	NS	NS	ND	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	
DK11611	NS	NS	NS	NS	ND	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	
DK11702	NS	NS	NS	NS	NS	NS	NS	ND	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	
DK11703	NS	NS	NS	NS	NS	NS	NS	ND	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	
DK11707	NS	NS	NS	NS	NS	NS	NS	ND	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	
DK11710	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	
DK11718	NS	NS	NS	NS	ND	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	
DK11719	NS	NS	NS	NS	ND	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	
DM11502	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	
DM11506	NS	NS	NS	NS	NS	ND	NS	ND	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	
DM11507	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	
DM11509	NS	NS	NS	NS	NS	NS	NS	ND	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	
DM11513	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	
DM11515	NS	NS	NS	NS	NS	NS	NS	ND	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	
DM11715	NS	NS	NS	NS	ND	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	No access, unable to contact owner.
ES11610	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	NS	ND	ND	ND	ND	ND	NS	Gate Locked NS
ES11627	1.9	1.6	2.2	3.40	3.1 J	2.4	3	6.1	4.2	2.7	1.1	3.1	3.3	2.4	4.2	7.1	6	4	2.9	2.8	4.1	Filtration System added Feb. '05.
ES11630	NS	0.3 J	ND	ND	ND	1	ND	ND	0.99	0.17 J	1.6	1.4	1.9	1.0	1.1	0.63	1.1	0.97	0.95	0.75	1	
ES11643	0.3 J	ND	ND	.35 J	ND	ND	0.36 J	ND	0.57	0.84	0.86	0.55	0.76	0.56	0.5	0.41 LJ	0.59	0.95	1.3	0.58	0.69	
ES11703	NS	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	NS	NS	NS	NS	NS	NS	NS	NS	NS	Jul. '06, Aug. '06, Nov. '06, Feb '07, May '07, Aug '07, and Feb '08 - no power to well; house under construction.
ES11713	NS	NS	NS	NS	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	
ES11718	NS	NS	ND	ND	NS	ND	ND	ND	ND	ND	ND	ND	ND	NS	NS	NS	NS	NS	NS	NS	NS	Nov. '06 no access gate locked.
ES11730	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	
FB11502	NS	NS	NS	NS	NS	ND	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	
FB11506	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	Lot is gated. No access, unable to contact owner.
FB11607	NS	NS	NS	NS	ND	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	Nov. '06 & Feb '07 - sampling refused by owner.
FB11610	NS	NS	NS	NS	ND	NS	ND	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	May '06-no access
FB11614	NS	NS	NS	NS	ND	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	
FV11011	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	Shares Well with JR11535
FV11014	204	178	240	590	240	210	240	200	210	200	270	470	230	230	281	207	206	11.6	115	103	97	Filtration System
FV11022	36.2	53.2	48	42	36	57 J	40	37	38	57	45	44	47	52	62.2	64.8	42.3	43.4	64	57	74.1	Filtration System
FV11023	183	153	190	240	190	210	170	140	120	130	150	90	130	130	145	142	130	104	93.1	89.2	111	Filtration System
FV11025	NS	NS	NS	NS	5.5	7.3	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	Filtration System Refused by Owner. Sampling refused by owner as of Nov. '04
FV11102	NS	6.3	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	No access from owner, filtration system refused.
FV11110	0.6	0.9	0.68	0.81	ND	0.98	0.20 J	0.36 J	0.51	0.57	0.46 J	0.33 LJ	0.47 LJ	ND	0.32 LJ	0.35 LJ	ND	0.39 LJ	0.23 LJ	ND	ND	

JONES ROAD GROUNDWATER PLUME SITE QUARTERLY SAMPLING RESULTS																					Updated: July 1, 2008	
Location ID	May '03	Aug. '03	Nov. '03	Feb. '04	May '04	Aug. '04	Nov. '04	Feb. '05	May '05	Aug. '05	Nov. '05	Feb. '06	May/ Jul. '06	Aug. '06	Nov. '06	Feb. '07	May '07	Aug. '07	Nov. '07	Feb. '08	May '08	Comments
FV11118	ND	ND	ND	ND	ND	ND	ND	ND	ND	0.076 J	ND	ND	ND	ND	ND	0.069 LJ	ND	ND	0.10 LJ	ND	ND	Owner installed filtration system as of Feb. '06.
FV11123	ND	ND	0.23J	ND	ND	0.29 J	0.15 J	0.25 J	ND	0.16 J	0.15 J	ND	0.19 LJ	ND	0.10 LJ	0.13 LJ	ND	ND	0.12 LJ	ND	ND	
FV11127	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	
FV11130	11.3	5.3	8.1	10	7.6	4	3.2	6.9	4.8	5	7.9	3.7	9.9	11	14.6	17.5	31.6	36.6	40.4	45	59.5	Filtration System
FV11135	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	
FV11202	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	Re-sampled July '06.
FV11203	ND	NS	NS	NS	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	
FV11210	ND	NS	NS	NS	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	Owner installed filtration system as of Feb. '06. Sample taken from faucet May 07
FV11215	ND	NS	NS	NS	ND	ND	ND	ND	ND	ND	ND	ND	0.16 LJ	ND	ND	ND	ND	ND	ND	ND	ND	Owner installed filtration system as of Feb. '06.
FV11226	ND	NS	NS	NS	NS	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	
FV11231	ND	NS	NS	NS	2.6 J	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	NS	ND	ND	ND	NS	ND	Feb '07 and Feb '08 - No power to the well.
FV11302	NS	NS	NS	NS	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	
FV11306	ND	NS	NS	NS	NS	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	Shares well with FV11314
FV11315	NS	NS	NS	NS	ND	NS	ND	ND	ND	ND	ND	ND	0.26 LJ	ND	ND	ND	ND	ND	ND	ND	ND	
FV11319	NS	NS	NS	NS	NS	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	Re-sampled July '06.
FV11322	NS	NS	NS	NS	NS	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	NS	ND	ND	No Access-Gate Locked Nov '07
FV11326	NS	NS	NS	NS	NS	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	
GL11302	NS	NS	NS	NS	NS	ND	ND	ND	ND	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	
GL11310	NS	NS	NS	NS	ND	ND	ND	ND	ND	ND	NS	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	
GL11402	NS	NS	NS	NS	NS	ND	ND	ND	NS	NS	NS	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	
GL11422	NS	NS	NS	NS	ND	ND	ND	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	No access. Gate locked.
GL11502	NS	NS	NS	NS	NS	ND	ND	ND	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	
GL11503	NS	NS	NS	NS	ND	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	
GL11506	NS	NS	NS	NS	NS	ND	ND	ND	NS	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	
GL11514	NS	NS	NS	NS	NS	ND	ND	ND	NS	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	
GL11606	NS	NS	NS	NS	ND	ND	ND	NS	NS	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	
GL11614	NS	NS	NS	NS	ND	ND	ND	ND	NS	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	
GL11622	NS	NS	NS	NS	ND	ND	ND	ND	NS	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	
GL11702	NS	NS	NS	NS	ND	ND	ND	ND	NS	ND	ND	ND	NS	NS	NS	NS	NS	NS	NS	NS	NS	May '06-not sampled per owner's request.
JR11010	ND	ND	ND	ND	ND	ND	ND	ND	ND	0.14 J	ND	0.18 LJ	ND	ND	0.13 LJ	ND	ND	ND	0.28 LJ	0.21LJ	0.37LJ	Shares w/PWS well JR11035. Too far south, not on the map.
JR11043	NS	NS	NS	NS	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	0.083 LJ	ND	ND	0.14	ND	UR	
JR11319	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	No Well
JR11414	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	
JR11427	9	9	12	19	14	20	20	21	24	24	24	21	29	31	43.2	47.4	43.9	50.4	41.2	37.4	44.8	Filtration System
JR11503	NS	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	
JR11515	0.7	1	0.75	0.62	ND	1	0.58	0.82	0.57	1.2	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	Oct. '05-not
JR11526	NS	1.2	1.8	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	Shares well with JR11528.
JR11527	NS	NS	NS	180	94	79	120	93	190	68	89	100	94	100	124	127	141	137	122	110	137	Could not sample prior to Nov. '03. Filtration System.
JR11528	1.3	1.5	1.3	2.6	1.5	3	2.2	3.1	1.7	2.9	3.6 J	6	3.4 J	3.10	4.3	4.5	3.9	6.6	9.6	6.6	8.6	Filtration system installed June '06.
JR11535	121	101	71	ND	69	45	84	64	140	64	57	67	50	71	67.4	84.7	75.1	85.5	83.9	74.7	93.2	Filtration System. Feb. '04 result is correct. Shares well with FV11011.
JR11600	0.8	1.1	1.4	2.7	2.4	1.8 J	1.9 JV	1.8	2.2	2.2 JV	2	3.3 J	2.1	3.40	3.4 J	5.3	4.4	4.2	7.1	6.2	5.9	
JR11614	8.8	10.2	14	15	15	21	16	18	19	22	36	31	28	33	42.5	23.4	30.8	33.8	33.8	28.2	48.1	Filtration System
JR11620	ND	ND	0.15J	.43J	ND	.39 J	0.29 J	0.44 J	0.15 J	0.36 J	0.40 J	0.43 LJ	0.46 LJ	ND	0.58	0.7	0.63	ND	1.1	0.72	1.8	
JR11642	0.6	1.2	0.86	2.2	0.77	1.7	1.4	1.6	0.64	1.6	1.6	2.3	2.1	1.6	1.7	1.6	3.8	11.3	24	28	39	Filtration System
JR11646	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	
JR11650	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	UR
JR11655	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	0.14 LJ	ND	ND	ND	ND	ND	ND	0.092 LJ	ND	ND	
JR11663	ND	NS	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	
JR11702	ND	NS	NS	NS	ND	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	
JR11707	ND	NS	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	UR	

JONES ROAD GROUNDWATER PLUME SITE QUARTERLY SAMPLING RESULTS																					Updated: July 1, 2008	
Location ID	May '03	Aug. '03	Nov. '03	Feb. '04	May '04	Aug. '04	Nov. '04	Feb. '05	May '05	Aug. '05	Nov. '05	Feb. '06	May/ Jul. '06	Aug. '06	Nov. '06	Feb. '07	May '07	Aug. '07	Nov. '07	Feb. '08	May '08	Additional Comments
JR11718	ND	NS	NS	NS	ND	NS	NS	NS	NS	NS	NS	NS	ND	ND	ND	ND	NS	ND	ND	ND	ND	No access. Gate locked May '07.
JR11729	NS	NS	NS	NS	ND	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	
JR117291/2	ND	NS	NS	NS	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	
JR11731	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	
JR11911	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	Too far north, Not on map
JRW11050	ND	NS	ND	ND	ND	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	
JRW11107	ND	NS	NS	NS	ND	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	
JRW11111	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	Shares Well with JRW11107
JRW11115	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	Shares Well with JRW11107
JRW11203	ND	NS	NS	NS	ND	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	
JRW11206	NS	NS	NS	NS	ND	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	
JRW11215	NS	NS	NS	NS	ND	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	
JRW11222	NS	NS	NS	NS	ND	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	
JRW11234	ND	NS	NS	NS	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	
JRW11351	NS	NS	NS	NS	ND	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	
JRW11352	NS	NS	NS	NS	ND	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	
JRW11354	NS	NS	NS	NS	ND	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	
JRW11358	NS	NS	NS	NS	ND	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	
MI11502	NS	NS	NS	NS	ND	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	
MI11507	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	
MI11510	NS	NS	NS	NS	ND	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	
MI11515	NS	NS	NS	NS	ND	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	
MI11603	NS	NS	NS	NS	NS	NS	NS	ND	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	
MI11611	NS	NS	NS	NS	ND	NS	NS	ND	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	
OV11503	NS	NS	NS	NS	ND	ND	ND	ND	NS	NS	NS	NS	ND	ND	ND	ND	ND	ND	ND	ND	ND	
OV11507	NS	NS	NS	NS	NS	ND	ND	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	No power to well in Nov. '05 and Feb. '06.
OV11519	NS	NS	NS	NS	ND	ND	ND	ND	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	
OV11523	NS	NS	NS	NS	NS	ND	ND	ND	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	
OV11527	NS	NS	NS	NS	NS	ND	ND	ND	ND	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	
OV11534	NS	NS	NS	NS	NS	ND	ND	ND	ND	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	
OV11547	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	
OV11602	NS	NS	NS	NS	ND	ND	ND	ND	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	
OV11603	NS	NS	NS	NS	ND	ND	ND	ND	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	
OV11610	NS	NS	NS	NS	ND	ND	ND	ND	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	
OV11618	NS	NS	NS	NS	ND	ND	ND	ND	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	
OV11623	NS	NS	NS	NS	ND	ND	ND	ND	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	
OV11626	NS	NS	NS	NS	ND	ND	ND	ND	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	Pump broken Nov. '05; shares well with OV11618
OV11634	NS	NS	NS	NS	ND	ND	ND	ND	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	Re-sampled July '06.
OV11635	NS	NS	NS	0.91	ND	ND	ND	ND	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	Feb '04 duplicate samples: ND & 0.91
OV11642	ND	NS	NS	NS	ND	ND	ND	ND	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	
OV11650	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	Owned by PH11651. No Well
OV11651	NS	NS	NS	NS	ND	ND	ND	ND	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	
OV11738	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	
PH11602	ND	NS	NS	NS	ND	ND	ND	ND	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	Re-sampled July '06.
PH11603	ND	NS	NS	NS	ND	ND	ND	ND	2.8	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	No water to well Nov. '05; gets water from PH11610
PH11610	ND	NS	NS	NS	ND	ND	ND	ND	3.4	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	Re-sampled July '06.
PH11611	ND	NS	NS	NS	ND	ND	ND	ND	1	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	Re-sampled July '06.
PH11618	ND	NS	NS	NS	ND	ND	ND	ND	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	Re-sampled July '06.
PH11619	ND	NS	NS	NS	ND	ND	ND	ND	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	Re-sampled July '06.
PH11626	ND	NS	NS	NS	ND	ND	ND	ND	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	No power to well Aug '07
PH11627	NS	NS	NS	NS	ND	ND	ND	ND	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	
PH11643	NS	NS	NS	NS	ND	ND	ND	ND	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	
PH11650	ND	NS	NS	NS	ND	ND	ND	ND	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	
PH11651	NS	NS	NS	NS	ND	ND	ND	ND	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	Feb. '07 not sampled per owner's request
PH11702	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	
PH11703	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	May '06-not sampled per owner's request.
PH11710	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	May '06-not sampled per owner's request.
PH11713	NS	NS	NS	NS	ND	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	
PH11722	NS	NS	NS	NS	ND	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	

JONES ROAD GROUNDWATER PLUME SITE QUARTERLY SAMPLING RESULTS																						Updated: July 1, 2008
Location ID	May '03	Aug. '03	Nov. '03	Feb. '04	May '04	Aug. '04	Nov. '04	Feb. '05	May '05	Aug. '05	Nov. '05	Feb. '06	May/ Jul. '06	Aug. '06	Nov. '06	Feb. '07	May '07	Aug. '07	Nov. '07	Feb. '08	May '08	Comments
PH11723	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	May '06-not sampled per owner's request.
PH11733	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	May '06-not sampled per owner's request.
PH11738	NS	NS	NS	ND	ND	NS	NS	NS	NS	NS	NS	NS	ND	ND	ND	ND	ND	ND	ND	ND	ND	
PH11739	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	ND	ND	NS	NS	NS	NS	NS	NS	Nov. '06 - no access gate locked; Feb '07 - not sampled per owner's request.
TC11010	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	No Well
TC11018	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	0.27 LJ	ND	ND	ND	
TC11019	1.5	2.9	1.4	2.5	.5 J	5.1	2.4	3.8	5.3	3.8	5.4	ND	ND	8.8	7.4	13.2	23	20.6	17.4	22.8	35	Filtration System
TC11022	4.7	5.3	6.8	6.1	7.4	6.2	7.5	9.5	8	12	15	15	16	17	19.4	15	12.3	11.2	8.6	9.2	11	Filtration System. Re-sampled July '06.
TC11027	NS	NS	NS	NS	10	6.6	13	12	8.7	10	23	17	18	11	NS	NS	16	21.9	21.1	22.4	32	Filtration System. No power to the well through Feb '04. Re-sampled July '06. Nov. '06 and Feb '07 - no power to well.
TC11034	ND	0.5	ND	ND	ND	ND	ND	ND	ND	0.37 J	0.28 J	0.28 LJ	0.31 LJ	0.73	0.37 LJ	0.57	ND	0.23 LJ	0.58	ND	0.33 LJ	
TC11035	1.6	ND	0.26J	1.4	.4 J	0.31 J	0.99	0.33 J	ND	0.57	2.1	1.1	1.1	0.82	1.9	2.5	ND	2.3	4.9	2.5	0.71	
TC11103	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	0.14 J	ND	0.090 LJ	ND	ND	ND	ND	ND	ND	ND	ND	Filtration System
TC11104	58.4	50.2	96	140	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	Currently sharing water with the well located at TC11034.
TC11106	1.4	1.9	1.4	2.2	2.3 J	2.9	2.7	2.3	ND	4.4	4	4	3	3.10	2.9	3.5	2.4	2.6	3.3	2.4	2.8	2 wells- 1st drilled
TC11107	13.4	11	15	14	17	16	18	21	18	21	19 J	17	20	21	32.8	35.7	NS	29.1	31.1	39.4	42.3	Filtration System. Unable to sample because pump head disconnected Aug '07.
TC11108	ND	0.5	ND	.18J	ND	.2 J	ND	0.16 J	ND	3	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	Shares well with TC11106.
TC11110	1.2	1	1.2	1.5	ND	1.9	1.8	1.3	2.6	1.8	2.3	3.1	3.1	3.40	3.1	2.2	2.2	1.7	2	1.8	2.2	
TC11115	NS	12.3	16	12	21	21	19	20	30	23	13 J	24	32 J	15	41.5	38	33.1	29.1	44	32.3	NS	Gate Locked/ Filtration System
TC11118	2	1.7	2.6	4.4	3 J	6.1	3.3	3.7	3.1	3.5	4.4	5.7 J^	ND	5.60	5.8	4.8	4.5	5.5	5.6	6.6	7.6	Filtration System
TC11126	2.7	3.2	3.1	5.1	6.6	10	5.7	7.7	7.1	7.1	6.7	7.2 J^	7	5.10	10.1	8.6	7.1	8	7.4	NS	11.6	Filtration System. No power to well Feb '08.
TC11130	1.9	1.9	1.4	3.7	3.8 J	4.4	1.9	1.4	1.8	3.4	3.2	2.3	4.4	7.30	10.8	6.4	6.3	5.2	5.3	4.2	4.1	Filtration System installed Oct. '06.
TC11131	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	Shares well with TO11116.
TC11132	ND	ND	ND	ND	ND	ND	ND	NS	ND	ND	ND	ND	ND	ND	NS	ND	ND	ND	ND	NS	ND	Nov. '06 no access gate locked. No power to well Feb '08.
TC11135	ND	NS	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	
TC11140	ND	NS	ND	.19J	.42 J	ND	ND	ND	0.32 J	0.30 J	0.38 J	0.29 LJ	0.38 LJ	0.40 LJ	0.47 LJ	0.44 LJ	ND	0.53	0.61	0.40LJ	0.51	Feb '07 - sample taken from kitchen faucet per owner's request.
TC11203	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	
TC11206	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	
TC11214	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	NS	NS	ND	ND	ND	ND	ND	NS	Nov. '06 and Feb '07 no access gate locked. Gate Locked '08
TC11215	ND	NS	NS	NS	NS	ND	ND	NS	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	The pump had problems, the sampler could not complete the purge in Feb. '05.

JONES ROAD GROUNDWATER PLUME SITE QUARTERLY SAMPLING RESULTS																					Updated: July 1, 2008	
Location ID	May '03	Aug. '03	Nov. '03	Feb. '04	May '04	Aug. '04	Nov. '04	Feb. '05	May '05	Aug. '05	Nov. '05	Feb. '06	May/ Jul. '06	Aug. '06	Nov. '06	Feb. '07	May '07	Aug. '07	Nov. '07	Feb. '08	May '08	Comments
TC11219	ND	NS	NS	ND	ND	ND	ND	ND	NS	NS	NS	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	
TC11222	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	Part of T11303
TC11227	ND	NS	NS	NS	NS	ND	ND	ND	ND	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	
TC11303	ND	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	
TC11315	NS	NS	NS	NS	ND	ND	ND	ND	NS	NS	NS	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	
TC11318	ND	NS	NS	NS	NS	ND	ND	ND	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	
TC11330	NS	NS	NS	NS	NS	ND	ND	ND	NS	NS	NS	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	
TC11331	NS	NS	NS	NS	NS	ND	NS	NS	NS	NS	NS	ND	ND	ND	ND	ND	ND	NS	ND	ND	ND	No power to the well Nov. '04 to Feb. '06 No power to well Aug '07.
TH11602	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	
TH11603	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	0.64	ND	ND	ND	ND	ND	ND	ND	ND	Multiple spigots needed to be used to get the pump running continuously.
TH11610	10.6	3.1	11	6	6.4	11	4.1	9.8	15	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	Filtration system removed prior to Aug. '05 at owner's request.
TH11611	ND	ND	ND	ND	.27 J	ND	0.21 J	ND	ND	0.32 J	0.36 J	0.66	ND	0.57	1.1	0.85	0.85	0.91	0.84	0.34LJ	0.39 LJ	
TH11618	7.9	ND	ND	4.8	7.6	5.6	ND	2.3	22	ND	ND	ND	0.64	ND	ND	26.2	136	89.9	93.5	98.5	113	Filtration System
TH11619	ND	ND	ND	ND	ND	ND	ND	ND	ND	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	Per owner request, not sampled Aug. '05.
TH11620	ND	ND	ND	ND	ND	ND	ND	ND	ND	0.19 J	0.15 J	0.21 LJ	0.11 LJ	ND	ND	0.056 LJ	ND	ND	0.071 LJ	ND	ND	
TH11627	NS	NS	NS	NS	ND	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	Currently sharing water with the well located at TH11635.
TH11635	ND	NS	NS	NS	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	
TH11642	ND	ND	ND	ND	ND	ND	ND	ND	ND	0.19 J	0.18 J	ND	0.20 LJ	0.24 LJ	0.19 LJ	0.27 LJ	0.21 LJ	0.22 LJ	0.32 LJ	ND	ND	
TH11643	ND	NS	NS	NS	ND	ND	ND	ND	ND	0.11 J	ND	ND	ND	ND	ND	ND	ND	ND	0.059 LJ	ND	ND	
TH11651	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	
TH11703	ND	NS	NS	NS	ND	ND	ND	ND	NS	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	
TH11713	NS	NS	NS	NS	NS	ND	ND	ND	NS	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	
TH11722	NS	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	
TH11723	NS	NS	NS	NS	NS	ND	NS	NS	NS	ND	ND	7.8 J	ND	ND	ND	ND	ND	ND	ND	ND	ND	Feb. '06-Owner independently sampled well and declined filtration system.
TH11733	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	0.11 LJ	ND	ND	ND	ND	NS	ND	ND	ND	
TH11737	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	ND	ND	ND	ND	ND	ND	ND	ND	ND	
TO10610	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	Too far east, not on map.
TO10615	ND	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	Too far east, not on map.
TO10619	NS	NS	NS	ND	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	Shares Well with TO10627
TO10623	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	Shares Well with TO10627
TO10624	ND	NS	NS	ND	ND	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	
TO10627	ND	NS	NS	NS	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	
TO10635	ND	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	
TO10700	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	
TO10700LF	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	ND	ND	ND	ND	ND	ND	Well discovered Nov. 2006
TO10727	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	0.051 LJ	ND	ND	
TO10827	0.5	NS	0.97	1.5	1.3	2	1.7	2	2.6	3.4	2.0 J	2.6	3	3.50	3.4	4	6	5.6	5	5.1	4.8	Filtration system installed July 2007.
TO10830	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	
TO10835	2	2.8	3.8	6.6	8.8	7.8	6.2	13	10	9.7	5.9	ND	NS	10.0	14.8	18.1	15.5	NS	24	29.6	38.5	Filtration System. No access Aug '07.
TO10860	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	No Well
TO10902	7.1	13.8	16	12	10	16	17	19	16	21	28 J	41	41	41	37.9	48.2	20.4	35.1	24.6	26.8	22.5	Filtration System. Re-sampled July '06.
TO10903	18.2	16.8	7.9	37	20	22	25	28	42	33	41	51 J^	54	56	66.5	67.4	65.2	74.2	99	75.3	87.9	Filtration System. Re-sampled July '06.
TO11002	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	MUD.
TO11011	ND	NS	NS	NS	NS	NS	ND	ND	ND	ND	ND	ND	NS	NS	NS	NS	NS	NS	NS	NS	NS	May '06-no power to well.
TO11022	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	No Well

JONES ROAD GROUNDWATER PLUME SITE QUARTERLY SAMPLING RESULTS																						Updated: July 1, 2008
Location ID	May '03	Aug. '03	Nov. '03	Feb. '04	May '04	Aug. '04	Nov. '04	Feb. '05	May '05	Aug. '05	Nov. '05	Feb. '06	May/ Jul. '06	Aug. '06	Nov. '06	Feb. '07	May '07	Aug. '07	Nov. '07	Feb. '08	May '08	Comments
TO11023	NS	NS	NS	NS	0.51	0.64 J	0.38 J	0.63	1.6	0.76	0.55	0.35 LJ	0.6	ND	0.56	1.5	1.4	1.7	2.1	1.2	NS	Difficult to access. Gate Locked '08
TO11024	24.5	19.9	30	37	15	18	22	25	18	32	33	42	25	NS	NS	NS	NS	NS	NS	NS	NS	Filtration System. No power to well Aug. '06, Nov. '06, Feb. '07, May '07, Aug '07, Nov '07, and Feb '08. May '08
TO11033	0.5	0.8	NS	1.1	1.2	1.4	1.4	1.4	1	NS	1.9	2.1	2.7	3.9	3.7	4.2	4.2	4	2.8	1.8	1.8	No power to well Aug. '05.
TO11051	ND	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	Shares Well with TO11033
TO11102	0.3 J	0.8	0.64	0.92	NS	1.1	0.99	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	Sampling crew was unable to contact owner. Difficult to access.
TO11104	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	MUD
TO11112	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	Well Broken
TO11115B	ND	NS	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	
TO11116	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	Shares Well with TC11131
TO1116M	NS	NS	NS	NS	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	
TO11202	ND	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	
TO11205	ND	NS	NS	NS	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	
TO11210	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	MUD
TO11230	ND	NS	NS	NS	NS	ND	NS	NS	NS	NS	NS	NS	NS	ND	ND	ND	ND	ND	NS	ND	ND	No power Nov. '04 to Feb. '06 and Nov '07.
TO11235	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	
TO11239	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	
TO11305	NS	NS	NS	NS	NS	NS	ND	ND	ND	ND	ND	ND	NS	NS	NS	NS	NS	NS	NS	NS	NS	
TO11309	NS	NS	NS	NS	NS	NS	ND	ND	ND	ND	ND	ND	NS	NS	NS	NS	NS	NS	NS	NS	NS	
TO11310	NS	NS	NS	NS	NS	ND	ND	ND	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	
TO11314	NS	NS	NS	NS	NS	ND	ND	ND	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	
TO11335	NS	NS	NS	NS	NS	ND	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	No Access , Gate locked. Aug '07-not sampled per property manager's request.
TO11338	ND	NS	NS	NS	ND	ND	ND	0.25 J	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	
TT11011	13.2	10.8	6.2	18	16 J	31 J	21	26	31	29	32	37	39	32	42.1	57.1	48.1	52.7	69	67.4	55	Filtration System
TT11014	27.3	25.7	24	38	28	20	16	25	20	32	27	59	44	26	31.6	99.6	106	95.2	140	80.6	105	Filtration System. Re-sampled July '06.
TT11015	*ND	*ND	*ND	*ND	*ND	*ND	*ND	*ND	*ND	30	30	38	42	28	32.6	36.8	27.3	23.1	28	28.6	23.5	* Filtration System inside the Garage. Difficult access, unable to contact owner.
TT11031	NS	5.3	7.1	12	9.1	11	7.4	12	14	9.2	15	14	13	7.6	11.9	10.5	13	9.3	NS	8.1	12.1	Filtration System -No Access-Gates Lock Nov '07
TT11039	ND	0.8	NS	0.2J	0.23 J	ND	0.88	0.45 J	0.63	2.7	3.6	1.9	NS	NS	NS	NS	NS	NS	NS	NS	NS	May '06-no access
TT11102	0.4 J	1.1	ND	0.55	0.54	0.84	0.82	0.93	0.86	1.3	1.5	1.3	ND	0.76	0.64	0.26 LJ	0.28 LJ	ND	0.22 LJ	ND	ND	
TT11103	ND	ND	ND	0.12J	ND	ND	ND	ND	ND	0.15 J	0.21 J	0.16 LJ	ND	ND	ND	0.073 LJ	ND	ND	ND	ND	ND	
TT11106	22.4	7.4	6	9.9	12	19	7.9	7.9	6.7	4.8	6.5	6.4	4.8	33	66.3	62.9	62.4	45.5	31	16.3	11.6	Filtration System. Pump replaced Mar. '06.
TT11107	4.2	3.7	5.3	7.5	5.2	9.7	9.4	16	19	35	44	38 J	57	98	120	142	129	158	230	183	186	Filtration System
TT11112	ND	ND	ND	ND	ND	ND	0.093 J	0.24 J	0.27 J	0.23 J	0.28 J	ND	ND	ND	ND	0.085 LJ	ND	ND	0.17 LJ	0.17LJ	ND	
TT11114	ND	ND	ND	ND	ND	ND	ND	0.17 J	0.16 J	0.26 J	0.23 J	ND	0.11 LJ	ND	0.15 LJ	0.15 LJ	ND	ND	0.16 LJ	ND	ND	
TT11115	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	ND	ND	ND	ND	ND	ND	New residence Feb. '07.
TT11118	1.4	1.6	1.5	1.3	1.2	1.7	1.2	1.5	1.3	1.7	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	No power as of Nov. '05.
TT11123	4.5	NS	2.7	2.7	NS	8.9	5.8	8.8	NS	8.1	6.8	6	NS	4.10	3.7	NS	NS	NS	NS	11	NS	Filtration System. Difficult to access. Feb. '07, May '07, and Aug '07, and Feb '08. May '08
TT11124	ND	0.6	ND	0.54	0.4 J	ND	0.34 J	0.28 J	0.26 J	0.33 J	0.42 J	0.47 LJ	0.37 LJ	ND	0.35 LJ	0.32 LJ	ND	0.38 LJ	ND	0.43LJ	ND	
TT11127	4.7	3.1	3.9	14	21	23	13	20	15	15	4.6	2.8	ND	3.50	2	12.4	14.6	16.4	23	23.3	21.1	Filtration System

