
### Reading Date

8/9/2019 7:00:00 AM to 8/9/2019 8:00:00 AM



### Recent Benzene Detections


Location Category	Reading Date	Range of Detections
Division E	8/9/2019 07:49:10	0.1100 ppm






### Reading Date

8/8/2019 8:00:00 AM to 8/8/2019 9:00:00 AM



## Recent Benzene Detections


Location Category	Reading Date	Range of Detections
Division E	8/8/2019 08:01:09	0.0300 ppm
	8/8/2019 08:03:00	0.0700 ppm
	8/8/2019 08:18:58	0.0700 ppm
	8/8/2019 08:38:01	0.0800 ppm
	8/8/2019 08:49:53	0.0900 ppm
	8/8/2019 08:47:50	0.2300 ppm
Impacted Tank Farm	8/8/2019 08:13:15	0.2500 ppm
	8/8/2019 08:25:20	0.3300 ppm
	8/8/2019 08:21:49	0.1500 ppm
	8/8/2019 08:26:56	0.0900 ppm





### Reading Date

8/8/2019 9:00:00 AM to 8/8/2019 10:00:00 AM



## Recent Benzene Detections


L. E. C.	B. P. B.L.	D (D.). (1)
Location Category	Reading Date	Range of Detections
Division E	8/8/2019 09:08:53	0.0400 ppm
	8/8/2019 09:22:49	0.1000 ppm
	8/8/2019 09:41:16	0.1000 ppm
	8/8/2019 09:25:55	0.2200 ppm
	8/8/2019 09:29:31	0.3500 ppm
	8/8/2019 09:38:52	0.1000 ppm
	8/8/2019 09:44:40	0.0600 ppm
	8/8/2019 09:58:29	0.2000 ppm
	8/8/2019 09:50:22	0.1900 ppm
	8/8/2019 09:55:09	0.0500 ppm





### Reading Date

8/9/2019 10:00:00 AM to 8/9/2019 11:00:00 AM



## Recent Benzene Detections

Location Category	Reading Date	Range of Detections
Division E	8/9/2019 10:21:25	0.0600 ppm
	8/9/2019 10:48:12	0.1200 ppm
	8/9/2019 10:50:22	0.0200 ppm
Impacted Tank Farm	8/9/2019 10:09:37	0.1400 ppm






### Reading Date

8/9/2019 11:00:00 AM to 8/9/2019 12:00:00 PM



## Recent Benzene Detections


Location Category	Reading Date	Range of Detections
Division E	8/9/2019 11:20:26	0.08000 ppm
	8/9/2019 11:39:30	0.02000 ppm
	8/9/2019 11:46:29	0.08000 ppm
	8/9/2019 11:52:27	0.02000 ppm






### Reading Date

8/9/2019 12:00:00 PM to 8/9/2019 1:00:00 PM



## Recent Benzene Detections


Location Category	Reading Date	Range of Detections
Division E	8/9/2019 12:04:04	0.07000 ppm
	8/9/2019 12:23:18	0.03000 ppm
	8/9/2019 12:17:47	0.03000 ppm
	8/9/2019 12:22:43	0.03000 ppm
	8/9/2019 12:46:31	0.05000 ppm
	8/9/2019 12:54:41	0.03000 ppm





### Reading Date

8/9/2019 1:00:00 PM to 8/9/2019 2:00:00 PM



## Recent Benzene Detections


Location Category	Reading Date	Range of Detections
Division E	8/9/2019 13:51:36	0.0300 ppm
	8/9/2019 13:22:18	0.0700 ppm
	8/9/2019 13:50:26	0.0500 ppm
	8/9/2019 13:42:21	0.1500 ppm





### Reading Date

8/9/2019 2:00:00 PM to 8/9/2019 3:00:00 PM




Recent Benzene Detections





### Reading Date

8/9/2019 3:00:00 PM to 8/9/2019 4:00:00 PM




Recent Benzene Detections





### Reading Date

8/9/2019 4:00:00 PM to 8/9/2019 5:00:00 PM



## Recent Benzene Detections


Location Category	Reading Date	Range of Detections
Division E	8/9/2019 16:17:13	0.03000 ppm
	8/9/2019 16:26:12	0.04000 ppm
	8/9/2019 16:34:14	0.09000 ppm
	8/9/2019 16:29:27	0.03000 ppm
	8/9/2019 16:36:47	0.07000 ppm
	8/9/2019 16:31:31	0.03000 ppm
Impacted Tank Farm	8/9/2019 16:59:30	0.09000 ppm





### Reading Date

8/9/2019 5:00:00 PM to 8/9/2019 6:00:00 PM



### Recent Benzene Detections

Location Category	Reading Date	Range of Detections
Impacted Tank Farm	8/9/2019 17:14:08	0.1500 ppm



