
#### Reading Date

8/12/2019 7:00:00 AM to 8/12/2019 8:00:00 AM



### Recent Benzene Detections


Location Category	Reading Date	Range of Detections
Impacted Tank Farm	8/12/2019 07:47:56	0.41000 ppm
	8/12/2019 07:59:04	0.37000 ppm
	8/12/2019 07:51:38	0.32000 ppm





#### Reading Date

8/12/2019 8:00:00 AM to 8/12/2019 9:00:00 AM



### Recent Benzene Detections


Location Category	Reading Date	Range of Detections
Impacted Tank Farm	8/12/2019 08:21:56	0.2500 ppm
	8/12/2019 08:19:31	0.0600 ppm
	8/12/2019 08:58:46	0.0500 ppm
	8/12/2019 08:37:58	0.2400 ppm
	8/12/2019 08:48:03	0.3300 ppm
	8/12/2019 08:54:22	0.0300 ppm






#### Reading Date

8/12/2019 9:00:00 AM to 8/12/2019 10:00:00 AM



### Recent Benzene Detections


Location Category	Reading Date	Range of Detections
Division E	8/12/2019 09:31:36	0.2200 ppm





#### Reading Date

8/12/2019 10:00:00 AM to 8/12/2019 11:00:00 AM




Recent Benzene Detections





#### Reading Date

8/12/2019 11:00:00 AM to 8/12/2019 12:00:00 PM



### Recent Benzene Detections


Location Category	Reading Date	Range of Detections
Impacted Tank Farm	8/12/2019 11:36:14	0.4000 ppm
	8/12/2019 11:43:36	0.0600 ppm
	8/12/2019 11:23:19	0.0300 ppm






#### Reading Date

8/12/2019 12:00:00 PM to 8/12/2019 1:00:00 PM




Recent Benzene Detections





#### Reading Date

8/12/2019 1:00:00 PM to 8/12/2019 2:00:00 PM




Recent Benzene Detections





#### Reading Date

8/12/2019 2:00:00 PM to 8/12/2019 3:00:00 PM




Recent Benzene Detections





#### Reading Date

8/12/2019 3:00:00 PM to 8/12/2019 4:00:00 PM



### Recent Benzene Detections

Location Category	Reading Date	Range of Detections
Impacted Tank Farm	8/12/2019 15:36:17	0.06000 ppm
	8/12/2019 15:44:01	0.13000 ppm

