

Segment ID: 1406 **Water body name:** Lake Lyndon B. Johnson

Reservoir Colorado River Basin Total size: 6,375 Acres

Assessment Year	Assessment Method	Status of Use Support or Concern	Location	Location size	# of samples	# of exceedances	Mean
-----------------	-------------------	----------------------------------	----------	---------------	--------------	------------------	------

Aquatic Life Use

2002	Dissolved Oxygen grab average	No Concern	Colorado River Arm	525	30	4	
2002	Dissolved Oxygen grab average	No Concern	Kingsland Cove	200	29	1	
2002	Dissolved Oxygen grab average	No Concern	Llano River arm	650	29	0	
2002	Dissolved Oxygen grab average	Use Concern	Main pool near dam	1,900	30	5	
2002	Dissolved Oxygen grab average	No Concern	Mid lake at Llano River confluence	1,200	30	0	
2002	Dissolved Oxygen grab average	No Concern	Mid lake near Sandy Creek	1,900	37	0	
2002	Dissolved Oxygen grab minimum	Fully Supporting	Colorado River Arm	525	30	2	
2002	Dissolved Oxygen grab minimum	Fully Supporting	Kingsland Cove	200	29	0	
2002	Dissolved Oxygen grab minimum	Fully Supporting	Llano River arm	650	29	0	
2002	Dissolved Oxygen grab minimum	Fully Supporting	Main pool near dam	1,900	30	0	
2002	Dissolved Oxygen grab minimum	Fully Supporting	Mid lake at Llano River confluence	1,200	30	0	
2002	Dissolved Oxygen grab minimum	Fully Supporting	Mid lake near Sandy Creek	1,900	37	0	
2002	Dissolved Oxygen 24hr average	Not Assessed	Colorado River Arm	525	0		
2002	Dissolved Oxygen 24hr average	Not Assessed	Kingsland Cove	200	0		
2002	Dissolved Oxygen 24hr average	Not Assessed	Llano River arm	650	0		
2002	Dissolved Oxygen 24hr average	Not Assessed	Main pool near dam	1,900	0		
2002	Dissolved Oxygen 24hr average	Not Assessed	Mid lake at Llano River confluence	1,200	0		
2002	Dissolved Oxygen 24hr average	Not Assessed	Mid lake near Sandy Creek	1,900	0		
2002	Dissolved Oxygen 24hr minimum	Not Assessed	Colorado River Arm	525	0		
2002	Dissolved Oxygen 24hr minimum	Not Assessed	Kingsland Cove	200	0		
2002	Dissolved Oxygen 24hr minimum	Not Assessed	Llano River arm	650	0		
2002	Dissolved Oxygen 24hr minimum	Not Assessed	Main pool near dam	1,900	0		
2002	Dissolved Oxygen 24hr minimum	Not Assessed	Mid lake at Llano River confluence	1,200	0		
2002	Dissolved Oxygen 24hr minimum	Not Assessed	Mid lake near Sandy Creek	1,900	0		

Segment ID: 1406 **Water body name:** Lake Lyndon B. Johnson

Reservoir	Colorado River Basin	Total size:	6,375	Acres
-----------	----------------------	-------------	-------	-------

Aquatic Life Use (continued)

Assessment Year	Assessment Method	Status of Use Support or Concern	Location	Location size	# of samples	# of exceedances	Mean
2002	Acute Metals in water	Not Assessed	Main pool near dam	1,900	1		
2002	Chronic Metals in water	Not Assessed	Main pool near dam	1,900	1		
2002	Acute Organics in water	Not Assessed	Main pool near dam	1,900	1		
2002	Chronic Organics in water	Not Assessed	Main pool near dam	1,900	1		
2002	Overall Aquatic Life Use	Fully Supporting	Colorado River Arm	525			
2002	Overall Aquatic Life Use	Fully Supporting	Kingsland Cove	200			
2002	Overall Aquatic Life Use	Fully Supporting	Llano River arm	650			
2002	Overall Aquatic Life Use	Fully Supporting	Main pool near dam	1,900			
2002	Overall Aquatic Life Use	Fully Supporting	Mid lake at Llano River confluence	1,200			
2002	Overall Aquatic Life Use	Fully Supporting	Mid lake near Sandy Creek	1,900			

Contact Recreation Use

2002	E. coli single sample	Fully Supporting	Colorado River Arm	525	25	0	
2002	E. coli single sample	Fully Supporting	Main pool near dam	1,900	24	0	
2002	E. coli single sample	Fully Supporting	Mid lake at Llano River confluence	1,200	25	0	
2002	E. coli single sample	Fully Supporting	Mid lake near Sandy Creek	1,900	25	0	
2002	E. coli geometric mean	Fully Supporting	Colorado River Arm	525	25		6
2002	E. coli geometric mean	Fully Supporting	Main pool near dam	1,900	24		1
2002	E. coli geometric mean	Fully Supporting	Mid lake at Llano River confluence	1,200	25		3
2002	E. coli geometric mean	Fully Supporting	Mid lake near Sandy Creek	1,900	25		2
2002	Fecal coliform single sample	Fully Supporting	Colorado River Arm	525	25	0	
2002	Fecal coliform single sample	Fully Supporting	Main pool near dam	1,900	24	0	
2002	Fecal coliform single sample	Fully Supporting	Mid lake at Llano River confluence	1,200	25	0	

Segment ID: 1406 **Water body name:** Lake Lyndon B. Johnson

Reservoir	Colorado River Basin	Total size:	6,375	Acres			
Assessment Year	Assessment Method	Status of Use Support or Concern	Location	Location size	# of samples	# of exceedances	Mean

Contact Recreation Use (continued)

2002	Fecal coliform single sample	Fully Supporting	Mid lake near Sandy Creek	1,900	25	0	
2002	Fecal coliform geometric mean	Fully Supporting	Colorado River Arm	525	25		12
2002	Fecal coliform geometric mean	Fully Supporting	Main pool near dam	1,900	24		2
2002	Fecal coliform geometric mean	Fully Supporting	Mid lake at Llano River confluence	1,200	25		4
2002	Fecal coliform geometric mean	Fully Supporting	Mid lake near Sandy Creek	1,900	25		3
2002	Overall Recreation Use	Fully Supporting	Colorado River Arm	525			
2002	Overall Recreation Use	Not Assessed	Kingsland Cove	200			
2002	Overall Recreation Use	Not Assessed	Llano River arm	650			
2002	Overall Recreation Use	Fully Supporting	Main pool near dam	1,900			
2002	Overall Recreation Use	Fully Supporting	Mid lake at Llano River confluence	1,200			
2002	Overall Recreation Use	Fully Supporting	Mid lake near Sandy Creek	1,900			

General Use

2002	Water Temperature	Fully Supporting	Colorado River Arm	525	25	0	
2002	Water Temperature	Fully Supporting	Kingsland Cove	200	29	0	
2002	Water Temperature	Fully Supporting	Llano River arm	650	29	0	
2002	Water Temperature	Fully Supporting	Main pool near dam	1,900	30	0	
2002	Water Temperature	Fully Supporting	Mid lake at Llano River confluence	1,200	30	0	
2002	Water Temperature	Fully Supporting	Mid lake near Sandy Creek	1,900	37	0	
2002	pH	Fully Supporting	Colorado River Arm	525	13	0	
2002	pH	Fully Supporting	Kingsland Cove	200	29	0	
2002	pH	Fully Supporting	Llano River arm	650	29	0	
2002	pH	Fully Supporting	Main pool near dam	1,900	30	0	
2002	pH	Fully Supporting	Mid lake at Llano River confluence	1,200	30	0	
2002	pH	Fully Supporting	Mid lake near Sandy Creek	1,900	30	0	

Segment ID: 1406 **Water body name:** Lake Lyndon B. Johnson

Reservoir Colorado River Basin Total size: 6,375 Acres

Assessment Year	Assessment Method	Status of Use Support or Concern	Location	Location size	# of samples	# of exceedances	Mean
-----------------	-------------------	----------------------------------	----------	---------------	--------------	------------------	------

General Use (continued)

2002	Chloride	Fully Supporting	Colorado River Arm	525	79		69
2002	Chloride	Fully Supporting	Kingsland Cove	200	79		69
2002	Chloride	Fully Supporting	Llano River arm	650	79		69
2002	Chloride	Fully Supporting	Main pool near dam	1,900	79		69
2002	Chloride	Fully Supporting	Mid lake at Llano River confluence	1,200	79		69
2002	Chloride	Fully Supporting	Mid lake near Sandy Creek	1,900	79		69
2002	Sulfate	Fully Supporting	Colorado River Arm	525	98		43
2002	Sulfate	Fully Supporting	Kingsland Cove	200	98		43
2002	Sulfate	Fully Supporting	Llano River arm	650	98		43
2002	Sulfate	Fully Supporting	Main pool near dam	1,900	98		43
2002	Sulfate	Fully Supporting	Mid lake at Llano River confluence	1,200	98		43
2002	Sulfate	Fully Supporting	Mid lake near Sandy Creek	1,900	98		43
2002	Total Dissolved Solids	Fully Supporting	Colorado River Arm	525	180		352.8
2002	Total Dissolved Solids	Fully Supporting	Kingsland Cove	200	180		352.8
2002	Total Dissolved Solids	Fully Supporting	Llano River arm	650	180		352.8
2002	Total Dissolved Solids	Fully Supporting	Main pool near dam	1,900	180		352.8
2002	Total Dissolved Solids	Fully Supporting	Mid lake at Llano River confluence	1,200	180		352.8
2002	Total Dissolved Solids	Fully Supporting	Mid lake near Sandy Creek	1,900	180		352.8
2002	Overall General Use	Fully Supporting	Colorado River Arm	525			
2002	Overall General Use	Fully Supporting	Kingsland Cove	200			
2002	Overall General Use	Fully Supporting	Llano River arm	650			
2002	Overall General Use	Fully Supporting	Main pool near dam	1,900			
2002	Overall General Use	Fully Supporting	Mid lake at Llano River confluence	1,200			
2002	Overall General Use	Fully Supporting	Mid lake near Sandy Creek	1,900			

Segment ID: 1406 **Water body name:** Lake Lyndon B. Johnson

Reservoir	Colorado River Basin			Total size:	6,375	Acres	
Assessment Year	Assessment Method	Status of Use Support or Concern	Location	Location size	# of samples	# of exceedances	Mean

Fish Consumption Use

2002	Human Health Criteria	Not Assessed	Colorado River Arm	525	1		
2002	Human Health Criteria	Not Assessed	Kingsland Cove	200	1		
2002	Human Health Criteria	Not Assessed	Llano River arm	650	1		
2002	Human Health Criteria	Not Assessed	Main pool near dam	1,900	1		
2002	Human Health Criteria	Not Assessed	Mid lake near Sandy Creek	1,900	1		
2002	Overall Fish Consumption Use	Not Assessed	Colorado River Arm	525			
2002	Overall Fish Consumption Use	Not Assessed	Kingsland Cove	200			
2002	Overall Fish Consumption Use	Not Assessed	Llano River arm	650			
2002	Overall Fish Consumption Use	Not Assessed	Main pool near dam	1,900			
2002	Overall Fish Consumption Use	Not Assessed	Mid lake at Llano River confluence	1,200			
2002	Overall Fish Consumption Use	Not Assessed	Mid lake near Sandy Creek	1,900			

Public Water Supply Use

2002	Overall Public Water Supply Use	Fully Supporting	Colorado River Arm	525			
2002	Overall Public Water Supply Use	Fully Supporting	Kingsland Cove	200			
2002	Overall Public Water Supply Use	Fully Supporting	Llano River arm	650			
2002	Overall Public Water Supply Use	Fully Supporting	Main pool near dam	1,900			
2002	Overall Public Water Supply Use	Fully Supporting	Mid lake at Llano River confluence	1,200			
2002	Overall Public Water Supply Use	Fully Supporting	Mid lake near Sandy Creek	1,900			

Overall Use Support

2002		Fully Supporting	Colorado River Arm	525			
2002		Fully Supporting	Kingsland Cove	200			
2002		Fully Supporting	Llano River arm	650			
2002		Fully Supporting	Main pool near dam	1,900			
2002		Fully Supporting	Mid lake at Llano River confluence	1,200			

Segment ID: 1406 **Water body name:** Lake Lyndon B. Johnson

Reservoir Colorado River Basin Total size: 6,375 Acres

Assessment Year	Assessment Method	Status of Use Support or Concern	Location	Location size	# of samples	# of exceedances	Mean
-----------------	-------------------	----------------------------------	----------	---------------	--------------	------------------	------

Overall Use Support (continued)

2002		Fully Supporting	Mid lake near Sandy Creek	1,900			
------	--	------------------	---------------------------	-------	--	--	--

Nutrient Enrichment Concern

2002	Ammonia Nitrogen	No Concern	Colorado River Arm	525	22	3	
2002	Ammonia Nitrogen	No Concern	Main pool near dam	1,900	22	4	
2002	Ammonia Nitrogen	No Concern	Mid lake at Llano River confluence	1,200	23	3	
2002	Ammonia Nitrogen	No Concern	Mid lake near Sandy Creek	1,900	23	3	
2002	Nitrite + Nitrate Nitrogen	No Concern	Colorado River Arm	525	24	1	
2002	Nitrite + Nitrate Nitrogen	No Concern	Main pool near dam	1,900	24	3	
2002	Nitrite + Nitrate Nitrogen	No Concern	Mid lake at Llano River confluence	1,200	25	3	
2002	Nitrite + Nitrate Nitrogen	No Concern	Mid lake near Sandy Creek	1,900	25	3	
2002	Orthophosphorus	No Concern	Colorado River Arm	525	24	0	
2002	Orthophosphorus	No Concern	Main pool near dam	1,900	24	0	
2002	Orthophosphorus	No Concern	Mid lake at Llano River confluence	1,200	25	0	
2002	Orthophosphorus	No Concern	Mid lake near Sandy Creek	1,900	25	0	
2002	Total Phosphorus	No Concern	Colorado River Arm	525	21	2	
2002	Total Phosphorus	No Concern	Main pool near dam	1,900	22	1	
2002	Total Phosphorus	No Concern	Mid lake at Llano River confluence	1,200	22	1	
2002	Total Phosphorus	No Concern	Mid lake near Sandy Creek	1,900	22	3	
2002	Overall Nutrient Enrichment Concerns	No Concern	Colorado River Arm	525			
2002	Overall Nutrient Enrichment Concerns	Not Assessed	Kingsland Cove	200			
2002	Overall Nutrient Enrichment Concerns	Not Assessed	Llano River arm	650			

Segment ID: 1406 **Water body name:** Lake Lyndon B. Johnson

Reservoir	Colorado River Basin	Total size:	6,375	Acres				
Assessment Year	Assessment Method	Status of Use Support or Concern	Location	Location size	# of samples	# of exceedances	Mean	

Nutrient Enrichment Concern (continued)

2002	Overall Nutrient Enrichment Concerns	No Concern	Main pool near dam	1,900				
2002	Overall Nutrient Enrichment Concerns	No Concern	Mid lake at Llano River confluence	1,200				
2002	Overall Nutrient Enrichment Concerns	No Concern	Mid lake near Sandy Creek	1,900				

Algal Growth Concern

2002	Chlorophyll a	No Concern	Colorado River Arm	525	23	3		
2002	Chlorophyll a	Not Assessed	Kingsland Cove	200				
2002	Chlorophyll a	Not Assessed	Llano River arm	650				
2002	Chlorophyll a	No Concern	Main pool near dam	1,900	22	1		
2002	Chlorophyll a	No Concern	Mid lake at Llano River confluence	1,200	23	1		
2002	Chlorophyll a	No Concern	Mid lake near Sandy Creek	1,900	23	1		

Sediment Contaminants Concern

2002	Metals in sediment	Not Assessed	Main pool near dam	1,900	1			
2002	Metals in sediment	Not Assessed	Mid lake at Llano River confluence	1,200	1			
2002	Metals in sediment	Not Assessed	Mid lake near Sandy Creek	1,900	1			
2002	Organics in sediment	Not Assessed	Main pool near dam	1,900	1			
2002	Organics in sediment	Not Assessed	Mid lake at Llano River confluence	1,200	1			
2002	Organics in sediment	Not Assessed	Mid lake near Sandy Creek	1,900	1			
2002	Overall Sediment Contaminant Concerns	Not Assessed	Colorado River Arm	525				
2002	Overall Sediment Contaminant Concerns	Not Assessed	Kingsland Cove	200				
2002	Overall Sediment Contaminant Concerns	Not Assessed	Llano River arm	650				

Segment ID: 1406 **Water body name:** Lake Lyndon B. Johnson

Reservoir

Colorado River Basin

Total size:

6,375

Acres

Assessment Year	Assessment Method	Status of Use Support or Concern	Location	Location size	# of samples	# of exceedances	Mean
-----------------	-------------------	----------------------------------	----------	---------------	--------------	------------------	------

Sediment Contaminants Concern (continued)

2002	Overall Sediment Contaminant Concerns	Not Assessed	Main pool near dam	1,900			
2002	Overall Sediment Contaminant Concerns	Not Assessed	Mid lake at Llano River confluence	1,200			
2002	Overall Sediment Contaminant Concerns	Not Assessed	Mid lake near Sandy Creek	1,900			

Fish Tissue Contaminants Concern

2002	Overall Fish Tissue Contaminant Concerns	Not Assessed	Colorado River Arm	525			
2002	Overall Fish Tissue Contaminant Concerns	Not Assessed	Kingsland Cove	200			
2002	Overall Fish Tissue Contaminant Concerns	Not Assessed	Llano River arm	650			
2002	Overall Fish Tissue Contaminant Concerns	Not Assessed	Main pool near dam	1,900			
2002	Overall Fish Tissue Contaminant Concerns	Not Assessed	Mid lake at Llano River confluence	1,200			
2002	Overall Fish Tissue Contaminant Concerns	Not Assessed	Mid lake near Sandy Creek	1,900			

Public Water Supply Concern

2002	Finished Water: Chloride	No Concern	Colorado River Arm	525			
2002	Finished Water: Chloride	No Concern	Kingsland Cove	200			
2002	Finished Water: Chloride	No Concern	Llano River arm	650			
2002	Finished Water: Chloride	No Concern	Main pool near dam	1,900			
2002	Finished Water: Chloride	No Concern	Mid lake at Llano River confluence	1,200			
2002	Finished Water: Chloride	No Concern	Mid lake near Sandy Creek	1,900			
2002	Finished Water: Sulfate	No Concern	Colorado River Arm	525			

Segment ID: 1406 **Water body name:** Lake Lyndon B. Johnson

Reservoir Colorado River Basin Total size: 6,375 Acres

Assessment Year	Assessment Method	Status of Use Support or Concern	Location	Location size	# of samples	# of exceedances	Mean
-----------------	-------------------	----------------------------------	----------	---------------	--------------	------------------	------

Public Water Supply Concern (continued)

2002	Finished Water: Sulfate	No Concern	Kingsland Cove	200			
2002	Finished Water: Sulfate	No Concern	Llano River arm	650			
2002	Finished Water: Sulfate	No Concern	Main pool near dam	1,900			
2002	Finished Water: Sulfate	No Concern	Mid lake at Llano River confluence	1,200			
2002	Finished Water: Sulfate	No Concern	Mid lake near Sandy Creek	1,900			
2002	Finished Water: Total Dissolved Solids	No Concern	Colorado River Arm	525			
2002	Finished Water: Total Dissolved Solids	No Concern	Kingsland Cove	200			
2002	Finished Water: Total Dissolved Solids	No Concern	Llano River arm	650			
2002	Finished Water: Total Dissolved Solids	No Concern	Main pool near dam	1,900			
2002	Finished Water: Total Dissolved Solids	No Concern	Mid lake at Llano River confluence	1,200			
2002	Finished Water: Total Dissolved Solids	No Concern	Mid lake near Sandy Creek	1,900			
2002	Finished Water: MTBE	No Concern	Colorado River Arm	525			
2002	Finished Water: MTBE	No Concern	Kingsland Cove	200			
2002	Finished Water: MTBE	No Concern	Llano River arm	650			
2002	Finished Water: MTBE	No Concern	Main pool near dam	1,900			
2002	Finished Water: MTBE	No Concern	Mid lake at Llano River confluence	1,200			
2002	Finished Water: MTBE	No Concern	Mid lake near Sandy Creek	1,900			
2002	Finished Water: Perchlorate	Not Assessed	Colorado River Arm	525			
2002	Finished Water: Perchlorate	Not Assessed	Kingsland Cove	200			
2002	Finished Water: Perchlorate	Not Assessed	Llano River arm	650			
2002	Finished Water: Perchlorate	Not Assessed	Main pool near dam	1,900			

Segment ID: 1406 **Water body name:** Lake Lyndon B. Johnson

Reservoir

Colorado River Basin

Total size:

6,375

Acres

Assessment Year	Assessment Method	Status of Use Support or Concern	Location	Location size	# of samples	# of exceedances	Mean
-----------------	-------------------	----------------------------------	----------	---------------	--------------	------------------	------

Public Water Supply Concern (continued)

2002	Finished Water: Perchlorate	Not Assessed	Mid lake at Llano River confluence	1,200			
2002	Finished Water: Perchlorate	Not Assessed	Mid lake near Sandy Creek	1,900			
2002	Finished Water: Overall	No Concern	Colorado River Arm	525			
2002	Finished Water: Overall	No Concern	Kingsland Cove	200			
2002	Finished Water: Overall	No Concern	Llano River arm	650			
2002	Finished Water: Overall	No Concern	Main pool near dam	1,900			
2002	Finished Water: Overall	No Concern	Mid lake at Llano River confluence	1,200			
2002	Finished Water: Overall	No Concern	Mid lake near Sandy Creek	1,900			
2002	Surface Water: Chloride	No Concern	Colorado River Arm	525	79		69
2002	Surface Water: Chloride	No Concern	Kingsland Cove	200	79		69
2002	Surface Water: Chloride	No Concern	Llano River arm	650	79		69
2002	Surface Water: Chloride	No Concern	Main pool near dam	1,900	79		69
2002	Surface Water: Chloride	No Concern	Mid lake at Llano River confluence	1,200	79		69
2002	Surface Water: Chloride	No Concern	Mid lake near Sandy Creek	1,900	79		69
2002	Surface Water: Sulfate	No Concern	Colorado River Arm	525	98		43
2002	Surface Water: Sulfate	No Concern	Kingsland Cove	200	98		43
2002	Surface Water: Sulfate	No Concern	Llano River arm	650	98		43
2002	Surface Water: Sulfate	No Concern	Main pool near dam	1,900	98		43
2002	Surface Water: Sulfate	No Concern	Mid lake at Llano River confluence	1,200	98		43
2002	Surface Water: Sulfate	No Concern	Mid lake near Sandy Creek	1,900	98		43
2002	Surface Water: Total Dissolved Solids	Not Assessed	Colorado River Arm	525	180		352.8
2002	Surface Water: Total Dissolved Solids	No Concern	Kingsland Cove	200	180		352.8

Segment ID: 1406 Water body name: Lake Lyndon B. Johnson

Reservoir	Colorado River Basin	Total size:	6,375	Acres
-----------	----------------------	-------------	-------	-------

Public Water Supply Concern (continued)

Assessment Year	Assessment Method	Status of Use Support or Concern	Location	Location size	# of samples	# of exceedances	Mean
2002	Surface Water: Total Dissolved Solids	No Concern	Llano River arm	650	180		352.8
2002	Surface Water: Total Dissolved Solids	No Concern	Main pool near dam	1,900	180		352.8
2002	Surface Water: Total Dissolved Solids	No Concern	Mid lake at Llano River confluence	1,200	180		352.8
2002	Surface Water: Total Dissolved Solids	No Concern	Mid lake near Sandy Creek	1,900	180		352.8
2002	Surface Water: Overall	No Concern	Colorado River Arm	525			
2002	Surface Water: Overall	No Concern	Kingsland Cove	200			
2002	Surface Water: Overall	No Concern	Llano River arm	650			
2002	Surface Water: Overall	No Concern	Main pool near dam	1,900			
2002	Surface Water: Overall	No Concern	Mid lake at Llano River confluence	1,200			
2002	Surface Water: Overall	No Concern	Mid lake near Sandy Creek	1,900			
2002	Overall Public Water Supply Concerns	No Concern	Colorado River Arm	525			
2002	Overall Public Water Supply Concerns	No Concern	Kingsland Cove	200			
2002	Overall Public Water Supply Concerns	No Concern	Llano River arm	650			
2002	Overall Public Water Supply Concerns	No Concern	Main pool near dam	1,900			
2002	Overall Public Water Supply Concerns	No Concern	Mid lake at Llano River confluence	1,200			
2002	Overall Public Water Supply Concerns	No Concern	Mid lake near Sandy Creek	1,900			

Segment ID: 1406 **Water body name:** Lake Lyndon B. Johnson

Reservoir	Colorado River Basin	Total size:	6,375	Acres
-----------	----------------------	-------------	-------	-------

Assessment Year	Assessment Method	Status of Use Support or Concern	Location	Location size	# of samples	# of exceedances	Mean
-----------------	-------------------	----------------------------------	----------	---------------	--------------	------------------	------

Narrative Criteria Concern

2002	Overall Narrative Criteria Concerns	No Concern	Colorado River Arm	525			
2002	Overall Narrative Criteria Concerns	No Concern	Kingsland Cove	200			
2002	Overall Narrative Criteria Concerns	No Concern	Llano River arm	650			
2002	Overall Narrative Criteria Concerns	No Concern	Main pool near dam	1,900			
2002	Overall Narrative Criteria Concerns	No Concern	Mid lake at Llano River confluence	1,200			
2002	Overall Narrative Criteria Concerns	No Concern	Mid lake near Sandy Creek	1,900			

Overall Secondary Concern

2002		No Concern	Colorado River Arm	525			
2002		No Concern	Kingsland Cove	200			
2002		No Concern	Llano River arm	650			
2002		No Concern	Main pool near dam	1,900			
2002		No Concern	Mid lake at Llano River confluence	1,200			
2002		No Concern	Mid lake near Sandy Creek	1,900			