#### Executive Summary – Enforcement Matter – Case No. 58940 City of Poteet RN102078417 Docket No. 2020-0267-MWD-E

**Order Type:** 1660 Agreed Order **Findings Order Justification:** N/A Media: **MWD Small Business:** No Location(s) Where Violation(s) Occurred: City of Poteet WWTF, 1304 South 9th Street, Poteet, Atascocsa County **Type of Operation:** Wastewater treatment facility **Other Significant Matters:** Additional Pending Enforcement Actions: No Past-Due Penalties: No Other: N/A **Interested Third-Parties: None Texas Register Publication Date:** September 17, 2021 **Comments Received:** No

#### **Penalty Information**

Total Penalty Assessed: \$48,874 Amount Deferred for Expedited Settlement: \$9,774 Total Paid to General Revenue: \$0 Total Due to General Revenue: \$0 Payment Plan: N/A Supplemental Environmental Project ("SEP") Conditional Offset: \$39,100 Name of SEP: Poteet UV System Improvements (Compliance) Compliance History Classifications: Person/CN - Satisfactory Site/RN - Satisfactory Major Source: No Statutory Limit Adjustment: N/A Applicable Penalty Policy: April 2014

#### Investigation Information

**Complaint Date(s):** N/A **Complaint Information**: N/A **Date(s) of Investigation:** December 10, 2019 **Date(s) of NOE(s):** January 30, 2020

#### Executive Summary – Enforcement Matter – Case No. 58940 City of Poteet RN102078417 Docket No. 2020-0267-MWD-E

#### **Violation Information**

1. Failed to submit quarterly progress reports. Specifically, the Respondent failed to submit quarterly progress reports due the first day of January and April 2019 [30 TEX. ADMIN. CODE § 305.125(1) and Texas Pollutant Discharge Elimination System ("TPDES") Permit No. WQ0013630001, Other Requirements No. 6].

2. Failed to report to the TCEQ in writing, any effluent violation which deviates from the permitted effluent limitation by more than 40% within five working days of becoming aware of noncompliance. Specifically, the Respondent did not provide noncompliance notifications for the exceedances during the monthly monitoring periods of December 2018 through September 2019 and November 2019 [30 TEX. ADMIN. CODE § 305.125(1) and (9) (A) and TPDES Permit No. WQ0013630001, Monitoring and Reporting Requirements No. 7.c].

3. Failed to install adequate safeguards to prevent the discharge of untreated or inadequately treated wastes during electrical power failures by means of alternate power sources, standby generators, and/or retention. Specifically, the backup diesel generator at the Facility was not operational [30 TEX. ADMIN. CODE § 305.125(1) and (5), and TPDES Permit No. WQ0013630001, Operational Requirements No. 4].

4. Failed to test the reduced-pressure backflow assembly ("RPBA") annually. Specifically, the RPBA was not tested by the June 10, 2018 due date [30 TEX. ADMIN. CODE § 317.4(a)(8)].

5. Failed to ensure the Facility and all of its systems of collection, treatment, and disposal are properly operated and maintained. Specifically, weir panels within the clarifier were partially separated which allowed wastewater between the weir panels and the clarifier wall into the trough; and of the three banks of ultraviolet lights used for disinfection, one was in disrepair and the other two appeared to have missing or dim bulbs [30 TEX. ADMIN. CODE § 305.125(1) and (5) and TPDES Permit No. WQ0013630001, Operational Requirements No. 1].

6. Failed to accurately calibrate all automatic flow measuring or recording devices and all totalizing meters for measuring flow and failed to have flow measurements, equipment, installation, and procedures conform to those prescribed in the Water Measurement Manual, United States Department of the Interior Bureau of Reclamation, Washington, D.C., or methods that are equivalent as approved. Specifically, the automatic flow meter was measuring a greater than 10% difference than the staff gauge and readings during peak flow were off the circle flow chart [30 TEX. ADMIN. CODE §§ 319.11(d) and 305.125(1) and TPDES Permit No. WQ0013630001, Monitoring and Reporting Requirements No. 5].

#### Executive Summary – Enforcement Matter – Case No. 58940 City of Poteet RN102078417 Docket No. 2020-0267-MWD-E

### **Corrective Actions/Technical Requirements**

#### **Corrective Action(s) Completed:**

The Respondent implemented the following corrective measures:

- a. Tested the RPBA by December 3, 2018;
- b. Calibrated the automatic flow measuring devices by December 30, 2019;
- c. Repaired the backup diesel generator by January 10, 2020;
- d. Repaired the weir panels within the clarifier by February 18, 2020; and
- e. Replaced the ultraviolet disinfection system at the Facility by January 11, 2021.

#### **Technical Requirements:**

The Order will require the Respondent to implement and complete a SEP (see SEP Attachment A).

#### **Contact Information**

#### **TCEQ Attorney:** N/A

TCEQ Enforcement Coordinator: Steven Van Landingham, Enforcement Division, Enforcement Team 3, MC 219, (512) 239-5717; Michael Parrish, Enforcement Division, MC 219, (512) 239-2548
TCEQ SEP Coordinator: Betty Sanders, SEP Coordinator, Litigation Division, MC 173, (512) 239-3992
Respondent: The Honorable Willie Leal, Jr., Mayor, City of Poteet, P.O. Box 378, Poteet, Texas 78065-0378
Kim Davis, City Administrator, City of Poteet, P.O. Box 378, Poteet, Texas 78065-0378
Respondent's Attorney: N/A

SCOMMISSION BURNISSION	Policy F	Pe Revision 4 (April 2014)	nalty Calc	ulatio	n Worksh	neet (PC	-	Revision March	n 26, 2014
DATES	Assigned						1		
	PCW	29-Jul-2021	Screening 11-	Feb-2020	EPA Due				
RESPO		TY INFORMATI	ON						
Rec	Respondent g. Ent. Ref. No.	City of Poteet							-
	ty/Site Region				Major/M	linor Source	Minor		
							•		
	NFORMATION f./Case ID No.	58940			No. c	of Violations	7		T
		2020-0267-MWD	)-Е			Order Type	-		1
Med	lia Program(s)				Government	•			]
	Multi-Media				Enf.		Steven Van La Enforcement 1		ł
Adn	nin. Penalty \$ I	Limit Minimum	\$0 <b>Ma</b> x	kimum	\$25,000				<u>1</u>
			Penalty (	Calcula	tion Section	on			
ΤΟΤΑΙ	L BASE PENA	LTY (Sum of	violation bas	e penalt	ties)		Subtotal 1		\$37,000
ADJUS	STMENTS (+	/-) TO SUBTO	DTAL 1						
	Subtotals 2-7 are of	otained by multiplying	the Total Base Penalt	, .					14.000
	Compliance Hi	· · ·		38.0%	Adjustment		tals 2, 3, & 7		\$14,060
	Notes		t for one order con nonths of self-rep	2	,	and nine			
	Culpability	No		0.0%	Enhancement		Subtotal 4		\$0
	Notes	The Re	spondent does no	ot meet the	culpability crite	eria.			
	Good Faith Eff	ort to Comply T	otal Adjustment	S			Subtotal 5		-\$2,186
			<b>,</b>						
	Economic Ben	efit		0.0%	Enhancement*		Subtotal 6		\$0
		Total EB Amounts I Cost of Compliance	\$11,395 \$142,955		d at the Total EB \$ A	Amount			
SUM C	OF SUBTOTA	LS 1-7				F	inal Subtotal	4	\$48,874
OTHE				1	0.0%		Adiusta	r	\$0
		AS JUSTICE M I Subtotal by the indic	<b>IAY REQUIRE</b> rated percentage.		0.0%		Adjustment		şυ
	Notes		· · · ·						
						Final Per	alty Amount		\$48,874
							-		,
STATI	JTORY LIMI	r adjustmen	IT			Final Asse	ssed Penalty		\$48,874
DEFEF	RRAL				20.0%	Reduction	Adjustment		-\$9,774
Reduces t	he Final Assessed Pe	enalty by the indicated	l percentage.				1		
	Notes	[	Deferral offered fo	or expedited	d settlement.				
PAYA	BLE PENALT	Y							\$39,100

		without a denial of liability, or default orders of this state or the federal government, or any final prohibitory emergency orders issued by the commission	0	0%	
	Judgments and Consent	Any non-adjudicated final court judgments or consent decrees containing a denial of liability of this state or the federal government ( <i>number of judgments or consent decrees meeting criteria</i> )	0	0%	
	Decrees Any adjudicated final court judgments and default judgments, or non-adjudicated final court judgments or consent decrees without a denial of liability, of this state or the federal government			0%	
	Convictions	Any criminal convictions of this state or the federal government ( <i>number of counts</i> )	0	0%	
	Emissions	Chronic excessive emissions events (number of events)	0	0%	
	Audits	Letters notifying the executive director of an intended audit conducted under the Texas Environmental, Health, and Safety Audit Privilege Act, 74th Legislature, 1995 (number of audits for which notices were submitted)	0	0%	
	Addits	Disclosures of violations under the Texas Environmental, Health, and Safety Audit Privilege Act, 74th Legislature, 1995 ( <i>number of audits for which violations were disclosed</i> )	0	0%	
				1	
		Environmental management systems in place for one year or more	No	0%	
	Other	Voluntary on-site compliance assessments conducted by the executive director under a special assistance program	No	0%	
		Participation in a voluntary pollution reduction program	No	0%	
		Early compliance with, or offer of a product that meets future state or federal government environmental requirements	No	0%	
		Adjustment Per	rcentage (Sub	ototal 2)	38%
> Re	peat Violator	(Subtotal 3)			
	No	Adjustment Per	rcentage (Sub	ototal 3)	0%
>> Co	mpliance Hist	ory Person Classification (Subtotal 7)			
	Satisfactory	Performer Adjustment Per	rcentage (Sub	ototal 7)	0%
>> Co	mpliance Hist	ory Summary			
	Compliance History Notes	Enhancement for one order containing a denial of liability and nine months of s effluent violations.	self-reported		
<b></b> Fina	Compliance	Total Compliance History Adjustment Percentage (S	Subtotals 2,	3, & 7) 📃	38%
>> rina	ai compliance	History Adjustment Final Adjustment Percent	200 Keened	at 100%	38%
		rinai Aujustinent Percent	aye "capped	at 100%	J070

#### Screening Date 11-Feb-2020 **Respondent** City of Poteet Case ID No. 58940 Reg. Ent. Reference No. RN102078417 Media Water Quality

Number of...

Other written NOVs

orders meeting criteria)

>>

Component

NOVs

Orders

#### Enf. Coordinator Steven Van Landingham

#### **Compliance History Worksheet Compliance History Site Enhancement (Subtotal 2)**

Written notices of violation ("NOVs") with same or similar violations as those in

Any agreed final enforcement orders containing a denial of liability (number of

Any adjudicated final enforcement orders, agreed final enforcement orders

the current enforcement action (number of NOVs meeting criteria)

Policy Revision 4 (April 2014) PCW Revision March 26, 2014

Number

0

9

1

Adjust.

0%

18%


20%




PCW

		ening Date			Doc	ket No. 2020-0267-MWD-E		PCW
		lespondent Case ID No.						Revision 4 (April 2014)
Reg.			RN102078417				PCWF	Revision March 26, 2014
		Media	Water Quality					
		Coordinator	Steven Van Lan	dingham				
	<b>VION</b>	Rule Cite(s)						
		Rule elle(3)				Texas Pollutant Discharge Elin 3630001, Other Requirements		
	Violatio	n Description				s. Specifically, the Responder he first day of January and Ap		
						Bas	e Penalty	\$25,000
>> Env	vironme	ntal, Propei	rty and Huma		Matrix			
		Release	Major	Harm Moderate	Minor			
OR		Actual						
		Potential				Percent 0.0%		
>>Pro	gramma	tic Matrix						
		Falsification	Major x	Moderate	Minor	Percent 5.0%		
	Matrix Notes		1009	% of the rule	requirements	were not met.		
						Adjustment	\$23,750	
						Augustinent	<i>4237730</i>	¢1 250
								\$1,250
Violati	on Event	ts						
		Number of \	violation Events	2		406 Number of violation	days	
			daily weekly monthly quarterly			Violation Bas	e Penalty	\$2,500
			semiannual annual single event	x				
				Two single ev	ents are recor	mmended.		
Good F	aith Effo	orts to Com		0.0%			Reduction	\$0
			Be Extraordinary	efore NOE/NOV	NOE/NOV to ED	PRP/Settlement Offer		
			Ordinary					
			N/A	х			1	
			- Notes	The Responde		neet the good faith criteria for iolation.		
						Violation	n Subtotal	\$2,500
Econor	nic Bene	efit (EB) for	this violatio	n		Statutory Limi	t Test	
		Estimate	ed EB Amount		\$525	Violation Final Pen	alty Total	\$3,450
				This viola	ation Final As	ssessed Penalty (adjusted f	for limits)	\$3,450
							,	


	Ec	conomic	Benefit	Wor	rksheet		
Respondent	City of Poteet						
Case ID No.							
eg. Ent. Reference No.	RN102078417						
	Water Quality					Percent Interest	Years of Depreciation
						5.0	15
	Item Cost	Date Required	Final Date	Yrs	Interest Saved	Costs Saved	EB Amount
Item Description		-					
p							
Delayed Costs							
Equipment		I IIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIII		0.00	\$0	\$0	\$0
Buildings				0.00	\$0	\$0	\$0
Other (as needed)				0.00	\$0	\$0	\$0
Engineering/Construction				0.00	\$0	\$0	\$0
Land				0.00	\$0	n/a	\$0
Record Keeping System				0.00	\$0	n/a	\$0
Training/Sampling				0.00	\$0	n/a	\$0
Remediation/Disposal				0.00	\$0	n/a	\$0
Permit Costs				0.00	\$0	n/a	\$0
Other (as needed)				0.00	\$0	n/a	\$0
Notes for DELAYED costs							
Avoided Costs		ITZE avoided o	osts before en	terina	item (except for	one-time avoide	l costs)
Avoided Costs	ANNUA	LIZE avoided c	osts before en	1	· · ·	one-time avoide	
Disposal	ANNU/	LIZE avoided c	osts before er	0.00	\$0	\$0	\$0
Disposal Personnel	ANNU/	LIZE avoided c	osts before er	0.00	\$0 \$0	\$0 \$0	\$0 \$0
Disposal Personnel nspection/Reporting/Sampling	ANNU/	LIZE avoided c	osts before er	0.00 0.00 0.00	\$0 \$0 \$0	\$0 \$0 \$0	\$0 \$0 \$0
Disposal Personnel	ANNU#	ALIZE avoided c	osts before er	0.00 0.00 0.00 0.00	\$0 \$0	\$0 \$0	\$0 \$0 \$0 \$0 \$0
Disposal Personnel nspection/Reporting/Sampling Supplies/Equipment	ANNUA	ALIZE avoided c	0sts before en 	0.00 0.00 0.00	\$0 \$0 \$0 \$0 \$0	\$0 \$0 \$0 \$0	\$0 \$0 \$0
Disposal Personnel nspection/Reporting/Sampling Supplies/Equipment Financial Assurance				0.00 0.00 0.00 0.00 0.00	\$0 \$0 \$0 \$0 \$0 \$0 \$0	\$0 \$0 \$0 \$0 \$0 \$0	\$0 \$0 \$0 \$0 \$0 \$0 \$0
Disposal Personnel nspection/Reporting/Sampling Supplies/Equipment Financial Assurance ONE-TIME avoided costs	\$503 Estimated avo	1-Apr-2019	11-Feb-2020 nit quarterly protection of the sequired is the se	0.00 0.00 0.00 0.00 0.87 0.00 ogress r he last r	\$0 \$0 \$0 \$0 \$0 \$22 \$0 reports due Januar	\$0 \$0 \$0 \$0 \$503 \$0 \$503 \$0 y and April 2019 (\$ parterly progress rel	\$0 \$0 \$0 \$0 \$525 \$0 250 per report



	E	conomic	Benefit	Wo	rksheet		
Respondent Case ID No.							
eg. Ent. Reference No.							
	Water Quality					Percent Interest	Years of Depreciation
						5.0	1
	Item Cost	Date Required	Final Date	Yrs	Interest Saved	Costs Saved	EB Amount
Item Description							
Delayed Costs				_			
Equipment				0.00	\$0	\$0	\$0
Buildings				0.00	\$0	\$0	\$0
Other (as needed)				0.00	\$0	\$0	\$0
Engineering/Construction				0.00	\$0	\$0	\$0
Land				0.00	\$0	n/a	\$0
Record Keeping System				0.00	\$0	n/a	\$0
Training/Sampling				0.00	\$0	n/a	\$0
Remediation/Disposal				0.00	\$0	n/a	\$0
Permit Costs				0.00	\$0	n/a	\$0
Other (as needed)				0.00	\$0	n/a	\$0
Notes for DELAYED costs		NITZE avoided o	osta hoforo or	toring	itom (overat for	· one-time avoided	d costs)
Avoided Costs	ANNUA	ALIZE avoided C	osts before en				
Disposal Personnel				0.00	\$0 \$0	\$0 \$0	\$0 \$0
					\$0 \$0	\$0	⇒U
							¢O
spection/Reporting/Sampling				0.00			\$0 \$0
spection/Reporting/Sampling Supplies/Equipment				0.00	\$0	\$0	\$0
spection/Reporting/Sampling Supplies/Equipment Financial Assurance	\$282	25-Dec-2019	11-Feb-2020	0.00	\$0 \$0	\$0 \$0	\$0 \$0
spection/Reporting/Sampling Supplies/Equipment Financial Assurance ONE-TIME avoided costs	\$282	25-Dec-2019	11-Feb-2020	0.00	\$0	\$0	\$0
spection/Reporting/Sampling Supplies/Equipment Financial Assurance				0.00 0.00 0.13 0.00	\$0 \$0 \$2 \$0	\$0 \$0 <mark>\$282 \$0</mark>	\$0 \$0 <mark>\$284</mark> \$0
spection/Reporting/Sampling Supplies/Equipment Financial Assurance ONE-TIME avoided costs	Estimated av December 203	oided cost to subr 18 through Septer	mit a noncompli mber 2019 and ate the last non	0.00 0.00 0.13 0.00 ance nc Novem	\$0 \$0 \$2 \$0 btification for the e ber 2019 (\$25 per nce notification wa	\$0 \$0 <b>\$282</b>	\$0 \$0 \$284 \$0 that occurred crued interest)



	E	conomic	Benefit	Wo	rksheet		
Respondent	City of Poteet						
Case ID No.	58940						
Reg. Ent. Reference No.	RN102078417						
	Water Quality						Years of
Violation No.						Percent Interest	Depreciation
Violation No.	. 5					5.0	
		Data Data ind	Eluci Dete	N.			-
		Date Required	Final Date	Yrs	Interest Saved	Costs Saved	EB Amount
Item Description							
Delayed Costs				_			
Equipment	\$5,000	10-Dec-2019	10-Jan-2020	0.08	\$1	\$28	\$29
Buildings				0.00	\$0	\$0	\$0
Other (as needed)				0.00	\$0	\$0	\$0
Engineering/Construction				0.00	\$0	\$0	\$0
Land				0.00	\$0	n/a	\$0
Record Keeping System				0.00	\$0	n/a	\$0
Training/Sampling				0.00	\$0	n/a	\$0
Remediation/Disposal				0.00	\$0	n/a	\$0
Permit Costs				0.00	\$0	n/a	\$0
Other (as needed)				0.00	\$0	n/a	\$0
Notes for DELAYED costs Avoided Costs		investiga	ition date and t	he Fina	Date is the comp	Facility. The Date F liance date.	
Disposal				0.00	\$0	\$0	\$0
Personnel				0.00	\$0	\$0	\$0
Inspection/Reporting/Sampling				0.00	\$0	\$0	\$0
Supplies/Equipment				0.00	\$0	\$0	\$0
Financial Assurance				0.00	\$0	\$0	\$0
ONE-TIME avoided costs		ĺ		0.00	\$0	\$0	\$0
Other (as needed)				0.00	\$0	\$0	\$0
Notes for AVOIDED costs							




	E	conomic	Benefit	Wo	rksheet		
Respondent	City of Poteet						
Case ID No.							
Reg. Ent. Reference No.							
	Water Quality					Percent Interest	Years of
Violation No.	4						Depreciation
						5.0	15
	Item Cost	<b>Date Required</b>	Final Date	Yrs	Interest Saved	Costs Saved	EB Amount
Item Description		•					
Item Description							
Delayed Costs							
Delayed Costs	r	<u></u>		0.00	¢0	¢0	¢O
Equipment				0.00	\$0 \$0	<u>\$0</u> \$0	<u>\$0</u> \$0
Buildings				0.00	\$0	\$0	\$0 \$0
Other (as needed) Engineering/Construction				0.00	\$0 \$0	\$0	\$0 \$0
Land				0.00	\$0	n/a	\$0 \$0
Record Keeping System				0.00	\$0 \$0	n/a	\$0
Training/Sampling				0.00	\$0	n/a	\$0
Remediation/Disposal				0.00	\$0	n/a	\$0
Permit Costs				0.00	\$0	n/a	\$0
Other (as needed)	\$250	10-Jun-2018	3-Dec-2018	0.00	\$6	n/a	\$6
Notes for DELAYED costs		was	due and the F	inal Dat	e is the compliance	Date Required is the date.	
Avoided Costs	ANNO	ALIZE AVOIDED C	USIS Delote el		· · ·		
Disposal				0.00	\$0	\$0	\$0
Personnel				0.00	\$0	\$0	\$0
Inspection/Reporting/Sampling				0.00	\$0 \$0	<u>\$0</u> \$0	<u>\$0</u> \$0
Supplies/Equipment Financial Assurance				0.00	\$0 \$0	\$0	\$0 \$0
ONE-TIME avoided costs				0.00	\$0 \$0	\$0 \$0	\$0 \$0
Other (as needed)				0.00	\$0	\$0	\$0
Notes for AVOIDED costs		<u></u>		<u>  0.00</u>		<u> </u>	30
Approx. Cost of Compliance		\$250			TOTAL		\$6

		ening Date			Do	cket No. 2020-0267-MWE	)-Е	PCW
		lespondent Case ID No.						Revision 4 (April 2014)
Rea. I			58940 RN102078417				PCW F	evision March 26, 2014
neg.			Water Quality					
			Steven Van Lar	ndingham				
	Viola	ation Number	5					
		Rule Cite(s)	30 Tex. Admin			5) and TPDES Permit No. WQ quirements No. 1	0013630001,	
	Violatio	n Description	disposal are p	roperly operat partially separa	ed and main ated which all	ts systems of collection, treat ained. Specifically, weir pan owed wastewater between the all into the trough.	els within the	
						I	Base Penalty	\$25,000
>> Env	ironme	ntal, Propei	ty and Hum		Matrix			
		Release	Major	Harm Moderate	Minor			
OR		Actual						
		Potential		х		Percent 5.0	0%	
>>Prog	Iramma	tic Matrix						
		Falsification	Major	Moderate	Minor			
						Percent 0.0	)%	
	Matrix Notes			are protective		ed to significant amounts of p alth or environmental recepto		
						Adjustment	\$23,750	
								\$1,250
								<i>41/200</i>
Violatio	on Event	ts						
		Number of \	/iolation Events	1		63 Number of violat	ion days	
			daily weekly monthly quarterly semiannual annual single event			Violation	Base Penalty	\$1,250
		One quarte	erly event is rec		om the Decer 1, 2020 scree	nber 10, 2019 investigation of ening date.	late to the	
Good Fa	aith Effo	orts to Com		10.0%			Reduction	\$125
			B Extraordinary	Before NOE/NOV	NOE/NOV to E	DPRP/Settlement Offer		
			Ordinary		X	<u> </u>		
			N/A					
			Notes	The Respor		d compliance by February 18 2020.	·	
						Viola	tion Subtotal	\$1,125
Econom	nic Bene	fit (EB) for	this violation	on		Statutory Li	mit Test	
		Estimate	ed EB Amount		\$499	Violation Final I	Penalty Total	\$1,600
				This vio	lation Final	Assessed Penalty (adjuste	d for limite)	\$1,600
						Assessed reliaity (aujuste	su for mints)	\$1,000

	E	conomic	Benefit	Wo	rksheet		
Respondent	City of Poteet						
Case ID No.	58940						
Reg. Ent. Reference No.	RN102078417						
	Water Quality						Years of
Violation No.						Percent Interest	Depreciation
	5					5.0	15
	Itom Cost	Date Required	Final Date	Vrc	Interest Saved	Costs Saved	EB Amount
	Item Cost	Date Required	Final Date	TIS	Interest Saved	Costs Saved	EB Amount
Item Description							
Delayed Costs	r						10
Equipment				0.00	\$0	\$0	\$0
Buildings Other (as needed)				0.00	\$0 \$0	\$0 \$0	<u>\$0</u> \$0
Engineering/Construction				0.00	\$0	\$0	\$0
Ligineering/construction		¦		0.00	\$0	n/a	\$0 \$0
Record Keeping System				0.00	\$0	n/a	\$0
Training/Sampling				0.00	\$0	n/a	\$0
Remediation/Disposal				0.00	\$0	n/a	\$0
Permit Costs				0.00	\$0	n/a	\$0
Other (as needed)	\$5,000	20-Feb-2018	18-Feb-2020	1.99	\$499	n/a	\$499
Notes for DELAYED costs		were initially	documented an	id the Fi	inal Date is the dat		
Avoided Costs	ANNU	ALIZE avoided c	osts before er	_	<u> </u>	r one-time avoide	
Disposal				0.00	\$0	\$0	\$0
Personnel				0.00	\$0	\$0	\$0
Inspection/Reporting/Sampling		<u> </u>		0.00	\$0 \$0	<u>\$0</u> \$0	<u>\$0</u> \$0
Supplies/Equipment Financial Assurance				0.00	\$0 \$0	\$0	\$0 \$0
ONE-TIME avoided costs				0.00	\$0	\$0	\$0 \$0
Other (as needed)				0.00	\$0	\$0	\$0
Notes for AVOIDED costs		<u>,                                     </u>		0.00	μο μο	<u> </u>	VU
Approx. Cost of Compliance		\$5,000			TOTAL		\$499

		ening Date		Docket No. 2020-0267-MWD-E	PCW
		lespondent Case ID No.			Revision 4 (April 2014)
Rea.			RN102078417	PCW F	Revision March 26, 2014
			Water Quality		
			Steven Van Landingham		
	Viola	ation Number Rule Cite(s)	6		1
		Rule Cite(s)	JU TEX. Autilit. Code 9 Ju.	5.125(1) and (5) and TPDES Permit No. WQ0013630001, Operational Requirements No. 1	
	Violatio	n Description	disposal are properly oper ultraviolet lights used fo	ility and all of its systems of collection, treatment, and ated and maintained. Specifically, of the three banks of or disinfection, one was in disrepair and the other two ared to have missing or dim bulbs.	
				Base Penalty	\$25,000
>> Env	vironme	ntal, Propei	rty and Human Health	n Matrix	
		Release	Harm Major Moderate	Minor	
OR		Actual			
		Potential	X	Percent 15.0%	
	a ka ma a	tic Motrix			
>>PTO	grannia	tic Matrix Falsification	Major Moderate	Minor	
				Percent 0.0%	
					1
	Matrix Notes			could be exposed to pollutants that would exceed levels r environmental receptors as a result of the violation.	
				Adjustment \$21,250	
					\$3,750
					\$3,730
Violatio	on Even	ts			
		Number of \	/iolation Events 3	63 Number of violation days	
			daily	_	
			weekly monthly x	-	
			quarterly	Violation Base Penalty	\$11,250
			semiannual		
			annual single event	_	
		-			
		Three month	,	f from the December 10, 2019 investigation date to the 11, 2020 screening date.	
Good 5	aith Eff	orts to Com	ply 0.0%	Reduction	\$0
GUUU F			Before NOE/NOV		30
			Extraordinary		
			Ordinary		
			N/A <u>x</u>		
			Notes The Respon	ident does not meet the good faith criteria for this violation.	
				Violation Subtotal	\$11,250
Econor	nic Bene	efit (EB) for	this violation	Statutory Limit Test	
		Estimate	ed EB Amount	\$10,051 Violation Final Penalty Total	\$15,525
			This vi	olation Final Assessed Penalty (adjusted for limits)	\$15,525

	E	conomic	Benefit	Wo	rksheet		
Respondent	City of Poteet						
Case ID No.	58940						
Reg. Ent. Reference No.	RN102078417						
	Water Quality						Years of
Violation No.						Percent Interest	Depreciation
						5.0	15
	Item Cost	Date Required	Final Date	Yrs	Interest Saved	Costs Saved	EB Amount
Item Description		•					
Delayed Costs							
Equipment				0.00	\$0	\$0	\$0
Buildings				0.00	\$0	\$0	\$0
Other (as needed)				0.00	\$0	\$0	\$0
Engineering/Construction	\$131,670	10-Dec-2019	11-Jan-2021	1.09	\$479	\$9,572	\$10,051
Land				0.00	\$0	n/a	\$0
Record Keeping System				0.00	\$0	n/a	\$0
Training/Sampling				0.00	\$0	n/a	\$0
Remediation/Disposal				0.00	\$0	n/a	\$0
Permit Costs				0.00	\$0	n/a	\$0
Other (as needed)				0.00	\$0	n/a	\$0
Notes for DELAYED costs		Required is the	investigation da	te and	the Final Date is th	on system at the Fac ne compliance date.	
Avoided Costs Disposal	ANNO		USIS DEIDIE EI	0.00	\$0	\$0	\$0
Personnel				0.00	\$0	\$0	\$0
Inspection/Reporting/Sampling		1		0.00	\$0	\$0	\$0
Supplies/Equipment				0.00	\$0	\$Ŭ	\$0
Financial Assurance				0.00	\$0	\$Ŭ	\$0
ONE-TIME avoided costs				0.00	\$0	\$0	\$0
Other (as needed)				0.00	\$0	\$0	\$0
Notes for AVOIDED costs							
Approx. Cost of Compliance		\$131,670			TOTAL		\$10,051



	E	conomic	Benefit	Wo	rksheet		
Respondent	City of Poteet						
Case ID No.	'						
Reg. Ent. Reference No.							
	Water Quality					Percent Interest	Years of
Violation No.	7						Depreciation
						5.0	15
	Item Cost	<b>Date Required</b>	Final Date	Yrs	Interest Saved	Costs Saved	EB Amount
Item Description							
Delayed Costs							
Equipment	1			0.00	\$0	\$0	\$0
Buildings				0.00	\$0	\$0	\$0
Other (as needed)				0.00	\$0	\$0	\$0
Engineering/Construction				0.00	\$0	\$0	\$0
Land				0.00	\$0	n/a	\$0
Record Keeping System				0.00	\$0	n/a	\$0
Training/Sampling				0.00	\$0	n/a	\$0
Remediation/Disposal				0.00	\$0	n/a	\$0
Permit Costs				0.00	\$0	n/a	\$0
Other (as needed)	\$250	10-Dec-2019	30-Dec-2019	0.05	\$1	n/a	\$1
Notes for DELAYED costs		investiga	ation date and t	he Fina:	I Date is the comp		
Avoided Costs	ANNU	ALIZE avoided c	osts before er		<u> </u>	one-time avoided	
Disposal				0.00	\$0	\$0	\$0
Personnel				0.00	\$0	\$0	\$0
Inspection/Reporting/Sampling				0.00	\$0	\$0 ¢0	\$0
Supplies/Equipment Financial Assurance				0.00	\$0 \$0	\$0 \$0	<u>\$0</u> \$0
ONE-TIME avoided costs	-			0.00	\$0 \$0	\$0 \$0	
Other (as needed)				0.00	\$0 \$0	\$0	\$0 \$0
Notes for AVOIDED costs		]]		0.00	50	<u> </u>	<u><u></u></u>
Approx. Cost of Compliance		\$250			TOTAL		\$1

# 🧖 Compliance History Report

Customer, Respondent, CK600734818, City of Poteet Classification: SATISFACTORY Rating: 19.00 or Owner/Operator: Regulated Entity: RN102078417, City of Poteet Classification: SATISFACTORY Rating: 19.00 Complexity Points: 7 Regondent, City of Poteet Classification: SATISFACTORY Rating: 19.00 Complexity Points: 7 Regondent, City of Poteet, Atascosa County, Texas TCEQ Region: REGION 13 - SAN ANTONIO DNUmber(s): WASTEWATER PERMIT WQ0013630001 WASTEWATER EPA ID TX0032387 WASTEWATER PREMIT WQ0013630001 WASTEWATER EPA ID TX0032387 WASTEWATER PREMIT WQ0013630001 WASTEWATER LICENSING LICENSE WQ0013630001 Compliance History Period: September 01, 2014 to August 31, 2019 Rating Year: 2019 Rating Date: 09/01/2019 Date Compliance History Report Prepared: May 06, 2020 Agency Decision Requiring Compliance History: Enforcement Components Period Selected: May 06, 2020 TCEQ Staff Member to Contact for Additional Information Regarding This Compliance History. Name: Steven Van Landingham Phone: (512) 239-5717 Ste and Owner/Operator History 1) Has the site been in existence and/or operation for the full five year compliance period? NO Components (Multimedia) for the Site Are Listed in Sections A - 1 A. Final Orders, court judgments, and consent decrees: 1 Effective Date: 09/02/2016 ADMINORDER 2015-0103-MWD-E (1660 Order-Agreed Order With Denial) Classification: Minor Classification: Moderate Classification: Minor Classification: Moderate Classification: Minor Classificatio	Compliance History		417, Rating Year 2019 which includes C	compliance History (CH)			
Regulated Entity:       RN102078417, City of Poteet       Classification: SATISFACTORY       Rating: 19.00         Complexity Points:       7       Repeat Violator: NO         CH Group:       08 - Sewage Treatment Facilities         Location:       1304 South 9" Street, City of Poteet, Atascose County, Texas         TCEQ Region:       REGION 13 - SAN ANTONIO         Dawnber(s):       WASTEWATER PERMIT WQ013630001       WASTEWATER PEA ID TX0032387         WASTEWATER PERMIT WQ013630001       WASTEWATER PEA ID TX0032387         WASTEWATER PERMIT WQ013630001       WASTEWATER LICENSING LICENSE WQ0013630001         WASTEWATER PERMIT WQ013630001       WASTEWATER LICENSING LICENSE WQ0013630001         Compliance History Period:       September 01, 2014 to August 31, 2019       Rating Year: 2019       Rating Date: 09/01/2019         Date Compliance History Report Prepared:       May 06, 2020       Mastrewater Autonown, Change In ownership/operator       Phone: (512) 239-5717         Test and Owner/Operator History:       Reference       Reference       No         2) Has there been a (known) change In ownership/operator of the site during the compliance period?       YES         2) Has there been a (known) change In ownership/operator of the site during the compliance Pariod?       No         2) Has there usen a (known) change In ownership/operator of the site during the convolagaps between the weir and clariffer walls),	Customer, Respondent,			DRY Rating: 19.00			
Complexity Points:       7       Repeat Violator: N0         CH Group:       08 - Sewage Treatment Facilities         Location:       1304 South 9th Street, City of Poteet, Atascosa County, Texas         TCEQ Region:       REGION 13 - SAN ANTONIO         ED Number(s):       WASTEWATER PERMIT WQ0013630001         WASTEWATER PERMIT WQ0013630001       WASTEWATER LICENSING LICENSE WQ0013630001         Compliance History Period: September 01, 2014 to August 31, 2019       Rating Year: 2019       Rating Date: 09/01/2019         Date Compliance History Report Prepared:       May 06, 2020       Agency Decision Requiring Compliance History: Enforcement         Component Period Selected:       May 06, 2015 to May 06, 2020       TCEQ Staff Member to Contact for Additional Information Regarding This Compliance History. Name: Steven Van Landingham       Phone: (512) 239-5717         Site and Owner/Operator History:       14 has the site been in existence and/or operation for the full five year compliance period?       YES         2) Has there been a (known) change in ownership/operator of the site during the compliance period?       NO         Components (Multimedia) for the Site Are Listed in Sections A - 1       Anial Orders, court judgments, and consent decrees:         1       Effective Date: 09/29/2016       ADMINORDER 2016-0103-MWD-E (1660 Order-Agreed Order With Denial)         Classification:       Minor         2       Dat Chapte	•	DN102070417 City of Datast	Classification, SATISFACT	Dating 10.00			
CH Group:       08 - Sewage Treatment Facilities         Location:       1304 South 9 <sup>th</sup> Street, City of Poteet, Atascosa County, Texas         TCEQ Region:       REGION 13 - SAN ANTONIO         ID Number(s):       WASTEWATER PERNIT WQ0013630001         WASTEWATER PERNIT WQ0013630001       WASTEWATER PENIT WQ0013630001         Compliance History Period:       September 01, 2014 to August 31, 2019       Rating Vear: 09/01/2019         Date Compliance History Report Prepared:       May 06, 2020         Agency Decision Requiring Compliance History:       Enforcement         Component Period Selected:       May 06, 2015 to May 06, 2020         TCEQ Staff Member to Contact for Additional Information Regarding This Compliance History.       Name: Steven Van Landingham         1) Has the site been in existence and/or operator for the full five year compliance period?       YES         2) Has there been a (known) change in ownership/operator of the site during the compliance period?       YES         1) Has the site baen in existence and/or operator for the full five year Compliance period?       YES         2) Has there been a (known) change in ownership/operator of the site during the compliance History:       Infor Charge Court Judgments, and consent decrees         1       Effective Date:       09/29/2016       ADMINORDER 2016-1013-MWD-E       (1660 Order-Agreed Order With Denial)         Classification:       Inder Chapter		. ,		DRF <b>Rating:</b> 19.00			
Location: IS 1304 South 9 <sup>th</sup> Street, City of Poteet, Atascosa County, Texas TCEQ Region: REGION 13 - SAN ANTONIO D Number(S): WASTEWATER PERMIT WQ0013630001 WASTEWATER PERMIT WASTEWATER PERMIT 1 Has the site been in existence and/or operation for the full five year compliance period? WES 2) Has there been a (known) change in ownership/operator of the site during the compliance period? NO Components (Multimedia) for the Site Are Listed in Sections A - J A. Final Orders, court judgments, and consent decrees: 1 Effective Date: 09/29/2016 ADMINORDER 2016-00103-MWD-E (1660 Order-Agreed Order With Denial) Classification: Minor Classification: Minor Classification: Minor Classification: Minor Classification: Minor Classification: Minor Mastewater to flow through apps between the weir and clarifier walls, the sludge blanket level in the large clarifier was 10.5 feet in a total water depth of 14 feet, and only 1 out of 3 pumps installed was operational. Classification: Moderate Classification: Moderate Classification: Moderate Classification: Moderate Clastion: 20 TAC Chapter 305, SubCh		-					
TCEQ Region:       REGION 13 - SAN ANTONO         ID Number(s):       WASTEWATER PERMIT WQ0013630001       WASTEWATER PEPA ID TX0032387         WASTEWATER PERMIT WQ0013630001       WASTEWATER PEPA ID TX0032387         WASTEWATER AUTHORIZATION R13630001       WASTEWATER LICENSING LICENSE WQ0013630001         Compliance History Period:       September 01, 2014 to August 31, 2019       Rating Year: 2019       Rating Date: 09/01/2019         Date Compliance History Report Prepared:       May 06, 2020         Agency Decision Requiring Compliance History:       Enforcement         Component Period Selected:       May 06, 2015 to May 06, 2020         TCEQ Staff Member to Contact for Additional Information Regarding This Compliance History.       Name: Steven Van Landingham         Phone:       (512) 239-5717         Stea and Owner/Operator History:       Name:         Name: Steven Van Landingham       Phone:         Phone:       (512) 239-5717         Stea and Owner/Operator History:       Name:         J has the stee been in existence and/or operation for the full five year compliance period?       YES         2) Has three been a (known) change in ownership/operator of the stee during the compliance Period?       No         Components (Multimedia) for the Site Arc Elsted in Sections A - J       Classification: Minor         Classification:       More       So	-						
ID Number(s): WASTEWATER PERMIT WQ0013630001 WASTEWATER AUTHORIZATION R13630001 WASTEWATER AUTHORIZATION R13630001 Compliance History Report Prepared: May 06, 2020 Agency Decision Requiring Compliance History: Enforcement Component Period Selected: May 06, 2015 to May 06, 2020 TCEQ Staff Member to Contact for Additional Information Regarding This Compliance History. Name: Steven Van Landingham Phone: (512) 239-5717 Site and Owner/Operator History: 1) Has the site been a (known) change in ownership/operator of the site during the compliance period? 2) Has there been a (known) change in ownership/operator of the site during the compliance period? 2) Has there been a (known) change in ownership/operator of the site during the compliance period? 2) Has there been a (known) change in ownership/operator of the site during the compliance period? 3) Has there been a (known) change in ownership/operator of the site during the compliance period? 3) Has there been a (known) change in ownership/operator of the site during the compliance period? 3) Has there been a (known) change in ownership/operator of the site during the compliance period? 4) Has there been a (known) change in ownership/operator of the site during the compliance period? 3) TAC Chapter 305, SubChapter F 305.125(1) 3) TAC Chapter 305, SubChapter F 305.125(5) Rgmt Prov: Operational Requirements No. 1 PERMIT Description: Failed to properly operate and maintain the Facility and all of its systems of collection, treatment and disposal, as documented during an investigation conducted on November 15, 2015. Specifically, the weir panels were not affixed to the clarifier walls (allowing wastewater to flow through gaps between the weir and clarifier walls), the sludge blanket level in the large clarifier was 10.5 feet in a total water depth of 14 feet, and only 1 out of 3 pumps installed was operational. Classification: Moderate Classification: Moderate Classification: Moderate Classification: Moderate Classification: Moderate Classif		1304 South 9 <sup>th</sup> Street, City of Poteet, Atascosa County, Texas					
WASTEWATER FERIOR TWQ0013630001       WASTEWATER PAID TX0032387         WASTEWATER AUTHORIZATION R13630001       WASTEWATER FLCENSING LICENSE WQ0013630001         Compliance History Period: September 01, 2014 to August 31, 2019       Rating Year: 2019       Rating Date: 09/01/2019         Date Compliance History Report Prepared:       May 06, 2020       Rating Year: 2019       Rating Date: 09/01/2019         Agency Decision Requiring Compliance History:       Enforcement       Component Period Selected:       May 06, 2020         TCEQ Staff Member to Contact for Additional Information Regarding This Compliance History.       Name: Steven Van Landingham       Phone: (512) 239-5717         Site and Owner/Operator History:       1) Has the site been a (known) change in ownership/operator of the site during the compliance period?       YES         2) Has there been a (known) change in ownership/operator of the site during the compliance period?       NO         Components (Multimedia) for the Site Are Listed in Sections A - J       A.         A. Final Orders, court judgments, and consent decrees:       1       Effective Date: 09/29/2016       ADMINORDER 2016-0103-MWD-E       (1660 Order-Agreed Order With Denial)         Classification:       Mior       Citation: 30 TAC Chapter 305, SubChapter F 305.125(1)       30 TAC Chapter 305, SubChapter F 305.125(5)         Rgmt Prov: Operational Requirements No. 1 PERMIT       Description: Failed to properly operate and maintain the Facility and all of	TCEQ Region:	REGION 13 - SAN ANTONIO					
Date Compliance History Report Prepared: May 06, 2020         Agency Decision Requiring Compliance History: Enforcement         Component Period Selected: May 06, 2015 to May 06, 2020         TCEQ Staff Member to Contact for Additional Information Regarding This Compliance History. Name: Steven Van Landingham Phone: (512) 239-5717         Site and Owner/Operator History:         1) Has the site been in existence and/or operation for the full five year compliance period? YES         2) Has there been a (known) change in ownership/operator of the site during the compliance period? NO         Components (Multimedia) for the Site Are Listed in Sections A - J         A. Final Orders, court judgments, and consent decrees:         1       Effective Date: 09/29/2016 ADMINORDER 2016-0103-MWD-E (1660 Order-Agreed Order With Denial)         Classification: Minor         Citation: 30 TAC Chapter 305, SubChapter F 305.125(1)         30 TAC Chapter 305, SubChapter F 305.125(5)         Rqmt Prov: Operational Requirements No. 1 PERMIT         Description: Failed to properly operate and maintain the Facility and all of its systems of collection, treatment and disposal, as documented during an investigation conducted on November 16, 2015. Specifically, the weir panels were not affixed to the carifier was 10.5 feet in a total water depth of 14 feet, and only 1 out of 3 pumps installed was operational.         Classification: Moderate       Classification: Moderate         Citation: 30 TAC Chapter 305, SubChapter F 305.125(1)       Rqmt Prov: Monitoring and Reportin	WASTEWATER PERMIT WQ0			WQ0013630001			
Agency Decision Requiring Compliance History:       Enforcement         Component Period Selected:       May 06, 2015 to May 06, 2020         TCEQ Staff Member to Contact for Additional Information Regarding This Compliance History.       Name: Steven Van Landingham         Phone:       (512) 239-5717         Site and Owner/Operator History:       1) Has the site been in existence and/or operation for the full five year compliance period?       YES         2) Has there been a (known) change in ownership/operator of the site during the compliance period?       NO         Components (Multimedia) for the Site Are Listed in Sections A - J       NO         A. Final Orders, court judgments, and consent decrees:       1         1       Effective Date:       09/29/2016       ADMINORDER 2016-0103-MWD-E       (1660 Order-Agreed Order With Denial)         Classification:       Minor       Classification:       Minor         Clation:       30 TAC Chapter 305, SubChapter F 305.125(1)       30 TAC Chapter 305, SubChapter F 305.125(5)         Rgmt Prov:       Operational Requirements No. 1 PERMIT       Description:       Failed to properly operate and maintain the Facility and all of its systems of collection, treatment and disposal, as documented during an investigation conducted on November 16, 2015.       Specifically, the weir panels were not affixed to the clarifier walls 0, SubChapter F 305.125(1)         Right Prov:       Molarifier walls (allowing wastewater to flow through gaps	<b>Compliance History Peri</b>	od: September 01, 2014 to August	31, 2019 Rating Year: 2019	Rating Date: 09/01/2019			
Component Period Selected: May 06, 2015 to May 06, 2020 TCEQ Staff Member to Contact for Additional Information Regarding This Compliance History. Name: Steven Van Landingham Phone: (512) 239-5717 Site and Owner/Operator History: 1) Has the site been in existence and/or operation for the full five year compliance period? YES 2) Has there been a (known) change in ownership/operator of the site during the compliance period? NO Components (Multimedia) for the Site Are Listed in Sections A - J A. Final Orders, court judgments, and consent decrees: 1 Effective Date: 09/29/2016 ADMINORDER 2016-0103-MWD-E (1660 Order-Agreed Order With Denial) Classification: Minor Classification: Minor Classification: 30 TAC Chapter 305, SubChapter F 305.125(1) 30 TAC Chapter 305, SubChapter F 305.125(5) Rqmt Prov: Operational Requirements No. 1 PERMIT Description: Failed to properly operate and maintain the Facility and all of its systems of collection, treatment and disposal, as documented during an investigation conducted on November 16, 2015. Specifically, the weir panels were not affixed to the clarifier walls (allowing wastewater to flow through gaps between the weir and clarifier walls), the sludge blanket level in the large clarifier was 10.5 feet in a total water depth of 14 feet, and only 1 out of 3 pumps installed was operational. Classification: Moderate Citation: 30 TAC Chapter 305, SubChapter F 305.125(1) Rqmt Prov: Monitoring and Reporting Regs 7.c PERMIT Description: Failure to provide notification of any effluent violation which deviates from the permitted effluent limitation by more than 40%. Specifically, during the record review period of October 2014 to September 2015, violations of the daily maximum concentration for E. coli, daily average concentration for ammonia nitrogen, and daily average and daily maximum concentration for to tal suspended solids were noted to have deviated from the permitted limit by more than 40% (See Attachment 2). Classification: Moderate Citation: 2D TWC Chap	Date Compliance History	<b>Report Prepared:</b> May 06, 20	20				
TCEQ Staff Member to Contact for Additional Information Regarding This Compliance History.         Name: Steven Van Landingham       Phone: (512) 239-5717         Site and Owner/Operator History:       1) Has the site been in existence and/or operation for the full five year compliance period?       YES         2) Has there been a (known) change in ownership/operator of the site during the compliance period?       NO         Components (Multimedia) for the Site Are Listed in Sections A - J       NO         A. Final Orders, court judgments, and consent decrees:       1         1       Effective Date: 09/29/2016       ADMINORDER 2016-0103-MWD-E (1660 Order-Agreed Order With Denial)         Classification:       Minor         Citation:       30 TAC Chapter 305, SubChapter F 305.125(1)         30 TAC Chapter 305, SubChapter F 305.125(5)       Rqmt Prov: Operational Requirements No. 1 PERMIT         Description:       Failed to properly operate and maintain the Facility and all of its systems of collection, treatment and disposal, as documented during an investigation conducted on November 16, 2015. Specifically, the weir panels were not affixed to the clarifier walls (allowing wastewater to flow through gaps between the weir and clarifier walls), the sludge blanket level in the large clarifier was 10.5 feet in a total water depth of 14 feet, and only 1 out of 3 pumps installed was operational.         Classification:       30 TAC Chapter 305, SubChapter F 305.125(1)         Rqmt Prov: Monitoring and Reporting Reqs 7.c PERMIT         Descr	Agency Decision Requiri	ing Compliance History: Enfor	rcement				
Name:       Steven Van Landingham       Phone:       (512) 239-5717         Site and Owner/Operator History:       1) Has the site been in existence and/or operation for the full five year compliance period?       YES         2) Has there been a (known) change in ownership/operator of the site during the compliance period?       NO         Components (Multimedia) for the Site Are Listed in Sections A - J       NO         A. Final Orders, court judgments, and consent decrees:       1         1       Effective Date:       09/29/2016       ADMINORDER 2016-0103-MWD-E       (1660 Order-Agreed Order With Denial)         Classification:       Minor         Citation:       30 TAC Chapter 305, SubChapter F 305.125(1)       30 TAC Chapter 305, SubChapter F 305.125(5)         Rqmt Prov:       Operational Requirements No. 1 PERMIT       Description:       Failed to properly operate and maintain the Facility and all of its systems of collection, treatment and disposal, as documented during an investigation conducted on November 16, 2015. Specifically, the weir panels were not affixed to the clarifier was 10.5 feet in a total water depth of 14 feet, and only 1 out of 3 pumps installed was operational.         Classification:       Moderate       Citation:       30 TAC Chapter 305, SubChapter F 305.125(1)         Rqmt Prov:       Moderate       Citation:       Specifically, during the record review period of October 2014 to September 2015, violations of the daily maximum concentration for E. coli, daily average concentration for	<b>Component Period Selec</b>	ted: May 06, 2015 to May 06, 202	20				
Site and Owner/Operator History:         1) Has the site been in existence and/or operation for the full five year compliance period?       YES         2) Has there been a (known) change in ownership/operator of the site during the compliance period?       NO         Components (Multimedia) for the Site Are Listed in Sections A - J       NO         A. Final Orders, court judgments, and consent decrees:       1         1       Effective Date: 09/29/2016       ADMINORDER 2016-0103-MWD-E (1660 Order-Agreed Order With Denial)         Classification: Minor       Classification: Minor         Citation: 30 TAC Chapter 305, SubChapter F 305.125(1)       30 TAC Chapter 305, SubChapter F 305.125(5)         Rqmt Prov: Operational Requirements No. 1 PERMIT       Description: Failed to properly operate and maintain the Facility and all of its systems of collection, treatment and disposal, as documented during an investigation conducted on November 16, 2015. Specifically, the weir panels were not affixed to the clarifier walls (allowing wastewater to flow through gaps between the weir and clarifier walls, old lowing wastewater to flow through gaps between the weir and clarifier walls, old allowing wastewater to flow through gaps between the weir and clarifier walls, during the record review period of October 2014 to September 2015, violations of the daily maximum concentration for E. coil, daily average concentration for ammonia nitrogen, and daily average and daily maximum concentrations for the subspended solids were noted to have deviated from the permitted limit by more than 40%. See fileally, during the record review period of October 2014 to September 2015, violations of the daily maximum concentration fo	TCEQ Staff Member to C	ontact for Additional Informat		-			
<ul> <li>1) Has the site been in existence and/or operation for the full five year compliance period? YES</li> <li>2) Has there been a (known) change in ownership/operator of the site during the compliance period? NO</li> <li>Components (Multimedia) for the Site Are Listed in Sections A - J</li> <li>A. Final Orders, court judgments, and consent decrees: <ul> <li>Effective Date: 09/29/2016</li> <li>ADMINORDER 2016-0103-MWD-E (1660 Order-Agreed Order With Denial)</li> <li>Classification: Minor</li> <li>Citation: 30 TAC Chapter 305, SubChapter F 305.125(1)</li> <li>30 TAC Chapter 305, SubChapter F 305.125(5)</li> <li>Rqmt Prov: Operational Requirements No. 1 PERMIT</li> <li>Description: Failed to properly operate and maintain the Facility and all of its systems of collection, treatment and disposal, as documented during an investigation conducted on November 16, 2015. Specifically, the weir panels were not affixed to the clarifier walls (allowing wastewater to flow through gaps between the weir and clarifier walls), the sludge blanket level in the large clarifier was 10.5 feet in a total water depth of 14 feet, and only 1 out of 3 pumps installed was operational.</li> <li>Classification: Moderate</li> <li>Citation: 30 TAC Chapter 305, SubChapter F 305.125(1)</li> <li>Rqmt Prov: Monitoring and Reporting Regs 7.c PERMIT</li> <li>Description: Failure to provide notification of any effluent violation which deviates from the permitted effluent limitation by more than 40%. Specifically, during the record review period of October 2014 to September 2015, violations of the daily maximum concentration for E. coli, daily average concentration for ammonia nitrogen, and daily average and dai</li></ul></li></ul>		-	<b>Phone:</b> (512) 239-57	717			
<ul> <li>2) Has there been a (known) change in ownership/operator of the site during the compliance period? NO</li> <li>Components (Multimedia) for the Site Are Listed in Sections A - J</li> <li>A. Final Orders, court judgments, and consent decrees: <ol> <li>Effective Date: 09/29/2016</li> <li>ADMINORDER 2016-0103-MWD-E (1660 Order-Agreed Order With Denial)</li> <li>Classification: Minor</li> <li>Citation: 30 TAC Chapter 305, SubChapter F 305.125(1)</li> <li>30 TAC Chapter 305, SubChapter F 305.125(5)</li> <li>Rqmt Prov: Operational Requirements No. 1 PERMIT</li> <li>Description: Failed to properly operate and maintain the Facility and all of its systems of collection, treatment and disposal, as documented during an investigation conducted on November 16, 2015. Specifically, the weir panels were not affixed to the clarifier walls (allowing wastewater to flow through gaps between the weir and clarifier walls), the sludge blanket level in the large clarifier was 10.5 feet in a total water depth of 14 feet, and only 1 out of 3 pumps installed was operational.</li> <li>Classification: Moderate</li> <li>Citation: 30 TAC Chapter 305, SubChapter F 305.125(1)</li> <li>Rqmt Prov: Monitoring and Reporting Regs 7.c PERMIT</li> <li>Description: Failure to provide notification of any effluent violation which deviates from the permitted effluent limitation by more than 40%. Specifically, during the record review period of October 2014 to September 2015, violations of the daily maximum concentration for total suspended solids were noted to have deviated from the permitted limit by more than 40% (See Attachment 2).</li> <li>Classification: Moderate</li> <li>Citation: 20 TWC Chapter 26, SubChapter A 26.121(a)(1)</li> <li>30 TAC Chapter 305, SubChapter F 305.125(1)</li> </ol> </li> </ul>				NEC.			
Components (Multimedia) for the Site Are Listed in Sections A - J         A. Final Orders, court judgments, and consent decrees:         1       Effective Date: 09/29/2016       ADMINORDER 2016-0103-MWD-E (1660 Order-Agreed Order With Denial)         Classification: Minor       Citation: 30 TAC Chapter 305, SubChapter F 305.125(1)       30 TAC Chapter 305, SubChapter F 305.125(5)         Rqmt Prov: Operational Requirements No. 1 PERMIT       Description: Failed to properly operate and maintain the Facility and all of its systems of collection, treatment and disposal, as documented during an investigation conducted on November 16, 2015. Specifically, the weir panels were not affixed to the clarifier walls (allowing wastewater to flow through gaps between the weir and clarifier walls), the sludge blanket level in the large clarifier was 10.5 feet in a total water depth of 14 feet, and only 1 out of 3 pumps installed was operational.         Classification: Moderate       Citation: 30 TAC Chapter 305, SubChapter F 305.125(1)         Rqmt Prov: Monitoring and Reporting Reqs 7.c PERMIT       Description: Failure to provide notification of any effluent violation which deviates from the permitted effluent limitation by more than 40%. Specifically, during the record review period of October 2014 to September 2015, violations of the daily maximum concentration for E. coli, daily average concentration for ammonia nitrogen, and daily average and daily maximum concentrations for total suspended solids were noted to have deviated from the permitted limit by more than 40% (See Attachment 2).         Classification:       2D TWC Chapter 26, SubChapter A 26.121(a)(1)         30 TAC Chapter 305, SubChapter F 305.125(1) <th>,</th> <td></td> <td></td> <td></td>	,						
A. Final Orders, court judgments, and consent decrees:         1       Effective Date: 09/29/2016       ADMINORDER 2016-0103-MWD-E       (1660 Order-Agreed Order With Denial)         Classification:       Minor         Citation:       30 TAC Chapter 305, SubChapter F 305.125(1)         30 TAC Chapter 305, SubChapter F 305.125(5)         Rqmt Prov:       Operational Requirements No. 1 PERMIT         Description:       Failed to properly operate and maintain the Facility and all of its systems of collection, treatment and disposal, as documented during an investigation conducted on November 16, 2015. Specifically, the weir panels were not affixed to the clarifier walls (allowing wastewater to flow through gaps between the weir and clarifier walls), the sludge blanket level in the large clarifier was 10.5 feet in a total water depth of 14 feet, and only 1 out of 3 pumps installed was operational.         Classification:       Moderate         Citation:       30 TAC Chapter 305, SubChapter F 305.125(1)         Rqmt Prov:       Monitoring and Reporting Regs 7.c PERMIT         Description:       Failure to provide notification of any effluent violation which deviates from the permitted effluent limitation by more than 40%. Specifically, during the record review period of October 2014 to September 2015, violations of the daily maximum concentration for E. coli, daily average concentration for amonia nitrogen, and daily average and daily maximum concentrations for total suspended solids were noted to have deviated from the permitted limit by more than 40% (See Attachment 2).         Classification:       <	, , ,		· · ·	110			
Rqmt Prov: Permit Conditions No. 2.g PERMIT Description: Failed to prevent unauthorized discharges of wastewater or any other waste into or adjacent to water in the state at any location not permitted as an outfall. Specifically, during the 18 months preceding the investigation, one unauthorized discharge (UD) occurred on October 2, 2015, discharging 200 gallons of untreated wastewater. Classification: Moderate Citation: 30 TAC Chapter 305, SubChapter F 305.125(1) Rqmt Prov: Monitoring and Reporting Reqs No. 7.b.i PERMIT Description: Failed to provide notification of any noncompliance which may endanger human health or safety, or the environment. Specifically, during the record review period of May 2014 to October 2015, one UD was noted to have	A. Final Orders, court ju 1 Effective Date: 0 Classification: 1 Citation: 30 T/ 30 T/ Rqmt Prov: Ope Description: Fa disposal, as docu affixed to the cla blanket level in to operational. Classification: 1 Citation: 30 T/ Rqmt Prov: Mon Description: Fa more than 40%. maximum conce 40% (See Attack Classification: 1 Citation: 2D T 30 T/ 30 T/ Rqmt Prov: Perr Description: Fa state at any loca unauthorized dis Classification: 30 T/ Rqmt Prov: Mon Description: Fa	udgments, and consent decree         9/29/2016       ADMINORDER         Minor         AC Chapter 305, SubChapter F 305.12         AC Chapter 305, SubChapter F 305.12         Ac Chapter 305, SubChapter F 305.12         Irational Requirements No. 1 PERMIT         siled to properly operate and maintain         umented during an investigation cond         arifier walls (allowing wastewater to fl         the large clarifier was 10.5 feet in a to         Moderate         AC Chapter 305, SubChapter F 305.12         nitoring and Reporting Reqs 7.c PERMIT         silure to provide notification of any eff         Specifically, during the record review         entration for E. coli, daily average con         entrations for total suspended solids w         mment 2).         Moderate         WC Chapter 26, SubChapter F 305.12         AC Chapter 305, SubChapter F 305.12         AC Chapter 305, SubChapter F 305.12         AC Chapter 305, SubChapter F 305.12         Moderate         WC Chapter 305, SubChapter F 305.12         AC Chapter 305, SubChapter F 305.12         AC Chapter 305, SubChapter F 305.12         Moderate         AC Chapter 305, SubChapter F 305.12         AC Chapter 305, SubChapter F 305.12	es:       2016-0103-MWD-E       (1660 Order-Advector)         25(1)       25(5)         a the Facility and all of its systems of collucted on November 16, 2015. Specific ow through gaps between the weir and obtal water depth of 14 feet, and only 1         25(1)         25(1)         25(1)         25(1)         Call of October 2014 to September centration for ammonia nitrogen, and devere noted to have deviated from the period of October 2014 to September centration for ammonia nitrogen, and devere noted to have deviated from the period of October 2014 to September centration for ammonia nitrogen, and devere noted to have deviated from the period of October 2014 to September centration for ammonia nitrogen, and devere noted to have deviated from the period of October 2014 to September centration for ammonia nitrogen, and devere noted to have deviated from the period of October 2014 to September centration for ammonia nitrogen, and devere noted to have deviated from the period of October 2015, discharging 200 gallons of untreated from the period of October 2015, discharging 200 gallons of untreated 25(1)         PERMIT         acompliance which may endanger huma	llection, treatment and cally, the weir panels were not clarifier walls), the sludge out of 3 pumps installed was permitted effluent limitation by 2015, violations of the daily aily average and daily ermitted limit by more than to or adjacent to water in the g the investigation, one ated wastewater.			

30 TAC Chapter 305, SubChapter F 305.125(1) Citation:

30 TAC Chapter 319, SubChapter A 319.9(c)

#### Rqmt Prov: Def and Std Permit Conditions No. 3.a PERMIT Description: Failed to properly collect flow-proportional composite samples. B. Criminal convictions: N/A C. Chronic excessive emissions events: N/A D. The approval dates of investigations (CCEDS Inv. Track. No.): Item 1 November 25, 2015 (1293776)Item 9 July 13, 2017 (1440294)June 07, 2016 Item 2 (1329057)Item 10 October 17, 2017 (1456436)Item 3 December 15, 2016 (1371178)Item 11 November 14, 2017 (1461903)Item 4 March 14, 2017 (1411584)December 15, 2017 Item 12 (1468288)April 17, 2017 Item 5 (1418081)Item 13 January 19, 2018 (1474984)Item 6 May 15, 2017 (1425673)Item 14 December 13, 2019 (1616855)Item 7 May 26, 2017 (1414550)Item 8 June 14, 2017 (1431710)E. Written notices of violations (NOV) (CCEDS Inv. Track. No.): A notice of violation represents a written allegation of a violation of a specific regulatory requirement from the commission to a regulated entity. A notice of violation is not a final enforcement action, nor proof that a violation has actually occurred. 05/31/2019 (1584160) 1 Date: Self Report? YES Classification: Moderate Citation: 2D TWC Chapter 26, SubChapter A 26.121(a) 30 TAC Chapter 305, SubChapter F 305.125(1) Description: Failure to meet the limit for one or more permit parameter 2 Date: 06/30/2019 (1593614) Self Report? YES Classification: Moderate 2D TWC Chapter 26, SubChapter A 26.121(a) Citation: 30 TAC Chapter 305, SubChapter F 305.125(1) Description: Failure to meet the limit for one or more permit parameter 3 07/31/2019 (1599944) Date: Self Report? YES Classification: Moderate 2D TWC Chapter 26, SubChapter A 26.121(a) Citation: 30 TAC Chapter 305, SubChapter F 305.125(1) Description: Failure to meet the limit for one or more permit parameter 4 Date: 08/31/2019 (1606846)Self Report? YES Classification: Moderate Citation: 2D TWC Chapter 26, SubChapter A 26.121(a) 30 TAC Chapter 305, SubChapter F 305.125(1) Failure to meet the limit for one or more permit parameter Description: 5 Date: 09/30/2019 (1613689) Self Report? YES Classification: Moderate Citation: 2D TWC Chapter 26, SubChapter A 26.121(a) 30 TAC Chapter 305, SubChapter F 305.125(1) Description: Failure to meet the limit for one or more permit parameter 6 Date: 10/31/2019 (1619502) Self Report? YES Classification: Moderate 2D TWC Chapter 26, SubChapter A 26.121(a) Citation: 30 TAC Chapter 305, SubChapter F 305.125(1) Failure to meet the limit for one or more permit parameter Description: 7 11/30/2019 (1626855) Date: Self Report? Classification: YES Moderate 2D TWC Chapter 26, SubChapter A 26.121(a) Citation: 30 TAC Chapter 305, SubChapter F 305.125(1) Description: Failure to meet the limit for one or more permit parameter

8 Date: 12/31/2019 (1634496)

	Self Report? Citation:	YES Classification: 2D TWC Chapter 26, SubChapter A 26.121(a) 30 TAC Chapter 305, SubChapter F 305.125(1)	Moderate
	Description:	Failure to meet the limit for one or more permit paramete	r
9	Date: 01,	/31/2020 (1641112)	
	Self Report?	YES Classification:	Moderate
	Citation:	2D TWC Chapter 26, SubChapter A 26.121(a) 30 TAC Chapter 305, SubChapter F 305.125(1)	
	Description:	Failure to meet the limit for one or more permit paramete	r
F. Environ	mental audit	S:	
N/A			

- G. Type of environmental management systems (EMSs): N/A H. Voluntary on-site compliance assessment dates:
  - N/A

- I. Participation in a voluntary pollution reduction program: N/A
- J. Early compliance: N/A

#### Sites Outside of Texas:

N/A

## **TEXAS COMMISSION ON ENVIRONMENTAL QUALITY**



§

8 8 8

Ş

#### IN THE MATTER OF AN ENFORCEMENT ACTION CONCERNING CITY OF POTEET RN102078417

BEFORE THE TEXAS COMMISSION ON ENVIRONMENTAL QUALITY

#### AGREED ORDER DOCKET NO. 2020-0267-MWD-E

#### I. JURISDICTION AND STIPULATIONS

On \_\_\_\_\_\_, the Texas Commission on Environmental Quality ("the Commission" or "TCEQ") considered this agreement of the parties, resolving an enforcement action regarding the City of Poteet (the "Respondent") under the authority of TEX. WATER CODE chs. 7 and 26. The Executive Director of the TCEQ, through the Enforcement Division, and the Respondent together stipulate that:

- 1. The Respondent owns and operates a wastewater treatment facility located at 1304 South 9th Street in Poteet, Atascosa County, Texas (the "Facility"). The Facility is near or adjacent to water in the state as defined in TEX. WATER CODE § 26.001(5).
- 2. The Executive Director and the Respondent agree that the TCEQ has jurisdiction to enter this Order pursuant to TEX. WATER CODE §§ 7.002, 7.051, and 7.073, and that the Respondent is subject to TCEQ's jurisdiction. The TCEQ has jurisdiction in this matter pursuant to TEX. WATER CODE § 5.013 because it alleges violations of TEX. WATER CODE ch. 26 and the rules of the TCEQ.
- 3. The occurrence of any violation is in dispute and the entry of this Order shall not constitute an admission by the Respondent of any violation alleged in Section II ("Allegations"), nor of any statute or rule.
- 4. An administrative penalty in the amount of \$48,874 is assessed by the Commission in settlement of the violations alleged in Section II ("Allegations"). The amount of \$9,774 is deferred contingent upon the Respondent's timely and satisfactory compliance with all the terms of this Order and shall be waived only upon full compliance with all the terms and conditions of this Order. If the Respondent fails to timely and satisfactorily comply with any of the terms and conditions contained in this Order, the Executive Director may demand payment of all or part of the deferred penalty amount.

Pursuant to TEX. WATER CODE § 7.067, \$39,100 of the penalty shall be conditionally offset by the Respondent's timely and satisfactory completion of a Supplemental Environmental Project ("SEP") as defined in the attached SEP Agreement ("Attachment A", incorporated herein by reference). The Respondent's obligation to pay the conditionally offset portion of the penalty shall be discharged upon full compliance with all the terms and conditions of this Order, which includes the timely and satisfactory completion of all provisions of the SEP Agreement, as determined by the Executive Director.

- 5. The Executive Director and the Respondent agree on a settlement of the matters alleged in this enforcement action, subject to final approval in accordance with 30 TEX. ADMIN. CODE § 70.10(a). Any notice and procedures, which might otherwise be authorized or required in this action, are waived in the interest of a more timely resolution of the matter.
- 6. The Executive Director may, without further notice or hearing, refer this matter to the Office of the Attorney General of the State of Texas ("OAG") for further enforcement proceedings if the Executive Director determines that the Respondent has not complied with one or more of the terms or conditions in this Order.
- 7. This Order represents the complete and fully-integrated agreement of the parties. The provisions of this Order are deemed severable and, if a court of competent jurisdiction or other appropriate authority deems any provision of this Order unenforceable, the remaining provisions shall be valid and enforceable.
- 8. This Order shall terminate five years from its effective date or upon compliance with all the terms and conditions set forth in this Order, whichever is later.
- 9. The Executive Director recognizes that the Respondent implemented the following corrective measures at the Facility:
  - a. Tested the reduced-pressure backflow assembly ("RPBA") by December 3, 2018;
  - b. Calibrated the automatic flow measuring devices at the Facility by December 30, 2019;
  - c. Repaired the backup diesel generator by January 10, 2020;
  - d. Repaired the weir panels within the clarifier by February 18, 2020; and
  - e. Replaced the ultraviolet disinfection system at the Facility by January 11, 2021.

City of Poteet DOCKET NO. 2020-0267-MWD-E Page 3

#### **II. ALLEGATIONS**

During an investigation conducted on December 10, 2019, an investigator documented that the Respondent:

- 1. Failed to submit quarterly progress reports, in violation of 30 TEX. ADMIN. CODE § 305.125(1) and Texas Pollutant Discharge Elimination System ("TPDES") Permit No. WQ0013630001, Other Requirements No. 6. Specifically, the Respondent failed to submit quarterly progress reports due the first day of January and April 2019.
- 2. Failed to report to the TCEQ in writing, any effluent violation which deviates from the permitted effluent limitation by more than 40% within five working days of becoming aware of noncompliance, in violation of 30 TEX. ADMIN. CODE § 305.125(1) and (9)(A) and TPDES Permit No. WQ0013630001, Monitoring and Reporting Requirements No. 7.c. Specifically, the Respondent did not provide noncompliance notifications for the exceedances during the monthly monitoring periods of December 2018 through September 2019 and November 2019.
- 3. Failed to install adequate safeguards to prevent the discharge of untreated or inadequately treated wastes during electrical power failures by means of alternate power sources, standby generators, and/or retention, in violation of 30 TEX. ADMIN. CODE § 305.125(1) and (5), and TPDES Permit No. WQ0013630001, Operational Requirements No. 4. Specifically, the backup diesel generator at the Facility was not operational.
- 4. Failed to test the RPBA annually, in violation of 30 TEX. ADMIN. CODE § 317.4(a)(8). Specifically, the RPBA was not tested by the June 10, 2018 due date.
- 5. Failed to ensure the Facility and all of its systems of collection, treatment, and disposal are properly operated and maintained, in violation of 30 TEX. ADMIN. CODE § 305.125(1) and (5) and TPDES Permit No. WQ0013630001, Operational Requirements No. 1. Specifically, weir panels within the clarifier were partially separated which allowed wastewater between the weir panels and the clarifier wall into the trough; and of the three banks of ultraviolet lights used for disinfection, one was in disrepair and the other two appeared to have missing or dim bulbs.
- 6. Failed to accurately calibrate all automatic flow measuring or recording devices and all totalizing meters for measuring flow and failed to have flow measurements, equipment, installation, and procedures conform to those prescribed in the Water Measurement Manual, United States Department of the Interior Bureau of Reclamation, Washington, D.C., or methods that are equivalent as approved, in violation of 30 TEX. ADMIN. CODE §§ 319.11(d) and 305.125(1) and TPDES Permit No. WQ0013630001, Monitoring and Reporting Requirements No. 5. Specifically, the automatic flow meter was measuring a greater than 10% difference than the staff gauge and readings during peak flow were off the circle flow chart.

City of Poteet DOCKET NO. 2020-0267-MWD-E Page 4

#### **III. DENIALS**

The Respondent generally denies each allegation in Section II ("Allegations").

#### **IV. ORDERING PROVISIONS**

NOW, THEREFORE, THE TEXAS COMMISSION ON ENVIRONMENTAL QUALITY ORDERS that:

1. The Respondent is assessed a penalty as set forth in Section I, Paragraph No. 4. The payment of this penalty and the Respondent's compliance with all of the requirements set forth in this Order resolve only the allegations in Section II. The Commission shall not be constrained in any manner from requiring corrective action or penalties for violations which are not raised here. Penalty payments shall be made payable to "TCEQ" and shall be sent with the notation "Re: City of Poteet, Docket No. 2020-0267-MWD-E" to:

Financial Administration Division, Revenue Operations Section Attention: Cashier's Office, MC 214 Texas Commission on Environmental Quality P.O. Box 13088 Austin, Texas 78711-3088

- 2. The Respondent implemented and completed an SEP as set forth in Section I, Paragraph No. 4. The amount of \$39,100 of the assessed penalty is conditionally offset based on the Respondent's implementation and completion of the SEP pursuant to the terms of the SEP Agreement, as defined in Attachment A. Penalty payments for any portion of the SEP deemed by the Executive Director as not complete shall be paid within 30 days after the date the Executive Director demands payment.
- 3. All relief not expressly granted in this Order is denied.
- 4. The duties and provisions imposed by this Order shall apply to and be binding upon the Respondent. The Respondent is ordered to give notice of this Order to personnel who maintain day-to-day control over the Facility operations referenced in this Order.
- 5. If the Respondent fails to comply with any of the Ordering Provisions in this Order within the prescribed schedules, and that failure is caused solely by an act of God, war, strike, riot, or other catastrophe, the Respondent's failure to comply is not a violation of this Order. The Respondent shall have the burden of establishing to the Executive Director's satisfaction that such an event has occurred. The Respondent shall notify the Executive Director within seven days after the Respondent becomes aware of a delaying event and shall take all reasonable measures to mitigate and minimize any delay.
- 6. The Executive Director may grant an extension of any deadline in this Order or in any plan, report, or other document submitted pursuant to this Order, upon a written and substantiated showing of good cause. All requests for extensions by the Respondent shall be made in writing to the Executive Director. Extensions are not effective until the Respondent receives written approval from the Executive Director. The determination of what constitutes good cause rests solely with the Executive Director.

- 7. This Order, issued by the Commission, shall not be admissible against the Respondent in a civil proceeding, unless the proceeding is brought by the OAG to: (1) enforce the terms of this Order; or (2) pursue violations of a statute within the Commission's jurisdiction, or of a rule adopted or an order or permit issued by the Commission under such a statute.
- 8. This Order may be executed in separate and multiple counterparts, which together shall constitute a single instrument. Any page of this Order may be copied, scanned, digitized, converted to electronic portable document format ("pdf"), or otherwise reproduced and may be transmitted by digital or electronic transmission, including but not limited to facsimile transmission and electronic mail. Any signature affixed to this Order shall constitute an original signature for all purposes and may be used, filed, substituted, or issued for any purpose for which an original signature could be used. The term "signature" shall include manual signatures and true and accurate reproductions of manual signatures created, executed, endorsed, adopted, or authorized by the person or persons to whom the signatures are attributable. Signatures may be copied or reproduced digitally, electronically, by photocopying, engraving, imprinting, lithographing, electronic mail, facsimile transmission, stamping, or any other means or process which the Executive Director deems acceptable. In this paragraph exclusively, the terms: electronic transmission, owner, person, writing, and written, shall have the meanings assigned to them under TEX. BUS. ORG. CODE § 1.002.
- 9. The effective date of this Order is the date it is signed by the Commission. A copy of this fully executed Order shall be provided to each of the parties.

City of Poteet DOCKET NO. 2020-0267-MWD-E Page 6

#### SIGNATURE PAGE

#### TEXAS COMMISSION ON ENVIRONMENTAL QUALITY

For the Commission

Date

For the Executive Director

3/7/2022 Date

I, the undersigned, have read and understand the attached Order. I am authorized to agree to the attached Order, and I do agree to the terms and conditions specified therein. I further acknowledge that the TCEQ, in accepting payment for the penalty amount, is materially relying on such representation.

I also understand that failure to comply with the Ordering Provisions, if any, in this Order and/or failure to timely pay the penalty amount, may result in:

- A negative impact on compliance history;
- Greater scrutiny of any permit applications submitted;
- Referral of this case to the Attorney General's Office for contempt, injunctive relief, additional penalties, and/or attorney fees, or to a collection agency;
- Increased penalties in any future enforcement actions;
- Automatic referral to the Attorney General's Office of any future enforcement actions; and
- TCEQ seeking other relief as authorized by law.

In addition, any falsification of any compliance documents may result in criminal prosecution.

O2f07/2022 Date City administrator

Name (Printed or typed) Authorized Representative of City of Poteet

□ If mailing address has changed, please check this box and provide the new address below:

#### Attachment A

#### Docket Number: 2020-0267-MWD-E

#### SUPPLEMENTAL ENVIRONMENTAL PROJECT

Respondent:	City of Poteet
Penalty Amount:	Thirty-Nine Thousand One Hundred Dollars (\$39,100)
SEP Offset Amount:	Thirty-Nine Thousand One Hundred Dollars (\$39,100)
Type of SEP:	Compliance
Project Name:	Poteet UV System Improvements
Location of SEP:	Atascosa County

The Texas Commission on Environmental Quality ("TCEQ") agrees to offset the administrative Penalty Amount assessed in this Agreed Order for Respondent to perform a Supplemental Environmental Project ("SEP").

Respondent is a Local Government that qualifies under Texas Water Code § 7.067 to apply the SEP Offset Amount set forth above to correct violations at its wastewater treatment facility (the "Facility") which are described in this Agreed Order.

#### 1. Project Description

#### A. Project

Respondent hired a contractor to purchase and replace the UV disinfection system at the Facility. Specifically, the SEP Offset Amount was used for materials, supplies, and equipment for the removal and replacement of the UV disinfection system (the "Project"). Respondent hired qualified contractors to perform the Project. The SEP was performed in accordance with all federal, state, and local environmental laws and regulations.

Respondent used the SEP Offset Amount only for the direct cost of implementing the Project, including supplies, materials, and equipment rentals, as listed in Subsection C. Expenses, below. No portion of the SEP Offset Amount was spent on administrative costs, including but not limited to operating costs, reporting expenses, handling of expenses, project coordination, liability, or equipment breakdowns.

Respondent's signature affixed to the attached Agreed Order certifies that Respondent had no prior commitment to perform this Project and that the SEP was performed solely as part of the terms of settlement in this enforcement action.

#### B. Environmental Benefit

This SEP will provide a discernible environmental benefit by improving the quality of wastewater effluent being released into the environment. Inadequately treated effluent can carry bacteria, viruses, protozoa (parasitic organisms), helminths (intestinal worms), and bioaerosols (inhalable molds and fungi). The diseases they may cause range in severity from mild gastroenteritis to life-threatening ailments such as cholera, dysentery, infectious hepatitis, and severe gastroenteritis. Additional risks include occurrences of low dissolved oxygen, fish kills, algal bloom, and bacterial contamination in waterways.

#### City of Poteet Docket No. 2020-0267-MWD-E Attachment A

#### C. Expenses

Respondent spent at least the SEP Offset Amount to complete the project described in Section 1, above, and complied with all other provisions of this SEP. Respondent understood that it may have cost more than the SEP Offset Amount to complete the Project.

#### Expenses

Item	Units	Total
UV Disinfection System Removal and Replacement	LS	\$131,670
Total		\$131,670

#### 2. Records

As of January 11, 2021, Respondent provided TCEQ the following documentation as proof of completion of the proposed SEP:

- 1. Itemized list of expenditures and total cost of the Project;
- 2. Copies of invoices or receipts corresponding to the itemized list in paragraph 2.1., above;
- 3. Copies of cleared checks or payment records corresponding to the itemized list in paragraph 2.1., above;
- 4. A certified statement of SEP completion and document authentication;
- 5. Copies of all engineering plans related to work performed pursuant to the Project, if applicable;
- 6. Detailed map showing specific location of the project site(s); and
- 7. Dated photographs of the purchased materials and supplies; before and after work being performed during the Project; and of the completed Project.

#### 3. Additional Information and Access

Respondent shall provide additional information as requested by TCEQ staff and shall allow access to all records related to the SEP Offset Amount. Respondent shall also allow representatives of the TCEQ access to the site of any work being financed in whole or in part by the SEP Offset Amount. This provision shall survive the termination of this Agreed Order.

#### 4. Failure to Fully Perform

If Respondent does not perform its obligations under this Attachment A, including full expenditure of the SEP Offset Amount and submittal of the required reporting described in Sections 2 through 4 above, the Executive Director ("ED") may require immediate payment of all or part of the SEP Offset Amount as set forth in the attached Agreed Order.

In the event the ED determines that Respondent failed to fully implement and complete the Project, Respondent shall remit payment for all or a portion of the SEP Offset Amount, as determined by the ED, and as set forth in the attached Agreed Order. After receiving notice of failure to complete the SEP, Respondent shall include the docket number of the attached Agreed Order and a note that the enclosed payment is for reimbursement of a SEP, shall make the check payable to "Texas Commission on Environmental Quality," and shall mail it to:

City of Poteet Docket No. 2020-0267-MWD-E Attachment A

> Texas Commission on Environmental Quality Litigation Division Attention: SEP Coordinator, MC 175 P.O. Box 13087 Austin, Texas 78711-3087

#### 5. Publicity

Any public statements concerning this Project made by or on behalf of Respondent must include a clear statement that **the Project was performed as part of the settlement of an enforcement action brought by TCEQ**. Such statements include advertising, public relations, and press releases.

#### 6. Recognition

Respondent may not seek recognition for this project in any other state or federal regulatory program.

#### 7. Other SEPs by TCEQ or Other Agencies

The SEP Offset Amount identified in this Attachment A and in the attached Agreed Order has not been, and shall not be, included as a SEP for Respondent under any other Agreed Order negotiated with TCEQ or any other agency of the state or federal government.