

Mobile Air Monitoring Vans - Summary of Survey Results

Date	Survey Location	Reported Start Time	Reported End Time	SO2 (ppb)			Benzene (ppb)			Toluene (ppb)			Xylenes/Ethylbenzene (ppb)			Styrene (ppb)			1,3-Butadiene (ppb)			H2S (ppb)		
				Min	Max	LOD	Min	Max	LOD	Min	Max	LOD	Min	Max	LOD	Min	Max	LOD	Min	Max	LOD	Min	Max	LOD
8/28/2020	Hemlock Street & Fulton Avenue, Charlton-Pollard Neighborhood, Beaumont, TX	14:48	14:55	0.0	2.5	5.0	0.0	0.0	2.0	1.9	5.6	6.0	--	--	--	0.0	0.4	2.0	0.0	0.0	5.0	--	--	--
8/28/2020	Hemlock Street & Fulton Avenue, Charlton-Pollard Neighborhood, Beaumont, TX	14:46	14:56	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	0.0	9.1	5.0
8/28/2020	Hemlock Street & Fulton Avenue, Charlton-Pollard Neighborhood, Beaumont, TX	15:01	15:12	0.0	0.0	5.0	0.0	0.0	2.0	0.0	6.2	6.0	--	--	--	0.0	1.1	2.0	0.0	0.0	5.0	--	--	--
8/28/2020	Hemlock Street & Fulton Avenue, Charlton-Pollard Neighborhood, Beaumont, TX	14:59	15:13	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	0.0	9.4	5.0